

Government of Maharashtra Water Resources Department



Superintending Engineer Dam Safety Organisation Nashik Chief Engineer Hydrology & Dam Safety Nashik

Director General Design, Training, Hydrology, Research and Safety, MERI, Nashik

Superintending Engineer Dam Safety Organisation Dindori Road, Nashik-422004. Phone (Off.): 0253 – 2530030. Fax: 0253 – 2530030. E-mail: <u>se.damsafety@gmail.com</u>	स्वयेव क्यते महाराष्ट्र शासन, जलसंपदा विभाग Government Of Maharashtra Water Resources Department	अधीक्षक अभियंता, धरण सुरक्षितता संघटना, दिंडोरी मार्ग, नाशिक - ४२२ ००४. दूरध्वनी (ऑ.): ०२५३ - २५३००३० फॅक्स : ०२५३ - २५३००३०. ई-मेल : <u>se.damsafety@gmail.com</u>
जा क धसविक १/ध मिंग आ (ए) २०२१ २२	1200/2022	Entre · 29 /90/2022

ई-मेल व्दारे

प्रति,

मा. कार्यकारी संचालक,

कृष्णा खोरे पाटबंधारे विकास महामंडळ, पुणे.

विषय :- धरण स्थिती अहवाल २०२१-२२ (पुणे प्रदेश)

संदर्भ :- १) शासन, पाटबंधारे विभागाचे पत्र क्र .पा .वि.१०७७ / २४०२/ १८६७/२ दिनांक- १९/०१/१९८२ २) शासन ,जलसंपदा विभागाचे पत्र क्र. संकीर्ण २०१४ /(२२०/२०१४)/सिं.व्य. (कामे) दि. ९/१०/२०१५

संदर्भिय शासन पत्र क्र. १ अन्वये आपले अधिनस्त अधीक्षक अभियंता व कार्यकारी अभियंत्याकडून या कार्यालयास प्राप्त झालेल्या पुणे विभागातील पर्जन्य पूर्व व पर्जन्योत्तर २०२१ धरण निरिक्षण अहवालांची छाननी तसेच धरण सुरक्षितता संघटनेकडुन करण्यात आलेल्या Test Inspection नुसार सन २०२१-२२ वर्षाचा धरण स्थिती अहवाल संदर्भ पत्र क्र. २ अन्वये प्राप्त निर्देशा नसार मा. महासंचालक, संप्रजसंवसु, मेरी, नाशिक यांचेकडुन प्रकाशीत करण्यात आलेला आहे.

मा. महासंचालक, संप्रजसंवसु, मेरी, नाशिक यांचे निर्देशानुसार

१) उपरोक्त प्रकाशीत धरण स्थिती अहवालातील प्रस्तावनेच्या अनुषंगाने भुद्येनिहाय अनुपालन अहवाल या कार्यालयास पार्जवण्याचे निर्देश संबंधित अधीक्षक अभियंता यांना आपल्या स्तरावरुन देण्यात यावेत ही विनंती.

२) सदरचा अहवाल दरवर्षी एप्रिल महिन्यात प्रकाशीत करण्यासंबंधी धरण सुरक्षा देखरेख संचालनालय, केंद्रिय जल आतेल, नर्ज दिल्ली यांचे निर्देश आहेत. तथापि संबंधित अधीक्षक अभियंता व कार्यकारी अभियंता यांच्याकडुन पर्जन्य पुर्व व पर्लन्योत्तर पहली अहवाल तसेच अधीक्षक अभियंता मार्फत प्राप्त होणारे त्रुटी पुर्वता अहवाल विहीत कालावधीत प्राप्त होत नसल्याने स्वरण दरण स्थिती अहवाल प्रकाशीत करण्यास विलंब झालेला आहे. यास्तव पाहणी व त्रुटी पुर्वता अहवाल विहीत कालावधीत कालावधीत पाठ यावेत. याबाबत आपल्या स्तरावरुन संबंधित अधीक्षक अभियंता यांना निर्देश देण्याची विनंती आहे.

३) महामंडळ स्तरावरुन त्रुटी दूर करण्यासाठी आवश्यक निधी उपलब्ध करुन देण्याची व आवश्यकतेनुरुप सनियंत्रण करण्याची विनंती आहे, जेणेकरुन धरण सुरक्षित ठेवण्यास मदत होईल.

४) शासन निर्णय संकीर्ण. २०१६ (८८/१६)) / आयएम (डब्ल्यू) दि.९/५/२०१६, नुसार पुढील कार्यवाही करण्यात दावी हि विनंतो.

५) धरण तपासणी अहवालातील त्रुटीचा पुर्तता अहवाल व पर्जन्य पुर्व व पर्जन्योत्तर पाहणी अहवाल विहीत कालावधीत धरण सुरक्षितता संघटना, नाशिक येथे प्राप्त होणेच्या अनुषंगाने संबंधित अधीक्षक अभियंता (वर्ग-१ धरणांसाठी) व कार्यकारी अभियंता (वर्ग-२ धरणांसाठी) यांना आपल्या स्तरावरुन कळविण्यात यावे ही विनंती.

६) पृणे विभागाचा एकत्रित धरणस्थिती अहवाल -२०२१-२२ चे अवलोकन केले असता वर्ग-२ थरणांचे ०३ पावसाळा पूर्व २०२१ व तसेच वर्ग-१ धरणांचे ४ व वर्ग-२ थरणांचे ३१ पावसाळोत्तर २०२१ धरण निरिक्षण अहवाल प्राप्त ज़ाले नाहीत.

७) मा. महासंचालक मेरी, नाशिक यांचे वर्ग-१ व वर्ग-२ धरणांचे पावसाळा पुर्व व पावसाळोत्तर तपासणी अहवालासोबन धरणांवरील विशेष त्रुटीबाबतचे प्रपत्र (संदर्भ परिच्छेद क्र. १.११) तांत्रिक परिपत्रक जा. क्र. सं.प्र.ज.सं व सु/भ अ सं/प्रशा/अधि/८८/सन २०२०, दि. २१/७/२०२० सादर करण्याबाबत सर्व संबंधीतांना आपले स्तरावर सूचना देण्यान यात्यात ही विलंती. 8) दि. 30/12/2021 पासुन संपूर्ण देशात धरण सुरक्षा कायदा-2021 लागू करण्यात आला आहे. सदर कायदयाच्या पार्श्वभूमिवर राज्यातील वर्ग-1 व वर्ग-2 धरणांचे पावसाळापुर्व व पावसाळोत्तर तपासणी अहवाल व त्रुटीचा पुर्तता अहवाल बेळेत सादर करण्याचे निर्देश संबंधित अधीक्षक अभियंता यांना आपल्या स्तरावरुन देण्यात यावेत ही विनंती, जेणेकरुन पुणे विभागाचा एकत्रित धरणस्थिती अहवाल वेळेत प्रकाशित करणे सोयीचे होईल.

हे आपले माहितीस्तव व पुढील कार्यवाहीसाठी सविनय सादर.

सहपत्र : धरण स्थिती अहवाल २०२१-२२(पुणे प्रदेश)

NIN (म. श. आमले) अधीक्षक अभियंता.

राज्य धरण सुरक्षितता संघटना, उद्दब्ध<u>्या न</u>ाशिक

प्रत- मा. सचिव (जसंव्य व लाक्षेवि), जलसंपदा विभाग, मंत्रालय, मुंबई यांना अहवालासह महितीस्तव सादर.

प्रत- मा. महासंचालक, संकल्पन, प्रशिक्षण, जलविज्ञान, संशोधन व सुरक्षितता, मेरी, नासिक यांना अहवालासह माहितीस्तव सादर.

प्रत- मुख्य अभियंता, जलविज्ञान व धरण सुरक्षितता, नाशिक यांना अहवालासह माहितीकरीता सादर.

प्रत- मुख्य अभियंता, यात्रिकी (जलसंपदा विभाग), नाशिक यांना अहवालासह माहितीस्तव सादर.

प्रत- मा. मुख्य अभियंता (ज.सं), जलसंपदा विभाग, पुणे यांना अहवाला सह माहिती स्तव सादर.

प्रत- मा. मुख्य अभियंता (वि. प्र), जलसंपदा विभाग,पुणे यांना अहवालासह माहितीस्तव सादर.

प्रत,

१.अधीक्षक अभियंता, पुणे पाटबंधारे मंडळ, पुणे.

२.अधीक्षक अभियंता, पुणे पाटबंधारे प्रकल्प मंडळ, पुणे.

३.अधीक्षक अभियंता, कोल्हापूर पाटबंधारे मंडळ, कोल्हापूर.

४.अधीक्षक अभियंता, सांगली पाटबंधारे मंडळ, सांगली.

५.अधीक्षक अभियंता, व प्रशासक, लाभक्षेत्र विकास प्राधिकरण, पुणे.

६.अधीक्षक अभियंता, कुकडी पाटबंधारे मंडळ, पुणे.

७ अधीक्षक अभियंता, सातारा पाटबंधारे प्रकल्प मंडळ, सातारा.

८.अधीक्षक अभियंता, व प्रशासक, लाभक्षेत्र विकास प्राधिकरण, सोलापूर.

९.अधीक्षक अभियंता, भीमा कालवे मंडळ, सोलापूर

१० अधीक्षक अभियंता, सातारा पाटबंधारे मंडळ, सातारा

११.अधीक्षक अभियंता, (धरण व दरवाजे), म. सं. चि. सं., नाशिक.

१२ व्यवस्थापक, टाटा पॉवर कंपनी लिमिटेड, मुंबई - पुणे रस्ता, लोणावळा कॅम्प, लोणावळा, ता.मावळ, जि. पुणे.

१३.व्यवस्थापक, ॲम्बी व्हॅली सिटी, सहारा इंडिया कॉर्पोरेशन साइट, ऑफिस कॉम्प्लेक्स अंबवणे, ता. मुळशी, जि.पुणे.

१४.स्टेशन कमांडर,आय एन यस शिवाजी,लोणावळा,पुणे.

१५.मुख्य आस्थापना अधिकारी, सिम्बायोसिस विद्यापीठ,पुणे.

१६.मा.आयुक्त, कोल्हापूर महानगरपालिका, कोल्हापूर.

१७.मुख्याधिकारी,कागल नगर परिषद, कागल जि. कोल्हापूर.

१८.धरण अधिकारी,सर पिराजीराव तलाव,मुरगुड जि. कोल्हापूर

यांना साहितीस्तव व पुढील योग्य त्या कार्यवाहीस्तव अहवालासह सस्नेह अग्रेषित.

२/- कृपया वरोल अहवालाची प्रत मिळाल्याची पोहच या कार्यालयास पाठवावी हि विनंती.

१.कार्यकारी अभियंता, पुणे पाटबंधारे विभाग, पुणे. २.कार्यकारी अभियंता, खडकवासला पाटबंधारे विभाग, पुणे. ३.कार्यकारी अभियंता, उपसा सिंचन व्यवस्थापन विभाग, पुणे. ४.कार्यकारी अभियंता, नीरा उजवा कालवा विभाग, फलटण. जि. सातारा. ५.कार्यकारी अभियंता, भामा आसखेड धरण विभाग, पुणे. ६.कार्यकारी अभियंता, नीरा देवघर प्रकल्प विभाग, सांगवी (भाटघर) जि. पुणे ७.कार्यकारी अभियंता, टेमघर प्रकल्प विभाग, पुणे. ८.कार्यकारी अभियंता, द्धगंगा कालवे विभाग क्र.१, कोल्हापूर. ९.कार्यकारी अभियंता, मध्यम प्रकल्प विभाग क्र. २, कोल्हापूर. १०.कार्यकारी अभियंता, लघु पाटबंधारे विभाग, (उत्तर) कोल्हापूर. ११.कार्यकारी अभियंता, सांगली पाटबंधारे विभाग, सांगली. १२.कार्यकारी अभियंता, कोल्हापूर पाटबंधारे विभाग, (दक्षिण) कोल्हापूर . १३.कार्यकारी अभियंता, कुकडी पाटबंधारे विभाग, क्र. १, नारायणगाव जि. पुणे १४.कार्यकारी अभियंता, कुंकडी पाटबंधारे विभाग, क्र. २, श्रीगोंदा, जि.अहमदनगर. १५.कार्यकारी अभियंता, धोम पाटबंधारे विभाग, सातारा. १६.कार्यकारी अभियंता, पिंपळगाव जोगे धरण विभाग, नारायणगाव जि. पुणे. १७.कार्यकारी अभियंता, डिंभे धरण विभाग, मंचर, जिल्हा पुणे. १८.कार्यकारी अभियंता, लघु पाटबंधारे विभाग, सातारा. १९.कार्यकारी अभियंता, कण्हेर कालवे विभाग क्र. १, कारवाडी (कराड). २०.कार्यकारी अभियंता, कण्हेर कालवे विभाग क्र. २, वाई, जिल्हा सातारा. २१. कार्यकारी अभियंता. उरमोडी धरण विभाग. सातारा. २२.कार्यकारी अभियंता, धोम बलकवडी प्रकल्प विभाग, वाई, जिल्हा सातारा. २३.कार्यकारी अभियंता, उजनी धरण व्यवस्थापन विभाग, भीमानगर, ता.माढा, जि. सोलापूर. २४.कार्यकारी अभियंता, सोलापूर पाटबंधारे विभाग, सोलापूर. २५.कार्यकारी अभियंता, भीमा विकास विभाग क्र. २, सोलापूर. २६.कार्यकारी अभियंता, लघु पाटबंधारे विभाग क्र. १, सोलापूर. २७कार्यकारी अभियंता, उजनी कालवा विभाग क्र. ८, सोलापूर. २८.कार्यकारी अभियंता, कोयना धरण व्यवस्थापन विभाग, कोयनानगर, जि.सातारां. २९.कार्यकारी अभियंता, चासकमान पाटबंधारे विभाग पुणे. यांना माहितीसाठी व पढील योग्य त्या कार्यवाहीसाठी अहवालासह रवाना.

दोष व त्रुटी बद्दल त्वरीत कार्यवाही करुन अनुपालन / पुर्तता अहवाल संबंधित मंडळ कार्यालयामार्फत धरण सुरक्षितता संघटना, नाशिक येथे त्वरित पाठवावे.

२/- सदंर अंहवालाची प्रत ई-मेल व्दारे पाठविण्यात आलेली आहे.

- **प्रत** कार्यकारी अभियंता, धरण सुरक्षा विभाग क्र .३, नाशिक ४ २/- यांना ग्रंथालयात संग्रहासाठी.
- प्रत ग्रंथालय, मध्यवर्ती संकल्पचित्र संघटना, नाशिक यांना अहवालाच्या प्रतीसह माहितीसाठी.

प्रत,

FOREWORD

- 1.0 Annual Dam Health Status Report (ADHSR) 2021-22 of Class-I & Class-II Dams in Pune Region is prepared based on the Inspection Reports (Pre and Post Monsoon 2021) received from field offices and Test Inspections carried out by Dam Safety Organization (DSO), Nashik during Year 2021-22. The period of the report is from April 2021 to March 2022.
- 2.0 This Report comprises of following Parts.

Part	Description
Part-1	General Information
Part-2	Action Taken Report (ATR)
Part-3	Annual Dam Health Status Report (ADHSR) of Pre & Post Monsoon 2021-22
Part-4	Annual Performance Report of Dam Instruments
Part-5	Annual Performance Report of Meteorological Instruments
Part-6	National Committee on Dam Safety (NCDS) Documents
Part-7	Dam Health and Rehabilitation Monitoring Application (DHARMA)
Part-8	Health Status of Gated Dam (As per Mechanical Organization)

Part-1 & Part-6 to 8 are envisaged by DSO, Nashik & Part-2 to 5 are in the format provided by Dam Safety Monitoring Directorate, Central Water Commission, New Delhi vide letter No. 3/19/NCDS/HS/DSM/2001/627-56 Dated 28/08/2002.

- 2.1 Part-1: Covers General Information viz. Time schedule of Inspection, Classification of Dams, Inspection Authorities, Preparation of ADHSR for Class-I & Class-II Dams, Categorization and Standardization of Deficiencies, NRLD updation, which will be helpful to field officers. Inspecting officers are requested to follow the suggestion given in 'Part-1' while carrying out forthcoming Pre/Post Monsoon inspections of dams.
- 2.2 Part-2: Covers Action Taken Report (ATR) on Deficiencies pointed out in last Year ADHSR 2020-21 & Status of efforts taken by field office.
- 2.3 Part-3: Covers condensed summary of Dam deficiencies noticed during inspection carried out by field officer and Dam safety Organization in the Year 2021-22.
- 2.4 Part-4: Covers details of Instrumentation provided in or on Dams & its Functionality. Prepared by Instrumentation and Research Division, Nashik.
- 2.5 Part-5: Covers details of Metrological Instrumentation provided at Dam Site & its Functionality. Prepared by Instrumentation and Research Division, Nashik.
- 2.6 Part-6: Covers status of Documents (EAP, ROS & GOS, Data Book, O & M Manual, Record Drawing, Completion Report) recommended by National Committee on Dam Safety.
- 2.7 Part-7: Covers Progress of updation of Dam Information filled in DHARMA Web Portal.
- 2.8 Part-8: Covers status of Action Taken Report on Deficiencies pointed out in ADHSR- 2020-21 & Deficiencies observed in ADHSR- 2021 of Mechanical Organization for Gated Dams.
- 3.0 This report covers Dam Health Status of 69 Class-I &193 Class-II Dams owned by WRD and Also covers 7 Class-I & 10 Class-II Private Owned Dams.

ADHSR_2021-22 (Pune)

4.0. There are total 262 Govt owned Dams in this Region. Out of 524 expected Inspection Reports,

this ADHSR is based on 488 Inspection Reports received in DSO, Nashik.

Dam Owner	Expected Inspection Report in DSO			Inspection Report Received in DSO			Inspection Report Not Received in DSO		
	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
WRD	138	386	524	134	354	488	4	32	36
Private	14	20	34	4	10	14	10	10	20
Total	152	406	558	138	364	502	14	42	56

Status of Receipt of Inspection Report 2021-22 (Ref. Table- 3.1 & 3.3)

Dams having Deficiencies (Ref. Table- 3.6)

		No. of Dams								
Dam owner	Year	Class of Dam To		Total	Class-I dams having Deficiencies			Class-II dams having Deficiencies		
					Cat-I	Cat-II	Cat-III	Cat-I	Cat-II	Cat-III
WDD	2020-21	69	193	262	00	54	69	0	71	193
W.R.D	2021-22	69	193	262	00	65	69	00	111	191
Drivoto	2020-21	07	10	17	00	06	7	00	05	10
Flivale	2021-22	07	10	17	00	04	04	00	07	10
Total	2020-21	76	203	279	0	60	76	0	76	203
	2021-22	76	203	279	00	69	73	00	118	201

Category wise Deficiencies

		No. of Deficiencies									
Dam	Voor	Category-1		Category-2			Category-3				
owner	rear	Cla	ass	Total	Class Total		Total	Class		Total	
				Totai			rolai			rolai	
	2020-21	00	00	00	418	150	568	797	1551	2348	
W.R.D	2021-22	00	00	00	469	187	656	996	1645	2641	
Drivato	2020-21	00	00	00	08	10	18	25	45	70	
Privale	2021-22	00	00	00	05	17	22	18	62	80	
Total	2020-21	00	00	00	426	160	586	822	1596	2418	
	2021-22	00	00	00	474	204	678	1014	1707	2721	

(Ref. Table- 3.7)

Gated Dams having Deficiencies (Class-I)(As per Mechanical Organization) (Ref. Table- 8.1)

_		Number of	No. of	No. of	Number of Deficiencies			
Dam	Year	Gated	dams	dams	Category			
owner		Dams	inspected	deficiencies	Category-1	Category-2	Category-3	
W.R.D	2020-21	40	37	37	0	724	1613	
	2021-22	39	39	39	0	858	2114	
Privato	2020-21	02	01	01	0	07	29	
Private	2021-22	01	01	01	0	05	35	
Total	2020-21	42	38	38	0	731	1642	
	2021-22	40	40	40	0	863	2149	

- 5.0: The responsibility of Health and Safety Monitoring of Class-III dams lies with the respective Chief Engineers. Hence for Class-III Dams based on periodical inspection reports, Annual Dam Health Status Report should be prepared & published by concerned Field Chief Engineers with submission to Government & forwarded to DSO, Nashik for record.
- 6.0: The deficiencies shown in the present report are based on the Pre/ Post Monsoon Inspections of the Dams carried out by the field officers and reports of them received by this organization. As such, the deficiencies and action taken thereof is the sole responsibility of the field officers.

7.0 Conclusions :

Government Owned Class-I Dams :

7.01 : Category-1 Deficiency is Not noticed in all 69 Dams.
7.02 :469 No. of Category-2 Deficiencies in 65 out of total 69 No. of Dams are noticed.
7.03 :996 No. of Category-3 Deficiencies in total 69 Dams are noticed.
7.04: Out of ATR expected for 445 No. of Category-2 Deficiencies, field action for removal of Deficiencies is noticed for 43 Deficiencies (Physically fully completed -43 & Physically partly completed-31) only.

Government Owned Class-II Dams :

7.05: Category-1 Deficiency is Not noticed in all 193 Dams.

7.06:187 No. of Category-2 Deficiencies in 111 out of total 191 No. of Dams are noticed.

7.07:1645 No. of Category-3 Deficiencies in total 191 Dams are noticed.

7.08:Out of ATR expected for 147 No. of Category-2 Deficiencies, field action for removal of Deficiencies is noticed for 1 Deficiencies (physically fully complied)Completed.

Private Owned Class-I Dams :

7.09: Category-1 Deficiency is Not noticed in all 04 Dams.

7.10 :05 No. of Category-2 Deficiencies in 04 out of total 04 No. of Dams are noticed..

7.11 :18 No. of Category-3 Deficiencies in total 04 Dams are noticed.

7.12:Out of ATR expected for 8 No. of Category-2 Deficiencies, No field action is noticed for removal of Deficiencies.

Private Owned Class-II Dams :

7.13:Category-1 Deficiency is Not noticed in all 10 Dams.

7.14 :17 No. of Category-2 Deficiencies in total 07Dams are noticed.

7.15 : 62 No. of Category-3 Deficiencies in total 10 Dams are noticed.

7.16 : Out of ATR expected for 10 No. of Category-2 Deficiencies, No field action is noticed for removal of Deficiencies.

- 8. Points of Attention:
 - 8.01: It is mandatory that Pre Monsoon Inspection Report must be submitted to DSO, Nashik by 30thJune & Post Monsoon Inspection Report must be submitted to DSO, Nashik by 31stDecember every Year.
 - 8.02: As per Dam Safety Monitoring Directorate, Central Water Commission, New Delhi Annual Dam Health Status Report (ADHSR) must be submitted in the month April every Year.
 - 8.03: It is pointed out that only 47 (8.97 %) Pre & Post Monsoon Reports out of 524 Pre & Post Monsoon Reports are received in stipulated period.
 441 (84.16 %) Pre & Post Monsoon Reports are received out of 524 Pre & Post Monsoon Reports after rigorous follow up by DSO officials & 36 (6.87 %) reports out of 594 Pre & Post Monsoon Reports were not received at all. All field officers & Higher Authorities shall take serious note of this in light of enactment of Dam Safety Act 2021.
 - 8.04: ATR expected for 134 No. of Dams (610 Cat-2 Deficiencies). However ATR was received for 30 No. (192 Cat-2 Deficiencies) of Dams i.e. only 22.91 % of Cat-2 Deficiencies fully addressed & for 30 No. (192 Cat-2 Deficiencies) of Dams i.e. only 16.66 % of Cat-2 Deficiencies partially addressed.
 - 8.05: Concerned Chief Engineer should monitor and instruct field Superintending Engineer & Executive Engineer regarding submission of ATR to DSO, Nashik to reflect exact status of Dam Safety works.
 - 8.06: The Chief Engineers should compel all Superintending Engineer & Executive Engineer of concerned Dams to carry out periodic inspections and submit report to D.S.O. in time. Brain storming of field officer regarding Dam Safety aspect is must otherwise the whole exercise done by Dam Safety Organization tends to become futile.
 - 8.07: In case of Mechanical Organization inspections, Out of ATR expected for 888 No. of Category-2 Deficiencies, 33 Action Taken Report (ATR) from field for removal of Deficiencies are received
 - 8.08: Earthen dam uprooting of trees & shrubs grown on embankment of Dam follow CWC guidelines for safety of dams 2018. [Page 54/90]
 - 8.09: Review of a need for painting of Gates & structural parts to avoid further deterioration in consultation with Mechanical organization.
 - 8.10: Being the dam owner, safety of the dam is the prime responsibility of the concerned field Executive Engineer. In order to ensure safety of dam/dams in his jurisdiction, he shall initiate The procedures for removal of deficiencies noticed in the Pre-Post Monsoon Inspection as well as pointed out in this ADHSR by following due procedure of approval.
 - 8.11: Higher authorities i.e. Superintending Engineer and Chief Engineer shall accord timely sanction to most economical and sustainable technical work required for Deficiency removal.
 - 8.12: Executive Director, Krishna Valley Irrigation Development Corporation are requested to make required funds available to the Deficiency removal and monitor the progress periodically. This will help in keeping the Dam safe.

- 8.13: As per Marathi Government Resolution Misc. 2016/(88/16)/IM(W) Dtd.- 09/05/2016, Responsibility of Approval of M & R Work's Procurement List & Prioritization of execution of work & its implementation is entrusted to Superintending Engineers. And Responsibility of Review & monitoring is entrusted to Chief Engineers.
- 8.14: Hence, It is expected that Superintending Engineers should verify whether Works of removal of Deficiencies are proposed to address Deficiencies pointed in ADHSR while approving Procurement List of the M & R works of the Project.
- 8.15:Gist of report is that though inspection of Dams are carried out &Reports are published however status of ATR depict that despite of M&R expenditure extreme poor performance of removal deficiency is observed. Field officers should take serious note of this.
- 8.16: Central Government has enacted Dam Safety Act 2021 from date 30/12/2021 to provide for surveillance, Inspection, Operation & Maintenance of the specified dam for prevention of dam failure disaster & to provide for institutional mechanism to ensure their safe functioning & for matters connected therewith or incidental thereto So that Dam owner shall give specific attention for implementation of Dam Safety Act 2021.

I hope this report will serve desired expectations expressed by Dam Safety Monitoring Directorate of C.W.C.New Delhi. Any error, discrepancies omissions if any may please kindly by brought to the notice. So that it can be taken into consideration in the next report.

The efforts taken by the Superintending Engineer, Dam Safety Organization, Nashik and his team, for completion of this report are highly appreciated.

Sd/-

Place: Nashik Date: 11/10/2022 (R. R. Shah) Director General Design, Training, Hydrology, Research and Safety, MERI, Nashik

INDEX

Sr. No.		Subject P					
1	Part-1 :Gen	eral Information	1				
1.01	Introduction		1				
1.02	Inspection o	f Dams	1				
1.03	District wise	and class wise break up of number of Dams	1				
1.04	Time Sched	ule of Inspections	2				
1.05	Classificatio	n of Dams	2				
1.06	Field Inspec	tion Authorities	3				
1.07	Preparation	of Annual Dam Health Status Reports of Class-I & class-II Dams	3				
1.08	Preparation	of Annual Dam Health Status Report of Class-III Dams	3				
1.09	Guidelines F	Regarding Preparation of Annual Dam Health Status Report	3				
1.9.1	Categorizati	on of Deficiencies	4				
1.9.2	Category-1	Standard Deficiencies	4				
1.9.3	Category-2	Standard Deficiencies	4				
1.9.4	Category-3 Standard Deficiencies						
1.10	Special Deficiencies						
1.11	Standard Procedure For Confirmation And Removal of Category-1 Deficiency of Dams						
1.12	National Register of Large Dams (NRLD)						
1.13	Point of Atte	ntion	9				
2	Part-2: Act	ion Taken Report	10				
2.1	General		10				
2.2	ATR Submi	tted by Field Offices	10				
2.3	Action Tak owned)	en Report of Class-I & Class-II Dams (Government & Private	10				
2.4	Conclusion	S	10				
2.5	Points of A	ttention	11				
	Table-2.1	Consolidated Abstract of Status of Compliance of Category-1 Deficiencies in ADHSR-2019-20	12				
	Table-2.2	Consolidated Abstract of Status of Compliance of Category-2 Deficiencies in ADHSR-2019-20	13				
	Table-2.3	Dams for which Compliance Report Not Received in DSO, Nashik	15				
	Table-2.4	ATR on Category-1 Deficiency in Class-I Dams	21				
	Table-2.5	ATR on Category-2 Deficiency in Class-I Dams	22				
	Table-2.6	ATR on Category-1 Deficiency in Class-II Dams	85				
	Table-2.7	Table-2.7 ATR on Category-2 Deficiency in Class-II Dams 86					

Sr. No.		Subject	Page No.			
	Table-2.8	ATR on Category-1 Deficiency in Class-I Dams (Private Owned)	114			
	Table-2.9 ATR on Category-2 Deficiency in Class-I Dams (Private Owned)					
	Table-2.10	Table-2.10 ATR on Category-1 Deficiency in Class-II Dams (Private Owned)				
	Table-2.11	Table-2.11 ATR on Category-2 Deficiency in Class-II Dams (Private Owned)				
3.0	Part- 3: Dam	Part- 3: Dam Health Status Report of Pre & Post Monsoon 2021				
3.1	General		121			
3.2	Inspection F	Reports submitted by Field Offices	121			
3.3	Test Dam In	spection by Dam Safety Organization	121			
3.4	Health Statu	s of Class-I & Class-II Dams (Government owned)	122			
3.5	Graphical R	epresentation appended in Annexure I	123			
3.6	Snapshots o	of DSO Test Inspection Test appended in Annexure II	123			
3.7	Conclusions	3	123			
	3.7.1	Frequent Deficiencies Class-I Dams	123			
	3.7.2	Frequent Deficiencies Class-II Dams	123			
3.8	Points of Attention					
	Table 3.1	Status of Receipt of Pre & Post Monsoon Inspection Reports 2020	124			
	Table 3.2	Dams for which Inspection Report of 2020 is Not Received in DSO, Nashik	125			
	Table 3.3	Status of Pre & Post Monsoon Inspection 2020 by DSO, Nashik (Private Owned)	128			
	Table 3.4	Dams for which Inspection Not carried out by DSO, Nashik (Private Owned)	129			
	Table 3.5	Dams inspected by Dam Safety Organization, Nashik (2020-21)	130			
	Table 3.6	Deficiency Classification (No. of Dam wise)	134			
	Table 3.7	Deficiency Classification (No. of Deficiency wise)	138			
	Table 3.8	Category-1 Deficiency Classification (Dam wise)	142			
	Table 3.9	Category-2 Deficiency Classification (Dam wise)	143			
	Table 3.10	Class-I Dams with Category-1 Deficiency	155			
	Table 3.11	Class-I Dams with Category-2 Deficiency	156			
	Table 3.12	Class-I Dams with Category-3 Deficiency	222			
	Table 3.13	Class-II Dams with Category-1 Deficiency	232			
	Table 3.14	Class-II Dams with Category-2 Deficiency	233			
	Table 3.15	Class-II Dams with Category-3 Deficiency	275			
	Table 3.16	Class-I Dams with Category-1 Deficiency (Private Owned)	297			
	Table 3.17	Class-I Dams with Category-2 Deficiency (Private Owned)	298			
	Table 3.18	Class-I Dams with Category-3 Deficiency (Private Owned)	300			

Sr. No.		Subject	Page No.
	Table 3.19	Class-II Dams with Category-1 Deficiency (Private Owned)	301
	Table 3.20	Class-II Dams with Category-2 Deficiency (Private Owned)	302
	Table 3.21	Class-II Dams with Category-3 or No Deficiency (Private Owned)	307
	Table 3.22	Category-1 Deficiency in Class-I Dams	310
	Table 3.23	Category-2 Deficiency in Class-I Dams	311
	Table 3.24	Category-1 Deficiency in Class-II Dams	315
	Table 3.25	Category-2 Deficiency in Class-II Dams	316
	Annexure-1	Graphical Representation	320
	1	. Dams in Districts of Pune Region (Government Owned)	320
	2	Dams in District of Pune Region (Private Owned)	321
	3	Deficiencies Attended by Field Offices (ATR for ADHSR 2019-20)	322
	4	. Submission of Pre/Post Monsoon Reports	323
	5	. Category wise Deficiencies of Class-I Dams	324
	6	. Category wise Deficiencies of Class-II Dams	325
	7	. Dams Deficiencies	326
	Annexure-2	Snapshots of Dams inspected by DSO	327
4.0	Part-4 : Anr	nual Performance Report of Dam Instruments	329
4.1	General		329
4.2	Instrumenta	tion in Earthen Dams	329
4.3	Instrumenta	tion in Concrete / Masonry Dams	330
4.4	Status Of Da	am Instrumentation In The Region	331
4.5	Observation	S	331
	Table-4.1	Status of Dam Instrumentation	332
	Table-4.2	Status of instruments Mortality	336
	Table-4.3	Comparison of instrumentation with Last Year ADHSR	338
5.0	Part-5 : An	nual Performance Report of Meteorological Instruments	339
5.1	General		339
5.2	Observation	S	339
	Table-5.1 Status of Dam Meteorological Instrumentation		340
	Table- 5.2 Status of Meteorological instruments Mortality		348
6.0	Part-6: Nati	onal Committee on Dam Safety (NCDS) Documents	349
	Table- 6.1	Status of Emergency Action Plan (EAP)	352
	Table- 6.2	Status of Reservoir Operation Schedule (ROS)	352
	Table- 6.3	Status of Gate Operation Schedule (GOS)	352

Sr. No.		Subject					
	Table- 6.4	Dam Wise Status of GOS & ROS, EAP (Class-I Dams)	353				
	Table- 6.5	Status of Other NCDS Documents (Class-I Dams)	359				
	Table- 6.6	Dam Wise Status of other NCDS Documents	360				
7.0	Part-7 : Dam Health and Rehabilitation Monitoring Application (DHARMA)						
	Table-7.1	Status of DHARMA Information Updation	369				
8.0	Part- 8: Health Status of Gated Dam (As per Mechanical Organization)						
8.1	General						
8.2	Health Status of Gated Dams						
	Table 8.1	Status of Deficiencies	373				



Part-1 General Information

1.01 Introduction:

As per National Register of Large Dam (NRLD) published by CWC, New Delhi, Maharashtra has the distinction of having largest numbers of dams in the country.

A separate Organization called Dam Safety Inspectorate, Nashik was functioning in the State since 20/10/1980.Its status is upgraded as Dam Safety Organization, Nashik from 01/05/1985. The organization consists of a circle level unit headed by Superintending Engineer under which Executive Engineer, Dam Safety Division No.1, Nashik looks after Pune Region.

1.02 Inspection of Dams:

The Government of Maharashtra has delegated powers of Pre and Post Monsoon Inspection to competent authority for Pre and Post Monsoon Inspection of the Dams vide G.R Dtd.23/08/1998.

Dam Safety Organization, Nashik carries out scrutiny of the inspection reports received from field offices for Class-I & Class-II Dams. Significant & Serious deficiencies observed during scrutiny are immediately intimated to Field Offices to carry out Remedial Measures.

The "Annual Dam Inspection Programme" is sanctioned by Director General, DTHRS MERI Nashik. Test inspections are carried out by Dam Safety Organization as a third party inspection to crosscheck the inspections carried out by Field Offices.

Pune Region comprising 262 Government owned Completed Dams (includes 2 National Important Dams, 13 Century Old Dams & 5 Dams under Construction Dams) & 17 Private Dams

DSO, Nashik monitors all Government Dams from safety point of view. In addition to this DSO, Nashik carried out detailed inspections of 17 Private Dams (6 owned by TATA, 3 owned by KMC Kolhapur, 2 owned by INS Shivaji, Indian Navy, Pune, 2 owned by Symbiosis, Lavale, Pune, and 1 owned by Kagal Nagar Parishad Kolapur.) on Consultancy basis.

District	No. Of Class- I Dams	No. Of Class- II Dams	No. Of Class- III Dams	Grand Total
Pune	24	45	21	90
Satara	15	30	9	54
Sangli	3	52	29	84
Kolhapur	21	37	6	64
Solapur	3	25	47	75
Ratnagiri	1	0	0	1
A.Nagar	1	4	0	5
Osmanabad	1	0	0	1
Govt. Total	69	193	112	374
Pune	7	6	0	13
Kolhapur	0	4	0	04
Private				
Total	7	10	0	17
Grand total	76	203	112	391

1.03 District wise and Class wise break up of number of Dams :

1.04 Time Schedule of Inspections :

The Government of Maharashtra has designed systematic approach for monitoring each and every dam. The periodical inspection of dams must be completed as per following schedule.

	Last dat	es for
Type of Inspection	Completion of Inspection	Sending of Inspection reports to concerned authorities.
(1) Pre Monsoon	15th May	30th June
(2) Post Monsoon	30th November	31st December
(3) Special inspection before the first filling (Report need not be sent to Dam safety Organization)	30th April	31st May
(4) Special inspection after the first filling	Within one week after the lake attains the intended storage level.	Within one week from the date of inspection.
(5) Special inspection after a severe distressing event or accident or incident.	Immediately after the event is noted.	Within one week form the date of inspection?

1.05 Classification of Dams :

The dams are categorized into three types based on their component and features as below.

SR No	Type of Dam	Height from general level of deepest foundation in m.	Impounded gross storage capacity Up to FRL in M Cum	Spillway capacity	Type of spillway
1	2	3	4	5	6
1	Class-I	Above 30 m	Above 60 M	Above 3,000	Gated Spillway
	Dam		Cum	Cumecs	
2	Class-II	15 m to 30 m	15 M Cum	2,000 to	Ungated Spillway
	Dam		upto 60	3,000	
			MCum	Cumecs	
3	Class-III	10 m.to15m	1.0 M Cum	2,000 to	Ungated Spillway
	Dam		upto 15 MCum	3,000	
				Cumecs	

Note :

- 1) All dams more than 15 meters in height will be classified under "Large Dam" Irrespective of other parameters.
- 2) All dams less than 10 meters in height will be classified as "Small Dam" irrespective of other parameters.
- 3) In order to determine the exact category of "Large Dam" following procedure shall be followed. The category of dam as per (I) Height (II) Storage Capacity & (III) Spillway Capacity shall be worked out individually. The highest of category shall be appropriate category of dam
- 4) Apart from above following additional parameters shall be considered for deciding

the category of the dams between 10 to 15 m. in height.

- a) Dams having length of crest more than 2000 m. OR
- b) Dams having specially difficult foundation problems OR
- c) Dams with unusual design shall be classified under "Large Dams (Class-II)"
- d) Dams having length of crest more than 500 meters but less than 2000 meters Shall be classified as "Large Dams (Class-III)"

1.06 Field Inspection Authorities :

The designated inspection authority for periodical inspection of dam depending upon the classification of type of dam is as below

Sr. No.	Type of Dam	Inspection authority	Inspection Reports to be sent to	Test Inspection
1	2	7	8	9
1	Class-I Dam	Superintending Engineer/ Administrator	1) Chief Engineer 2) Superintending Engineer Dam Safety Organization.	Test Inspection by the Regional Chief Engineer/ Chief Administrator for the dams having height more than 60 m or storage capacity more than 1000 MCum or spillway capacity 10000 Cumecs or more
2	Class-II Dam	Executive Engineer	 Superintending Engineer/ Administrator Superintending Engineer, Dam safety Organization 	
3	Class-III Dam	Deputy Engineer	1)Superintending Engineer/ Administrator 2) Executive Engineer	

1.07 Preparation Of Annual Dam Health Status Reports Of Class-I & class-II Dams :

Dam safety Organization carried out scrutiny of the periodical inspection reports of Class-I & Class-II dams received from field offices and significant deficiencies are immediately communicated to concern authorities to carry out remedial measures.

Based on all periodical inspection reports from Field Offices and Test Inspections carried out by DSO, Nashik, Region wise Annual Dam Health Status Report is published by DG, DTHRS, MERI, Nashik and submitted to Government, CWC and circulated to all concerned Field Offices.

1.08 Preparation of Annual Dam Health Status Report of Class-III Dams :

The responsibility of Health and Safety Monitoring of Class-III dams lies with the respective Chief Engineer. Hence for Class-III Dams based on periodical inspection reports, Annual Health Status Report of Class-III dams should be prepared by concern Field Chief Engineers and forwarded to DSO, Nashik for record.

1.09 Guidelines Regarding Preparation of Annual Dam Health Status Report :

ADHSR is prepared in DSO, Nashik as per Central Water Commission New Delhi's guidelines received vide letter Dtd. 28/08/2002. As per this letter it is intimated that all States / Organizations should submit the Annual Dam Health Status Report (ADHSR) in the month of 'April' every year.

1.09.1 Categorization of Deficiencies

The deficiencies observed are categorized as per CWC, New Delhi's letter Dtd. 28/08/2002 as below

Category	Action to be taken
Category-1	Dams with Major deficiencies which may lead to dam failure.
Category-2	Dams with Major rectifiable deficiencies needing immediate attention.
Category-3	Dams having Minor/ No deficiencies.

For further detailing of deficiencies based on the nature and priority of deficiency, DSO, Nashik has standardized all the three types of deficiencies. These standardized deficiencies are as follows

1.09.2 Category-1 Standard Deficiencies :

Sr. No.	Deficiencies	Category identifier
1 E -	Earthen Dam	
1	Seepage water has created an open pathway or pipe through dam, which may lead to failure of dam by piping.	1E.1
2	Heavy seepage with muddy or turbid water is observed through any part of dam.	1E.2
3	Seepage water flooding from a boil in the foundation or from relief well on downstream side of dam.	1E.3
4	Outlet well / Head regulator well and hoisting structure is collapsed/completely damaged.	1E.4
5	Outlet pipe in the body of the dam is damaged/failed and uncontrolled outlet- releases eroding Toe of dam.	1E.5
6	Debris stuck under gate or gate leaf is cracked / failed resulting uncontrolled flow through outlet.	1E.6
1 M	Masonry Dam	
1	Downstream movement or tilting of dam.	1M.1
2	Differential movement of dam blocks/monoliths. 1M.2	
3	Vertical Displacement with visible cracking in the body of dam. 1M.3	
4	Spillway gate damaged / not working.	1 M.4

1.09.3 Category-2 Standard Deficiencies : Deficiency Cat II (A)

Deficiency Cat II (A)	Deficiency Cat II (B)
Earthen Dam	·
A.1 : Boil/leakage/ seepage/ wet patches/ slushiness in Earthen Dam.	B 1: Dam section is not as per design
A 2: Standing pool / Ponding / Water Logging / Slushy condition on D/S of Dam	B 2: Cross and toe drains not working properly/ drains silted or vegetated causing stagnant pool of water.
A 3 : Leakages in vicinity of junction between earthen dam & masonry dam portion.	B 3: Considerable settlement of embankment / Rock toe/Pitching/ U/S & D/S slops, bulging/concavity of slopes.
A 4 : Major leakages through outlet conduit/pipe joints/Gates.	B 4 : Longitudinal / Transverse cracks/ low area/sink holes/gully formation on top side slope of earthen dam.
A 5 ; Relief wells not functioning properly./	B 5: Outlet gates not functioning properly. Stem

Deficiency Cat II (A)	Deficiency Cat II (B)
Abnormal rise in water level in wells.	rod is bent(Service gate/Emergency gate/Stop log gate/sluice gate)
A 6 : Outlet well is damaged/not in good condition /cracks observed/jets of water in well.	B 6: Approach to dam through all weather road not constructed/maintained properly.
A 7 : Retrogression /scouring in tail channel.	B 7: Waste weir/waste weir bar not in good condition/coping damaged/leakage through waste weir.
Masonry / Concrete Dam	
A 8 : Drainage gallery inaccessible/No adequate lighting./ No dewatering arrangement or failure.	B 8: Pointing on U/S face of dam not in good condition./deterioration spalling of concrete surface.
A 9 : Foundation drains / holes/ porous pipes/chocked/ no seepage through foundation drain holes.	B 9: Instruments not in working condition.
A 10 : Heavy leakages through porous pipes/ through dam body in gallery /monolith joints.	B 10: Leakages through River sluice.
A 11 : Sweating / seepages through D/S of masonry dam	
A 12 : Excessive considerable leaching from seepage water.	
A 13 : Swelling / minor cracking observed on body of dam.	
A 14 : EDA / Stilling basin damaged/Hydraulic performance not good.	
A 15 : Leakages through spillway /piers//junction of flank wall.	
A 16: Damages / foundation erosion/ scour/undermining observed in vicinity of flank walls/ guide walls/ junction walls/return walls.	
A 17 :End weir not in good condition / scouring noticed on immediate D/S.	
Spillway gates	
A 18 :Wire ropes of hoist not in good condition/hoisting structure damaged/cracked.	B 11 : Surface paint/steel surface of spillway gates deteriorated.
A 19 : Alternative power system Generator for gate operation not working properly.	B 12 : Damage to Rubber seals/ considerable Leakages through gates.
A 20 : Operation of gates not smooth needs repair.	
Other structures	
	B 13 : Heavy vegetation/big trees on embankment top/slope making dam portion not accessible.
	B 14 : Deck bridge slab/ pier / damaged cracked/ alignment disturbed.
	B 15 :Major portion of Pitching damaged/washed away.

1.09.4 Category-3 Standard Deficiencies :

Sr. No.	Deficiencies	Category identifier
1	Profuse growth of bushes and trees over dam portion.	3.1
2	Guard stones/ chainage stones and parapet wall not provided /damaged.	3.2
3	Growth of aquatic weeds in reservoir of dam is observed.	3.3
4	Ant hills or crab holes/holes made by rodents/animals.	3.4
5	Minor undulation/ settlement/slightly less top width/ Rain cuts / pot holes observed on dam top & slopes.	3.5
6	Access road/Dam top road surface/ slab joints damaged needs repair.	3.6
7	Pitching on embankment of dam is dislocated /disturbed at some places.	3.7
8	Breaching section is not accessible/ Instruction board showing operation of breaching section is not available.	3.8
9	Section of Toe drain/cross drain/ out fall drain/rock toe damaged at some places. Pitching of drains disturbed. Some weed, vegetation growth/ siltation in nalla/drains. Nalla needs regradation.	3.9
10	Surface drain/ Catch water drains for berms are silted /damaged	3.10
11	Electric cable & wiring are damaged/not in good condition.	3.11
12	Minor leaching in the gallery/ body of dam.	3.12
13	V – notches/ measuring devices are not in working condition/ silted /damaged/ not provided.	3.13
14	Mosquito net door is to be provided to avoid entry of reptiles in the gallery.	3.14
15	Damage to natural slope protection works,guniting damaged/washed out. Wire mesh exposed.	3.15
16	Guide wall/Divide wall/Guide bund/End Sill wall damaged/ Pointing is not in good condition/weep holes not functioning. At some places w.w bar/coping is damaged.	3.16
17	Provision of access to stilling basin/ladder not provided.	3.17
18	EDA ponding with water not possible to Inspect.	3.18
19	Minor erosion/ Scouring/Retrogression/ pot holes in tail channel. Ponding, standing Water in EDA / Tail channel.	3.19
20	Lubrication/painting/minor repairs required for parts of Gates / hoisting Structure/Rubber seal damaged/ replacement.	3.20
21	Approach bridge to intake well / spillway gates railing /flooring plates damaged / need repairs. Need of ladder for inspection well/EDA.	3.21
22	Minor leakages through river sluice/outlet/ gates.	3.22
23	Air vent not periodically cleaned./damaged/closed.	3.23
24	EAP / ROS /GOS /Record drawings/ not provided / not prepared at dam site.	3.24
25	The record of periodical measurements of leakage discharge from dam / relief well is not maintained.	3.25
26	Street light on dam top is not provided/not working.	3.26
27	Security / CC TV camera/entry gate not provided/not working.	3.27
28	Sufficient staff arrangement is not available for security ,instrument readings and measurements and maintenance on dam site.	3.28
29	Fencing around dam is not provided/ damaged due to which unauthorized trespassers are seen.	3.29
30	Communication facilities like mobile wireless, warning devices, telephone is not available at dam site.	3.30
31	Sufficient stock of spares/stationary required is not available at dam site. Storage arrangement not provided at site.	3.31
32	Minor leakages through masonary/ concrete dam body/gallery of dam/outlet well.	3.32

Sr. No.	Deficiencies	Category identifier
33	Security cabin at dam entrance/Irrigation outlets not provided/damaged/needs repair.	3.33
34	Approach channel silted. Trash rack need to be cleaned/ damaged/not provided.	3.34
35	Minor damages to spillway / masonary/ concrete portion of dam/outlet well.	3.35
36	Porous pipes/foundation drains / holes not periodically cleaned.	3.36

1.10 Special Deficiencies

Director general, DTHRS, Nashik has circulated a circular of special deficiencies dated 21/07/2020(सं.प्रा.ज.सं.सु./म.अ.सं.सं./प्रशा/अधि/88/सन2020) to all field offices to attend the above special deficiencies along with periodical inspection report

Special Attention Deficiencies (Civil), Attached with Pre- Post monsoon Inspection Reports

(Ava	ilability of Compulsory Manpower & Documents at dam Site)
Deficiency	Deficiency

category	Deficiency
Sp-1	Whether Emergency Action Plan is kept at dam site or not ?
Sp-2	Whether Approved Reservoir Operation Schedule is kept at dam site or not ?
Sp-3	Whether Latest approved gate Operation Schedule is to be kept at dam site or not ?
Sp-4	Whether Record Drawings sets are kept at dam site / section / Sub Divn. office or not ?
Sp-5	Whether Standard Operating Procedure copy with Updated contact numbers of all concerned authorities are kept at dam site or not ?
Sp-6	Whether Chart showing location of rain gauges / river gauges on U/s catchment & approximate travel time of discharge is maintained & displayed at dam site.
Sp-7	If CCTV is established, how observations are done round the clock & who is responsible person to observe these.
Sp-8	Whether Sufficient arrangement of staff is available or not. Engineers / Operators / Electrician / Watchmen / Security etc. and also staff for instrument reading, measurement &maintenance. They may be Govt. employee or through outsourcing. This staff is especially compulsory during monsoon period.
Sp-9	Whether Communication facilities like mobile, wireless, warning devices, telephone are available at dam site, or otherwise.
Sp-10	Whether The record of periodical measurements of leakage discharge from dam / relief well etc. is maintained or not.
Sp-11	Is there any profuse growth of bushes or trees over any portion of dam ?

Statement No-2 Special Attention Deficiencies (Mech & Elect), Attached with Pre- Post monsoon Inspection Reports (Compulsory Minimum repairs, For Spillway Gates & Gallery)

Deficiency category	Deficiency
Sp-12	Whether Wire ropes of hoist are in good condition/hoisting structure damaged/cracked ?.
Sp-13	Whether Alternative power system- Stand by two Generators for gate operation are working properly or not ?
Sp-14	Whether the o peration of all gates is smooth or needs repair ?.
Sp-15	Whether Lubrication/ painting/ minor repairs for parts of Spillway Gates and Hoisting structure are carried out or not ?.
Sp-16	Whether Rubber seals of gates are damaged or needs replacement ?.
Sp-17	Due date of painting of each part should be displayed on dam site as per mechanical maintenance schedule
Sp-18	Whether Electric cable / wiring / lights etc are in working condition are not ?
Sp-19	Whether gallery is having excessive leakages ?

1.11 Standard Procedure For Confirmation And Removal of Category-1 Deficiency of Dams

A systematic approach and working methodology is very essential to monitor the safety aspects of the dams.

During the scrutiny of Pre and Post Monsoon report or during DSO test Inspection whenever it is found that the deficiency is of Category-I, it will be immediately communicated to concern SE and CE.

Concerned SE /CE should immediately visit the dam and should satisfy himself that the deficiency pointed out is a major deficiency which may lead to failure of dam and should confirm to the DSO, Nashik regarding the classification of deficiency as per his opinion.

After conformation from Field Chief Engineer it will appear in ADHSR.

Remedial Measures for Category-I deficiency removal shall be undertaken immediately. And after completion of physical work of deficiency removal, Concern Chief Engineer should communicate status to DSO, Nashik immediately.

1.12 National Register of Large Dams (NRLD) :

Dams having Height above 10 meter are classified as per the norms of International Commission on Large Dams (ICOLD).

NRLD is consists of information of Large Dams as per 20 columns proforma covering information regarding salient features.

NRLD is updated in every January. Hence Field offices need to submit the information of new dams every year to DSO by December to incorporate it in NRLD. The response regarding submission of NRLD information from field offices is very poor, it is always observed that DSO officials has to take rigorous follow up to obtain requisite information.

1.13 Point of Attention :

General	Details
Inspection details	 The periodical inspection reports of all the dams shall be sent in original instead of carbon or xerox copy. (Signed copy shall be emailed in advance to DSO. Ambiguous or incomplete replies shall be avoided. It is necessary to check point wise replies, which should clear and self explanatory. The deficiencies observed frequently since long shall be deleted after verification of rectification work. The inspecting officer is advised to write the word "special attention" in inspection report against all such items wherever immediate attention is necessary from concerned field officer in charge of dam from safety point of dams and life & property on the downstream & would be useful for identifying categorization of deficiencies in Dam Safety Organization, Nashik. The information in Appendix II (Performance of meteorological instruments installed) and Appendix III (performance of taking observation of instruments installed in large dams) shall be filled properly and complete. The compliance of rectification work of deficiencies of each dam mentioned in status report shall be communicated to Dam Safety Organization, Nashik every year so that this can be included in the Action Taken Report Part-I of retartion report
Salient features	 Due care shall be taken while filling the salient features of dam and information regarding N.C.D.S. documents. Date of inspections is not mentioned in some Pre / Post Inspection Reports. This is mandatory since it will reflect in the Annual health status report.
Dam and Dam reach (Embankment)	 If the existing dam section is found under section as compared to the design section during inspection then the work of re-sectioning shall be carried out and opinion of inspecting officer shall be stated in inspection report. The extent of embankment settlement shall be furnished with its measurement & Reduced Distance (R.D.) and it shall be with compared designed cross section.
Gallery / Shaft Drainage (Concrete / Masonry)	The monolith wise quantum of leaching in galleries and all type of leakages in dam shall be noted in inspection report.
Spillway and Energy Dissipation Structure	The quantum of retrogression/scouring in tail channel shall be given in inspection report.
Hydro- Mechanical Component and Turbine/Pump	The trial of spillway gates shall be carried out before monsoon every year & observed condition shall be mentioned in inspection report.
Instrumentation	It is observed that the information regarding number of instruments installed does not tally for pre & post monsoon inspection report of the same dam. In some cases it is observed that the list of instruments given in previous year do not appears in the current year. These discrepancies should be avoided.

Part-2

Action Taken Report

Part-2: Action Taken Report (ATR)

2.1 General :

Annual Dam Health Status Reports (ADHSR) of Dams for Year 2020-21 was published by Director General, DTHRS, MERI, Nashik in June 2021 and submitted to Govt. of Maharashtra and also circulated to all Field Offices ranging from Divisions to Corporations for information and carrying out remedial measures.

It is expected that Field Officers should go through the Status Report scrupulously and attend remedial measures on priority basis and submit Action Taken Report (ATR) for reflecting necessary repairs & attention given for maintaining safety of Dams in the ADHSR.

2.2 ATR Submitted by Field Offices:

In this region there are Government owned 69 Class-I & 193 Class-II Dams & Private owned 07 Class-I & 10 Class-II.

As per ADHSR 2020-21 Action Taken Report was expected from Government owned 54 Class-I Dams & 69 Class-II Dams & Private owned 3 Class-I & 4 Class-II Dams.

However Action Taken Report were received from Government owned 25 Class-I Dams & 5 Class-II Dams & Private owned 0 Class-I Dams & 0 Class-II Dams. [Ref. Table 2.1, 2.2 & 2.3]

	Category		Tota	l Dan	ı		ATR r	eceiv	ed	F	hysic	ally f	ully c	omple	ted	P	hysic	ally p	partly	comple	eted
	Class		I				I		II		I		11		%		I		11		%
	No. of	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency	Dam	Deficiency
			Category 1																		
1	WRD											Nil									
2	Private																				
		Category 2																			
3	WRD	54	445	69	147	25	183	5	9	1	43	1	1	6.66	22.9	17	31	1	1	60	16.66
4	Private	6	8	5	10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Total	60	453	74	157	25	183	5	9	1	43	1	1	6.66	22.9	17	31	1	1	60	16.66

2.3 Action Taken Report of Class-I & Class-II Dams (Government & Private Owned)

2.4 Conclusions :

Out of 54 Class I dams ATR of 29 dams are not received in DSO. Also Out of 69 Class II Dams ATR of 64 dams are not received. After scrutiny of ATR received it is concluded that only 6.66% dams and 22.91% deficiencies are physically fully completed. And 60% dams and 16.66% deficiencies are physically Partly completed. Field officers & higher Authorities shall take note of this seriously.

2.5 Points of Attention:

A) Government & Private Owned Dams :

Sr. No.	Expected ATR in DSO	Received D	l in time in SO	Even afte up by	er follow DSO	ATR w rece	ere not ived
		Number	%	Number	%	Number	%
1	610	192	31.47	0	00.00	418	68.53

- 1. Concerned Chief Engineer should monitor and instruct field Superintending Engineer & Executive Engineer regarding submission of ATR to DSO, Nashik to reflect exact status of Dam Safety works. Otherwise whole exercise of publishing ADHSR will be futile.
- 2. Concerned Dam owner should give serious attention regarding submission of ATR to DSO, Nashik to reflect exact status of Dam Safety works. Otherwise whole exercise of publishing ADHSR will be futile.

Table	- 2.1
-------	-------

Consolidated Abstract of Status of Compliance of Category-1 Deficiencies in ADHSR-2020-21

Sr.No	Agency	6	Dams	s & D	efici	enci	es				Sta	atus	of De	eficie	ncies	s ren	noval	as p	er co	ompl	iance	repo	ort re	eceiv	ed in	DSC), Na	shik			
		Cla D	ass-l am	Cla Da	ss-II am	Т	otal	Ph	ysica	lly fu	illy c	omp	leted		Phy	ysica com	lly pa plete	artly d		A	dmir	nistra initi	ative iated	actio	on	С	omp rec	lianc eive	e rep d in l	oort r DSO	ot
								Cla D	ass-l am	Cla D	iss-II am	Тс	otal	Cla D	ass-l am	Cla D	ss-II am	Тс	otal	Cla D	iss-l am	Cla Da	ss-II am	Тс	otal	Cla D	iss-l am	Cla Da	ss-II am	Тс	otal
		No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1	No. Of Dams	No. of Def. Cat -1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
														NIL																	

Table - 2.2

Consolidated Abstract of Status of Compliance of Category-2 Deficiencies in ADHSR-2020-21

Sr.	Agency		Dar	ns & D	eficienc	ies							Stat	us of	Defi	cienc	ies r	emov	/al as	per o	compl	iance	repo	ort re	ceived	l in D	SO				
NO		Cla Da	ss-l am	Cla: Da	ss-ll Im	То	tal	Phy	/sica	lly fu	lly co	mple	eted		Phy	/sica comp	lly pa pleteo	artly d			Admi	nistra initia	tive a	actio	n	4	ATR N	ot Re	ceive	d in D	SO
								Cla Da	ss-l am	Cla II D	iss- am	То	tal	Cla Da	ss-l am	Cla II D	iss- am	Тс	otal	Cla D	ass-I am	Cla II D	ss- am	Тс	otal	Cla Da	ıss-l am	Cla Da	ss-II am	Тс	ıtal
			-2		-2		-2		-2		?		-2		-2		-7		?		5		-2		-2		5		-2		5
		ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat	ams	Cat
		Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	of D	Def.	of D	Def.	of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.	Of D	Def.
		No.	o. of	No.	o. of	No.	o. of	°No.	o. of	No.	o. of	No.	o. of	No.	o. of	°.	o. of	No.	o. of	°.	o. of	No.	o. of	°.	o. of	°.	o. of	No.	o. of	No.	o. of
		•	z	_	z	_	z	_	z		z	10	z		z		z	10	z	~	z		z		z		z		z	~	z
1		3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
A)		le							<u> </u>								<u> </u>	r –	1		1										1
1	P.I.C., Pune	15	149	16	28	31	177	0	18	1	1	1	19	5	3	1	1	6	4	1	37	1	4	2	41	9	91	13	22	22	113
2	P.I.P.C., Pune	2	27	0	0	2	27	0	4	0	0	0	4	1	12	0	0	1	12	0	0	0	0	0	0	1	11	0	0	1	11
3	S.I.C., Sangli	2	3	15	24	17	27	0	1	0	0	0	1	1	0	0	0	1	0	1	2	2	3	3	5	0	0	13	21	13	21
4	S.I.C, Satara	6	52	14	59	20	111	0	6	0	0	0	6	3	4	0	0	3	4	2	32	0	0	2	32	1	10	14	59	15	69
5	K.I.C., Kolhapur	11	66	11	11	22	77	1	14	0	0	1	14	7	12	0	0	7	12	3	38	0	0	3	38	0	2	11	11	11	13
B)	C.E. S.P. Pune	•																			•										
6	K.I.C. Pune	8	91	5	10	13	101	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	8	91	5	10	13	101
7	SIPC, Satara	7	32	1	4	8	36	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	7	32	1	4	8	36
8	CADA Solapur	2	16	5	8	7	24	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	16	5	8	7	24
9	O.I.C., Osmanabad	1	9	0	0	1	9	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	9	0	0	1	9
10	SE BCC Solapur	0	0	2	3	2	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	3	2	3
G	overnment Total	54	445	69	147	123	592	1	43	1	1	2	44	17	31	1	1	18	32	7	109	3	7	10	116	29	262	64	138	93	400
		Total 54 445 69 147 123																													

Sr.	Agency		Dai	ns & D	eficien	cies							Stat	us of	Defi	cienc	ies re	emov	val as	per	compl	iance	e repo	ort re	ceived	d in D	SO				
NO		Cla Da	ss-l am	Cla Da	ss-II am	То	tal	Phy	ysical	lly fu	lly co	mple	eted		Ph	ysica com	lly pa pleteo	nrtly d			Admi	nistra initi	ative ated	actio	n	4	ATR N	ot Re	ceive	d in D	SO
								Cla Da	ss-I am	Cla II D	iss- am	Тс	otal	Cla Da	iss-l am	Cla II D	ass- Dam	Тс	otal	Cla D	ass-I am	Cla II D	ass- Dam	To	otal	Cla D	ass-l am	Cla Da	ss-II am	То	otal
		No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2	No. Of Dams	No. of Def. Cat -2
Priv	ate							1		1	1	1	1								1				1	I				<u> </u>	L
1	Sahara India	3	4	0	0	3	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3	4	0	0	3	4
2	KMC Kolhapur	0	0	2	3	2	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	3	2	3
3	INS	0	0	2	6	2	6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2	6	2	6
4	Kagal Nagar Parishad	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Private Total	6	8	5	10	11	18	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	6	8	5	10	11	18
	Grand Total	60	453	74	157	134	610	1	43	1	1	2	44	17	31	1	1	18	32	7	109	3	7	10	116	35	270	69	148	104	418

Table - 2.3

Sr. No.	Compliance Report not Received	Total Number of Dam	Sr. No.	Compliance Report Not Received	Total Number of Dam
1	2	3	4	5	6
Class	s-I Dams			Class-II Dams	
A) Chi	ef Engineer, Water Resources Departme	ent, Pune	A) Chi	ef Engineer, Water Resources Department	, Pune
I) Sup	erintending Engineer, Pune Irrigation Cir	cle, Pune.	I) Sup	erintending Engineer, Pune Irrigation Circl	e, Pune.
1) Exe	ecutive Engineer, Pune Irrigation Divisior	n, Pune	1) Exe	ecutive Engineer, Pune Irrigation Division, I	oune
	NIL			NIL	
			2) Exe	cutive Engineer,Khadakwasla Irrigation Di	vision, Pune
			1.	Bhugaon	
2) Ex Pune	ecutive Engineer, Khadakwasla Irriga	tion Division,	2.	Matoba	
1.	Khadakwasla		3.	Malad	5
2.	Panshet		4.	Palasdeo	
3.	Pavana	4	5.	Shirsuphal	
4.	Varasgaon		3) Exe	cutive Engineer,Nira Right Bank Canal Div	ision, Phaltan
3) Exe	ecutive Engineer, Chaskman Irrigation Di	vision, Pune	1.	Naigaon	
1.	Chaskman		2.	Mhasavad	3

2	Aralkalmodi	3	3.	Banganga	
3	BhamaAskhed				
			4) Exe	ecutive Engineer,Lift Irrigation Management	Div, Pune
4) Ex Phalta	ecutive Engineer,Nira Right Bank Ca an	anal Division,	1.	Pilanwadi	
1.	Veer	2	2.	Garade	2
2	Nazare				
	·				
			5) Exe	ecutive Engineer, Chaskman Irrigation Divis	ion, Pune
			1.	Nimgaon Mhalungi	3
			2	Dahiwadi	
			3	Kadus	
II) Su Pune	perintending Engineer, Pune Irrigation	Project Circle	, II) Su	berintending Engineer, Sangli Irrigation Cire	cle, Sangli
1) Ex Sangv	cecutive Engineer, Nira Deoghar Pro ri, Pune.	ject Division,	1) Ex	ecutive Engineer, Sangli Irrigation Division	, Sangli.
1.	Gunjawani	1			
III) Su	perintending Engineer, Sangli Irrigation	Circle, Sangli		NIL	
1) Ex	ecutive Engineer, Sangli Irrigation Divisi	on, Sangli.			
	NIL		2) E Divisi	xecutive Engineer, Tembhu Lift Irrigation on,Ogalewadi, Karad.	Management
IV) Su	perintending Engineer, Satara Irrigation	Circle, Satara.	1.	Biddhihal	12
1) Ex	ecutive Engineer, Satara Irrigation Divisi	on, Satara.	2.	Dighanchi	12

						3	Atpadi	
		NIII				4	Ghanand	
						5	Kadegaon	
						6	Karandewadi	
2) Koyai	Executive nanagar	Engineer,	Koyna	Irrigat	ion Division,	7	Morale	
1	Kolkewadi					8	Nimbhavade	
					1	9	Pare	
						10	Vejegaon	
						11	Walunj	
						12	Jambhulani	
						3) Ex	ecutive Engineer, Minor Irrigation Division,	Sangli
3) Ex	ecutive Engi	ineer, Krishi	na Irrigati	on Divis	sion, Satara	1.	Mahadikwadi	1
						Execu	itive Engineer, Kolhapur Irrigation Division	(N), Kolhapur
						1	Drayachi vadgaon	
						2	Kasarde	
		NIL				3	Kumbhavade	5
						4	Padsali	
						5	Pombre	
							utive Engineer, Kolhapur Irrigation Division	(S), Kolhapur
						1	Dindalkop	
						2	Kitwad 1	6
						3	Kumari	

	4	Shendri	
	5	Sundi	
	6	Yenechevandi	
	III) Si	uperintending Engineer, Satara Irrigation Cir	cle, Satara
	1) Ex	ecutive Engineer, Krishna Irrigation Divisio	n, Satara
B) Chief Engineer, Water Resources Department (SP), Pur	e 1.	Kankatrewadi	
I) Superintending Engineer, Kukadi Irrigation Circle, Pune	2.	Thoseghar	
1) Executive Engineer, Kukadi Irrigation Division No. Narayangaon	1 , 3.	Ner	
1. Manikdoh	4.	Pingli	
2. Dimbhe	5.	Yerelwadi	
3. Pimpalgaon Joge	6	Jambhulani	13
4. Vadaj	7	Mayni	
5. Yedgaon	8	Ranand	
	9	Andhali	
5	10	Arabwadi	
	11	Daruj	
	12	Mhasalwadi	
	13	Dhakani	
	2) Ex	ecutive Engineer, Koyna Irrigation Division,	Koyananagar
	1.	Chaphal	1
	B) Ch	ief Engineer, Water Resources Department	(SP), Pune
2) Executive Engineer, Kukadi Irrigation Division No. Shrigonda	^{2,} I) Su	perintending Engineer, Kukadi Irrigation Cire	cle, Pune

1.	Ghod		1)Exe	cutive	Engineer,	Kukadi	Irrigation	Div	vision	No.1,
		2	Naray	angaor)			<u> </u>		
2.	Sina		1.	Ramjev	wadi					
3) Ex	ecutive Engineer, Dimbhe Dam Division,	Manchar.	2.	Anepeo	dara					
			3	Otur wa	aghdara				ł	5
			4	Ghanga	aldara					
			5	Uchhil						
1.	Chillewadi	1	1							
Super	intending Engineer, SIPC, Satara									
Execu	itive Engineer, Minor Irrigation Division,	Satara.								
1	Nagewadi									
2	Morna									
3	Pangare	5								
4	Kalgaon									
5	Kusawade		II) Su	perinter	nding Engin	eer, CAD	A, Solapur.			
II) Su	berintending Engineer, CADA, Solapur.		1) Ex	ecutive	Engineer, S	Solapur Ir	rigation Divi	ision	n, Solaj	pur
1.	Ujjani		1.	Kaziku	nbus					
2.	Ekrukh	2	2.	Rajuri						
		1	3	Hingan	i				4	4
			4	Mangi						
	TE DAMS		2) E	xecutiv	e Engineer	, Bhima	Developmer	nt D	ivision	No.2,
			Solap	ur						
SAHA	RA India (Ambey Valley) Limited Pune		1.	Ashti						1

1	Ambavane	2					
2.	Kolavali	- 3					
3	Visakhar						
Tata Power Ltd,Pune							
1	Thokarwadi						
2	Walvhan	3	III) Superintending Engineer, Bhima Canal Circle, Solapur				
3	Shirwata		1) Executive Engineer, Minor Irrigation Division No.1, Solapur				
			1.	Babhulgaon	1		
				Pimplagaon Dhale	1		
			III) Superintending Engineer, Satara Irrigation Project Circle,Satara				
			1) Executive Engineer, Minor Irrigation Division, Satara				
			1	Mahind	1		
			PRIVATE DAMS				
			1) Kolhapur Municipal Corporation, Kolhapur				
			1	Rankala	1		
			2.	Kalamba	1		
			3) INS Shivaji , Lonavala				
			1.	New Shivsagar	2		
		2	Old shivsagar	L			

Table 2.4

ATR on Category-1 Deficiency in Class-I Dams

Sr.No	Dam Features	Date of Inspection	Main component of Dam	Observation / Significant Deficiencies Noticed	Remedial Measures Suggested	Implimentation Status
1	2	3	4	5	6	7
				NIL		
Table 2.5

ATR on Category-2 Deficiency in Class-I Dams

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures	Implementation
0		Inspection	Officer	Component	Noticed	Suggested	Status
				of Dam			
1	2	3	4	5	6	7	
[A]Ch	ief Engineer (W.R.), Water Res	ources Depar	tment, Pune				
(1) Su	perintending Engineer, Pune	rrigation Circl	e, Pune				
(a) Ex	ecutive Engineer, Pune Irrigat	ion Division, F	une 1				
1	Name : Bhatghar (Gated) Tal. BhorDist.Pune Year of completion : 1926 Location : Longitude 73⁰52' Latitude 18⁰11' Height : 57.62 m Gross Capacity : 672.65 Mm ³ Spillway capacity: 1600 m³/sec Sr.No.In Large Dam Register 2009: MH09HH 0048	12.05.2020 28.10.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Gallery Body Wall	 There is no proper ventilation & lighting & handrails arrangement.(A8) Problems of inadequate drainage- Clogged porous pipes. The proper arrangements are not made for the measurement of seepage into the gallery. (A8) The total seepage into gallery from the porous pipes in the dam at lake full condition - 8.50 LPS @ FRL (A10) There been 	Repairs should be carried out. Proper arrangement should be made for the measurement of seepage into gallery. Repairs should be carried out in consultation with Mechanical Organization. It should be kept under observation & leaching material should be sent to MERI, Nashik Lab for testing.	Work Planned to be rectified in year 2021-2022 Porous Pipes are cleaned Arrangements for seepage discharge will be made. Porous pipes are Cleaned. After monsoon
				EDA Spillway	 considerable leaching observed from the seepage water and deposition of line near the seepage exit spots. (A12) 5. The existing pointing on U/S side is in lime mortar and it seems to be slightly weak (broken / washed out). (B8) 	Necessary repairs shall be carried out. Necessary remedial measures should be carried out.	leaching material will be sent to Meri Nasik. The work is proposed to carried out under DRIP-II programmed

				6.	Due to erosion in			The work is
					central spillway stilling	Necessarv	remedial	proposed to carried
					basin, pond cannot be	measures should	be carried	out under DRIP-II
					drained automatically			programmed
					below the adjacent	000		programmou
					nala bed level (A14)			
				-	Control montions of visible			
				7.	Some portion of right	NI	ale and do have	New York
					side guide wall of	Necessary repair	snould be	Necessary Repairs
		S	piliway		south spillway is	done.		are carried Out.
		G	Sate		broken and damaged			
					at ground level. (A16)			
				8.	D/S face @ south			Pointing work is
					spillway needs			completed.Groutin
					grouting with epoxy			g work will be
		C	Crest of		pointing repairing. (B7)			taken in hand
		D	Dam					in2021-22
		E	nd Weir	9.	Due to rust, there are	Necessary	remedial	Such holes are
					small holes to gate no.	measures should	be carried	closed by provding
					- 3, 5, 10 & 13 of south	out.		additional
					& 11, 12, & 13 of			MS.Plates by
			Dutlet		central spillway			weldina.
					observed. (B11)			5
				10	Nut bolts of quide			
		G	General		frame are not in good	Necessary	remedial	This work will be
			Jonoral		condition & need to be	measures should	he carried	taken in hand in
					replaced Due to		be carried	2021-22
					missing or loose holts	out.		2021-22
					there are lookages			
					Concernator mach of			
					Conservator mesh or			
					gates is broken. (B12)			
				11.	Pointing on Crest	Necessary	remedial	This work will be
					should be done with	measures should	be carried	taken in hand in
					epoxy material. (B8)	out.		2021-22
				12.	The check wall / end			
					weir is damaged &	Necessary	remedial	This work will be
					erosion is observed at	measures should	be carried	taken in hand in
					D/S of End weir.(A17)	out.		2021-22
	•							
				13.	The vibrations and	Necessary repair	should be	Mechanical wing is
				12.	The check wall / end weir is damaged & erosion is observed at D/S of End weir.(A17)	Necessary measures should out.	remedial be carried	This work will be taken in hand in 2021-22

						operation	of c	outlet	Nasik.	action.
						gates.(B5)				
					14	Uplift press	sure ce	ell &		This work is
						Water stag	je reco	order		Proposed in 2021-
						are not work	king.(B	9		22
2	Name : Vadivale(Gated)	14.05.2020	Shri. S. D.	Waste Weir	1.	There is a s	scourin	ig on	Necessary remedial	Work is taken in
	Tal. Maval Dist.Pune	30.10.2020	Chopade,	Bar and Tail		downstream	n side	e of	measures should be carried	Hand Due to Covid
	Year of completion :1999		S.E., P.I.C.,	Channel		the bar a	nd/or	EDA	out.	19 unavailability of
	Location :		Pune	Spilllway		observed. (/	A7)			abor, progress of
	Longitude 73°31'16 "				2.	The surface	e of og	ee is		work is stopped.
	Latitude 18°49'20"					not smooth	& it is	s not	Location & quantum of	Work will be
	Height :29.00 m					in profile. E	Big cav	vities,	leakage should be investigate	completed by the
	Gross Capacity: 40.87. Mm ³					pot holes ar	re obse	erved	causes of leakage should be	end of june-2022
	Spillway capacity:					on ogee	sur	face.	ascertained & proper remedial	\ \
	746.82m³/sec					Heavy le	akage	is	measures to prevent leakages	
	Sr.No.In Large Dam Register					observed th	rough	body	should be carried out.	
	2009:					of spillway	y, thr	ough		
	MH09MH1517					junction	of	each		
						spillway o	constru	ction		
						joint. Big c	cavities	s are	N	
						observed a	and n	eeds	Necessary remedial	
					~	rectification	S. (B8)	laura l	measures should be carried)
					3.	Concrete at		level	out	,
						or spillway i	is dama	ageu	Necessary	
				Downotroom		anu	(P7)	eeas	necessary remedial	
				Downstream	4	Concrete	S. (D7)	00004	ineasures snouid be carried	
				Face	4.	deterioration		rvod	out	
						(B7)	1 0056	iveu.		
					5	Significant	leakad	e on	Necessary	
					5.	snillway	rearray	lacis	measures should be carried	
						observed (I	B7)	,) Work is taken in
					6.	Mild seena	ae on	D/S	Leakages should be attended	Hand Work of
				Upstream	0.	face of mas	onrv. (A11)	in time by providing suitable	Sr.No.6&7
				Face	7.	Significant	leakad	ie at	remedial measures after	completed
						Overflow	Sectior	n &	ascertaining the exact cause	physically and fully
				River oulet/		non-over fl	ow se	ction	of leakage.	.Work of Sr.No.9
				Sluice		junction		on		Completed
						downstream	<u>ו</u>	face.		Partelly.due to
						(A15)				Covid 19
					8.	Deterioratio	n	of	Necessary remedial	Onavailabilityof
						concrete	in	ogee	measures should be carried	Labour ,progress
								-		/

					9. 10	portion. (B8) Honeycombing to RBC outlet gate, overflow section & Pier concrete above crest RL. (B5) . The heavy leakage observed from wall of intake wells & which is collected in conduit. (B10)	out Leakages should be attended in time by providing suitable remedial measures after ascertaining the exact cause of leakage.	of remaining work stopped. Work will be completed by the end of June2022
3	Name : Kasarsai(Gated) Tal. MulashiDist.Pune Year of completion :1995 Location :73°40'00" Latitude 18°35'30" Height :36.0 m Gross Capacity :17.38 Mm ³ Spillway capacity : 933.00 m ³ /sec Sr.No.In Large Dam Register 2009: MH09MH1373	14.05.2020 18.11.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Slope Outlet Downstream Face	1.	Wet and slushy patches are observed at ch 300 to 360 m. on downstream slopes when water level is above 626.50m. Boils were observed from ch 300 to 360 at RL 626.50 to 626.61 m (A1)	This deficiency should be kept under observation and after confirmation by competent field authority, if necessary repair should be carried out in consultation with CDO, Nashik.	1)The size of those observed Boils is not increasing. The portion of the dam from ch.300to 360m is kept under strict supervision. Estimates under Special repairs work will be prepared Remedial work will be carried out after getting approval.
				Energy Dissipation Structure Outlet Gates	2.	Leakages are observed through divide wall and outlet of LBC& RBC upto 1 to 2 cusec. (A15) Mild seepage observed on d/s face	Leakage path should be ascertained & necessary repairs to reduce leakage should be carried out. Both rubber seals need to be changed. Necessary remedial measures should be carried out. Necessary remedial measures should be carried out.	 2) Repair work for Small leakages through divide wall and outlet of LBC will be included in annual maintenance & repair programmed after approval from competent authority repair work will be carried out 3)Works for minimize wet spots

						of masonry. (A11)	with Mechanical Organization.	treatment in the dam body will be included in annual Maintenance and repair Programmed After approval from competent authority repair work will be carried out.
					4.	Concrete/masonry deterioration (B8)	Necessary remedial measures should be carried	4)Repairs will be carried in annual
					5.	The under drainage of the stilling basin (or bucket) is not satisfactory. All the open drain holes are not clear and functioning well. (A14)	Necessary remedial measures should be carried out.	5)Work of cleaning open drain holes is proposed in M&R Programmed.
					6.	The surface of gates and the paints is deteriorated. (B11)	Necessary repairs should be carried out in consultation with Mechanical Organization	6) The work is completed by Mechanical wing.
4	Name :M.I.Tank Jadhavwadi (Gated) Tal. MavalDist.Pune Year of completion :2001 Location :73°43'00" Latitude 18°47'00" Height :35.52 m Gross Capacity :12.03 Mm ³ Spillway capacity : 664.14.00 m ³ /sec Sr No In Large Dam Register	14.05.2020 18.11.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Spillway Outlet Gates	1.	The obstructions observed in or immediately downstream of the spillway.(A17)	Necessary remedial measures should be carried out.	1)Repair work will be included in annual maintenance & repair programmed after Approval from competent authority repair work will be carried out
	2009: MH09HH1587			U/s slope	2. 3.	The full length of the wire rope of the hoist is not in serviceable condition.(A18) The rollers are not well lubricated.(A20)	Necessary repairs should be carried out in consultation with Mechanical Organization.	Sr.no.2,3,&4 The work is completed by Mechinical Wing
				Crest of	4.	The stem rods for		

26

				Dam		lifting the gates are not	Necessary repairs should be	
						perfectly straight. (B5)	carried out. in consultation	
					5.	Concavity appears	with Mechanical Organization	Sr.No.5,6,&7
				U/s Face		from ch.480 m. to 545		Estimate Under
						m. and between		irrigation
						ch.810 m. to 980 m. on		rehabitation repair
				WW Bar		U/S slope & pitching		work is prepared
						settled down. (B3)		& will be submitted
								to competent
					6.	There are signs of	Necessary remedial	authority for
						excessive and/or	measures should be carried	approval .Remedial
						uneven settlement	out.	work will be carried
						between ch. 400 to		out after getting
						700 & Ch. 850 to		approval from
					_	990.(B3)		competent
					7.	Pitching settlement in	Necessary remedia	authority.
						between chainage 480	measures should be carried	8) Work Planned to
						to 545 m and Ch 810	out	be taken under
					0	to 980 m.(B15)		regular M&R
					8.	is domaged (RZ)		during 2021-2022
5	Namo : NiraDovabar (Gatod)	12 5 2020	Shri S D	W/W/ Bor	1	Thoro is scouring in	Nocossany romodia	Popair work will be
3	Tal BhorDist Pune	28 10 2020	Chopade	WWW Dai	1.	central spillway stilling	measures should be carried	included inannual
	Year of completion ·2007	20.10.2020	SE PIC			basin and concrete		Maintenance &
	Location '73 ⁰ 43'36"		Pune			filling is proposed to	out.	repair programmed
	Latitude 18⁰06'18 "		i uno			prevent further		After approval from
	Height :58.525m					scouring.(A7)		competent
	Gross Capacity :337.39 Mm ³			Gallerv				authority repair
	Spillway capacity :1852.00 m ³			,				wprk will be carried
	/sec							out.
	Sr.No.In Large Dam Register			Outlet	2.	Guide wall beyond	Necessary remedial	The work is
	2009:					Check Weir is	measures should be carried	completed in
	MH09HH1554					damaged(A16)	out.	20210-21
					3.	Problems of		The work is
				Body Wall		inadequate drainage -		completed in
						29 Clogged porous		20210-21
				General		pipes out of 48		
						nos.(A9)		
					4.	The total seepage into		The pours pipes
				David	gal	lery from the porous		are cleaned
				Downstream	pip	es in the dam on	Nananan, nagata akasil ta	
				Drainage	28.	10.2020 - 37.50 LPS @	Necessary repair should be	
					(A)	11)	aone.	

					6	The energy dissipation arrangement is not working satisfactorily - Bed concrete is disturbed.(A14) Cumulative seepage in the body of the dam collected in gallery is measured, seepage water 35LPS@FRL	Necessary remedial measures should be carried out.	The work is completed in 20219-20 Though dam is earthen after stable stage seepage is minimized
					7 8	Leaching @ some extent is noticed.(A12) The Plumb bomb, Uplift pressure cell &Piezometer pressure cells are not working.(B9)	Necessary remedial measures should be carried out. Necessary repair should be done in consultation with IRD, Nashik.	Leaching material is removed from gallery The plumb bob ,Unlift pressure cell & Piezometer pressure cells are repaired in 2020- 21
					9	The exposed drains at ch 100, 410 to 510 &ch 1000 to 1100 are working satisfactorily. In remaining chainages flow not observed.(B2)	Necessary remedial measures should be carried out.	The work is completed in 20210-21
6	Name-Andravalley (Ungated) Tal.Maval Dist.Pune Year of completion :2003 Location :73 ⁰ 39'00" Latitude 18 ⁰ 20'00" Height :34.50m Gross Capacity :83.31 Mm ³ Spillway capacity :3021.00 m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH1622	14.05.2020 18.11.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Gallery	1.	Foundation gallery not accessible due to flooding during inspection.(A8) Excessive seepage/sweating along gallery/shaft observed. (A10)	Necessary remedial measures should be carried out Necessary remedial measures should be carried out	 Work of dewatering gallery is done for inspection of foundation gallery. Work of grouting for minimize seepage /sweating along the gallery will be included in annual maintenance

						and repair
						nrogrammed
						After opprovel
						Arter approval
						from competent
						authority repair
						work will be
		Spillway				carried out
			3.	Seepage through	Necessary remedial	Necessary
				porous pipes,	measures should be carried	action is in
				foundation drains &	out	progress
				monolith joints		
		Outlet Gates		collected in Gravity		
				chamber @ D/s of		
				FDA (A10)		
			Δ	Significant or	Necessary remedial	
		Outlet	ч.		measures should be carried	
		Ouliet		along	out	LCanage
				allong	out	
				gallery/sharvporous		
			_	drain observed. (A10)	N	
			5.	Almost all porous	Necessary remedial	4) Work of cleaning
				pipes in inspection	measures should be carried	porous pipes will
				gallery are	out in consultation with	be included in
				blocked.(A9)	mechanical organization.	annual
						Maintenance and
						repair programmed
						after approval from
						competent
						authority repair
						work will be carried
						out.
			6.	Concrete / masonry		6)There is no
			0.	deterioration (B8)		deterioration to
						Concrete /masonry
						7)Thoro is no
			7	Significant lookage on		7)THEIE IS HU
			1.	Significant leakage on		Significant leakage
				downstream lace		on downstream
				observed. (A10)		side
						\
			8.	Light sweating		Estimates are
				observed at foundation	Necessary remedial	prepared for this
				gallery.(A11)	measures should be carried	work .The repair
			9.	The surface of gates	out	work will be
				and the paints is		included in

					deteriorated (B11) 10. Wire ropes required to be changed. (A18) 11. (1) Service gate & (2) Emergency gate - Leakages is observed through rubble seals. It requires to be changed. Electric wiring and electric motor requires to be repaired. (B5)	Necessary remedial measures should be carried out in consultation with mechanical organization	annual maintenance & repair programmed and After approval from competent authority repair work will be carried out.
7	Name : Panshet (Gated) Tal. Velhe Dist.Pune Year of completion : 1972 Location : Longitude 73 ⁰ 37 ' Latitude 18 ⁰ 22 ' 5Height : 63.56 m Gross Capacity : 303 Mm ³ Spillway capacity : 1162.0 m ³ / sec Sr.No.In Large Dam Register 2009: MH09HH0310	13.05.2020 17.11.2020	Shri.S.D. Chopade, S.E., P.I.C., Pune	Body Wall Instrumentat ion Spillway Gates	 There has been considerable leaching from the seepage water and deposition of lime near the seepage exit spots. (A12) Piezometers are out of order.(B9) The damage or wear caused to the seal plates observed. (B12) The seepage flow is measured on 17.11.2020 is 101.0 LPS There is retrogession observed due to redamialodial basalt at depth of 1 to 2m) 	It should be kept under observation & leaching material should be sent to MERI/ Lab for testing. Necessary repair should be done in consultation with IRD, Nashik. Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repairs should be carried out	Not Received
8	Name: Khadakvasala (Gated) Tal. Haveli Dist.Pune Year of completion : 1879 Location : Longitude 73⁰45 ' Latitude 18⁰25 ' Height : 32.92 m	13.05.2020 17.11.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Drainage Junction of Earth work with	 1. Standing pool observed on D/S of Dam at Ch 1/066 to 1/095 m. (A2). 2. The seepage is observed from outlet 	Suitable drainage arrangement should be done to drain out the water. Seepage & sweating be monitored and necessary remedial measures be taken.	Not Received

	Gross Capacity :86 Mm ³			Masonry		provided at ch. 0/035	It should be kept under	
	Spillway capacity :2755 m ³ /			sections and		to 0/040m and 0/060	observation and verification of	
	sec			outlets		to 0/150m (A11).	competent authority remedial	
	Sr.No.In Large Dam Register						measures should be taken if	
	2009:			W.W & TC	3.	The scouring observed	necessary.	
	MH09HH0013					on downstream side of		
						the bar and/or EDA.	It should be repaired properly.	
						(A17)		
					4.	The coping over the		
				End Weir		spillway bar is not in		
						good condition.(B7)		
					5.	The erosion and	Proper remedial measure	
						damages observed on	should be taken and scouring	
						the concrete or	should be monitored &	
				EDA		masonry surface.	prevent the further scouring.	
					6.	The scour noticed on		
						the immediate		
						downstream. (A17)		
					7.	Some friction blocks	Necessary repairs should be	
						are damaged. (A14)	carried out in consultation	
				Outlet Gates	8.	The concrete surface	with Mechanical Organization.	
						of the stilling basin and	Necessary repairs shall be	
						apron (or bucket) is	done in consultation with IRD,	
				Instrumentat		not in good condition.	Nashik.	
				ion		(A14)		
					9.	The stem rod for lifting		
						the gates is not		
				General		perfectly straight. (B5)		
					10	.Only Pan		
						Evaporimeter is in		
						working condition,		
						Piezometer & Water		
						Stage Recorder are		
						out of order. (B9)		
					11	. All the registers of		
						observations posted		
						are not up-to-		
						date.(B10)		
9	Name : Warasgaon (Gated)	13.05.2020	Shri. S. D.	Gallery/Shaf	1.	Excessive	Seepage & sweating be	Not Received
-	Tal. VelheDist.Pune	17.11.2020	Chopade,	t Condition		seepage/sweating at	monitored and necessary	
	Year of completion :1972		S.E., P.I.C.			M6, M11, M12, M13	remedial measures be taken.	
	Location : Longitude 73°37'		Pune			observed along		

Latitude 18°23'	Gallery		gallery/shaft (A10)	Necessary repairs should be	
Height :63.40 m	-	2.	Some drain holes in	carried out	
Gross Capacity : 374.00 Mm ³			gallary are chocked		
Sr.No.In Large Dam Register			(A9)		
2009:	Dam body	3.	Foundation holes are	Seepage & sweating be	
MH09HH0592			not cleaned	monitored and necessary	
			periodically. (A9)	remedial measures be taken.	
		4.	There is excessive		
			seepage sweating at		
			the monolith no. 8, 9,	Necessary repairs should be	
			10 &12 on the	carried out	
			downstream face of		
	Downstrea		the dam.(A11)		
	m Face	5.	There is no pointing		
			on upstream face of	Necessary repairs should be	
			the dam. (B8)	carried out out in consultation	
		6.	Considerable	with Mechanical Organization.	
			leaching from		
			seepage water and		
			deposition of lime		
			near the seepage exit		
	Tail		spots.(A12)		
	Channel				
	&WW Bar				
				It should be kept under	
				observation and necessary	
		_		remedial measure to be taken	
		7.	Erosion of foundation	by permission of field	
			of end weir at stilling	competent authority.	
		~	basin observed (A16)	Necessary repairs should be	
		δ.	The leakages	carried out.	
	Deverseting and		observed through		
	Downstream		divide wall. (location-		
	Drainage		roundation gallery's		
		0	The demograph to	Drain balan abauld ba	
		9.	me damages to	Drain noies snouid be	
			well and other	Necessary repairs should be	
			anu Ullel	carried out	
	Energy		d (A16)	Camed Out.	
	Dissipation				
	Structure	10	The nortions of		
	Gliuciule	10.	Inditudinal toe drain		
			and exposed cross	Necessary repairs should be	
	1		una expessed 01033	repairs should be	

				Instrumentat	11. 12. 13. 14.	drains beyond the downstream toe of the dam is not in regular section and freely draining (B2) The concrete surface of the stilling basin and apron (or bucket) is not in good condition. (A14) D/s foundation erosion at the end of stilling basin observed. (A16) The foundation erosion of end wall observed. (A16) Piezometer & Water Stage Recorder are out of order. (B9)	carried out. Necessary repairs shall be done in consultation with IRD, Nashik.	
10	Name : Pawana (Gated) Tal. BhorDist.Pune Year of completion : 1972 Location : Longitude 73°40' 30 Latitude 18°21 30' Height : 42.37 m Gross Capacity : 305 Mm ³ Spillway capacity:1250 m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH 0311	13.05.2020 30.10.2020	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstrea m Drainage Gallery	1. 2. 3.	Toe drains & cross drains are not freely draining.(B2) Toe drain repair work is in progress. (B2) There has not been substantial progressive reduction in the seepage through the foundations. (Number of drain holes cleaned not mentioned.) (A9) Water jet observed inside on right side	Drain holes should be cleaned. Necessary repairs should be carried out. Drain holes should be cleaned. Proper remedial measure should be taken and scouring	Not Received

			drainage gallery from	shall be monitored &	
			sides and roof (A10)	prevented further scouring	
			5 Water jet observed	provonica ratinor coodinigi	
		Downstrea	inside on right side	Necessary repairs should be	
		m Face	drainage gallery from	carried out	
		Spillway	sides and roof (A10)	camed out.	
		Opinway	6 L & R side both		
			$(\Lambda 10)$		
			7 Soopage flow as on		
		End Weir	30 10 2020 -1362 lpm	Necessary repairs should be	
			8 Mild swooting	carried out	
			observed on d/s face	carried out.	
			of maconny (A11)		
				Necessary repairs should be	
			9. Al some places	necessary repairs should be	
			lover deterioreted in	camed out.	
			layer deteriorated in		
			opening span of gale		
			no. 1 & 3 al bollom	Necessary repairs should be	
			part touching to	necessary repairs should be	
			10 The creation pitting or	carried out.	
		Downotroom	TO. The erosion, pluing of		
		Downstream	spanning of the		
		Face	concrete or masonry		
			(AI7)	Necessary repairs should be	
		Conoral	11. The damage to end	Necessary repairs should be	
		General	weir on right side	carried out.	
			Junction to guide wall		
			IOF about 10m length.		
			UCR stones washed	Dropor remodial managements	
			away on u/s lace of	Proper remediar measures to	
			end weir creating	De taken in consultation with	
			cavity. Water IS	wechanical Organization.	
			coming out from		
			weir. (AT7)		
			I∠. IVIIIO SWEATING		
			observed on d/s face		
			or masonry. (A11)		
			13. The alternative power		
			system for gate		
			operation is not		
			working properly.		

	contine Engineer Oberta	Instantion Division	cian Duna 44		14 1:	 (A19) 4. Piezometer & Uplift Pressure Cells are yet to be installed. (B9) 5. Spillway Gates - Minor leakage at sill of gate no. 6, when totally lowered. (B12) 			
(C) EX	Nome : Chaskaman (Ceted)	15 05 2020		Downotreem	1	Daila ara abaarwad @	Cause of boild may be	Not Dessived	
	Name : Chaskaman(Gated) Tal. KhedDist.Pune Year of completion :1999 Location : Longitude 73°47' Latitude 18°57' Height :46.28 m Gross Capacity :241.69Mm ³ Spillway capacity : 2860 m ³ / sec Sr.No.In Large Dam Register 2009: MH09HH1522	15.05.2020 18.10.2020	Shri. S. D. Chopade, S.E., P.I.C. Pune	Downstream Drainage Gallery/Shaf t and Drainage	1. 2. 3. 4. 5. 6. 7. 8.	Boils are observed @ RD 800m d/s 180m; Boils are observed @ 860m, d/s 285m in existing well left side. (A1) In the d/s of dam @ ch 860m downstream 285m, standing pool of water observed. (existing well) (A2) Toe drains and cross drains are not working satisfactorily. (B2) Gallery remains flooded due to heavy leakages through porous pipe. (A8) Some porous drains and foundation drain holes are not in working condition. (A9) Total 71 drain holes are choked. (A9) The foundation drain holes and porous pipes are not periodically cleaned. (A9). Lighting arrangement has been destroyed and heavy leakages in inspecting gallery. (A10)	Cause of boils may be treated; check the drainage arrangement function of Long, cross, toe drains and then proper remedial measures shall be carried out. The downstream area from toe shall be free from slushy condition by draining water properly. Proper drainage arrangement shall be provided to drain out water. Proper remedial measures to be taken to reduce leakage & gallery always made available for inspection. It should be kept under observation & leaching material should be sent to MERI/ Lab for testing. Proper remedial measures to be taken to reduce leakage.	Not Received	
					9.	Excessive seepage	remedial measures.]

				Body Wall	through porous pipe	Leaching material should be	
				(Masonry	in gallery. (A10)	tested and remedial	
				/Concrete)	10. Leachet deposition is	measures should be carried	
				,	observed around the	out as per CWPRS, Pune	
					porous pipe in gallery.	•	
					(A12).		
					11. There is heavy		
					erosion at the toe of	Foundation holes should be	
					the end wall. (A17)	cleaned.	
				Outlet		Proper remedial measures to	
					12. There has been	be taken in consultation with	
					considerable leaching	Mechanical Organization	
					from the seenage	inconanical organization	
					water and deposition		
					of lime near the		
				General	seenade exist		
				Conorai	spots (A12)		
					13 There is no reduction		
					in seenage through	Necessary repairs shall be	
					nines	done	
					(Δ11)	done	
				Instrumentat	14 71 Foundation holes		
				instrumentat	are choked and not		
				ion		Necessary repairs shall be	
					15 In the concrete	done in concultation with IDD	
					15. III life concrete	Nachik	
						Nashik.	
					gale, linere is a		
					leakage inrough the		
					(DE)		
					(65)		
					40. The relief wells are not		
					ro. The relief wells are hold		
					property surged and		
					cleaned periodically		
					17. Uniy rain gauge &		
					plezometers provided-		
					which are not in		
					working condition. All		
					the instruments are not		
40				Option	in working order. (B9)		Not Dess'
12		15.5.2020	Shri. S. D.	Gallery	1. Electrification	Electrification arrangement	Not Received
	(UnGated)	18.10.2020	Chopade,		arrangement has not	snall be provided.	
	Tal. KhedDist.Pune		S.E., P.I.C.,		been provided. (A8)		

	Year of completion :2010		Pune		2.	Excessive seepage		
	Location :					through porous pipe in		
	Longitude 73⁰40'30 "					gallery, (A10).	Necessary repairs should be	
	Latitude 19⁰00'00 "				3.	Seepage though porous	carried out	
	Height :40.61 m					pipes, foundation drains		
	Gross Capacity :42.87Mm ³					& monolith joints	Necessary repairs should be	
	Spillway capacity : 963.21 m ³					collected in gravity	carried out	
	sec			EDA		chamber @ d/s of EDA		
	Sr No In Large Dam Register			20/1		measured manually is		
	2009.					$1.0 \ln s$ (A10)		
	MH09HH1672				Δ	The energy dissination		
					ч.	arrangement is not		
						working satisfactorily for		
				Access		all the discharges (A14)	Necessary repairs should be	
				Road	5	Emergency gate is not	carried out	
				Roau	5.	in operating condition	camed out.	
						(B5)		
				Conoral	6	(BS) The structures on the	Instruments should be fixed	
				General	0.	The structures of the	Instruments should be lixed.	
						access Toaus are Tho		
						dogradation to road		
						curface observed (P6)		
					7	Instruments are not		
					1.	fixed yet (PO)		
						lixed yet.(B9)		
13	Name : Bhamaaskhed	14 5 2020	Shri S D	Outlet Gates	1	The rollers are not	Necessary repairs should be	Not Received
15	(Gated)	18 10 2020	Chonada	Outlet Oales	۰.	working properly (A20)	carried out	
	Tal Khed Dist Pune	10.10.2020	SE PIC		2	The stem rod for lifting	camed out.	
	Vear of completion ·2014		0.L., 1.1.0., Puna		۷.	the dates is not		
	(Dam Portion)		T UNC			perfectly straight (B5)	Necessary repairs should be	
	Location :			Hoists	х	The alternative power	carried out out in consultation	
	Longitude 73⁰/13'00 " Latitude			Cranes and	0.	system for gate	with Mechanical Organization	
	18 ⁰ 15'00"			Operating		operation is required	with Mechanical Organization.	
	Height :51 125 m			Mechanisms		(410)		
	Gross Capacity · 230 173Mm ³			1010011011131113	Δ	Emergency gate(s)		
	Spillway capacity : 1736 m^3			Outlet	4.	Emergency Gate is not		
	sec			Julici		in operation due to		
	Sr. No. In Large Dam Register					concrete failure of side	Necessary repairs should be	
						drume broken rubber	carried out	
	2009. МНООНН1550					soal (R5)		
	WI 1031 II 1 1 3 3 3				5	Service Cate(s)		
					5.	Leakages observed		
						through Service Catos	Necessary repairs should be	
				Downstream		(R12)	carried out	
				_	5.	Service Gate(s)- Leakages observed through Service Gates.	Necessary repairs should be	
				Downstream		(DIZ)	Carrieu Oul.	

				Drainage				I
				General	 Drain at ch. 500m is not working.(B2) 	Necessary repairs shall be done in consultation with IRD, Nashik.		
					7. Rain gauge on Dam - 2			
					nos 1 In working			
					condition, 1 in not			
					working condition (B9)			ł
(d) Ex	ecutive Engineer, Nira Right	Bank canal Div	vision, Phaltan,	Dist. Satara				J
14	Name: Veer (Gated)	12.05.2020	Shri. S. D.	Spillway	1. Service gate no 7 is	Necessary repairs should be	Not Received	
	Tal.PurandarDist.Pune	28.10.2020	Chopade,	Gates	blocked and operation	carried out in consultation		
	Year of completion : 1965		S.E., P.I.C.,		or gate no 5 not smooth	with Mechanical Organization		
	Location . Longitude 74^0 5'55		Fulle	Raliaf Walls	plate (B5)	of under their advice.		
	Latitude 18 ⁰ 07'05"				2 The relief wells are not	Necessary repairs should be		
	Height :39.11 m				properly surged and	carried out.		
	Gross Capacity :278.49 Mm ³			Body Wall	cleaned periodically.			
	Spillway capacity :5154 m ³			5	(A5)			
	sec			General	3. Wet patches are seen	Necessary repairs should be		
	Sr.No.In Large Dam Register				at 0/075 (A1)	carried out		
	2009: MH09HH0116				4. Light arrangement			
				Intake/Outle	required at escape @			
				t Structure	Ch. $0/140 \& 0/160 \&$	Neccessi, was in the detailed by		
					CR Gate. (A8)	Necessary repairs should be		
				Walls: Guide	5. Evidence of abrasion,	camed out		
				walls/Divide	intake/outlet structure-			
				walls	Embeded parts of S G			
				Hoists.	no. 3. 4. 5. 6 is eroded.	Necessary repairs should be		
				Cranes	(A16)	carried out		
				Access	6. The foundation erosion			
				Road	or scour noticed near			
					NRBC @ Ch. 0/45 to			
				Access	Ch. 0/510 (A16)	Necessary repairs should be		
				Road	7. The alternative power	carried out		
					system for gate			
					properly (A10)	Necessary repairs should be		
					8 There is not a properly	carried out		1
					constructed and well			
					maintained all weather			1
					access road to the dam			1
					site. (B6)			1
					9. Service Gate-Leakage			l

					through SG 5, 4, 6 observed after closer.(B12) 10. Evidence of degradation to condition of instrument. (B9)			
(e) Lif	t Irrigation Management Divis	on, Pune						
15	Name: Nazare (Gated) Tal.PurandarDist.Pune Year of completion :1974 Location : Longitude 74 ⁰ 12'50" Latitude 18 ⁰ 17'30" Height :22.545 m Gross Capacity :22.316 Mm ³ Spillway capacity :2424.71 m ³ / sec Sr.No.In Large Dam Register 2009:MH09MH0453	12.05.2020 22.10.2020	Shri.S. D. Chopade, SE, P.I.C., PUNE	EDA End Weir Outlet Gates Downstream Drainage	 EDA end wall washed out - 5m. The portion of stilling basin concrete (40x6m) is broken. (A14) The flow conditions in the stilling basin (or bucket) have a tendency to draw material into the bucket and because its churning and abrasion damage to the surface of buckets baffle blocks, apron and end sill. (A14) Erosion of concrete and masonry wall observed - 75m. Scour (158m length) observed on immediate downstream of weir. (A 17) The stem rod for lifting the gates is not perfectly straight. (B5) The downstream area is not sufficiently clear and free draining- weeds of bushes/trees required to be cleaned. (B2) Toe drains and cross drains are silted and 	Necessary repairs should be carried out Necessary repairs should be carried out Scouring should be monitored and Necessary repairs should be carried out. Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice.	Not Received	
					weeds of bushes/trees			

					required to be clea (B2)	aned.	
Supe Exec 10	erintending Engineer, F cutive Engineer, Bhama Name : Temghar	Pune Irrigati aaskhed dar	on Project n division, P.S.Kolhe	Circle, Pune Pune	Wet or slushy patches are	Suitable treat-	As per the recommendation of Temgha
	Tal : Mulashi Dist. Pune Year of completion : 2000	13-05-20	SE, PIPC Pune	and Drainage	(A1)	carried out as per suggestion of Temghar Expert Committee for balance work	preventing measures are in progres Grouting work is almost completed whi upstream treatment of PFRS is progress. The shotcrete work in monoli no. 1 to 9 is completed upto foundation level and in monolith no. 10 to 14A, it
	Location : Longitude: 73 ⁰ 32' Lattitude: 18 ⁰ 27' Height: 86.67m			Seepage measurement	Safety issues - no hand rails	Suitable treat-	completed upto overburden level. Thu there is substantial reduction in wet slushy patches in the dam body. For no the repair work is adjourned sine die du expenditure incurred more than RPR. Th remaining grouting and shotcreting wo is proposed to complete after approval II nd RPR from GoM which will ultimate reduce the wet and slushy patches. Lighting is done in the inspection galle in 2019 and in foundation gallery
	107.96 Mm3 Spillway capacity: 626 m3/sec Sr. No. Large Dam			EDA		carried out as per suggestion of Temghar Expert Committee for balance work	accessible portion and in remaining portion it will be done after dewatering foundation gallery. The repair to staircas will be taken in hand after completion leakage preventing measures. As per the recommendation of TDE
	Register 2009: MH09HH1544	15.9.2020	Shri. Y. K. Bhadane SE DSO Nashik	Upstream slope	The seepage from VPD ove flows from the steps, which makes the accessibility to gallery difficult. Foundation gallery is also not accessible due to accumulation of debris. (A9)	Suitable treat- ment should be carried out as per suggestion of Temghar Expert Committee for balance work	leakage preventing measures are progress due to which almost 95' leakages are reduced as compared year 2016. The inspection gallery is no accessible and foundation gallery accessible except the some portion where debris is accumulated. Also it expected that after completion of leakage preventing measures leakages will be within the specified limit. Cleaning VPD, dewatering of gallery and remove

Guide walls Etc	5 y		of debris is included in the Temghar dam leakage preventing measures. For now the repair work is adjourned sine die due expenditure incurred more than RPR. The remaining repair work is proposed to
	 The leakage from VPD is very heavy-measurement difficult. From ch 425 m to 620 m drain 	Suitable treat- ment should be carried out as per	As per the recommendation of TDEC leakage preventing measures are in progress. It is observed that due to work done in season 2017-18, 2018-19 & 2019-20 almost 95% leakages are
Inspection Gallery	hole cannot be measured due to flooded gallery. Out of 378 VPD only 78 are functioning reaming 100 are slightly functioning & 200 VPD does not exist (A 9)	suggestion of Temghar Experi Committee for balance work	reduced. It is expected that after completion of repair work the leakages will be within the specified limit. Dewatering of gallery, removal of debris and Cleaning VPDs by redrilling is included in the Temghar dam leakage preventing measures. In the portion where VPD does not exist, the proposal of drilling new VPDs is included in IInd RPR of Temghar dam. For now the repair work is adjourned sine die due expenditure incurred more than RPR. The remaining repair work is proposed to complete after approval of IInd RPR from CoM
	Excessive seepage observed in gallery, Gallery is flooded from RL 425 m to 715 m. (A 10)	Suitable treat- ment should be carried out as per suggestion of Temghar Expert Committee for balance work	As per the recommendation of TDEC leakage preventing measures are in progress. uptill now 80% grouting & 40% shotcrete work is completed due to which 95% leakages are reduced as compared to 2016. After the Shotcrete work is completed, entry of water from upstream portion will be restricted which will reduce the seepage in gallery. Dewatering of gallery and removal of debris is included in the Temghar dam leakage preventing measures. For now the repair work is adjourned sine die due expenditure incurred more than RPR. The remaining repair work is proposed to complete after approval of

			6. There observed the leachate deposition in gallery.(A 12)	Suitable treat- ment should be carried out as per suggestion of Temghar Expert Committee for balance work	Ind RPR from GoM. Most of the leaching observed existed before rehabilitation work, hence to reduce the leaching in dam body/gallery fly ash and silica is added in mix design of grouting which is given by CWPRS, Pune. The leaching will reduced after the completion of leakage treatment work. Also, the new leaching which is observed every year gets tested form MERI Nashik.
			7. There observed the leachate deposition in gallery.(A 12)	Necessary repair should be carried out.	Most of the leaching observed existed before rehabilitation work, hence to reduce the leaching in dam body/gallery fly ash and silica is added in mix design of grouting which is given by CWPRS. Pune. The leaching will reduced after the completion of leakage treatment work. Also, the new leaching which is observed every year gets tested form MERI Nashik
		Stilling basin	8. Out of 378 VPDs, only 78 are functioning, remaining 100 are slightly functioning & 200 VPDs does not exist. (A9)	Necessary repair should be carried out	The cleaning of existing VPD by redrilling is in progress. In the portion where VPD does not exist, the proposal of drilling new VPDs is included in IInd RPR of Temghar dam. After getting the approval from government the work will be taken in hand.
			9. Seepage increases with the increase in water level. (A11)	Necessary repair should be carried out	As per the recommendations of TDEC leakage preventing measures are in progress. The leakage observed at various levels is recorded and graph is plotted which shows considable reduction in leakage compared to previous years at same level.
		Instruments	10. All the open drain holes are blocked and hence the tail pond always remains flooded. (A9)	Necessary repair should be carried out	Cleaning of tail pond is done in June 2018. Cleaning of drain holes and dewatering of tail pond will be done along with Dam strengthening works after completion of leakage preventing measures.

		 58 drain holes are not in working & 94 drain holes are not inspected as gallery is flooded. Porous pipes are chocked. Drilling is started (A9) 	Necessary should be out	repair carried	The cleaning of drain holes will be carried out after dewatering and removal of debris in the gallery. Cleaning VPDs by redrilling is included in the Temghar dam leakage preventing measures and will be completed after getting the approval to RPR from GoM.
		12. D/S side wall of D. S. S. gate seems to be damaged & Gate of ICPO: Manual operation of stem rod seems to be heavy, bearings are damaged & leakages are			Work is carried out through mechanical Division. Instead of manual operation of Stem Rod it is now operated electrically and it is working smoothly. Bearings are also changed. Shotcrete work in this portion was done in
		observed. (B5) 13. Concavity of depth 1.5m - 2m is observed on the upstream side of dam at monolith 12, Ch.415 to 430m. (B 3) 14. There is foundation erosion or scour noticed.	Necessary should be	repair carried	season 2019-20 The repair works of the foundation will be carried out along with the dam strengthening work after completion of leakage preventing measures.
		15. Foundation gallery was flooded from ch 425 to ch 705 (Flow measured = 159.3 lps). Hence could not be inspected. The leakages measured at the time of inspection in monolith no. 14= 14.3 lps, Monolith No. 20 = 28.2 lps, Monolith No. 18-19 =7 lps. (A8).			The seepage observed in gallery will be reduced after completion of leakage prevention measures. Once the shotcrete work is completed, entry of water from upstream portion will be restricted which will reduce the seepage in gallery. Maximum leakage observed was 2587 lps in year 2015-16. Due to work done in working season 2017-18, 2018-19, 2019- 20, around 95% leakages are reduced. Leakages reduced from 2587 Lps to 173.1 Lps at same level in the year2020- 21
		16. Leakages observed at some chainages in inspection gallery. (A10)			The leakage in the inspection gallery has only been observed in areas where shotcreting has not been done. These leakages will be reduced after completion of leakage preventing measures. Once the shotcrete work is completed, entry of water from upstream portion will be

				restricted which will reduced the seepage in gallery.
		17. Leaching from gallery a some chainage is observed. (A12)	Necessary repa should be carrie out	r before rehabilitation work, hence to reduce the leaching in dam body/gallery fly ash and silica is added in mix design of grouting which is given by CWPRS, Pune. The leaching will reduced after the completion of leakage treatment work. Also, the new leaching which is observed every year gets tested form MERI Nashik.
		18. The leakage observed at the junction of OF and NOF section (A10) (A11)	Necessary repa should be carrie out	This leakage is observed at the Spray wall portion. The grouting and shotcreting work in spillway portion could not be done due to incomplete bridge construction. Now as the bridge is completed the grouting work in this portion will be completed. Also the shotcrete in monolith no. 10 to 14A is completed upto overburden level due to gorge. After getting the approval for IInd RPR from GoM the grouting and shotcrete in this portion will be completed which will ultimately reduce the leakage at the junction of OF and NOF section.
		 Due to standing water in stilling basin it could not be inspected. Also leakage through guide wall observed.(A 14) Sweating observed on d/s face indicates VPD cleaning is required for monolith displaying sweating. Cracks and vegetation was observed on downstream side of spillway. (A11) 	Necessary repa should be carrie out	Cleaning of stilling basin is done in june 2018. The repair of the guide wall will be carried out along with the strengthening work after completion of leakage preventing measures. The cleaning of VPD by redrilling is included in IInd RPR of Temghar dam. After getting the approval from government the work will be taken in hand. Vegetation that come to the dam downstream side are cleaned from time to time. Dam safety instruments will be installed after the completion of leakage

	21. Dam safety instrument are not installed on dam site.(B 9)	prevention works. The cost of the dam safety instrument is included in IInd RPR. After the approval of IInd RPR from government, this work will be done.

(b) E	b) Executive Engineer, NeeraDeoghar Project Division, Sangvi(Bhatghar), Tal Bhor, Dist. Pune.												
17	Name -Gunjawani (Gated) Tal. VelheDist.Pune Year of completion : 2018 Location : Longitude: 73° 37 '00" Latitude :18° 18 '00" Height :52.825 m Gross Capacity :104.69 Mm ³ Spillway capacity: 1924 m ³ / sec Sr.No.In Large Dam Register 2009: MH09HH1552	13.05.2020 20.11.2020	Shri.P.S. Kolhe SE PIPC Pune Shri.H.T .DHumal SE PIPC Pune	Outlet Gates Downstrea m Slope	 Gates not closed properly. (A20) Minor undulations are observed in the WBM unsealed road section. (B6) The leakage observed through rubber seal. The leakage observed through gates. (B12) Growth of bushes observed on D/S pitching(B13) Crest profile is not at proper elevation.(B1) Bushes & weed growth found at some places.(B2) 	Necessary repairs should be carried out Necessary repairs should be carried out out in consultation with Mechanical Organization Necessary repairs should be carried out	Not Received						

Supe	Superintending Engineer, Sangli Irrigation Circle, Sangli									
(a) E	a) Executive Engineer, Sangli Irrigation Division, Sangli									
18	Name : Morna Tal. Shirala Dist.Sangali Year of completion : 1984 Location : Longitude 74°06'30" Latitude 16°59'20" Height :31.20 m Gross Capacity : 21.18 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1101	16.07.2020 07.11.2020	Shri H.V.Gunale S.E.SIC Sangali	Outlet	 Hoist mechanisms is faulty & Emergency gate mechanisms is faulty (B5) 	It should be repaired properly in consultation Mechanical organization.	Gate repair and ancillary works are included in the non irrigation procurement list 2021-22 of the mechanical department.			
(0) E 19	Name :Satpewadi barrage Tal. Walwa Dist.Sangali Year of completion : 2005 Location : Longitude Latitude Height : 25.50 m Gross Capacity : 3.886 Mm ³ Proposed for updation in NRLD 2018	16.07.2020 08.11.2020 21.01.2021	Shri H.V. Gunale S.E.SIC Sangali Shri Y K Bhadane SE DSO Nashik	Abutment Contacts	 Due to River Flood in Aug.2019 both side slope pitching near abutment Eroded and embankment washed out (B15) 	It should be repaired properly	In Progress Not attached .Proposal of Pitching and embankment restoration was sent to District Collector, Sangli for approval but it is not sanctioned yet.Amount Required for this work is about Rs.450 Lacks Completed			
					 Deck slab of slot no. 12 is damaged and some reinforcements are exposed. (B14) 	It should be repaired properly				

(3) Su								
(a) Ex								
20	Name: Kadavi Tal.Shahuwadi Dist. Kolhapur Year of completion : 2000 Location : Longitude 73°52'30" Latitude 17°00'05" Height : 36.05m Gross Capacity : 71.34 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1541	20.05.2020 16.11.2020	Shri M. S. Surve SE, KIC Kolhapur	W.W. Bar	1.	Waste wier bar work still not completed by construction wing (B7)	It should be completed.	1)Waste wear bar is 100% completed Chute Portion from Ch.20 to ch.146m Stilling basin from Ch.146 to 162m & End weir from ch.162 to 186m with side linin on both sides of entire portion is proposed on D/S of bar .Out of which only chute portion from ch.20to 122m is executed. Remaining part of Chute portion from Ch.122 to 12 m& End wear from ch.162 to 166m with side lining on both sides of entire portion is not executed. 2)Good quality hard rock is available at down stream of ww bar Waste wear is functioning since year 2004 inspite of this exposed rock in non executed par of chute portion stilling basin & end wear is not disintegrated. Hence necessary to construct remaining work of
21.	Name- Radhanagari (Gated) Tal.Radhanagari Dist- Kolhapur Year of completion : 1954	08.05.2020 16.11.2020	Shri M. S. Surve SE, KIC Kolhapur	D/S Face	1. 2.	Concrete/masonry deterioration (spalling, leaching, disintegration(A10) Significant leakage at	It should be repaired properly Proper remedial measures	Necessary repair work of grouting will be done after proper consultation of DRIP Phase-II Necessary repair work
	Longitude 73°57'40" Latitude 16°020'20"			EDA		o715m on downstream face .(A10)	leakage.	after proper consultation of DRIP

 				r			
Height : 42.83m Gross Capacity : 936.56Mm ³ Sr.No.In Large Dam Register 2009: MH09HH0067			Spillway	3.	Scouring at all the gates obstruction of penstock in sluice of 5(A14) Condition of energy dissipation arrangement is not satisfactory(A14)	After rechecking of deficiency by competent field authority, Necessary repairs should be carried out in consultation with CDO Nashik. It should be repaired properly	Phase-II Necessary repair work will be carried out after proper consultation of CDO. Necessary repair work will be carried out after proper consultation of CDO.
			Hoists	5.	Chains/ wire ropes Required to replace heavy rusted channels rusted need to repairs(A18) There is the mechanical or structural components and fastners or seals subjected to	It should be repaired properly consultation Mechanical organization It should be repaired properly consultation Mechanical organization	Necessary repair work will be carried out in 2022-23 It should be repaired properly by Mechanical organization in 2022-23
	20.01.2021	Test Inspected by Shri Y K Bhadane SE DSO Nashik	Outlet	7. 8. 9. 10	excessive wear (A20) There is problems with the rollers (A20) Seal angle is damaged (A20) Fulrum pin & lock plate nuts rusted required to replace(A20) 0. Gantry (Gliate with trusses to be repaied or replaced (A20) . Due to wire rope	It should be repaired properly consultation Mechanical organization	It should be repaired properly by Mechanical organization in 2022-23 Work Completed Out of 3 service gate 1 gate (Gate no.3) repaired properly by Mechanical org.in.2021- 22 Necessary repairs work

		hoist service gate cannot be loaded @ FSL (A20)	It should be repaired properly consultation Mechanical organization	will be carried out in 2022-23
		12 The rubber seals required to be replaced (B12)		Leakage has been measured by V Notch and maintained the record.
		13 Leakage and leaching was observed on downstream side of dam near power outlet @ Ch 701.4m. Heavy leakage was observed through joint of buttress and dam masonry at Ch 450m. Leakage should be measured daily and kept under observation. Record of the leakage should be	Leakage should be measured daily and kept under observation. Record of the leakage should be maintained.	Necessary repair work will be carried out in 2022-23
		 14 Leakage through spillway masonry was observed. Pointing of spillway masonry was damaged (B7) 	Pointing should be repaired. Necessary remedial measures should be done to stop the leakage	New Concrete Divide wal constructed in20210-21 Work Compleed
		 15 Divide wall masonry was heavily damaged. Stones of masonry were collapsed.(A16) 16 Loft eide guide wall 	The divide wall masonry should be repaired	Work Completed in 2020-21
		was broken.(A16)	It should be restored.	

22	Name : Warana (Gated)	05.06.2020	Shri M. S.	D/S Face	1.	Seepage at lower level	Proper remedial measures	To reduce seepage
	Tal. Shirala Dist. Sangli	03.12.2020	Surve SE,			at RD 230 to 330m	shall be taken to reduce	Grouting work is
	Year of completion :1989		KIC Kolhapur			(A11)	leakage	Proposed under special
	Location :			Gallery	2.	Problems accessing or		repairs. AA Is
	Longitude 73°05'50					inspecting gallery/shaft	Necessary work shall be	sanctioned by govt.
	Latitude17°08'10"					(obstruction)due to	carried out for easily	Vide GR.dt.27.01.2022
	Height :77.00 m					Leakage (A8)	accessible gallery.	estimate and D.I.P.
	Gross Capacity 974.18 Mm							Work is in Progress
	Sr.No.In Large Dam Register						Proper lighting arrangement	
	2009: MH09HH1542						snouid be provided.	Lighting arrangement
					2	Lighting ownerses	It should be kept under	done in year 2020-21
					3.	Lighting arrangement	It should be kept under	
						(water proof) is	observation and necessary	
						issues (A9)	hy permission of field	
						Issues (AO)	competent authority	Grouting work is
							competent autionty.	Proposed under special
					4	There is excessive	It should be kent under	repairs $\Delta\Delta$ is
						seepage/sweating	observation and necessary	sanctioned by govt
						along gallery/shaft	remedial measure to be taken	Vide GR dt 27 01 2022
						(A9)	by permission of field	estimate and DTP
						()	competent authority.	Work is in Progress
					5.	There is significant or		
					0.	evcessive leakage at		
						along gallon/chaft /		
								Cleaning drain Holes
						porous drain (ATU)		will be proposed after
								Grouting work
								J
					6	Thora is substantial		
				Body Wall	0.		Foundation drain holes should	
						progressive reduction	be cleaned for effective	
						in the seepage through	drainage	Leaching work
						the foundations. Due		completed. Material will
						to choking of the drain		be sent for further
						holes. (A9)		investigation.
					7.	There is leachate		Work Completed in
						deposition at RHS of	It should be kept under	2020-21
						inspection Gallery	observation &leaching	
				a		(Δ12)	material should be sent to	
				Spillway		(~· ~)	MERI/ Lab for testing.	
								Grouting work is
								Proposed

				River Outlet	8. There is considerable leaching from the seepage water (A12)	It should be kept under observation & leaching material should be sent to MERI/ Lab for testing.	
				Instrumentat ion	9. There is excessive seepage, sweating at any locations on the downstream Face of the dam RD160 to 230 LHS(A11)	Proper remedial measures shall be taken to reduce leakage	Work will be done by Mechanical Department in 2022-23
					10. The embedded parts of spillway gates, emergency gates and stop-logs in is not sound condition and free from	Proper remedial measures to be taken in consultation with Mechanical Organization	Work is in Process by Mechanical Department Proposal is sent to
					corrosion(A20) 11. The overall condition of river outlet works/river sluices satisfactory (A20)	Proper remedial measures to be taken in consultation with Mechanical Organization	MERI NASIK
					12. Majority of instruments are in dead condition. Need new installation (B9)	Proper remedial measures to be taken in consultation with IRD, Nashik	
23	Name: Dudhaganga (Gated) Tal. Radhanagari Dist. Kolhapur Year of completion : 1989 Location : Longitude 74⁰ 1' Latitude 16⁰21'	08.05.2020 18.11.2020	Shri M. S. Surve SE, KIC Kolhapur	Relief Well Gallery	 Relief wells are not functioning, chocked & needs cleaning(A5) Foundation gallery is flooded and hence not easily accessible 	They should be cleaned and made functional Necessary work shall be carried out for easily accessible gallery.	Rectified in March 2021 work completed Necessary repair work of grouting will done after proper construction of drip
	Height : 85.30 m Gross Capacity : 719.12 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1226				 (A10) 3. For safety issues Lighting arrangement is deteriorate (A8) 	Proper lighting arrangement should be provided	PHASE II Work will done in year 2022-23 Necessary repair work

			Body Wall	 4. There is excessiv seepage/sweating along gallery/shates (A9) 5. There is significant of excessive leakage a along gallery/shaft porous drain (A10) 6. The total seepage 	 It should be kept under observation and necessary remedial measure to be taken by permission of field competent authority. It should be kept under observation and necessary remedial measure to be taken by permission of field competent authority. 	of grouting will done after proper construction of drip PHASE II
			Spillway	53.90.lps into galler @ R.L.630.45m (A11)		Work Completed
			River Sluice	7. There is considerabl leaching from th seepage water (A12)	 It should be kept under observation and necessary remedial measure to be taken by permission of field 	
			Instrumentat ion	8. There excessiv seepage, sweating o the downstream fac of the dam (A11)	competent authority. It should be kept under observation & leaching material should be sent to MERI/ Lab for testing.	Necessary repair work of grouting will done after proper construction of drip PHASE II Work is in Progress
	20.01.2021	Test Inspected by Shri Y K Bhadane SE DSO		 9. The embedded part of spillway gates emergency gates an stop-logs in Is no sound condition an free fror corrosion(A20) 10. The overa condition of river outle works/river sluice 	 Proper remedial measures shall be taken to reduce leakage Proper remedial measures to be taken in consultation with Mechanical Organization 	Necessary repair work of grouting will done after proper construction of drip PHASE II
		Nashik		satistactory (A20) 11. Majority co instruments are i under repair. (B9)	f The Under repair instrument will be repaired with MERI Nasik consultation	Work is in Progress

							Mapping register is maintained
					12. Sweating was observed on downstream side of non overflow section. (A11)	Mapping of sweating with respect to reservoir water level should be done.	
					 13. Heavy leakage through non overflow section was observed on almost entire length. Leaching was also observed on downstream side of overflow section.(A11) 14. Leakage and sweating were observed on downstream side on spillway.(B7) 15. Heavy seepage and leaching was observed in gallery (A10) (A12) 16. Gallery was flooded and inaccessible for most of the portion. Lighting arrangement is not 	It should be kept under observation with respect to reservoir water level. Leaching material should be sent to MERI for testing	Necessary repair work of Grouting will done after proper consultation of DRIP Phase –II .Leaching material is sent to MERI Nasik.
24	Name: Kumbhi (Gated)	12.05.2020	Shri M. S.	Conduit	provided in gallery(A8) 1. The conduit structurally	After necessary investigation,	Work Completed in
	Tal. Gaganbavda Dist. Kolhapur Year of completion : 2007 Location : Longitude73°51'49" Latitude 16°31'29" Height : 42.58 m Gross Capacity : 76.88 Mm3 Sr.No.In Large Dam Register 2009: MH09HH1671	16.11.2020	Surve SE, KIC Kolhapur		sound but minor leakages are observed in conduit (A4)	repairs should be carried out to stop the leakage.	year 2021-22

2	25	Name: Tulshi	08.05.2020	Shri M. S.	Downstream	1. There is signs of water	Necessary remedial	Growth of aquatic
		Tal. Radhanagari Dist.	18.11.2020	Surve SE,	of Dam	logging, slushy	measures Should be	weeds on the
		Kolhapur		KIC Kolhapur		conditions or growth of	carried out	downstream of the dam
		Year of completion :1978				aquatic weeds on the	weeds on the	is observed
		Location :				downstream of the dam		This is regular
		Longitude 74°01'00"		Test Inspeced		(A2)		maintenance work& this
		Latitude 16°31'15"	19.01.2021	by Shri Y K				work is done yearly the
		Height : 48 .6 m		Bhadane				leakage should be
		Gross Capacity :96.28 Mm ³		SE DSO				maintained. Vegetation
		Sr.No.In Large Dam Register		Nashik				on
		2009:						NOF section should be
		MH09HH0726						cleaned
						2. Standing pool of water	Source of the seepage	
						was observed on	should be identified and	
						downstream side. Its	necessary arrangement	
						location could not be	should be done to stop the	
						ascertained as	seepage	
						chainages were not		
						marked on dam (A2)		Work Completed in year
						3. Sweating and Leakage	Leakage should be measured	2020-21
						was observed on	daily with respect to reservoir	
						downstream of Non	water level. Records of	
						overflow section (A11)	leakage should be maintained	
							Vegetation on NOF section	
							Should be cleaned	
								Work Completed in year
						4. Spillway gates were		2020-21
						rusted on upstream	They should be painted with	
						face. (B11)	anticorrosive paint.	
							All structural components	
							of spillway gates should be	
							well lubricated. Mock drills of	
							spillway gates should be	
							taken when water level goes	
							down. Record of the	
							mock drills should be	
							maintained	

b)Exe	cutive Engineer , Medium Pro	ject Division N	o2, Kolhapur					
26	Name: Ghatprabha (Phatakwadi) Tal. Chandgad Dist. Kolhapur Year of completion : 2009 Location : Longitude 74°04'20" Latitude 15°56'45" Height : 48 .30 m Gross Capacity : 43 .75 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1900	08.05.2020 04.12.2020	Shri M. S. Surve SE, KIC Kolhapur	General Embankmen t W.W.Bar	1.	There is major alterations or changes to the dam since the last inspection Right side guide wall is Collapsed due to heay rainfall and land slide some Pitching under side of well bridge is disturbed (40sq.m) (A16)	Guide wall shall be get repaired as suggested by Design Dn.(MD2)CDO To avoid land slide obtain the opinion from Sr. Geologist, Geology Dn CDO Nashik and do the needful.	The estimate for permanent remedial measures for right side new guide wall of stilling basin, balanced EDA structure augmentation of NOF wall remaining works of dam including permanent measures to the downstream sliding portion of Saddle dam is prepared under Extension & Improvement /Special Repairs.
		21.01.2021	Test Inspected by Shri Y K Bhadane SE DSO Nashik	Outlet	2.	Some Pitching under side of well bridge is disturbed (40sq.m) (B15)	Necessary repairs should be carried out.	 2) Before sending proposal for Administrative Approval to GoM it is mandatory to take decision in the Governing Council of MKVDC for taking up this work on priority. The said Extension & Improvement /Special Repairs work is included in Priority list of 107th meeting of Govrning Council of MKVDC Pune dated 12/11/2021 3) After Getting AA from GoM to said estimate, the work will

					be taken in hand after
					completing necessary
					tender procedure After
					executing said work,
		3.	Small amount of	Guide wall shall be get	observed deficiencies at
			leakages was	repaired as suggested by	sr.No.1 to 5 and 7 to 10
			observed through	Design Dn.(MD2)CDO	will get cleared.
			waste weir(B7)	To avoid land slide obtain the	4)Mechanical
				opinion from Sr.Geologist,	organization is
				Geology Dn CDO Nashik and	instructed to repair
				do the needful.	service gate on priority
					basis. This work is
					included in Proforma
					Schedule of 2021-22 of
					mechanical
					organization. After
					repair work is done
					observed deficiency
		4.	There is damages or	Guide wall shall be get	No.6 will get cleared.
			undermining to guide	repaired as suggested by	6
			walls (A16)	Design Dn.(MD2)CDO	Work is in Progress
				To avoid land slide obtain the	C
				opinion from Sr. Geologist,	
				Geology Dn CDO Nashik and	
				do the needful.	
				It should be repaired properly	
				consultation Mechanical	
				organization	Work is in Progress
				C	C
		5.	There is obstructions	Guide wall shall be get	
			due to excessive	repaired as suggested by	
			rainfall with land	Design Dn.(MD2)CDO	Work is in Progress
			slide, large size	To avoid land slide obtain the	-
			boulders with soil &	opinion from Sr. Geologist,	
			guide wall is	Geology Dn CDO Nashik and	
	 		collapsed in the	do the needful.	Work is in Progress

			stilling basin (A14)								
		 6. 7. 8. 	The service gate vibrates more while operating service gate needs repair. There is no supply of electricity on dam site Generator is necessary (A20) Standing water on was observed on downstream side of earthen embankment(A2) Seepage was observed on downstream side of saddle dam. (A1)	It should be repaired properly consultation Mechanical organization The source of water should be identified and it should be kept under observation Vegetation on the embankment should be cleared to find the source of seepage. Seepage should be measured and its record should be maintained with respect to reservoir water level.	Work is in Progress Work is in Progress						
		9. 10.	Scouring was observed on downstream side of saddle dam. (A7) Left side concrete guide wall is collapsed (A16)	Geology experts should be consulted in this matter It should be repaired							
27	Name: Jambre Tal.Chandgad Dist. Kolhapur Year of completion : 2013 Location : Longitude 74°06'40" Latitude 15°52'47" Height :58 m Gross Capacity : 23.23 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1925	08.05.2020 04.12.2020	Shri M. S. Surve SE, KIC Kolhapur		1.	Rubber seals slot are on opposite(wrong) side needs Repairing .Emergency gate is not in plumb line need maintaince (B5)	It should be repaired properly consultation Mechanica organization	Necessar will be Mechanic Organiza 2022-23	y repai carried :al tion ir	r wo out i ye	ork by ∘ar
----	---	--------------------------	---	----------	----	---	--	--	--------------------------------------	---------------------	------------------
28	Name: Jangamhatti Tal.Chandgad Dist. Kolhapur Year of completion : 2005 Location : Longitude 74°17'00" Latitude 15°51'30" Height : 31.40m Gross Capacity : 34.21 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1365	26.05.2020 27.11.2020	Shri M. S. Surve SE, KIC Kolhapur	W W. Bar	1.	Excess amount of leakages was observed through waste weir B7)	Necessary remedia measures should be carried out.	Repair carried 2022-23	work v	vill j	be ar

(b) Ex								
29 30	Name: Phaye Tal.Bhudargad Dist. Kolhapur Year of completion : 2005 Location : Longitude 74°04'15" Latitude 16°07'04" Height : 34.12m Gross Capacity : 3.932 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1629 Name: Ambewadi Tal Chargadist Dist. Kolhapur	19.05.2020 21.1.2021	Shri M. S. Surve SE, KIC Kolhapur	Outlet Rock Toe	1. 2. 3.	There is structural damages to the intake well 6 holes are found at various level(A4) There is leakage observed through the well proper and the conduit (A4) There is damage noticed to the conduit concrete, breast wall and gate slots (A4) 1. Standing pool of water and slusby	It should be repaired properly. It should be repaired properly to reduce leakages. It should be repaired properly.	Necessary repair work will being carried out and all deficiencies will be rectified till June 2022
	Year of completion : 2011 Location : Longitude 74°15'26" Latitude 15°52'49" Height : 33.05m Gross Capacity : 7.00 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1889		Shri Y K Bhadane			condition was observed near rock toe. (A2)	reservoir water level	necessary data is being maintained at field level.
(4) Su	perintending Engineer, Satara	Irrigation Cir	cle, Satara					
(a) Executive Engineer, Satara I	rrigation Divis	sion, Satara			<u> </u>		
31	Name : Dhom (Gated) Tal. Wai Dist. Satara Year of completion : 1976 Location : Longitude 73⁰ 40 ' Latitude 17⁰58 '	15.05.2020	Mr.Doiphode S. L. SE, S.I.C., Satara	Dam Body Downstream Face Guide walls	1. 2.	some sweating observed at D/S face at the portion of redundant well. (A11) Guide wall of canal HR structure	After rechecking of deficiency by competent field authority, Necessary repairs should be carried out in consultation with CDO Nashik.	In Administration process (Design Estimate/Tender) In Administration process (Design
	Height : 50.00 m Gross Capacity : 332.00 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH0655			General Outlet Gates Access Road	3.	damaged and collapsed. (A16) Piezometers: Out of 13 Casagrande piezometers 10 piezometers are not in working condition. (B9)	Proper remedial measures shall be taken. Proper remedial measures	Estimate/Tender) In Administration process (Design Estimate/Tender)

Inter- deteriorated. (B11) deteriorated. (B11)Necessary repair should be carried out in consultation with IRD, NashikInter- deteriorated. (B11)14.09.2020Test Inspected by Mr. Y K Bhadane SE DSO Nashk6. Growth of bushes and trees on the d/s slope - RD 0 to 2478.& RL 725.00 to 751.30m. (B13)Necessary repair should be no subtraction Proce shall be taken.14.09.2020DSO Nashk6. Growth of bushes and trees on the d/s slope - RD 0 to 2478.& RL 725.00 to 751.30m. (B13)Proper remedial measures shall be taken.Bush trees in207. Piezometer- Out of 7 piezometers installed at ch 1760, not a singte piezometer is in working condition. Out of 6 piezometers installed at ch 1940, only three piezometers are in working condition.(B9)Proper remedial measures shall be taken.In Proce Proper remedial measures shall be taken.8. Minor through damaged rubber seal of radial ertore are im working condition.(B9)In Proper remedial measures shall be taken.In Proce Proper remedial measures shall be taken.	Slope and the paint Mechanical wind
14.09.2020 Bhadane SE DSO Nashk 6. Growth of bushes and trees on the d/s slope - RD 0 to 2478& RL 725.00 to 751.30m. (B13) Proper remedial measures shall be taken. Bush D/S in20 7. Piezometer- Out of 7 piezometers installed at ch 1760, not a single piezometers in working condition. Out of 6 piezometers installed at ch 1940, only three piezometers are in working condition.(B9) Proper remedial measures shall be taken. Bush Proper remedial measures shall be taken. 8. Minor leakage through damaged rubber seal of radial proper remedial measures In Proper remedial measures	ComparingComparingComparingComparingdeteriorated (B11)5. Asphalt Road needsNecessary repair should beInTest Inspectedasphalting. (B6)carried out in consultationProcessby Mr. Y Kwith IRD, NashikEstimate /Tender)
7. Piezometer- Out of 7 piezometers installed at ch 1760, not a single piezometer is in working condition. Out of 6 piezometers installed at ch 1940, only three piezometers are in working condition.(B9) In 8. Minor leakage through In 8. Minor leakage through In 9. Oper remedial measures 9. Oper measures shall be taken.	Bhadane SE DSO Nashk 6. Growth of bushes and trees on the d/s slope - RD 0 to 2478& RL 725.00 to 751.30m. (B13)
8. Minor leakage through damaged rubber seal of radial Proper remedial measures Mech	7. Piezometer- Out of 7 piezometers installed at ch 1760, not a single piezometer is in working condition. Out of 6 piezometers installed at ch 1940, only three piezometers are in working condition.(B9)
yates was shall be taken. observedAlso the pointing to the ogee spillway required, the cracks on d/s face of spillway observed. There is no provision for stop log gate and emergency gate. Leakages through	8. Minor leakage through damaged rubber seal of radial gates was observedAlso the pointing to the ogee spillway required, the cracks on d/s face of spillway observed. There is no provision for stop log gate and emergency gate.
Service gate observed.(B12) 9. Standing water observed in stilling basin.(A14) 10. The Automatic Water RTD	service gate observed.(B12) 9. Standing water observed in stilling basin.(A14) 10. The Automatic Water RTDS Functioni

					11. 12.	Stage Recorder was not in working condition (B9) Pointing is required to end weir wall.(A17) Sweating, cracks and vegetation was observed on downstream side of spillway. It should be monitored.(A11)		In Administration Process Vegetation Removed
32	Name :DhomBalkavadi (Gated) Tal. Wai Dist. Satara Year of completion :2006 Location : Longitude 73 ⁰ 42' 30" Latitude 17 ⁰ 51'00"	15.05.2020 18.12.2020	Mr.Doiphode S. L. SE, S.I.C., Satara	Masonry Dam General	1.	Due to muddy and slushy condition gallery is not accessible, so could not inspected (A8)	Necessary work shall be carried out for easily accessible gallery.	Action not initiated yet Epoxy treatment is to be done at upstream side of spillway to prevent leakage & avoid water logging in the inspection.
	Gross Capacity : 115.53 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1655			Gallery Water Conveyance Structure Hoists, Cranes Downstream Slope	 2. 3. 4. 5. 	The instruments are installed in the body of dam but are not yet connected properly to pressure gauges. So they are not in working condition and needs to rectify. (B9) The foundation and porous holes not cleaned periodically. (A9) Leakage through longitudinal duct of ICPO. (A10) Hoist of EG of power house outlet is not working. (A18)	Necessary repair should be carried out in consultation with IRD, Nashik. Necessary work shall be carried out Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repairs should be carried out.	Action not initiated yet Action not initiated yet Action not initiated yet In administration process (Design/ Estimate /Tender) In administration process (Design/ Estimate /Tender) Estimate is Prepared

			~		and Orders'the day in
			ь.	On the downstream	and Submitted to
				pitching large	division office and
				amount of buches	further process is in
				amount of busiles	iuitilei piocess is ili
				have grown. (B13)	progress
				e ()	
					Action not initiated vet
					Demont to Droiset
					Report to Project
					division vide sub
					division office Marsthi
					division office warath
					Letter No.dbisbd
					1/ph/247 dt 02/12/2021
					1/pb/347 ul03/12/2021
			7.	Slushy condition or	
				water	In administration
				water logging	in auninistration
				immediately d/s of	process (Design/
				dam observed (A2)	Estimate /Tender)
					Estimate / Tender)
					Estimate is Prepared
					and Cubritted to
					and Submitted to
					division office and
					further process is in
			_	-	iuitilei piocess is ili
			8.	Stagnant water	progress
				observed in stilling	
					• ·· ·· ·· · ·
				basin.(A14)	Action not initiated yet.
			0	All the ener drain	
			9.	All the open drain	
				holes are not clear	
				and not functioning	
				and not runctioning	
				well.(A14)	
				. ,	

(b) Ex	ecutive Engineer, Krishna Irrig	ation Divisio	n, Satara					
33	Name Kanher (Gated)	12.05.2020	Mr.Doiphod	e Relief Well	1.	The relief wells (4	Necessary repairs be carried	Relief wall Cleaned
	Tal. Satara Dist. Satara		S. L.			nos.) are not in good	out	
	Year of completion :1986		SE, S.I.	C.,		working condition and		
	Location :		Satara	Gallery		functioning well. (A5)	Necessary repairs should be	
	Longitude 73°55'			5	2.	Problems of	carried out	Proper Pumping
	Latitude 17º45'					inadequate drainage		Machinerv sets are
	Height :50.34 m	15.12.2020				observed, dewatering	Quantum of seepage should	established
	Gross Capacity : 286.00 Mm ³					pumping station is not	be monitored monolith wise.	
	Sr.No.In Large Dam Register					fully operational. (A8)		
	2009:				3.	The foundation and	Necessary repairs should be	Proposed in drip –II
	MH09HH1141				0.	porous holes not	carried out	
						cleaned periodically.		
						(A9)		
				Body Wall	4	55 porous pipes are		Proposed in drip –II
				Douy main		not in function needs	Leaching material should be	
						to be cleaned (A9)	tested and remedial	Proposed in drip –II
					5	There has been	measures should be carried	
					0.	considerable leaching	out as per CWPRS Pune	
				Outlet		from the seenage		
				Outlot		water and deposition		
						of lime near the	Necessary repairs should be	Not Received
						seenage exit spots	carried out	
						$(\Delta 12)$	carried out	
				Guide	6	Damage noticed to		
				walls/Divida	0.	the conduit concrete-		
				walls Divide		secondary concrete		
				waiis		damaged (A4)		Not Received
				End Woir		The seened noticed		Not Received
						around the conduit	Bropor romodial moasures	
					7	The operation	shall be taken to reduce	
					1.	discipation	lookogo	
						arrangement is not	leanaye.	
				A		working satisfactorily		
				Read		working satisfactorily-		
				Ruau		all concrete washed		Proposed in drip
						for irrigation outlet	Necessary repairs should be	Froposed in drip –ii
				Soonage			apprint out	
				Moogureme	o	(AIH) The foundation	Camed Out	
				nt	0.			
				III		erosion or scour		Broposod in drip
						nutueu in u/s side of		Froposeu in anp –n
						you're wall of waste		
					~	well.(A16)		
					9.	The scour noticed on		

				Instrumenta tion General		the immediate downstream - on right side of end weir some scour & retrogression is observed. Some pitting of surface observed. (A17)	Necessary work shall be carried out	Proposed in drip –II Not Received
					10. 11.	Asphalt Road needs asphalting. The fencing & gates damaged. (B6) Hoist of EG of power house outlet is not	Necessary repair should be carried out in consultation with IRD, Nashik.	Not Received
					12. 13. 14	working.(A18) Alternate power system of gate operation needs replacement.(A19) All piezometers are not working. (B9) The portion of	Necessary work shall be carried out	Not Received Proposed in drip –II
					14.	upstream and downstream of dam is not easily accessible due to growth of bushes grass and trees. (B13)		
34	Name Urmodi (Gated) Tal. Satara Dist. Satara Year of completion : 2012 Location : Longitude 73 ⁰ 54'40" Latitude 17 ⁰ 40' 00" Height : 51.10 m	19.05.2019 14.12.2020	Mr.Doiphode S. L. SE, S.I.C., Satara	Gallery/Shaf t and Drainage (Concrete/ Masonry) Access	1.	The foundation and porous holes are not periodically cleaned with reaming tool and air water jetting. (A9)	Necessary repair should be carried out Necessary repairs should be carried out	Not Received
	Gross Capacity : 282.14 Mm ³ SpillwayCapacity :3840 Cumecs Sr.No.In Large Dam Register 2009: MH09HH1594			Road Instrumenta tion	2.	Access Road to gallery, instrumentation room needs to construct. (B6)	Necessary repair should be carried out in consultation with IRD, Nashik	Planned
					3.	Instruments need to repair. (B9)		Planned

(c) Ex	ecutive Engineer, Koyana Irrig	gation Divisior	i, Koyananagai	r			
35	Name: Kolkewadi(Gated)	18.05.2020	Mr.Doiphode	Gallery/Shaf	1. Total no. of foundation	It should be repaired by	Not Received
	Tal. Chiplun Dist. Ratnagiri		S. L.	t Condition	holes are 119, 109 are	suitable remedial measures in	
	Year of completion :1975		SE, S.I.C.,		in chocked condition.	consultation with Mechanical	
	Location :		Satara	Gallery	(A9)	organization and CDO,Nashik	
	Longitude 73°38' 50''				2. Total seepage is		
	Latitude 17º 25'				336.23lpm,total		
	Height :66.00 m				seepage during first		
	Gross Capacity :36.22 Mm ³	22.11.2020			filling in may 1975 was		
	Sr.No.In Large Dam Register				43.00lpm		
	2009:MH09HH0527			Spillway and		Leaching material should be	Not Received
				Energy	3. Leachate deposition	tested and remedial	
				Dissipation	observed all over	measures should be carried	
				Structure	gallery portion.	out as per CWPRS,Pune	
					Excessive seepage		
					and leaching observed		
					through the body of the	Necessary repairs should be	Not Received
					dam and the	carried out	
					foundation. (A12)		
					4. Abrasion of the		
					glacious concrete at		
					few locations		
					(especially near upper		
					tangent point of the		
					ogee) is observed.		
					(B8)		
36	Name: Koyana	18.05.2020	Mr.Doiphode	Gallery	1. Major number of drain	Necessary repairs should be	Repair Work of Stilling
	(Gated)		S. L.		holes choked. (number	carried out	Basin is Proposed
	Tal. Patan Dist. Satara		SE, S.I.C.,		of holes not		Under DRIP-II
	Year of completion :1967		Satara	Dam and	mentioned) (A9)	Necessary repairs should be	Repair Work of Stilling
	Location :			Dam Block	2. Evidence of damage to	carried out	Basin is Proposed
	Longitude 73°44' 26''	21.11.2020			joints and/or water		Under DRIP-II
	Latitude 17°23'00"				stops observed -		
	Height :103.02m				sharing of few water		
	Gross Capacity :2980.68 Mm			FD 4	stops on upstream		
	Spillway Capacity :			EDA	face of monolith joints,		
	5/42.25cumecs				resulting in increase of	Necessary repairs should be	
	Sr.No.In Large Dam Register				leakage through joints.	carried out	Repair Work of Stilling
	2009: MH090H0100				(A10)		Basin is Proposed
				Quillet	3. Evidence of abrasion,		Under DRIP-II
				Outlet	cavitations or scour on		
					dissipation structure		
					observed - Surface of		

			stilling basin anron 3		Field Officers are not
			cm to 13cm eroded.		observed or Recorded
			(A14)		such Observation,
			4. The energy dissipation		However we will keep
		General	arrangement is not	Necessary repairs should be	observation and
		Condition	working satisfactorily	carried out	investigate &
			for the all discharges.		Communicate it with
			(A14)		due Course time.
			5. There are vibrations	Necessary repairs should be	Repair Work of Stilling
	Teet		and noise noticed in	carried out	Basin is Proposed
	Test Increated by	Divor Sluico	operation of outlet		Under DRIP-II
	Mr V K Bhadn	River Sluice	6 There is a evidence of		Already C.D.work is
		Stilling	degradation to		present to access road
	SE. DSO	Basin	condition of instrument		and the necessary
	Nashik		(rusting, vandalism) -	Necessary repairs should be	cleaning work will be
			details not given. (B9)	carried out	done.
			7. Appropriate cross		Field Officers are not
		Spillway	drainage work need to		observed or Recorded
			be provided to access		such Observation,
			road.(3.6)		However we will keep
					invostigato
					Communicate it with
			8 River Sluice Valve is		due Course time
			not in working		
			condition.(B5)		
					Stilling Basin is
					inspected on
					22/01/2020
			0 Stilling Designation		
			9. Sulling Basin observed		done by Mochanical
			standing water instilling		done by Mechanical
			basin it could not be		wing.
			inspected (A14)		
			10. Minor leakage		
			observed on nappe of		
			spillway gate no.6 (B7)		

[B] Cł	nief Engineer (S.P.),Water Reso	ources Departr	nent, Pune					
(1) Su	perintending Engineer, Kukadi	Irrigation Cire	cle, Pune					
(a) Ex	ecutive Engineer, Kukadi Irriga	ation Dn No. 1,	Narayangaon,	Dist.Pune				
[B] Cr (1) Su (a) Ex 37	hief Engineer (S.P.),Water Resc perintending Engineer, Kukadi ecutive Engineer, Kukadi Irriga Name: Manikdoh (Gated) Tal. Junnar Dist. Pune Year of completion : 1984 Location : Longitude :73 ⁰ 49' Latitude :19 ⁰ 14' Height :57.80 m Gross Capacity :308.06 Mm ³ Spillway apacity:143m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH1060	trigation Ciro trigation Ciro ation Dn No. 1, 18.05.2020 26.11.2020	nent, Pune cle, Pune , Narayangaon, Shri H.T. Dhumal SE KIC, Pune	, Dist.Pune Gallery Body Wall	1. 2. 3. 4. 5. 6.	Safety issues like inadequate handrails, lighting or ventilation, etc observed. Problem to inspect the pump observed. The deterioration of pump and associated equipment observed. (A8) The foundation and porous holes not cleaned periodically, with reaming tool and air water jetting. (A9) Excessive seepage/sweating along gallery/shaft observed (location - ch. 435 to 600) (A10) Significant or excessive leakage along gallery/shaft / porous drain observed. (A10) Excessive seepage and leaching through the body of the dam and the foundation Leaching observed at left guide wall. (A12) It is observed that there is excessive seepage, sweating on the downstream face of the dam (Location not mentioned) (A11)	Providing proper draining arrangement seepage in the gallery. Leakages to be minimized by suitable treatment on upstream surface. The foundation and porous holes shall be cleaned periodically. Necessary repairs should be carried out	Not Received
					7.	The pointing on upstream face of the dam is not in good condition. (B8)	measures should be carried out. Leached material to be collected and	
				Downstree	δ.	excessive seepage/sweating	weighed & record of	
				m Face		downstream face. (A11)	to be maintained.	
					9.	Obstructions observed in or	Leaching material	
				Energy		immediately downstream of	should be tested	
				Dissipation		dissipation structure -needs	from Lab.	
				Structure		nalla regradation. (A14)		
					10.	The full length of wire rope of	, , , , , , , , , , , , , , , , , , ,	
						the hoist is not in serviceable	The repairs should	

	16.9.2020	Test Inspected by Shri Y K Bhadane SE DSO Nashik	Outlet Gates Crest of Dam Upstream Face	condition. (A18)be11. The operation of outlet gates is not smooth. (B5)be12. All the lifting beams are not in proper working order and in leveled condition. (B5)It s under and repa13. The connecting bolts of rubber seals are not properly tightened or damaged. (B12)It s under and repa14. Degradation to access road observed. Bituminous road needs repairs. (B6)Qual seep15. Spalling of concrete observed at some places. (Location not mentioned) (B8)mon wise16. The approximate quantity of leakage through the gates.(B10)Nece shou out17. Leakages observed at the junction of flank OF and NOF section (A15)Nece shou out18. Stilling Basin observed flooded.(A14)Nece shou out19. Plumb bob is not is working condition.(B9)out	carried out Jgh mechanical nization. hould be kept or observation necessary irs should be ed out. ntum of page should be itored monolith tr essary repairs Jld be carried essary repairs Jld be carried
				Nece shou out Nece shou out	essary repairs Ild be carried essary repairs Ild be carried

r								
38	Name: Wadaj (Gated) Tal. Junnar Dist. Pune Year of completion : 1982 Location : Longitude : 73⁰52'30 " Latitude : 19⁰ 09'00 " Height : 28.00 m Gross Capacity : 36 Mm³ Spillway apacity: 1426m³/sec Sr.No.In Large Dam Register 2009: MH09HH1006	18.05.2020	Shri H.T. Dhumal SE KIC, Pune	Water Conveyanc e Structure Crest of Dam Spillway Gates Outlet Gates	1. 2. 3. 4. 5. 6. 7.	There is an evidence of seepage or leakage from water conveyance structure at ch. 435m. (A11) Cracks observed on dam top between ch.0/840 to ch.1/010. (A13) Cracks observed on dam top between ch.0/840 to ch.1/010. Depth of cracks has been observed by taking open trenches. It is found that bottom of cracks extends below possible open trench depth. (B4) Gate 1 & 3 is not working smoothly. (A20) The condition of the steel surface and the surface paint deteriorated - gate 3 & 5 is leakage through bottom rubber seal. (B11) The operation of outlet gates is not smooth - Gate no 1 & 3 is suddenly dropped appro.2 to 3 cm while gate closing. (B5) The degradation of slope protection (rip-rap)observed. Pitching disturbed.	Necessary repairs should be carried out Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repairs should be carried out Necessary repairs should be carried out Necessary repairs should be carried out	Not Received
							-	
39	Name : Dimbhe (Gated) Tal. Junnar Dist. Pune Year of completion : 2002 Location : Longitude 74⁰44'30 " Latitude 19⁰5'45 " Height : 72.10 m Gross Capacity : 328.22 Mm³ Spillway capacity: 2870 m³	18.05.2020	Shri H.T. Dhumal SE KIC, Pune	Gallery	1. 2.	Problems of inadequate drainage (slippery stairs, water logging of gallery, clogged porous or foundation drains, etc) observed. (A8) The foundation and porous holes not cleaned periodically, with reaming tool and air water jetting. (A9)	Seepage in the gallery to be minimised by suitable treatment to upstream portion	Not Received

sec				3.	Excessive seepage/sweating	Porous pipes &	
Sr.No.In Large Dam Register	3.12.2020				along gallery/shaft observed	drain holes should	
2009:	-				(location not mentioned) (A10)	be cleaned for	
MH09HH1558				4.	Significant or excessive	proper functioning.	
					leakage along gallery/shaft /	F F - · · · · · · · · · · · · · · · · ·	
					porous drain observed (location		
					not mentioned) (A10)	Quantum of	
				5	Leachate deposition observed	seenage should be	
				0.	$(\Delta 12)$	monitored monolith	
				6	Excessive seenage/sweating		
				0.	throughout on downstream	WISE.	
			Downetroo		face Significent lookage on		
			Downstrea		downstroom food observed		
			IIIFace		(looption not montioned)	Loophad motorial to	
					(location not mentioned)		
					Seepage water springs	be collected and	
					observed in the downstream	weignea & record	
				_	area (A11)	snould be	
				7.	Slushy condition or water	maintained.	
					logging observed immediately	Leaching material to	
			Body wall	_	d/s of dam.(A2)	be tested from lab.	
				8.	There has been considerable		
					leaching observed from the		
					seepage water and deposition		
					of lime near the seepage exit		
			Energy		spots. (A12)		
			Dissipation	9.	Obstructions observed in or		
			Structure		immediately downstream of		
					dissipation structure(near		
			Crest of		bridge over river) (A14)		
			dam	10.	Degradation to access road	Necessary repairs	
					observed (unsealed) (B6)	should be carried	
			D/s face	11.	Concrete/masonry deterioration	out	
			Outlet		observed (B8)		
			Gates	12.	The surface of gates and the		
					paint deteriorated. (B11)		
		Test		13.	Wetness/Sweating observed on		
		Inspected by			almost 70% portion of d/s slope	Necessary repairs	
	16 9 2020	Shri Y K			of dam(A11)	should be carried	
	10.0.2020	Bhadane		14	Heavy Leakages observed near	out in consultation	
				17.	Inspection Gallery & Monolith	with Mechanical	
		Nashik			no $A\Delta AB T\Delta$ as well ($\Delta 10$)	Organization	
		INASIIIN		15	The inspection College couldn't	organization	
				15.	he inspection Gallery Couldn't		
					due to begins to		
					due to neavy		

					16. 17.	leakages.(A8)(A10) Stilling Basin observed flooded.(A14) Leaching from gallery at some chainage is observed(A12)	Necessary repairs should be carried out	
							Necessary repairs should be carried out	
							Necessary repairs should be carried out	
40	Name: Pimpalgaonjoge Gated Tal. Junnar Dist. Pune Year of completion : 2000 Location : Longitude : 75⁰52'30'' Latitude : 19⁰18'45'' Height : 34.204 m Gross Capacity : 235.28 Mm³ Spillway capacity: 1167.3 cu sec Sr.No.In Large Dam Register 2009: MH09MH1520	18.05.2020 26.11.2020	Shri H.T. Dhumal SE KIC, Pune	Crest of Dam Instrumenta tion River Sluice Spillway Gates	1. 2. 3. 4. 5. 6. 7. 8.	The bituminous road needs repairs. The degradation observed to road surface - pot holes observed (B6) The pan evaporimeter not in working order. (B9) The overall condition of river outlet works/river sluices is not satisfactory. Heavy leakages observed in river sluices.(quantity of leakage is not mentioned) (B10) Some leakage observed in river outlet works/river sluice. (B10) The approximate quantity of the leakage through the gates is 60 to 70 cusecs. (B12) The condition of the steel surface and the surface paint deteriorated. (B11) Leakages observed through radial gates.(B12) The leakage is observed through the well and the conduit concrete.(Quantity of	Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repairs shall be done in consultation with IRD, Nashik. Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repairs should be carried out be carried out	Not Received

						leakage not mentioned.)(A4)				
								Necessary should be out	repairs carriec		
(b)Ex	ecutive Engineer ,Dimbhe Dam	Division, Mar	nchar, Dist. Pu	ne				•			
(b)Ex 41	ecutive Engineer ,Dimbhe Dam Name :Chilewadi (Gated) Tal. Junnar Dist. Pune Year of completion :2000Location : Longitude 73 ⁰ 50'00" Latitude 19 ⁰ 21'00" Height :62.56 m Gross Capacity :27.17 Mm ³ Spillway capacity: 1686 m ³ / sec Sr.No.In Large Dam Register 2009:MH09HH1553	Division, Mar 18.05.2020 3.12.2020	Shri H.T. Dhumal SE KIC, Pune	ne Downstream Drainage Spillway Energy Dissipation Structure Waste Weir Bar and Tail Channel	1. 2. 3. 4. 5.	There are signs of water logging, slushy conditions or growth of aquatic weeds on the downstream of the dam. (A2) Excessive seepage/sweating observed on spillway glacis (A11) The under drainage of the stilling basin (or bucket) is not functioning satisfactorily. All the open drain holes are not clear and functioning well. (A14) One Side of West Weir coping eroded (Approx size - 19 X 5 m) (A14) The scouring observed on downstream side of the bar and/or EDA. End weir apron erode on right side, hole is observed on end weir wall. (A17) Erosion on surface at	Necessa carried with Mec Scouring and nec be carried be carried Necessa carried o Necessa carried o	g should be o chanical Orga g should be o ressary repair ed out. ary repairs shout.	nould be sultation nization observed res shall nould be nould be	Not Received	
				Hoists, Cranes and Operating Mechanisms	υ.	d/s side of weir observed. The concrete eroded size	Necessa carried o	ary repairs sh but	ould be		

				EG		- 19x5m. (A17)		
					7.	The coping over the		
						spillway bar in good		
						condition or not ?		
						(not clearly		
						mentioned) (B7)		
				Conorol	o	Emorgonov gotos oro	Necessary repairs should be	
				General	0.	Energency gates are	Necessary repairs should be	
				Condition			camed out	
						condition, they are in		
						hanging position at		
						top level. Guide tees		
						are bent, guide tee is		
				Instrumentat		absolutely disturbed,	Necessary repairs should be	
				ion		and corroded and not	carried consultation with IRD,	
						functioning. (B5)	Nashik.	
				Spillway	9.	The considerable		
				Gates		noise noticed in		
						operation of outlet		
						gate. (B5)		
					10.	The access road of	Necessary repairs should be	
						WBM needs repair	carried out	
						The obstructions	camed out.	
						along or at entrance		
						to poppor road		
						to access toau		
						observed, river bridge		
						Is needed. (B6)		
					11.	Out of 8 only 2		
						piezometers are in		
						working condition.		
						(B9)		
					12.	The general condition		
						of rubber seals- Gate		
						No.1 Bottom rubber		
						seals damaged. (B12)		
					13	The rubber seals of		
					.0.	Gate no 1 side and		
						bottom not touching		
						uniformly all along the		
						cooling ourface (P12)		
						sealing surface. (BTZ)		
40	Nama Yadagaa	19.05.2020		Dom and	1	Hairling gradka at	Neessan, repairs should be	Not Dessived
42	Tal Junnar Dist Dura	10.05.2020		Dam Daarb	١.		ivecessary repairs should be	NUL RECEIVED
	Tal. Junnar Dist. Pune	00.44.0000		Dam Reach		some places on crest	carried out.	
	year of completion	26.11.2020	SE KIC, Pune	(Embankme		of dam. (B4)		

	:1977Location : Longitude 74 ⁰ 01'30" Latitude 19 ⁰ 10'30" Height :24.60 m Gross Capacity :93.43 Mm ³ Spillway capacity: 3844 m ³ / sec Sr.No.In Large Dam Register 2009: MH09MH0658			nt)		
(c)Exe	cutive Engineer ,Kukadi Irriga	tion Division	No. 2, Shrigono	da, Dist. Ahm	gar	
43	Name : Ghod (Gated) Tal. Shirur Dist. Pune Year of completion : 1965 Location : Longitude 74⁰51'50 Latitude 17⁰ 8'10" Height : 34.75 m Gross Capacity : 216.30 Mm³ Spillway capacity: 7465 m³/ sec Sr.No.In Large Dam Register 2009: MH09MH0117	19.05.2020 21.11.2020	Shri H.T. Dhumal SE KIC, Pune	Structural performance Earthen Dam Spillway Outlet gate End Weir	Excessiveseepage duantum of seepage should be monitored monolithwise. Necessary repairs should be carried out.Not Receivedbody of the dam and the foundation. (A10) Sweating was observed d/s of spillway gate (A11) The minor leakage/sweating observed at few gate spillway portion. (A11) Seepage noticed in conduit.(A4)Necessary repairs be carried out in consultation with Mechanical Organization.Necessary repairs should be carried out.Necessary repairs be carried out in consultation with Mechanical Organization.Necessary repairs should be carried out consultation with damages observed in r/s portion of checkNecessary repairs should be carried out consultation with	
				Downstream Face Outlet W.W.& T.C	 wall. (A16) The scour noticed on he immediate downstream of check vall. (A16) The Presence of small cracking (structural, hermal, along joints) observed on the few bortion (B4) Necessary repairs should be carried out in consultation with Mechanical Organization. 	

			not fixing. (ii) GRBC. The lifting beams are not in proper working order and not in levelled condition. (B5)	Necessary repairs should be carried out	
		End Weir	 9. Standing pool of water in the downstream of dam in river portion. (A2) 10. Three Service gates of LBC are not working properly. Steam rods of gate are bent and need to be replaced with alignment. Leaf and brass plates of all gates to be replaced. 	Necessary repairs should be carried out in consultation with Mechanical Organization.	
		Outlet Gates	Guide brackets are broken and need to be replaced with alignment. Leakages are observed.(B5)	Necessary repaires shall be carried out.	
			 11. EDS undewr drainage block due to deposition of debris material in EDA.(A14) 12. Erosion and damage is observed at R/S portion of check wall. (A16) 	Asphalt road shall be get repaired. Necessary repairs should be	
			 13. Few portion of asphalt road observed the potholes. (B6) 14. U/S portion of spillway structure needs concreting. (B8) 	Carried consultation with IRD, Nashik.	
			15. Piezometers: Stand pipe - 10 nos not in		

					working condition. (B9)		
4.4	Nome (Cated)			D/a	1 Loopl pando at 50m	Necessary repairs should be	Not Dessived
44	Name :Sina (Galed)	27 05 2020		D/S Droinago	from the tee drain at ch	necessary repairs should be	Not Received
	Tal. Kaljal, DISLA Nagal	27.05.2020	SE KIC Duna	Dramage		camed out.	
	Location :	10 12 2020	SE KIC, Pulle	Concroto	2 Somo minor lookagos		
	Location .	10.12.2020		dom	2. Some minor leakages		
	Latitude 18°49'00"			sections	observed (A 15)		
	Height :28 5 m			End Wair	3 Frosion and damages	Necessary repairs should be	
	Gross Capacity · 67 95 Mm ³				observed in right side	carried out	
	Sr No In Large Dam Register				portion of check	barried bat.	
	2009: MH09MH1142				wall.(A16)		
					4. Scour noticed		
					immediate downstream	Necessary repairs should be	
				Outlet	of check wall.(A16)	carried out in consultation	
					5. SRBC service gate no.	with Mechanical Organization.	
					1 is not properly	Ũ	
					working. SLBC service		
					gate & emergency gate		
					both are not working		
					properly. EG is rusted	Necessary repairs should be	
					and guide channel is	carried out in consultation	
				Outlet Gates	damaged. (B5)	with Mechanical Organization.	
					6. SLBC & SRBC stem		
					rods bend. (B5)		
				Instruments	7. The operation of outlet		
					gates is not smooth.		
					(B5) 9 Den Evenerimeter 1		
					 van Evaporimeter - 1 	Nanana and and a start of the	
				Stilling	NUS INUL III WUIKING	necessary repairs should be	
				Sulling	Condition (B9)	carried out	
				Dasili	Becordor - 1 no Not in		
					working condition (RQ)		
					10 Water		
					accumulated in stilling		
					basin could not be		
				Access	drain out in proper		
				Road.	manner.Under		
					drainage of stilling		

(2) Su	Inorintonding Engineer Sata	ra Irrigation Br	oiost Circlo St	htara	basin is unsatisfactory.(A14) 11. There is no properly constructed and well maintained access road.(B6)	
(a) Fx	ecutive Engineer Minor Irrig	ation Division	Satara	alara		
45	Name :Nagewadi (Gated) Tal. Wai Dist. Satara Year of completion : 1999	20.03.2020	Shri. B. R. Pawar, SE, SIPC, Satara	Earth dam	1. There is a leakage It should be kept und from the junction of conduit with repairs should be carried of	In Not Received Y ut
	Location : Longitude 73 ⁰ 51'45" Latitude 17 ⁰ 55'17" Height :40.02 m Gross Capacity : 6 47 Mm ³	26.11.2020			surrounding earth by permission of compete work. The leakage is @ 1.235 lps in the form of clear water. (A1)	ıt
	Sr.No.In Large Dam Register 2009: MH09HH1518				2. The slushy patch at ch 855 to 870 near rock toe on d/s of the dam observed.(A2)	e
					 The hoist mechanism is not available at site.(A18) Necessary repaires shall carried out. 	e
					4. Enlegency gate – Chain pulley arrangement not available at site to take trail of	
					emergency gate.(B5) 5. The surface of gates and paints are deteriorated.(B11)	
46	Name :Morna (Gureghar) Tal. Patan Dist. Satara Year of completion : 2000 Location :	24.11.2020	Shri. B. R. Pawar, SE, SIPC, Satara	Gate	1. The alternate hand operating system of hoist is not working.(A18)	e
	Longitude 73°50'00" Latitude 17°17'30" Height :47.02 m Gross Capacity : 39.55 Mm ³ Sr.No.In Large Dam Register 2009:MH09HH1664			Access road	 I he indications of major active or inactive landslide observed on d/s of the dam near access road to the with IRD Nashik 	e n

				Instrumentat	3. 4.	dam.(B6) 14 nos foundation type Piezometers and 36 nos embankment type piezometers and uplift pressure cell ,6 nos are not in working condition.(B9) The condition of steel surface and surface paint deteriorated.(B11)		
47	Name :Pangare Tal. Satara Dist. Satara Year of completion :2000 Location : Longitude 73 ⁰ 52'30" Latitude 37 ⁰ 09'01" Height :32.10 m Gross Capacity : 2.72Mcum Sr.No.In Large Dam Register 2009:NA	19.5.2020 19.1.2021	Shri.S.L. Doiphode, SE SIPC Satara Shri P.B.Misal, SE SIPC Satara	Tail Channel	1.	Landslide in tail channel @ch 120m from waste weir has been observed.(A7) Evidence of structural distress on d/s of HR well,18m long portion of RCC conduit has sunk ny 0.45 m approx. and leakge through conduit observed.(A6)	Necessary repairs should be carried out Necessary repairs should be carried out	Not Received
48	Name :Kalgaon Tal. Patan Dist. Satara Year of completion :Work in progress Location : Longitude 73°53'00" Latitude 17°19'03" Height :32.26 m Gross Capacity : 2.692Mm ³ Sr.No.In Large Dam Register 2009:MH09HH2416	12.3.2020 21.11.2020	Shri. S.J.Hirey ,EE MID Satara	WW bar Access road	3.	Leakage through middle portion of spillway is observed.(A15) There is not properly constructed and well maintained access road.(B6)	Necessary repairs should be carried out Necessary repairs should be carried out	Not Received
49	Name :Kusawade Tal. Satara Dist. Satara Year of completion :2010 Location :	16.3.2020 26.11.2020	Shri. S.J.Hirey ,EE MID Satara		1.	The alternate hand operation syatem of hoist mechanism not	Necessary repairs should be carried out	Not Received

	Longitude 73 ⁰ 57'00" Latitude 17 ⁰ 34'46" Height :30.90 m Gross Capacity : 3.495 Mm ³ Sr.No.In Large Dam Register 2009:MH09HH2411		Shri. Y.K. Bhadane , SE DSO, Nashik		 working .(A18) Srevice gate and emergency gate needs periodical maintainance.(B5) The WBM road is in poor condition.(B6) Minor leakage from left side of ww bar at foundation level.(B7) No instruments installed at dam site.(B9) The dam section should be restored as per design(B3) Dam safety instrument are not installed on dam site.(B9)
50	Name : Tarali (Gated) Tal. Patan Dist. Satara Year of completion : 2007 Location : Longitude 73⁰54'15 " Latitude 17⁰32'00 " Height : 73.41 m Gross Capacity 165.70 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1666	12.04.2020	Shri.B. R. Pawar, SE, S.I.P.C., Satara	Body Wall OF & NOF Section Outlet / ICPU	 Electrification work in gallery is in progress. (A8) The u/s face of dam is in good condition. But damages at some spots.(B8) Appearance of sweating on the downstream face of dam is observed at monolith no.3, 4, 4A, 15 & 16. (A11) Considerable leaching observed on D/S face of dam (NOF) section.(A12) While operating D/S service gate, some noise is observed as the capacity of hoisting arrangement is less than required, Enhancing of hoist capacity is in progress.(B5) Necessary repairs should be carried out. Necessary repairs should be carried out. Leached material to be collected & recorded of quantity & wait to be maintained. Leaching material should be tested from MERI Nashik.

				Stop Gate	 Trash rack: Operating mechanism is not in position. (B5) Stop log gates/EG/SG: Operating mechanism in not in position. Not working satisfactorily. (B5) Pressure gauges for 5 pressure cells in inspection gallery are fixed which are choked up.Rain gauge at dam site not in working condition (B9) 	Necessary repairs be carried out in consultation with Mechanical Organization, Nashik. Necessary repairs should be carried out in consultation with	
			Test Inspected by Shri. Y.K. Bhadane , SE DSO, Nashik		 9. Sweating and leakages observed on d/s face of dam at Monolith no.3, 4, 4A, 15 and 16 (A11) 10. Considerable leaching from seepage water observed at some spots on NOF section of dam (A12) 11. Electrification in the gallery was not satisfactory (A8) 12. Leaching/Sweating is observed at some locations in inspection gallery (A12) 13. 	Mechanical Organization, Nashik. Necessary repairs should be carried consultation with IRD, Nashik. Necessary repairs should be carried out	
51	Name :Uttarmand Tal. Patan Dist. Satara Year of completion : 2001 Location : Longitude 74⁰28'00 " Latitude 17⁰24'24 " Height : 44.45 m Gross Capacity 24.925 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1591	12.04.2020	Shri.B. R. Pawar, SE S.I.P.C., Satara	Instrumenta tion Gate	 Foundation Piezometers - 24 Nos. Embankment Piezometers - 11 Nos. Plastic Cap Piezometers - 70 Nos. Earth Pressure Cells - 4 Nos. These instruments are not in working condition.(B9) The surface of gates and paints are deteriorated.(B11) 	Necessary repairs should be carried out in consultation with IRD, Nashik.	Not Received

(3)Su	3)Superintending Engineer & Administrator, C.A.D.A. Solapur									
(a)Exe	ecutive Engineer, Ujjani Dam M	laintenance D	ivision, Bhima	nagar						
52	Name : Ujjani (Gated)	11.05.2020	Shri. D.B.	EarthDam	1.	Concavity seen on U/S	Dam section should be			
	Tal. MadhaDist Solapur		Sale	Masonry		between Ch.2015 to	restored to design section.			
	Year of completion : 1980		SE & Adm.	dam		2040 m. is since last				
			CADA,	Outlet gate		15 years. However				
			Solapur.			there is no increase in				
	Latitude $14^{-}08'00'$			Callburg		its concavity	The summer easting should be			
	Height :56.40 m			Spillway	~	thereafter. (B1)	The current section should be			
	Gloss Capacity 332.00 Min				Ζ.	Ugee crest shows	superimposed on design			
						deterioration at many	section to find out degree of			
	2009.1010900043			Collony			remedial maggure			
				Gallery		places.(B7)	suggested			
							callery should be cleaned and			
					3	In gallery safety issues	proper safety rrabgements			
					0.	arrangement	should be made			
				Body wall		(inadequate handrails.				
				,		nosing to steps is				
						necessary.) (A8)	Porous pipes need should be			
					4.	Porous pipes need	cleaned.			
				Spillway		cleaning (A9)				
					5.	There is considerable	It should be kept under			
						leaching at some	observation & leaching			
				River outlet		places, particularly	material should be sent to			
						NOF and O.F. joints	MERI/ Lab for testing.			
						(A12				
				Instrumentat	~	-	Proper remedial measure be			
				ion.	6.	There is retrospective	taken and scouring be			
						erosion on d/s or tall	monitored aprevented rutther			
						EDA. It needs	scounny.			
						attention (A17)	It should be repaired properly			
					7.	River sluice conduits	in consultation with			
						need attention. (B10)	mechanical organization			
		22.01.2021	Test	EE			It should be repaired properly			
			Inspected by		8.	some Instruments are	in consultation with IRD,			
			Shri Y K			not installed& Some	Nashik.			
			Bhadane			not working as per				
			SE DSO			Annexure-I (B9)				
			Nashik	Quartlaw		Longitudinal araptares	Settlement of dam top should			
				Overnow	9.	Longitudinal Crack Was	ourront cross costion			
				Section		opserved on earmen	Longitudinal contian on the			
						empankment at Ch	iongludinal section on the			

				2575 m. (B4)	original design cross section	
			10.	Leakage was		
				observed on the	It should be kept under	
		Spillwov		junction of overflow	observation.	
		Spillway		overflow section The		
				leakage should be		
				kept under observation		
				with respect to	It should be kept under	1
				reservoir water	observation	
				level.(A3)		
			11.	Leakage from sides of		
				spillway gates was	It should be kept under	1
				observed at some	observation with respect to	
				places. (B12)	reservoir water level.	
			12	Sweating was	Leaching material should be	
				observed on some	sent to MERI for testing.	
				piers of overflow	They should be cleaned	
				section. (A11)	periodically	
			13.	Leaching was		
				observed in gallery.		
				(A12)		
			14	Many relief holes are		
			17.	chocked due to		
				leaching. Many vertical		
				porous drains are		
				chocked with		
				construction material.		
				that it is since	It should be provided	
				construction. Chocked		
				porous pipes should		
				be drilled and made		
				functional.(A10)		
			15.	Lighting arrangement		
				is not provided in		
				gallery. (A8)		

(b)Ex	ecutive Engineer, Solapur Irrig	ation Divisior	n, Solapur				L	L
(2) \$	Name : Ekruk (Un Gated) Tal. Dist Solapur Year of completion :1871 Location : Longitude 75⁰54'30" Latitude 17⁰43'30" Height : 21 .45 m Gross Capacity : 61.160 Mm³ Sr.No.In Large Dam Register 2009: MH09HH0007	12.05.2020	Shri. D.B. Sale SE & Adm. CADA, Solapur.	Earth Dam	1.	Longitudinal deep cracks observed on u/s crest of dam at ch.0/528 to ch.0/650 similarly deep cracks on dam topch.0/600toch.0/650, ch.0680 to ch.0/700,ch.1/020 to ch.1/050 . (B4)	Dam section should be restored to design section.	Not Received
(3)3u	perintending Engineer Osman	abau inigation	Circle, Osmar	labau				
(a)Ex	ecutive Engineer, SinaKolegad	onProject Divis	sion, Paranda	Dist. Osmana	bad			
54	Name :SinaKolegaon Tal.ParandaDist Osmanabad Year of completion : 2007 Location : Longitude 75°24'00' Latitude 17°18'00' Height : 36.60 m Gross Capacity : 19.19 Mm ³ Sr.No.In Large Dam Register 2009:MH09HH1673	16.05.2020 09.12.2020	Shri. S.S.Pagar&. R.ShingadeS E OIC Osmanabad	Gallery EDA NOF General D/S Drainage	1. 2. 3.	Drainage Gallery is not accessible , In gallery safety issues arrangement not provided (inadequate handrails, lighting or ventilation) (A8) There is Significant or excessive leakage at along gallery/shaft / porous (A10) The under drainage of the stilling basin (or bucket) not satisfactory The open drain holes are not clear and functioning well (A14) Small seepage found through the body of the dam (B8)	Redrilling the hole is being carried ut by mechanical organization It should be kept under observation and Necessary repairs should be carried out by permission of competent field authority. It should be repaired properly It should be kept under observation	The work is proposed in the program DRIP II &III estimate for the work is prepared and work will be carried out aftr sanction Not Received The work is proposed in program DRIP II estimate for the work is prepared and work will carried out after sanction The work is proposed in program DRIP II estimate for the work is prepared and work will carried out after sanction There is 12m difference in River bed level and lower bucket level for re-gradation purpose, it is necessary to

		Junction				excavate in river bed at
		Crest	5.	There is slushy condition or water logging immediately downstream of dam (A2)	It should be kept under observation and its source should be identified.	least 60Kk.m. length in which foundation of many K.T. Weirs & bridges will be distributed Hence it is not possible to re-grade the river bed. The work is proposed in program DRIP II estimate for the work is prepared and work will carried out after sanction
			6. 7.	There is the portions of longitudinal toe drain and exposed cross drains beyond the downstream toe of the dam is not in regular section and freely draining (B2) Earthen portion near masonry dam have been settled to tune of 90 Cm. in depth for 55 Mtr in length (B3)	Drains should be cleaned. Drain section should be restored as per design. Dam section should be restored to design section.	The work is proposed in program DRIP II estimate for the work is prepared and work will carried out after sanction The work is proposed in program DRIP II estimate for the work is prepared and work will carried out after sanction
			8.	The surface is degraded and reinforcement is open (B8)	Necessary repairs should be done	
			9.	Instruments are not installed in dam (B9)	Instruments should be installed in dam	

Table 2.6

ATR on Category-1 Deficiency in Class-II Dams

Sr. No.	Dam Features	Date Of Inspection	Main Component Of Dam	Observation / Significant Deficiencies Noticed	Remedial Measures Suggested	Implementation Status
1	2	3	4	5	6	7
	2	3	4	5	6	7

Table 2.7

ATR on Category-2 Deficiency in Class-II Dams

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status	
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested		
1	3	2	4	of Dam	6	7		
ı IAlChie	Engineer (W.R.) Water Resource	es Denartm	ent Pune	5	0	1		
(1)Sup	erintending Engineer Pune Irriga	tion Circle.	Pune					
(a)Exec	cutive Engineer. Pune Irrigation	Division. Pur	ne					
1	Name :Shetphal	16.4.2020	Shri.	W.W	1. Wet Patches on	Necessary repairs to	Work for minimize wet	
	Tal. Indapuri Dist. Pune	Not	Rajendra		d/s are observed.	be carried out.	spots treatment in the	
	Date of completion:-1901	Received	Dhodapkar				dam body will be	
	Location :		E.E				included in annual	
	Longitude - 75°00'30"		PID. Pune				maintenance and repair	
	Latitude- 18°01'00"						programmed .After	
	Height :-20.11 m.						approval from competent	
	Gross capacity :- 17.36 Mcum						authority repair work will	
	Sr.No.In Large Dam Register						be carried out.	
	2012: MH09MH0021							
2	Name :Marnewadi	24.4.2020	Shri.	Outlet	1. Strengthening	Necessary repairs to	Estimates under special	
	Tal. Mulashi Dist. Pune	Not Received	Rajendra		work is essential	be carried out	repairs work will be	
	Date of completion:-1998		Dhodapkar		for outlet well.(A6)	Superimpose	prepared and submitted	
	Location :		E.E				to Govt fro approval.	
	Longitude - 73°40'00"		PID. Pune				Remedial Work will be	
	Latitude- 18°30'00"	15 09 2020	Shri				carried out after getting	
	Height :-18.35 m.	10.00.2020					approvarition	
	Gross capacity :- 0.87 Mcum		T. N. Bhadane				government.	
	2012:MHOOMH1452		SE DSO			Existing Cross Section	Existing Cross Section	
	2012.WH09WH1455		Nashik	FF		and L section on	and L section on Design	
					2.Earthen section	Design Cross Section	Cross Section and L	
					seems to be under	and L Section at every	Section at every 30 m	
					section in certain	30 m C/C to ascertain	C/C to ascertained soon	
					portion.	whether earthen	and will be	
						embankment is under	communicated to	
						section or not.	DSO,Nashik	
						Communicate facts to		
						USU, NASNIK	The work planned to be	
				WW bar		it should be brought to	taken under regular M&R	

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested	Implementation Status
1	2	3	Δ	or Dam	6	7	
	۷	5		5	0	original design section	during 2021-22
				Outet Well	WW Bar is in damaged condition Stem rod is bent	Necessary repairs should be carried out. Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Work is completed by Mechanical wing.
		0.4.4.0000	01.1			N1	
3	Tal.Mulashi Dist. Pune Date of completion:- 1998 Location: Longitude :- 73°50'00" Latitude : - 18°05'00" Height :- 24.00 m. Gross capacity :- 2.28 Mcum Sr.No.In Large Dam Register 2012: MH09MH1474	24.4.2020 Not Received	Rajendra Dhodapkar E.E PID. Pune	w.w.Bar	n. Splilway central portion 38.00mtr washed out. (B7)	should be carried out.	Work is carried out.
(b)Exec	cutive Engineer Khadakwasala Ir	rigation Div	ision, Pune11				
4	Name : Bhugaon Tal. Mulashi Dist. Pune Date of completion:- 1983 Longitude: - 73° 45'00" Latitude:- 18°30'00" Height :- 21.19 Gross capacity :- 1.90 Mcum Sr.No.In Large Dam Register 2012: MH09MH0963	14.05.2020 8.12.2020	Shri. V.P.Patil E.E KID. Pune	Earthen Embankment	1. Sectioning of embankment is necessary(B1)	Necessary repairs should be carried out.	Not Received
5	Name : Matoba Tal. Daund Dist. Pune Date of completion:- 1978 Longitude: - 74° 34'00 "	15.05.2020 5.12.2020	Shri. V.P.Patil E.E KID. Pune	E. E. WW Bar	1. Standing pool of water observed on RHS of embankment at	This area should be well drained so as to avoid any stagnant pools of water.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
		_		of Dam			
1	2	3	4	5	6	7	
	Latitude:-18°00'23"				some places. (A2)		
	Height :-17.50				2. Stone of masonry		
	Gross capacity :-45.2 Mcum				spillway and	Necessary repairs	
	Sr.No.In Large Dam Register				supporting soil is	should be carried out	
	2012: MH09MH0721				washed out due to		
					heavy rain.		
					Foundation of	Necessary repairs	
					spillway is now	should be carried out	
					visible. Masonry		
					spillway bar need		
					strengthening		
					urgently.(B7)		
					3. Huge scouring is		
					observed on D/S		
		45.05.0000	01 :		of bar.(A7)	. ·	
6	Name : Malad	15.05.2020	Shri.	Outlet	1.Leakages through	Necessary repairs	Not Received
	Tal. Daund Dist. Pune	5.12.2020	V.P.Patil		outlet well	should be carried out.	
	Date of completion1979		E.E KID Duna	MMA Bor	2 Outlet gete pet in		
			RID. Fulle	WWW Dai	2. Outlet gate flot in	It should be repaired	
	Latitude: $15^2 23 00$			Tail Channel	vers (B5)	it should be repaired,	
	Gross capacity :-1 74 Moum				3 Some portion of	and brought to original	
	Sr No In Large Dam Register				masonry bar is in	Design.	
	2012:MH09MH0796				broken condition.	It should be repaired	
					(B7)	It should be repaired.	
					4 .Due to heavy	Necessary repairs	
					rainfall on	should be carried out	
					15.10.2020		
					scouring noticed in		
					tail channel approx.		
					100m UCR wall and		
					embankment		
					washed out. (A7)		

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested	Implementation Status
		•		of Dam			
1	2	3	4	5	6	7	
7	Name : Palasdeo Tal. Indapur Dist. Pune Date of completion:- 1953 Longitude: - 74° 34'00" Latitude:- 18°23'00" Height :- 18.23 Gross capacity :- 1.09 Mcum Sr.No.In Large Dam Register 2012: MH09MH0063	15.05.2020 5.12.2020	Shri. V.P.Patil E.E KID. Pune	W.W.Bar	1. W. W. Bar is damaged due to heavy rainfall@ 14.10 2020 (B7)	Necessary repairs should be carried out.	Not Received
8	Name : Shirsuphal Tal. Baramati Dist. Pune Date of completion:- 1879 Location: Longitude: - 74° 35'20 " Latitude:- 18°21'00 " Height :- 20.11 Gross capacity :- 10.1 Mcum Sr.No.In Large Dam Register 2012: MH09MH0011	15.05.2020 5.12.2020	Shri. V.P.Patil E.E KID. Pune	Earthen Embankment	1. Crest profile is below by 1.15 m. than design crest and section is disturbed. (B1)	Necessary repairs are to be carried out to proper section after confirmation by competent field authority.	Not Received
(d) Exe	cutive Engineer, Nira Right Bank	Canal Divis	ion, Phaltan				
9	Name : Naigaon Tal.Khandala Dist. Satara Date of completion: 1983 Location: Longitude: 73° 58' 5" Latitude: 18° 06' 10" Height :18.0 m. Gross capacity :1.34 Mcum Sr.No.In Large Dam Register 2012:MH09MH.0986	22.05.2019 17.10.2020	Shri. S.R. Bodke E.E. N.R.B.C. Division Phaltan	W.W. Bar and tail channel Outlet	 Waste weir bar is damaged condition. Heavy Leakage is observed through Waste weir bar. (B7) Maintenance of outlet gate is required. (A6) 	Necessary repairs are to be carried out. Leakage record needs to verify before repair. Necessary repairs are to be carried out in consultation with mechanical organization.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
1	2	2	4	of Dam	6	7	
10		3	4 Toot	3	0 1 Drofuce growth	/ Trace vegetation and	Not Received
10	Name : Minasavad	25.02.2021	Test	EE		hushes must be	NOL RECEIVED
	Data of completion: 4976				OI ITEES,	busites must be	
	Date of completion: 1876		Shinin.S		vegetation and	uprobled before they	
	Location:		Dusane		DUSNES IS	will grow into trees	
			EE Dam		observed on the	endangering eartnen	
			Sarety		u/s side slopes of	empankment.	
	Height :24.00m.		DIV.NO.1		embankment.		
	Gross capacity :46.13Mcum		Nashik		Pitching on U/S		
	Sr.No.In Large Dam Register				side could not be		
	2012: MH09MH0017				inspected due to		
					heavy vegetation.		
					Vegetation is so		
					thick that unable to		
					see reservoir from		
				_	dam top		
11	Name : Banganga	23.05.2019	Shri.	Downstream	1. Wet patches are	Necessary repairs are	Not Received
	Tal.Phaltan Dist. Satara	17.10.2020	S.R.		seen at	to be carried out to	
	Date of completion: 1975		Bodke		downstream	proper section after	
	Location:		E.E.	EE	portion between	confirmation by	
	Longitude: 74° 25' 5"		N.R.B.C.		LBC and RBC (competent field	
	Latitude: 17° 40' 00"		Division		A2)	authority.	
	Height :16.76m.		Phaltan				
	Gross capacity :6.50 Mcum					Necessary repairs	
	Sr.No.In Large Dam Register				2. Edges of crest are	should be carried out	
	2012: MH09MH.0071				cut up resulting		
					reduction in width		
					of dam top(B1)		
(e) Exe	cutive Engineer, Lift Irrigation M	anagement I	Division , Pun	e			
12	Name : Pilanwadi	6.5.2020	Shri. M. B.	Outlet	1. Stem Rod of outlet	Necessary repairs to	Not Received
	Ial.Purander Dist. Pune	N.A.	Kanitkar,		gate is not in	be carried out in	
	Date of completion: 1978		EE,		operation ,need to	consultation with	
	Location:		L.I.M.D,		be changed.(B5)	mechanical	
	Longitude: 73° 52' 00"		Pune		2. Sluice outlet gate	organization.	
	Latitude: 18° 36' 00"				is not opening		
	Height :22.77 m.				smoothly.(B5)		
	Gross capacity :1.94 Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09MH.0729						

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
1	2	2	4	of Dam	6	7	
1/	Z Nama : Garada	3	4 Shri M B	D utlot	0 1 Operation of	/ Nocossary ropairs to	Not Possived
14	Tal Purander Dist Pune	4 12 2020	Kanitkar	Oullet		be carried out in	Not Received
	Date of completion: 1070	4.12.2020			outlet gate is	consultation with	
	Location:			W/W/ Bor	smooth Minor	mochanical	
	Location.		LIND, Fulle	WWW Dai	Sinootii.Minoi	organization	
	Latitude: 18° 15' 00"				through gate	organization.	
	Height :18.82 m				is observed	Necessary repairs to	
	Gross capacity :1 869 Moum				(B5)	he corried out	
	Sr No In Large Dam Register				2 Leakage from	be carried out	
	2012:MH09MH 0794						
	2012.10103001.0734				bar (Quantity		
					of leakage is		
					not given) (
					BZ)		
(f)Exec	utive Engineer, Chaskaman Irrig	ation Divisio	on, Pune				
15	Name : Nimgaon Mhalungi		Shri. B. K.	Earthen	1. Embankment is	Necessary repairs	Not Received
	Tal.Shirur Dist. Pune	21.05.2020	Shete,	Embankment	not as per design	should be carried out.	
	Date of completion: 1971	22.11.2020	E E CID,		section .(B1)		
	Location:		Pune				
	Longitude: 74° 12' 30"						
	Latitude: 18° 43' 30"						
	Height :17.30 m.						
	Gross capacity :3.37 Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09MH.0993						
16	Name : Dahiwadi		Shri. B. K.	WW Bar	1 .Leakage seen	Necessary repairs	Not Received
	Tal.Shirur Dist. Pune	21.05.2020	Shete,		from foundation	should be carried out.	
	Date of completion: 1971	22.11.2020	E E CID,		WW bar. (B7)		
	Location:		Pune				
	Longitude: 74° 12' 30"						
	Latitude: 18° 43' 30"						
	Height :17.30 m.						
	Gross capacity :3.37 Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09MH.1623						

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed	Remedial Measures Suggested	Implementation Status
1	2	3	4	5	6	7	
17	Name : Kadus Tal.Khed Dist. Pune Date of completion: 1986 Location: Longitude: 73° 55' 00" Latitude: 18° 56 00" Height : 16.65 m. Gross capacity : 2.63Mcum Sr.No.In Large Dam Register 2012: MH09MH.1126	20.05.2020 26.11.2020	Shri. B. K. Shete, E E CID, Pune	Outlet	 Stem rod for lifting the gate is slightly bent in top portion.(B5) 	Necessary repairs should be carried out in consultation with mechanical organization.	Not Received
(2)Supe	erintendingEngineer,Sangli Irriga	ation Circle S	angli				
18	Name : Antri Tal. Shirala Dist. Sangli Date of completion:-1991 Location : Longitude -74°05′00 Latitude -17°02′00 Height :-22.79 m. Gross capacity - 2.82Mcum Sr.No.In Large Dam Register MH09MH1215	02.05.2020 11.09.2020	Smt. J.A.Deokar EE,SIDSan gali	Embankment Outlet	 Leakage or oozing is noticed on d/s side (A1) H.R well is collapsed (A6) 	Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly. It should be repaired properly.	According to procurement list 2020-21 work is in progress and the work is in the final stage.
19	Name : Soradi Tal. Jath Dist. Sangli Date of completion:-1983 Location : Longitude -75°22'30" Latitude -17°03'05" Height :-18.08 m. Gross capacity - 4.40 Mcum Sr.No.In Large Dam Register MH09MH. 1002	08.05.2020 04.11.2020	Smt. J.A.Deokar EE,SIDSan gali	Outlet	1. Stem rod is not straight (B5)	Necessary remedial measures should be done in consultation with mechanical organization.	Stem rod repair and ancillary works are included in the non irrigation procurement list 2021-22 of the mechanical department

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed	Remedial Measures Suggested	Implementation Status
1	2	3	4	5	6	7	
(a) Exe	cutive Engineer,Tembhu Lift Irrig	gation Projec	t Managemen	t Division, Og	jalewadi		
21	Name : Atpadi Tal. Atpadi Dist. Sangli Date of completion:- 1972 Location : Longitude -74°55′00" Latitude -17°24′00" Height :- 16.50 m. Gross capacity - 8.67Mcum Sr.No.In Large Dam Register MH09MH0314	26.05.2020 16.10.2020	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Outlet	1. Stem rod is bent	Necessary remedial measures should be done in consultation with mechanical organization.	Not Received
22	Name : Buddhihal Tal. Mangalwedha Dist. Solapur Date of completion:- 1966 Location : Longitude - 74°59'54'' Latitude - 17°18'30'' Height :- 18.52 m. Gross capacity - 19.03Mcum Sr.No.In Large Dam Register MH09MH0134	14.04.2020 21.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Embankment	 Raincuts are developed on embankment. Crest profile is not at proper elevation. Undulations and local depression are observed. (B4) 	Original dam section should be restored.	Not Received
Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
-----	--	--------------------------	--	---------------------	--	--	-----------------------
NO.		Inspection	Officer	Component of Dam	Deficiencies noticed	Suggested	
1	2	3	4	5	6	7	
23	Name : Dighanchi Tal. Atpadi Dist. Sangli Date of completion:- 1976 Location : Longitude - 74°55'30'' Latitude - 17°24'30'' Height :- 15.80 m. Gross capacity - 4.0Mcum Sr.No.In Large Dam Register MH09MH0591	26.05.2020 16.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Outlet	1. Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received
24	Name : Ghanand Tal. Atpadi Dist. Sangli Date of completion:- 1986 Location : Longitude - 74°44'00'' Latitude - 17°44'30'' Height :- 15.46 m. Gross capacity - 1.44 Mcum Sr.No.In Large Dam Register MH09MH1120	20.05.2020 06.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Outlet	1. Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received
25	Name :Kadegaon Tal. Kadegaon Dist. Sangli Date of completion:- 1975 Location : Longitude -74°16′00" Latitude -17°16′00" Height :- 17.54 m. Gross capacity - 2.36 Mcum Sr.No.In Large Dam Register MH09MH0510	21.03.2020 10.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Embankment	 There is standing pool on d/s side at 400m. chainage (A2) Leakage or oozing through dam slope is observed(A1) Stem rod is slightly bent.(B5) Masonry of outlet well is disturbed at top coping (A6) 	It should be kept under observation and its source should be identified Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly. Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization	Not Received

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed	Remedial Measures Suggested	Implementation Status
1	2	3	4	5	6	7	
						It should be repaired properly	
26	Name :Karandewadi Tal Kadegaon Dist. Sangli Date of completion:-1995 Location : Longitude -74°17'12'' Latitude -17°22'00'' Height :-18.45 m. Gross capacity - 1.36Mcum Sr.No.In Large Dam Register MH09MH1348	21.03.2020 NA	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Embankment Outlet	 Settlement is gorge is observed, top width is reduced than design. (B1) Stem rods are not straight.(B5) 	Original dam section should be restored. Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received
27	Name : Morale Tal Tasgaon Dist. Sangli Date of completion:- 1974 Location : Longitude - 74°42'09'' Latitude - 17°11'43'' Height :- 16.10 m. Gross capacity - 0.65 Mcum Sr.No.In Large Dam Register MH09MH023	14.03.2020 24.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	General	 Approach road is not provided. (B6) 	Road should be constructed	Not Received
28	Name : Nimbhavade Tal Atadi Dist. Sangli Date of completion:- 1986 Location : Longitude - 74°52'30'' Latitude - 17°28'00'' Height :- 16.13 m. Gross capacity - 6.68 Mcum Sr.No.In Large Dam Register MH09MH1187	26.05.2020 16.10.2020	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Embankment	 Heavy longitudinal cracks and also deep upto 1.00 to 2.00m. Upper embankment of dam is not showing properties of casing should be removed and embankment to be done (B4) Heavy settlement 	Original dam section should be restored. Original dam section should be restored. It should be repaired properly	Not Received
				Callot	of bankwork in	Depending on severity	

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
				of Dam			
1	2	3	4	5	6	7	
					 gorge portion upto 1.20m to 0.5@ end (B4) 3. Outlet well is not in good condition. Concrete on top of well is disturbed (A6) 4. Stem rod is bent (B5) 	of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	
29	Name : Pare Tal Khanapur Dist. Sangli Date of completion:- 1973 Location : Longitude - 74°35'00'' Latitude - 17°12'00'' Height :- 18.73 m. Gross capacity - 34.6 Mcum Sr.No.In Large Dam Register MH09MH0296	13.03.2020 24.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Outlet	1. Upper slab, masonry portion of 1.5 m height completely damaged. (A6)	It should be repaired properly	Not Received
30	Name : Vejegaon Tal Khanapur Dist. Sangli Date of completion:- 1979 Location : Longitude - 74°36'00'' Latitude - 17°23'00'' Height :- 16.77 m. Gross capacity - 2.21 Mcum Sr.No.In Large Dam Register MH09MH0296	13.03.2020 23.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Embankment	1. Boils and we patches are observed on downstream side (A1)	Necessary repairs should be carried out properly.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	-
				of Dam			
1	2	3	4	5	6	7	
31	Name : Walunj Tal Lath Dist. Sangli Date of completion:- 1984 Location : Longitude -74°00'37" Latitude -17°00'19" Height :- 17.81 m. Gross capacity - 1.69 Mcum Sr.No.In Large Dam Register MH09MH0635	13.03.2020 23.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Outlet	1.Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received
32	Name : Mahadikwadi Tal Atpadi Dist. Sangli Date of completion:- 2003 Longitude - 74°40'00'' Latitude - 17°11'00'' Height :- 16.02 m. Gross capacity - 2.10 Mcum Sr.No.In Large Dam Register MH09MH1547	20.03.2020 06.10.2020	Shri.R.Y.Red diyar EE,TLIPD Ogalewadi	Outlet	 Leakage through outlet gate is observed (A4) 	Necessary remedial measures should be done in consultation with mechanical organization.	Not Received
33	Name : Jambhulani Tal Atpadi Dist. Sangli Date of completion:- 1975 Longitude -74°60′00" Latitude -17°34′00" Height :- 15.87 m. Gross capacity - 2.85 Mcum Sr.No.In Large Dam Register MH09MH0517	20.05.2020 06.10.2020	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Embankment Outlet	 Heavy raincut is observed on d/s (B4) Stem rod is not straight (B5) 	Original dam section should be restored Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status	
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested		
	-		-	of Dam		_		
1	2	3	4	5	6	7		
(3)Sup	erintending Engineer, Kolhapur	Irrigation Cir	cle, Kolhapur					
(a) Exe	cutive Engineer. Kolhapur Irriga							
34	Name :DaryachiVadgaon Tal. Chandgad Dist. Kolhapur Date of completion:-1993 Location: Longitude: -74°00' Latitude: -16°36' Height -:23.65 m. Gross capacity-0.8473 Mcum Sr.No.In Large Dam Register 2012:MH09MH1302	02.05.2020 13.11.2020	Shri.R. B. Bandiwadeka r EE. KID (North) Kolhapur	Embankment	1. Leakage through dam body is observed when water level at R.L. 88.00 to 92.70 m. from ch.135 to 195 m, but water is clear.(A1)	Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly.	Not Received	
35	Name : Kasarde Tal. Shahuwadi Dist. Kolhapur Date of completion:- 2009 Location: Longitude -74°51′00" Latitude -16°55′30" Height -: 29.85 m. Gross capacity- 4.416 Mcum Sr.No.In Large Dam Register 2012: MH09MH1908	22.05.2020 03.12.2020	Shri.R. B. Bandiwadeka r EE. KID (North) Kolhapur	Embankment	 There are some boils / wet patches on downstream of dam within 200m. (A1) 	Necessary repairs should be carried out properly	Not Received	
36	Name :Kumbhavade Tal. Shahuwadi Dist. Kolhapur Date of completion:-1999 Location: Longitude -73°46'00'' Latitude -16°47'00''Height :25.16 m. Gross capacity-5.615 Mcum Sr.No.In Large Dam Register 2012:MH09MH1499	15.05.2020 16.11.2020	Shri.R.B.Ban diwadekar EE. KID (North) Kolhapur	W.W. Bar	 There are heavy leakages through weir bar. (Quantity of leakage is not given.) (B7) 	Necessary repairs should be done to stop the leakage	Not Received	

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	•
		-		of Dam		33	
1	2	3	4	5	6	7	
37	Name : Padsali	18.05.2020	Shri.R.B.Ban	W.W. Bar	1. There are heavy	Necessary repairs	Not Received
	Tal. gandhinglaj Dist. Kolhapur	16.11.2020	diwadekar		leakages through	should be done to stop	
	Date of completion:-1997		EE. KID		weir bar. (Quantity	the leakage	
	Longitude -74°50'50''		(North)		of leakage is not	_	
	Latitude -16° 48'00''		Kolhapur		given.) (B7)		
	Height -:29.15 m.						
	Gross capacity-6.90 Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09MH1427						
38	Name : Pombre	18.05.2020	Shri.R.B.Ban	Embankment	1.There are some	Necessary repairs	Not Received
	Tal. Panhala Dist. Kolhapur	16.11.2020	diwadekar		boils/wet	should be carried out	
	Date of completion:-1985		EE. KID		patches/seepage/sluus	properly	
	Longitude -73°50'15"		(North)		hy/boggy ground on		
	Latitude -18°42'35"		Kolhapur		downstream side		
	Height -:24.11 m.				within 200m. (A1)		
	Gross capacity-6.50 Mcum						
	Sr.No.In Large Dam Register						
	2012:MH09MH1078						
(b) Exe	cutive Engineer,Kolhapur Irrigat	ion Circle (S	outh), Kolhap	ur			
39	Name :Dindalkop	26.05.2020	Shrimati S.C.	Outlet	1. Stem rods for	Necessary remedial	Not Received
	Tal. gadhinglaj, Dist. Kolhapur	25.11.2020	Mane		lifting gate are not	measures should be	
	Date of completion:-2014		E.E.		straight (B5)	done in consultation	
	Location:		KID (S)			with mechanical	
	Longitude- 74°25'30"		Kolhapur			organization.	
	Latitude: -15°45′45"						
	Height :-27.61 m.						
	Gross capacity 2.625 Mcum						
	Sr.No.In Large Dam Register						
10	2012:MH09MH1925	20.05.2020	Charing att 0.0	Outlat	1 Otom vodo	Den en die er en en veriter	Net Dessived
40	Name : Kitwad - 1	26.05.2020	Shrimati S.C.	Outlet	1. Stem rods	Depending on severity	Not Received
	Tal. Chanuyau, DISL Nomapur	27.11.2020			ore not	or benuing Stern Kod	
	Date of completion2000				are not	should be either	
	Lucaliun.		Kolbonur (S)		Straight (BO)	repared or replaced In	
			Romapur			Mochanical	
	Latitude: -15°58'00"					Organization	
	Height :-29.59 m.					organization.	
	Gross capacity 5.53 Micum						
	Sr.No.In Large Dam Register						
	2012: NIHU9NIH1543						

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
				of Dam			
1	2	3	4	5	6	7	
41	Name : Kumari Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1998 Location:	26.05.2020 17.11.2020	Mane E.E. KID (S)	Outlet	1. Stem rods for lifting gate are not straight (B5)	of bending Stem Rod should be either repaired or replaced in	Not Received
	Longitude: 74°18'00" Latitude: -15°30'00" Height :- 23.64 m. Gross capacity 2.59 Mcum Sr.No.In Large Dam Register 2012: MH09MH1457		Koinapur			Consultation with Mechanical Organization.	
42	Name : Shendri Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1981 Location: Longitude- 74°21′00" Latitude: -16°16′00" Height :- 21.14 m. Gross capacity 1.81 Mcum Sr.No.In Large Dam Register 2012: MH09MH0853	07.04.2020 27.11.2020	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	1. H.R. well is damaged (A6)	It should be repaired properly.	Not Received
43	Name : Sundi Tal. Chandgad, Dist. Kolhapur Date of completion:- 2009 Location: Longitude- 74°22'00" Latitude: -15°16'00" Height :- 27.00 m. Gross capacity 2.594 Mcum Sr.No.In Large Dam Register 2012: MH09MH1910	12.05.2020 25.11.2020		Shrimati S.C. Mane E.E. KID (S) Kolhapur	1. Stem rod for lifting gate is not straight (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures	Implementation Status
				of Dam			
1	2	3	4	5	6	7	
44	Name : Yenechavandi Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1996 Location: Longitude- 74°20' Latitude: - 16° 11' Height :- 21.65 m. Gross capacity 1.545 Mcum Sr.No.In Large Dam Register 2012: MH09MH139	12.05.2020 21.10.2020	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Earth Dam	1. D/S leakages at Ch 100 & 240m is observed. (A1)	It should be kept under observation. Leakage data should be mainted and reason for leakage should be in investigated & treated properly. Necessary repairs be carried out to damage portion.	Not Received
(4)Sup	erintending Engineer, Satara Irri cutive Engineer, Krishna Irrigati	gation Circle	e, Satara				
			Salara	F outhout	A Lashawa tha	This should be by t	Net Deschard
45	Name : Kankatrewadi Tal. Phaltan Dist. Satara Date of completion: 1978 Location: Longitude: 74°35′00" Latitude:17°29′00" Height :19.51 m. Gross capacity :1.24 Mcum Sr.No.In Large Dam Register 2012:MH09MH0736	17.5.2020	Shrii. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	Earnen Embankment W.W.Bar	 Leakage through masonry and foundation was observed (A3) There is leakgage between joint of guide wall and earthen embankment.(A4) Boil, wet patches ,water seepage ,slushy ground on the d/s of dam within 200mtr from the toe drain are observed.(A1) Retrogression and scouring observed in tail channel.(A7) Operation of outlet gate is not smooth. (B5) There is 	Inis should be kept under observation. Leakage should be measured, monitored and necessary repair to be carried out if necessary. Necessary repairs should be carried out.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	-
		_		of Dam			
1	2	3	4	5	6	7	
					settlement and displacement of stones in rock toe are observed.(B3)		
46	Name : Thoseghar Tal. Satara Dist. Satara Date of completion:- 1989 Location : Longitude- 73°52'00 " Latitude - 17°36'00 " Height :- 18.05 m. Gross capacity : 1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH1208	10.5.2020 27.11.2020	Shri. A.S.Pawar E.E., KID, Satara	Earthen Dam Outlet W.W.Bar Tail Chanel	 Relief wells are not functioning. (A5) Some leakage is observed through w.w. bar. (B7) Gate is not working smoothly,unusual noise during operation.(B5) EDA is heavily damaged. (A14) Guide wall,divide wall and guide bund damaged.(A16) 	Necessary repairs should be carried out. Causes of exact leakages should be investigated & treated accordingly. Necessary repairs should be carried out.	Not Received
47	Name : Ner Tal. Khatav Dist. Satara Date of completion:- 1981 Location : Longitude- 74°18′00 " Latitude - 17°44′00 " Height :- 22.50 m. Gross capacity : 9.12 Mcum Sr.No.In Large Dam Register 2012: MH09MH0018	17.5.2020 19.12.2020	Shri. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	Earthen Embankment	 Longitudinal cracks are observed on dam top during summer period. (B4) There is weak construction joint observed 3ft below ww bar and 	There should be close vigil on the behavior of cracks. Depthwise extend of crack shall be find out and proposed remedial action with necessary drawings shall be communicated to DSO, Nashik.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	•
		•		of Dam			
1	2	3	4	5	6	7	
1	2	3 25.02.2021	4 Test Inspected by Shri. N.S.Duane EE Dam Safety Div No.1 Nashik	EE	 6 heavy leakage through these jonts.(B7) 3. Relief well are not functioning properly.(A5) 4. Scouring on d/s side of bar is noticed.(A17) 5. Retrogession and scouring noticed in tail channel.(A7) 6. Longitudinal Cracks are noticed on dam top 	7 Necessary remedial actions should be taken. There should be close vigil on the behavior of cracks. Depthwise extend of crack shall be find out and proposed remedial action with necessary drawings shall be communicated to DSO, Nashik.	
48	Name : Pingali Tal.Man Dist. Satara Date of completion:- 1878 Location : Longitude- 74°33′00 " Latitude - 17°41′00 " Height :- 16.00 m. Gross capacity : 2.38 Mcum Sr.No.In Large Dam Register 2012: MH09MH00731	7.5.2020 19.12.2020	Shri. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	Earthen Embankment Outlet	 Standing pool of water is observed on D/S side of earthen dam.(A2) Outlet well not in good condition.(A6) Relief well not functioning properly.(A5) Operation of outlet gate is not smooth/not functioning properly.(B5) There is settlement and 	Necessary repairs shall be carried out. Necessary repairs should be carried out in consultation with mechanical organization.	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	•
		-		of Dam			
1	2	3	4	5	6	7	
					displacement of stones in rock toe are observed.(B3)		
49	Name : Yeralwadi Tal.Khatav Dist. Satara Date of completion:- 1973 Location : Longitude- 74°29'35" Latitude - 17°31'24" Height :- 19.50 m. Gross capacity : 32.80 Mcum Sr.No.In Large Dam Register 2012: MH09MH00386	17.5.2020 5.11.2020	Shri. A.S.Pawar E.E., KID, Satara	Outlet	 Stem rod of both gates are bent.(B5) At vertical slope side displacement is seen.(B3) 	Necessary repairs shall be carried out through mechanical organization. Necessary repairs should be carried out	Not Received
50	Name : Jambhulani Tal.Man Dist. Satara Date of completion:- 1981 Location : Longitude- 74°60′00 " Latitude - 17°34′00 " Height :- 15.21 m. Gross capacity : 2.41 Mcum Sr.No.In Large Dam Register 2012: MH09MH0516	7.5.2020 19.12.2020	Shri. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	Outlet well Outlet gate	 Stem rod for lifting the gate is not straight.(B5) Relief wells are not functioning properly.(A5) There is settlement and displacement of stones in rock toe.(B3) Operation of outlet gate is not smooth,unus 	Necessary repairs shall be carried out through mechanical organization. Necessary repairs should be carried out	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	-
		-		of Dam			
1	2	3	4	5	6	7	
					ual noise		
					during		
					operation.(B5		
)		
					5. Outlet well		
					not in good		
					condition.(A6		
)		
51	Name : Mayani	17.5.2020	Shri.	EE	1. There is	Necessary repairs	Not Received
	Tal.Khatav Dist. Satara	19.12.2020	A.S.Pawar		settlement and	shall be carried out	
	Date of completion:-1872		E.E., KID,		displacement of		
	Location :		Satara	Drains	stones in rock	Vegetation should be	
	Lonaitude- 74°34′00"				toe.(B3)	removed from the	
	Latitude -17°26′00"		Shrimati		2. Drains are	drains for free flow.	
	Height :-18.00m.		S.S.Magdum		not free from		
	Gross capacity : 1.46 Mcum		E.E., KID,	Outlet well	vegetation and		
	Sr.No.In Large Dam Register		Satara		bushes etc.(B2)	Necessary repairs	
	2012 [.]			Outlet gate	3. Outlet well	should be carried out	
	MH09MH0008			Sansi gana	not in good		
				Tail channel	condition.(A6)	Necessary repairs	
					4. Operation of	should be carried out	
					outlet gate is not		
			Test		smooth.(B5)		
			Inspected by	WW Bar	5. Retrogession		
			Shri.		and scpuring		
		25.02.2021	N.S.		noticed in tail		
			Dusane		channel.(A7)	Timely repairs of	
			EE DSD -1		(),	localized deteriorated	
			Nashik			pointing is must to	
						avoid further exposure	
						of masonry joints.Also,	
						repointing of UCR	
						masonry shall be done	
					6. Leakages	following due	
					and sweating from	procedure as raking	
					WW bar is	etc complete.	
					observed		
52	Name :Ranand	7.5.2020	Shri.	Tail Channel	1. Standing pool	Necessary repairs	Not Received
	Tal.Man Dist. Satara	19.12.2020	A.S.Pawar		of water on	shall be carried out.	-
	Date of completion:-1956		E.E., KID,		d/s of dam is		

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	-
		-		of Dam			
1	2	3	4	5	6	7	
	Location : Longitude- 74°40′00 " Latitude - 17°43′00 " Height :- 19.32 m. Gross capacity : 7.12 Mcum Sr.No.In Large Dam Register 2012: MH09MH0078		Satara Shrimati S.S.Magdum E.E., KID, Satara	Outlet gate	observed.(A2) 2. Retrogessiop n/scouring noticed in tail channel.(A7) 3. There is settlement and displacement of stones in rock toe.(B3) 4. Operation of outlet gate is not smooth.(B5) 5. Some leakage through the gate frame is observed.(B12)	Necessary repairs should be carried out	
53	Name : Andhali Tal.Man Dist. Satara Date of completion:- 1997 Location : Longitude- 74°30′00" Latitude - 17°45′07" Height :- 18.60 m. Gross capacity : 9.273 Mcum Sr.No.In Large Dam Register 2012: MH09MH01443	7.5.2020 19.12.2020	Shri. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	Outlet well	 Repairing of outlet well is required.(A6) Emergency gate/Stop log gate not in working condition.(B5) Longitudinal cracks are observed.(B4) Relief well is not functioning properly.(A5) 	Necessary repairs shall be carried out. Necessary repairs should be carried out	Not Received

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	•
				of Dam			
1	2	3	4	5	6	7	
54	Name · Arabwadi	7 6 2020	Shri	Outlet Gate	1 Stem rod for	Depending on severity	Not Received
	Tal.Koregaon Dist. Satara	7 12 2020	A S Pawar	Cullor Culo	lifting the gate	of bending Stem Rod	
	Date of completion:-1977	1.12.2020			is not	should be either	
	Location :		Satara	FF	straight (B5)	repaired or replaced in	
	Longitude- 74°04'00"		Jalara		Straight.(D3)	consultation with	
	Latitude -17°50′07"		Shrimati			Mechanical	
	Height :- 17.35 m.		S S Maadum		2 Top width of the	Organization	
	Gross capacity :1.89 Mcum				2.10p width of tha	Organization.	
	Sr.No.In Large Dam Register 2012:		C.L., ND,		reduced (P1)	chould be restored	
	MH09MH00621		Salara		Teduced.(DT)		
55	Name : Darui	17.5.2020	Shri.	EE	1. There is	Necessary repairs	Not Received
	Tal.Khatav Dist. Satara	19.12.2020	A.S.Pawar		settlement and	shall be carried out.	
	Date of completion:-1956		E.E KID.		displacement of		
	Location :		Satara		stones in rock		
	Longitude- 74°25′00 "				toe.(B3)		
			Shrimati	Tail Channel	2.Relief well is not	Necessary repairs	
	Height :-16 46 m		S.S.Magdum		functioning	should be carried out	
	Gross capacity :2 88 Mcum		E.E., KID.	Outlet well	properly.(A5)		
	Sr No In Large Dam Register		Satara	0 0.000 0.000	3.Retrogession		
	2012.				observed in tail		
	MH09MH00074				channel.(A7)		
					4.Outlet well not in		
					good		
					condition.(A6)		
56	Name : Masalwadi	7.5.2020	Shri.	EE	1.Growth of	Necessary repairs	Not Received
	Tal.Man Dist. Satara	19.12.2020	A.S.Pawar		vegetation is	shall be carried out.	
	Date of completion:-1975		E.E., KID,		observed in		
	Location :		Satara		pitched portion		
	Longitude- 74°50'00"				(B13)		
	Latitude -17°40′00"		Shrimati		2.There is		
	Height :-14.30 m.		S.S.Magdum		settlement and	Necessary repairs	
	Gross capacity :2.41 Mcum		E.E., KID,	Tail Channel	displacement of	shall be carried out.	
	Sr.No.In Large Dam Register		Satara		stones in rock		
	2012:				toe.(B3)		
	MH09MH00377				3.Drains are silted		
					and growth of		
					vegetation is		
					observed.(B2)		
					4.Retrogession		
					/scouring noticed		

2			of Dam	Deficiencies noticed	Suggested	
-	3	4	5	6	7	
				in tail channel.(A7)		
Name : Dhakani Tal.Man Dist. Satara Date of completion:- 1994 Location : Longitude- 74°41′00" Latitude - 17°35′00" Height :- 18.50 m. Gross capacity : 3.05 Mcum Sr.No.In Large Dam Register 2012: MH09MH01335	7.5.2020 19.12.2020	Shri. A.S.Pawar E.E., KID, Satara Shrimati S.S.Magdum E.E., KID, Satara	EE Outlet Gate	 Relief wells are not functioning properly.(A5) There is settlement and displacement of stones in rock toe.(B3) The leakage through the gate is observed.(B5) 	Necessary repairs shall be carried out. Necessary repairs shall be carried out.	Not Received
utive Engineer, Koyna Irrigation	Division, Ko	oynanagar	1404/5	·		
Name : Chaphal Tal. Satara Dist. Satara Date of completion:- 1983 Location : Longitude- 74°00′28 " Latitude - 17°24′24 " Height :- 18.05 m. Gross capacity : 1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH0966	6.5.2020 2.12.2020 13.01.2021	Shri. K.H. Patil E.E., Koyna Irrigation Division, Koynanagar Shri. V. H. Phalke E.E., Koynalrrigatio n Division, Koynanagar Test Inspected by Shri.N.S. Dusane	WW Bar	 There is damages below the protection wall (@base of the wall of UCR masonry,) (B7) 	Damaged portion of UCR masonry due to dislodging of stones shall be repaired. Also, repointing of UCR masonry shall be done following due procedure as raking etc complete.	Not Received
	Tal.Man Dist. Satara Date of completion:-1994 Location : Longitude- 74°41′00" Latitude -17°35′00" Height :-18.50 m. Gross capacity :3.05 Mcum Sr.No.In Large Dam Register 2012: MH09MH01335 Itive Engineer, Koyna Irrigation Name :Chaphal Tal. Satara Dist. Satara Date of completion:-1983 Location : Longitude- 74°00′28" Latitude -17°24′24" Height :-18.05 m. Gross capacity :1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH0966	Tal.Man Dist. Satara19.12.2020Date of completion:-1994Location :Longitude- 74°41′00"Latitude -17°35′00"Height :-18.50 m.Gross capacity :3.05 McumSr.No.In Large Dam Register2012:MH09MH01335Itive Engineer, Koyna Irrigation Division, KoName :ChaphalTal. Satara Dist. SataraDate of completion:-1983Location :Longitude- 74°00′28"Latitude -17°24′24"Height :-18.05 m.Gross capacity :1.91 McumSr.No.In Large Dam Register2012:MH09MH096613.01.2021	Tal.Man Dist. SataraTal. Nan Dist. SataraDate of completion:-1994E.E., KID,Location :SataraLongitude- 74°41′00"ShrimatiLatitude -17°35′00"ShrimatiHeight :-18.50 m.Sr.No.In Large Dam Register2012:MH09MH01335MH09MH013356.5.2020Name :Chaphal6.5.2020Tal. Satara Dist. Satara2.12.2020Date of completion:-1983Shri.Location :2.12.2020Longitude- 74°00′28"Shri.Latitude -17°24′24"KoynanagarHeight :-18.05 m.Shri.Sr.No.In Large Dam RegisterShri.V. H. PhalkeE.E.,KoynalrrigationShri.V. H. PhalkeE.E.,Z012:MH09MH0966MH09MH096613.01.2021Test Inspected by Shri.N.S.Dusane E.E., Dam	Tai.Man Dist. Satara Date of completion:-1994 Location : Longitude-74°41′00" Latitude -17°35′00" Height :-18.50 m. Gross capacity :3.05 Mcum Sr.No.In Large Dam Register 2012: MH09MH01335Tsi.2.2020 Shrimati S.S.Magdum E.E., KID, SataraOutlet Gatevitve Engineer, Koyna Irrigation Division, Koynanagar Tal. Satara Dist. Satara Date of completion:-1983 Location : Longitude-74°00′28" Latitude -17°24′24" Height :-18.05 m. Gross capacity :1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH09666.5.2020 Shri. 2.12.2020Shri. WW BarWW BarK.H. Patil E.E., Koyna Irrigation Division, Koynanagar8.5./. Shri. V. H. Patil E.E., Koyna Irrigation Division, KoynanagarWW BarTal. Satara Dist. Satara Date of completion:-1983 Location : Longitude-74°00′28" Latitude -17°24′24" Height :-18.05 m. Gross capacity :1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH0966Shri. V. H. Phalke E.E., Koynalrrigation No.In Large Dam Register 2012: MH09MH0966WW bar13.01.2021Test Inspected by Shri.N.S. Dusane Division, KoynanagarWW bar	Tai.Man Dist. Satara 15.12.2020 A.S. Pawar are not functioning properly.(A5) Location : Satara Outlet Gate Congregative (A5) Longitude - 74°41'00" Satara Outlet Gate Settlement and displacement of stones in rock toe.(B3) Latitude - 17°35'00" Satara Outlet Gate Settlement and displacement of stones in rock toe.(B3) Shrimati Satara Satara Outlet Gate Settlement and displacement of stones in rock toe.(B3) MH09MH01335 MH09MH01335 E.E., KID, Satara Name : Chaphal S.5.2020 Shri. Tal. Satara Dist. Satara 6.5.2020 Shri. WW Bar 1. There is damages below the gate is observed.(B5) Jongitude- 74°00'28" 2.12.2020 K.H. Patil E.E., Koyna Irrigation Location : Longitude- 74°00'28" Shri. WW Bar 1. There is damages below the gate wall of UCR masonry.) Latitude - 17°24'24" Shri. Shri. WW Bar 1. There is damages below the gate is observed. Shri. N.S. Shri. N.S. Shri. N.S. Shri.N.S. Shri.N.S. Shri.N.S. Journa Ja.01.2021 Jusane WW bar Image: Shri.N.S.	1al.Man Dist. Satara A.S. Pawar A.S. Pawar are not shan be carried out. Date of completion1994 Location : Satara Outlet Gate functioning properly.(A5) 2. There is settlement and A.S. Pawar Shrimati Outlet Gate Outlet Gate Settlement and Naccessary repairs shall be carried out. Str.No.In Large Dam Register Shri Stara Outlet Gate Settlement and Shall be carried out. Necessary repairs shall be carried out. Name: Chaphal Satara Stria Stria Settlement and Shall be carried out. Necessary repairs shall be carried out. Titve Engineer, Koyna Irrigation Division, Koynanagar Stria Stria Stria Necessary repairs shall be carried out. Titve Engineer, Koyna Irrigation Division, Koynanagar 6.5.2020 Shri. V.H. Patil Stria Stria Damaged portion of UCR masonry.) UCR masonry.) UCR masonry.) repointing of UCR shall be repaired. Also, repointing of UCR Shri. Stria Shri. Stria Stria Shall be fone tall stria Shall be fone tall stria S

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
		•		of Dam			
1	2	3	4	5	6	7	
			Safety Div.				
			No.1, Nashik		2. UCR masonry of	Damaged portion of	
					Waste Weir bar of	UCR masonry due to	
					about 17.00 m	dislodging of stones	
					length is	shall be	
					damaged.(B7)	repaired.Also,repointin	
						g of UCR masonry	
						shall be done following	
						due procedure as	
	of Financia (C.D.) Water Deserve		ant Duna			raking etc complete.	
	er Engineer (S.P) Water Resourd	ces Departm	ent, Pune				
(1) Sup	erintending Engineer Kukadi Irrig		e Pune				
(a) Exe	Nomo : Bamiowadi	5 6 2020	C. I Narayang	AUTI	1 The LICP	Negocony repairs	Not Received
59	Name . Ramjewau	5.0.2020 9.11.2020	SIII.P.P. Koduckor			Necessary repairs	Not Received
	Date of completion: 1983	0.11.2020			collapsed and it	snouid de carried out.	
	Location:		Naravngaon		is very serious		
	Longitude -73°41'00''		Narayngaon		needs urgent	Necessary repairs	
	Latitude - 19°13'00''				repairs	should be carried out	
	Height :- 21.48m.				2. The repaire of		
	Gross capacity 1.72 Mcum				WW bar is		
	Sr.No.In Large Dam Register				incomplete (B7)		
	2012:MH09MH 0965						
60	Name : Otur Waghdara	12.5.2020	Shri.P.P.	EE	1. Leakage in	Necessary repairs	Not Received
	Tal. Junnar Dist. Pune	25.11.2020	Kaduskar		Dam Rough	should be carried out.	
	Date of completion:1992		EE KID,		body (A1)		
	Location:		Narayngaon	Outlet	2. Outlet gate	It should be lubricated	
	Longitude -74°02'00''				not in	periodically. At least, it	
	Latitude - 19°05'00''				working	should be properly	
	Height :- 20.16m.				condition.(B5	Iubricated after	
	Gross capacity 0.953 Mcum) 2 Lifting beem	monsoon season.	
	SI.NO.III Large Darii Register				3. Litting beam		
	2012.WHU9WH1202				order and		
					sound		
					condition (B5		
)		
61	Name : Ghangaldara	5.6.2020	Shri.P.P.	E. Gate	1. Emergency	Necessary repairs	Not Received
-	Tal. Junnar Dist. Pune	8.11.2020	Kaduskar		gate is	should be carried out.	

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
			_	of Dam	-	_	
1	2	3	4	5	6	7	
	Date of completion:2009		EE KID,		supplied but		
	Location:		Narayngaon		not installed.		
					(B5)		
	Latitude - 18°20'00"						
	Height :- 20.34m.						
	Sr No In Lorgo Dom Bogistor						
	2012:MHOQMH1QO6						
62	Name : Licchil	5 6 2020	Shri D D	\//\// bar		Necessary repairs	Not Received
02	Tal Junnar Dist Pune	8 11 2020	Kaduskar		Masonry of	should be carried out	Not Received
	Date of completion 2001	0.11.2020			spillway bar	should be carried out.	
	Location.		Naravngaon		is totally		
	Longitude -73°41'00''		rtarayngaon		damaged		
	Latitude - 19°13'00''				and leakage		
	Height :- 13.01m.				through		
	Gross capacity 3.12 Mm3				masonry is		
	Sr.No.In Large Dam Register				seen.(B7)		
	2012: MH09MH1572						
63	Name : Anepemdara	13.5.2020		Outlet	1. Operation of	Necessary repairs	Not Received
	Tal. Junnar Dist. Pune	24.11.2020	Shri.P.P.		outlet gate is not	should be carried out.	
	Date of completion:1998		Kaduskar		smooth (B5)		
	Location:		EE KID,		2. Stem rod		
	Longitude -73°14'00''		Narayngaon		damaged (B5)		
	Latitude - 19°11'00''			WW Bar	3. Heavy leakage	Necessary repairs	
	Height :- 14.37m.				between joint of	should be carried out.	
	Gross capacity 2.09 Mcum				earthwork and		
	Sr.No.In Large Dam Register				flank wall, heavy		
	2012:MH09LH 1473						
					VVVV bar. (B7)		
(2) Sum	erintending Engineer & Admn		2011	I			
(2) Sup		C.A.D.A. 30	apui				
(a) Exe	cutive Engineer,Solapur Irrigatio	on Division, a	Solapur				
64	Name : Hingani (K)	19.11.2020	Shri.	Outlet	1. One stem rod is	Necessary remedial	Not Received
	Tal. Karmala Dist. Solapur		M.T.Jadhvar		bend (B5)	measures should be	
	Date of completion:1974		EE,SID,			done in consultation	
	Location:		Solapur			with mechanical	
	Longitude -75°24'30"					organization.	
	Latitude - 18°16'00"						
	Height :- 16.15 m.						

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	•
		•		of Dam			
1	2	3	4	5	6	7	
	Gross capacity 2.22 Mcum						
	Sr.No.In Large Dam Register						
	2012:MH09MH 0441						
65	Name : Kazikunbus	22.05.2020	Shri.R.K	Outlet	1. Stem rod is	Necessary repairs be	Not Received
	Tal. Akkalkot Dist. Solapur	20.11.2020	Jagtap &		kniped by farmers	carried out in	
	Date of completion:1992		Shri.		hence gate is not	consultation with	
	Location:		M.T.Jadhvar		in operation. (B5)	Mechanical orgasition.	
	Longitude -76°10'00''		EE,SID,		2. In head regulator		
	Latitude - 17°43'00''		Solapur		stem rod is		
	Height :- 20.00m.				broken, repairing		
	Gross capacity 4.031 Mcum				necessary (B5)		
	Sr.No.In Large Dam Register						
	2012: MH09MH 1224						
66	Name : Mangi	29.05.2020	Shri.	Embankment	1. Longitudinal	Original dam section	Not Received
	Tal. Karmala Dist. Solapur	19.11.2020	M.T.Jadhvar		cracks developed	should be restored	
	Date of completion:1966		& Shri. D.J.		in embankment		
	Location:		Kondekar		Ch 1621-1645m.		
	Longitude -75°17'00"		EE,SID,Sola		variable depth	They should be	
	Latitude -17°17'00"		pur		approx. 1.2m	cleaned and made	
	Height :-22.95 m.				(B4)	functional.	
	Gross capacity :3.09 Mcum				2. Relief wells are		
	Sr.No.In Large Dam Register				not in working		
	2012: MH09MH0131				condition (A5)		
	<u> </u>		<u>.</u>	T 11 01 1			
67	Name :Rajuri	29.05.2020	Shri.	Tail Channel	1. Heavy	Protective measures,	Not Received
	Tal. Karmala Dist. Solapur	19.11.2020	M. I.Jadhvar		retrogression is	as per necessity shall	
	Date of completion:1981		& Shri. D.J.		noticed on	be undertaken to	
	Location:		Kondekar		downstream of bar	prevent progressive	
	Longitude -74°58		EE,SID,		near divide wall.	damage.	
	Latitude -18°22		Solapur		(A7)		
	Height :-19.29 m.						
	Gross capacity :2.520 Mcum						
	Sr.No.In Large Dam Register						
	2012: MHU9MHU894						
(b)Exec	cutive Engineer Bhima Develope	ment Divisio	n No.2 Solan	ur			
	anto Engineer Brinna Bevelope						

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	
				of Dam			
1	2	3	4	5	6	7	
68	Name : Ashti Tal. Mohol Dist. Solapur Date of completion:-1883 Location : Longitude - 75°-26' 00'' Latitude - 17°47'30'' Height :- 17.60 m. Gross capacity :23.01 Mcum Sr.No.In Large Dam Register 2012: MH09MH0014	05.05.2020	Shri. R. N. kshirsagar EE BDD no.2 Solapur	Earthen Embankment	 Cracks are observed at top of embankment in between ch. 2/240 to 2/385 m (B4) Top of embankment not as per design section of dam. Ch 2340 m. to 2360 m (B1) 	Necessary repairs should be carried out and dam section should be restored.	Not Received
Superi	ntending Engineer, Bhima Canal	Circle Solar	our				
		VIVISION NO.1	, Solapur	Foutback	4 Della wateratak	Nagaga	Not Dessived
69	Tal. Mohol Dist. Solapur Date of completion:-1993 Location : Longitude - 75°-46' 55'' Latitude - 18°19'23'' Height :- 16.93 m. Gross capacity :6.40 Mcum Sr.No.In Large Dam Register 2012: MH09MH1620	20.03.2020 20.11.2020	Snri. R.P.More EE,MID No.1 Solapur	Eartnen Embankment Outlet	 Bolis, wet patches or water seepage slushiness is seen on d/s slope (A1) Outlet well not in good condition &Silted fully. (A6) 	Necessary repairs should be done to stop the leakage Well should be desilted	Not Received
70 (2) Sup	Name : PimpalgaonDhale Tal. Barshi Dist. Solapur Date of completion:-2008 Location : Longitude - 75°47'40" Latitude - 18°10'10" Height :- 18.70 m. Gross capacity :12.66 Mcum Sr.No.In Large Dam Register 2012: MH09MH1840 perintending Engineer, SataraPro	20.03.2020 20.11.2020	Shri. R.P.More EE,MID No.1 Solapur	Outlet	1. Stem rod for lifting gate is not straight (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.	Not Received
(a) Exe	cutive Engineer, Minor Irrigation	Division Sat	ara				
71	Mahind Tal- Patan Dist- Satara	N.A N.A.	Shri.S.J. Hirav	W.W.Bar and Tail Channel	1. Retaining wall of right side of tail	Necessary repairs should be carried out.	Not Received
			- 7				

Sr.	Dam Features	Date of	Inspecting	Main	Significant	Remedial Measures	Implementation Status
No.		Inspection	Officer	Component	Deficiencies noticed	Suggested	-
		_		of Dam			
1	2	3	4	5	6	7	
	Date of completion: 2000		EE MID		channel is		
	Location:		Satara	E.E.	collapsed for		
	Longitude 73°54'13"				length of 19m (A7)	Original dam section	
	Latitude 17°22'05"				2. Top width of dam	should be restored	
	Height :21.32 m.				as per design is		
	Gross capacity- 2.404 Mcum				3.00m.Due to		
	Sr.No.In Large Dam Register				movement of live		
	2012: MH09MH1838				stock it is eroded		
					and now top width		
					remains 2.50m on		
					average	Necessary repairs	
					throughout the	should be carried out.	
					The nertice of the		
					3. The portion of the		
					drain and avroad		
					drain and exposed		
					beyond the d/s toe		
					of the dam are not		
					in regular section		
					and not freely		
					draining.(B2)		
					4. Depression in		
					embankment near		
					head regulator is		
					observed.A pit of		
					size 3X3 m is		
					formed. Also a pit		
					is formed in u/s		
					embankment at ch		
					155 to 165.		

ATR on Category-1 Deficiency in Class-I Dams (Private Owned)

SR.NO.	NAME OF DAM	DATE OF INSPECTION	MAIN COMPONENT OF DAM	SIGNIFICANT DEFICIENCIES NOTICED	REMEDIAL MEASURES SUGGESTED	IMPLEMENTATIO N STATUS
1	2	3	4	5	6	7
				NIL	-	

ATR on Category-2 Deficiency in Class-I Dams (Private Owned)

Sr.I	Dam Features	Date o	Inspecting	Main	Significant	Remedial Measures	Implementat
ο		Inspection	Officer	Component	Deficiencies	Suggested	ion Status
				of Dam	Noticed		
1	2 (4) Ook and the U.S. (Ansternet)(etter	3	4	5	6	7	
1	(1) Sanara India (Ambeyvalley	/)Limited Pu	ne Shri V. K. Bhadana	Moin don		It was also suggested to	Not
	Name :Ambavane(Gated)Tal. MulashiDist. PuneYear of completion : 2000Location :Longitude 73°25'00"Latitude 18°40'00"Height : 38.76 mGross Capacity : 8.575 McumSpillway capacity: 738 m³/secSr.No. in Large Dam RegisterMH09MH1898	07.10.2020	S.E. D.S.O, Nashik	Body	1.Heavy leakages were observed or downstream side o NOF section at many places major water jets were also observed or NOF section near righ side guide wall (A11)	treat upstream side by adopting suitable remedial measures such as raking out joints and filling the voids by using suitable concrete or cement grouting or epoxy grouting etc	Received
2	Name :Kolawali (Ungated) Tal. Mulashi Dist. Pune Year of completion : 2000 Location : Longitude 73°25'00" Latitude 18°40'00" Height : 43.50 m Gross Capacity : 2.17 Mcum Spillway capacity : 90 m³/sec Sr. No. in Large Dam Registe :MH09MH1903	07.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Earth Dan section	 Approach road up to the dam top and steps on downstream slope have not been provided (B6) Heavy vegetation observed on the top of dam (B13) 	Approach road should be provided. It should be cleaned periodically.	Not Received
3	Name :Visakhar (Ungated) Tal. Mulashi Dist. Pune Year of completion : 2006 Location : Longitude 73°25'00" Latitude 18°40'00"	07.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Earth Dan section	1.Stagnant water was observed on the downstream side on lef side of spillway. (A2)	Source of the water should be verified	Not Received

Sr.M	Dam Features	Date o	Inspecting	Main	Significant	Remedial Measures	Implementat
0		Inspection	Officer	Component of Dam	Deficiencies Noticed	Suggested	ion Status
1	2	3	4	5	6	7	
	Height : 38 m Gross Capacity : 4.72 Mcum Spillway capacity: 245 m³/sec Sr. No. in Large Dam Registe : MH09MH1904						
(2)	The Tata Power Co. Ltd. Lona	avala	I	I	1	I	J
4	Name :Thokarwadi (gated) Tal. Maval Dist. Pune Year of completion : 2006 Location : Longitude 73°30'34" Latitude 18°54'00" Height : 59.44 m Gross Capacity : 36370 Mcum Spillway capacity: 546 m³/sec Sr. No. in Large Dam Registe :MH09MH0043	08.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Dam body	1. The sign of leakages and sweating were observed with vegetation on downstream surface of NOF section (A15)	The records of leakages with respect to reservoir level needs to be prepared.	Not Received

Sr.N	Dam Features	Date o	Inspecting	Main	Significant	Remedial Measures	Implementat
ο		Inspection	Officer	Component	Deficiencies	Suggested	ion Status
				of Dam	Noticed		
1	2	3	4	5	6	7	
5	Name :Walwhan (gated) Tal. Maval Dist. Pune Year of completion : 1916 Location : Longitude 73°25'25" Latitude 18°45'51" Height : 26.37 m Gross Capacity : 72.50 Mcum Spillway capacity: 546 m³/sec Sr. No. in Large Dam Registe :MH09MH0036	08.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Dam body	1.The sign of leakages and sweating were observed with vegetation or downstream surface o NOF section (A15)	The records of leakages with respect to reservoir leve needs to be prepared.	Not Received
6	Name :Shirwata (gated) Tal. Maval Dist. Pune Year of completion : 1920 Location : Longitude 73°28'41" Latitude 18°47'59" Height : 38.70 m Gross Capacity : 186.84 Mcum Spillway capacity: 593m ³ /sec Sr. No. in Large Dam Registe :MH09MH0041	08.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Dam body	1.There was leakage observed through the junction of overflow and non overflowsection.(A15) 2.Leakages/Sweating observed on d/s from ch 100m to 1970m.(A11)	The records of leakages with respect to reservoir leve needs to be prepared. Necessary remedial measures should be done	Not Received

ATR on Category-1 Deficiency in Class-II Dams (Private Owned)

Sr.No.	Name of Dam	Date of Inspection	Main component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested	Implementation Status
1	2	3	4	5	6	7
				NIL		

ATR on Category-2 Deficiency in Class-II Dams (Private Owned

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested	Implementa tion status
1	2	3	4	5	6	7	
(1)	Commissioner,Municipal Cor	poration Kolh	apur				
1.	Name : Kalamba Tal. Karveer Dist.Kolhapur Date of completion: 1983 Location: Longitude 74°21'27 " Latitude 16°55'41 " Height : 16.26 . m . Gross capacity 2.75 Mcum Sr.No.In Large Dam Registe 2012: MH09MH1015	23.02.2021	Shri N. S. Dusane, EE, DSD1, Nashik	Earth Dam	 Earthen section seems to be undersection in certain portion .(B1) Dam top seems to be undulating .(B1) 	Superimpose existing cross section and L section on design cross and L section at every 30 m. C/C to ascertain whether earthen embankment is undersection or not. Communicate facts to DSO, Nashik	Not Received
2.	Name :Rankala Tal. Karveer Dist.Kolhapur Date of completion:1883 Location: Longitude 73°40'00" Latitude 16°43'00" Height :15.00. m. Gross capacity 4.30 Mcum Sr.No.In Large Dam Registe 2012:MH09MH0010	23.02.2021	Shri N. S. Dusane, EE, DSD1, Nashik		 Waterway is blocked due to pipes, stones and ongoing concreting in tail channel. 	Sufficient waterway is must to pass safely overflow discharge. Hence clear the obstacles and encroachments in tail channel.	Not Received
(2)	INS Shivaji ,Indian Navy , Lo	navala.					
3.	Name : New Shivsagar Tal. Mawal Dist. Pune Date of completion:1989 Location: Longitude- 73°52'00″ Latitude 18°45'00 Height :2570 m Gross capacity 1.81 Mcum Sr.No.In Large Dam Registe MH09MH1230	7.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Body of dam Overflow Section	 Leakages was observed through dam masonry at ch 420- 435m and 470m. (A11) Spots of leaching and leakage was observed through overflow section. (A15) Heavy leakage was observed through 	Necessary actions should be taken Necessary actions should be taken	Not Received

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested	Implementa tion status
1	2	3	4	5	6	7	
					junction of overflow section and non overflowsection.(A3)		
4	Name : New Shivsagar Tal. Mawal Dist. Pune Proposed for updation ir NRLD 2018	7.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik	Masonry Section	1.Water jets and leakages was observed through masonry section.(A11)	Necessary actions should be taken	Not Received
				WW Bar	2. Leakage was observed through junction of earther embankment and WW bar.(A3)	Necessary actions should be taken	
					3. The expansion joint of WW bar was seen opened. Heavy leakage was seen through it.(B7)	Necessary actions should be taken	
(2)T	ata Power Company Ltd Lona	wala,Dist Pun	е		•		
5	Name : Lonavala Tal. Mawal Dist. Pune Date of completion:1916 Location: Longitude- 73°24'07″ Latitude 18°44'00 Height :15.35 m Gross capacity 11.50 Mcum Sr.No.In Large Dam Registe MH09MH0035	8.10.2020	Shri.Y. K. Bhadane, S.E. D.S.O, Nashik		 Sweating on d/s side of dam was observed. Leakage through dam masonry was observed at some places.(A15) 	Necessary remedial measures should be carried out.	Not Received



Part-3: Dam Health Status Report of Pre & Post Monsoon 2021

3.1 General:

Dam Safety Division No. 1 under Dam Safety Organization, Nashik excersies compilation of Annual Pre & Post Inspection Reports of Dams submitted by Field Offices as well as Test Inspection Reports of Selected Dams carried out by Dam Safety Organization, Nashik in the form of Annual Dam Health Status Report (ADHSR).

3.2 Inspection Reports submitted by Field Offices:

In all there are 262 Government owned Dams & 17 Private owned Dams are monitored by Dam Safety Organization, Nashik from safety point of view.

262 Government owned Dams constitute 69 Class-I & 193 Class-II Dams. 17 Private owned Dams constitute 7 Class-I & 10 Class-II Dams.

Government owned Dams: Out of 262 Dams, Pre Monsoon Reports were received from 259 Dams. However, out of 262 Dams, Post Monsoon Reports were received from 229 Dams. 36 Dams Reports were not received in DSO. [Ref. Table 3.1 & 3.2]

3.3 Test Dam Inspection by Dam Safety Organisation:

Test Inspection Programme for Test Inspection of selected Dams is approved by Director General, DTHRS, MERI, Nashik.

As per approved Annual Test Dam Inspection Programme, Class-I Dams are inspected by SE, DSO along with EE, DSD-1& Class-II Dams are inspected by EE, DSD-1, Nashik.

On similar lines in case of Private owned Dams, full fledged inspection of Class-I Dam is carried out by SE, DSO along with EE,DSD-1& Class-II Dam is carried out by EE, DSD-1, Nashik.

Government owned Dams : Despite of Covid-19 pandemic (6 out of 8 Class-I, 19 out of 19 Class-II & 1 century old Class-III (Bhadalwadi) as proposed for test inspection were inspected by team of Dam Safety Organization, Nashik. [Ref. Table 3.5]

Private owned Dams : Post Monsoon Inspections for 14 Dams were carried out by DSO. [Ref. Table 3.3 & 3.4]

Following team of officers have inspected targeted Dams in Pune Region

- 1) Shri M.S.Amale, Superintending Engineer, Dam Safety Organization, Nashik
- 2) Shri U.T.Murkute, Executive Engineer, Dam Safety Division No.1, Nashik
- 3) Shri V.Z.Nemade, Sub Divisional Officer, Dam Safety Division No.1, Nashik
- 4) Shri. H.P.Deokate, Junior Engineer, Dam Safety Division No.1, Nashik

5) Shri. R.R.Salunkhe, Assistant Engineer-II, Dam Safety Division No.1, Nashik And Following team of officers have taken efforts to prepare this report.

- 1) Shri M.S.Amale, Superintending Engineer Dam Safety Organization, Nashik
- 2) Shri U.T.Murkute, Executive Engineer, Dam Safety Division No.1, Nashik
- 3) Shri R.A. Pawar, Sub Divisional Officer, Dam Safety Division No.1, Nashik
- 4) Shri M.R.Rasal, Sub Divisional Officer, Dam Safety Division No.1, Nashik
- 5) Shri P.N.Pawar, Sub Divisional Officer, Dam Safety Division No.1, Nashik
- 6) Shri V.Z.Nemade, Sub Divisional Officer, Dam Safety Division No.1, Nashik
- 7) Shri. H.P.Deokate, Junior Engineer, Dam Safety Division No.1, Nashik
- 8) Shri. R.R.Salunkhe, Assistant Engineer-II, Dam Safety Division No.1, Nashik

3.4 Health Status of Class-I & Class-II Dams (Government & Private Owned)

This report excerpts details of Deficiencies received from Pre & Post Monsoon Inspections Reports based on detailed inspections carried out by concerned field Superintending Engineer for Class-I Dams & Executive Engineer for Class-II Dams.

And it also covers Test Inspection carried out by team of officers from Dam Safety Organization, Nashik.

Sr. No.	Category	To Da	otal ams	Rep	oorts D	receiv SO	Cat 1					C	at 2		Cat 3				
INO.	Class	Ι			I		П		I		П		I				I		
	No. of			Pre	post Pre		post	Dam	Deficiency										
1	WRD	69	193	69	65	190	164	0	0	0	0	65	469	111	187	69	996	191	1645
2	Private	7	10	0	4	4	5	0	0	0	0	4	5	7	17	4	18	10	62
	Total	76	293	69	69	194	169	0	0	0	0	69	474	118	204	73	1014	201	1707

- 3.5 A Graphical Representation of Deficiencies attended, Submission of Pre/Post Monsoon Reports, Category wise Deficiencies, Class wise of Deficiencies is appended in Annexure I.
- 3.6 Selected Snapshots of DSO Test Inspection Test Inspections are compiled in Annexure II.

3.7 Conclusions :

3.7.1 Frequent Deficiencies Class-I Dams

- a) B9: Instruments not in working condition. (48 Dams)
- b) B 5: Outlet gates not functioning properly. Stem rod is bent (Service gate / Emergency gate/Stop log gate/sluice gate) (20 Dams)
- A 14: EDA / Stilling basin damaged/Hydraulic performance not good.(18 Dams)
- d) A 11: Sweating / seepages through D/S of masonry dam Leakage /Seepage through dam body. (22 Dams)
- e) **A 10 :** Heavy leakages through porous pipes/ through dam body in gallery or monolith joints (16)

3.7.2 Frequent Deficiencies Class-II Dams

- a) **B 5:** Outlet gates not functioning properly. Stem rod is bent(Service gate/Emergency gate/Stop log gate/sluice gate). (55 Dams)
- b) B7:Waste weir/waste weir bar not in good condition/coping damaged/leakage through waste weir.W.W. Bar is damaged / Coping of w.w. Bar damaged. (20 dams)
- c) A6: Outlet well is damaged/not in good condition /cracks observed/jets of water in well. (18 dams)
- A 2: Standing pool / Ponding / Water Logging / Slushy condition on D/S of Dam (17 Dams)
- e) **B 1** Dam section is not as per design.(19 Dams)

3.8 Points of Attention :

1) This overview provides condensed summary of deficiencies noticed in the Pre & Post Monsoon Inspection Reports Received in DSO & also during test inspection conducted by DSO Officials. Field Officers / Owners of the Dams are required to pay attention to Deficiencies pointed out in ADHSR to maintain Dams in Safe condition.

2) The Chief Engineers are requested to flag this issue and compel all Superintending Engineer & Executive Engineer of concerned Dams to carry out periodic inspections and submit report to D.S.O. in time.

Table 3.1

Status of Receipt of Pre & Post Monsoon Inspection Reports 2021

Sr. No.	Name of Office	E In: Rep	xpecte spection ort in	ed on DSO	Pre Monsoon Inspection Report Received in time (By 30 th June)			Pre Monsoon Inspection Report Not Received in time (By 30 th June)			Pre Monsoon Inspection Report Not Received			Post Monsoon Inspection Report Received in time (By 31 st Dec)			Post Monsoon Inspection Report Not Receivedin time (By 31 st Dec)			Post Monsoon Inspection Report Not Received		
		Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
1	2	3	4	5	6	7 hief F	8	9	10	11	12 2 Dor	13	14	15	16	17	18	19	20	21	22	23
_	A) Chief Engineer, Water Resources Department (WR), Pune											0	07	07								
1	SE, PIC, Pune	15	47	62	0	04	04	15	42	57	0	2	2	00	00	00	15	20	35	0	27	27
2	SE, PIPC, Pune	02	01	03	02	0	02	00	00	00	0	1	1	00	0	00	02	01	03	0	0	0
3	SE SIC Sangli	03	53	56	03	0	03	00	53	53	0	0	0	0	0	0	03	53	56	0	0	0
4	SE KIC Kolhapur	22	39	61	0	0	0	22	39	61	0	0	0	0	0	0	21	39	60	1	0	1
5	SE SIC Satara	06	20	26	06	00	06	0	20	20	0	0	0	0	1	1	06	18	24	0	1	1
					B)C	hief E	ngine	er, Wa	ter Re	source	es Dep	bartme	ent (SF), Pun	е							
6	SE Kukadi IC Pune	08	12	20	0	0	0	08	12	20	0	0	0	0	12	12	08	0	08	0	0	0
7	S.E.SIPC. Satara	09	02	11	03	2	5	06	00	06	0	0	0	0	02	02	09	00	09	0	0	0
8	SE &Adm, CADA, Solapur	03	16	19	0	5	5	03	11	14	0	0	0	0	01	01	0	15	15	3	0	3
9	SE,BCC, Solapur	0	03	03	0	3	3	00	00	00	0	0	0	0	02	02	0	00	00	0	1	1
10	SE, OIC Osmanabad	01	0	01	1	0	1	0	0	0	0	0	0	0	0	0	01	0	01	0	0	0
	Total	69	193	262	15	14	29	54	177	231	0	3	3	00	18	18	63	146	211	4	29	33

Table 3.2

Dams for which Inspection Reports of 2021 is Not Received in DSO, Nashik

Sr.	Pre & Post Mons	oon Report Not	Either	Either Pre or Post Monsoon Inspection Report Not Received											
No.	Received	d (Both)	Pre Mo	onsoon	Pos	t Monsoon									
	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II									
1	3	3	4	5	6	7									
	A) Chief Engineer, Wa	ater Resources Departn	nent (WR), Pune												
	I) Superintending I	Engineer,Pune Irrigat	ion Circle, Pune												
	1) Executive Engine	eer, Pune Irrigation D	ivision, Pune												
1		Adale													
2						Chinchwad									
3						Divale									
4						Gadadawane									
5						Hadashi-1									
6						Hadashi-2									
7						Khamboli									
8						Mahakoshi									
9						Marnewadi									
10						NaigaonDevgaon									
11						Pimpali									
12						Rihe									
13						Shere									
14						Shetphal									

Sr.	Pre & Post Mon	soon Report Not	Either	Either Pre or Post Monsoon Inspection Report Not Received											
No.	Receive	ed (Both)	Pre Mo	onsoon	Post M	onsoon									
	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II									
1	3	3	4	5	6	7									
15						Urawade									
16						Walen									
17						Wagajwadi									
18						Bhongawali									
	2) Executive Engin	neer, Lift Irrigation M	anagement Division	, Pune											
19		Malwandi													
	3)Executive Engine	eer, Nira Right Bank	Canal Division, Pha	Itan		I									
20						Girzani									
21						Mhasavad									
22						Naigaon									
23						Nimgaon									
24						Phondshiras									
25						Sangavi Shirval									
26						Tisangi									
27						Vadgaon									
	II) Superintending	g Engineer,Pune Irrig	ation Project Circle,	Pune											
	1) Executive Engin	eer, Bhama Askhed	Dam Division, Pune.												
28				Palsunde											
	III) Superintendin	g Engineer,Kolhapu	r Irrigation Circle, Ko	lhapur		L									
	1) Executive Engin	eer, Kolhapur Irrigat	tion Division (S), Koll	hapur.											
29					Megholi										

Sr.	Pre & Post Mons	oon Report Not	Either	Pre or Post Monso	on Inspection Report N	ot Received
No.	Received	i (Both)	Pre Mo	nsoon	Post	Monsoon
	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II
1	3	3	4	5	6	7
	IV) Superintending	Engineer,Satar irrig	gation Circle, Satara			
	1) Executive Engine	er, Koyna Irrigation	Division, Koyananag	jar.		
30						Chaphal
	A)Chief Engineer, Wa	ater Resources Depar				
	I) Superintending E	ngineer,Satara Irrig	ation Project Circle,	Satara		
	1) Executive Engine	eer, Minor irrigation	Division,Solapur			
31						Gholasgaon
	II) Superintending E	Engineer,Bhima Car	nal Circle, Solapur			
	1) Executive Engine	eer, Solapur Irrigatio	on Division, Solapur			
32					Ekrukh	
33					Bori	
	2) Executive Engine	eer, Ujjani Dam Man	agement Division, BI	himanagar		
34					Ujjani	
	00	02	00	01	04	29

Table 3.3

Status of Pre & Post Monsoon Inspection 2021 by DSO, Nashik (Private Owned)

Sr. No.	Name of Office	Ins	To be P nspected by Ir DSO (E			Pre Monsoon Inspection in time (By 30 th June)			Pre Monsoon Inspection Not in time (By 30 th June)			Pre Monsoon Not Inspected by DSO			Post Monsoon Inspection in time (By 31 st Dec)			Post Monsoon Inspection Not in time (By 31 st Dec)			Post Monsoon Not Inspected by DSO	
		Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23
1	TATA Power Company Ltd	4	2	6	0	0	0	0	0	0	4	2	6	4	2	6	0	0	0	0	0	0
2	SAHARA Pune	3	0	3	0	0	0	0	0	0	3	0	3	0	0	0	0	0	0	3	0	3
3	INS Shivaji	0	2	2	0	0	0	0	2	2	0	0	0	0	2	2	0	0	0	0	2	2
4	KMC Kolhapur	0	2	2	0	0	0	0	0	0	0	2	2	0	2	2	0	2	2	0	0	0
5	KagalNagarparishad,Kagal	0	1	1	0	0	0	0	0	0	0	1	1	0	1	1	0	1	1	0	0	0
6	VikramsinghGhatge	0	1	1	0	0	0	0	0	0	0	1	1	0	1	1	0	1	1	0	0	0
7	Symbiosis, Lavale, Pune	0	2	2	0	0	0	0	2	2	0	0	0	0	2	2	0	2	2	0	0	0
Dams for which Inspection Not carried out by DSO, Nashik (Private Owned)

Sr. Pre & Post Monsoon Report Not			Either Pre or Post I	nspection Not Re	eceived
Received	(Both)	Pre Mo	onsoon	F	Post Monsoon
Class-I	Class-II	Class-I	Class-II	Class-I	Class-II
3	3	4	5	6	7
		A) TATA Power Comp	any Ltd		
		Thokarwadi			
		Walvhan			
		Shirwata			
		Mulashi			
			Lonavala		
			Kundali		
B) SAHARA Pune					
Ambavane					
Visakhar					
Kolawali					
					C) INS Shivaji
					New Shivsagar
					Old Shivsagar
		D) KMC Kolhapur			
			Rankala		
			Kalamba		
		E)KagalNagarparisha	d,Kagal		
			JaysingraoTalao		
		F)VikramsinghGhatge)		
			Sir PirajiraoTalao		
			-		G)Symbiosis, Lavale, Pune
					Upper Tank
					Lower Tank
	Pre & Post Monse Received	Pre & Post Monsoon Report Not Received (Both) Class-I Class-II 3 3 3 3 B) SAHARA Pune	Pre & Post Monsoon Report Not Received (Both) Pre Mo Class-I Class-II Class-I 3 3 4 A) TATA Power Comp Thokarwadi Walvhan Walvhan Shirwata Mulashi Mulashi Mulashi Kolawali D) KMC Kolhapur E) SAHARA Pune E)KagalNagarparisha Kolawali F)VikramsinghGhatge	Pre & Post Monsoon Report Not Received (Both) Either Pre or Post In 3 3 4 5 3 3 4 5 A) TATA Power Company Ltd Thokarwadi 1 Walvhan Walvhan 1 Mulashi Lonavala 1 Mulashi Lonavala 1 Mulashi Lonavala 1 Visakhar 0 1 Visakhar 0 1 D) KMC Kolhapur Rankala 1 E) KagalNagarparishad,Kagal 1 1 Sir PirajiraoTalao Sir PirajiraoTalao 1	Either Pre or Post Inspection Not R Received (Both) Either Pre or Post Inspection Not R Pre Monsoon Pre Monsoon 3 3 4 5 6 3 3 4 5 6 A) TATA Power Company Ltd Thokarwadi 0 0 Walvhan 0 0 0 0 Mulashi 0 0 0 0 0 Mulashi 0 0 0 0 0 0 0 Ambavane 0 <

Table 3.5
Dams Inspected by Dam Safety Organization, Nashik (2021-22)

Sr. No	Name of Dam	Date of Inspection	Sr. No	Name of Dam	Date of Inspection						
1	2	3	4 5		6						
	Class - I Dams		Class - II Dams								
[A]Chie	f Engineer(W.R.)Water Resources Depa	artment Pune									
(1)Supe	rintending Engineer, Pune Irrigation Ci	rcle, Pune									
(a)Exec	utive Engineer, Pune Irrigation Division	on, Pune									
1	Nira Deoghar	17.3.2022	1	Rihe	27.8.2021						
			2	Shetphal	30.1.2022						
(b) Exec	utive Engineer,Khadakwasla Irrigation	Division, Pune									
2.	Khadakwasla	18.3.2022	3	Palasdeo	31.1.2022						
			4	Shirsuphal	31.1.2022						
			5	Bhadalwadi	31.1.2022						
(c) Exec	utive Engineer,Chaskman Irrigation Div	ision, Pune									
3.	Bhamaaskhed	18.3.2022	6	Kadus	22.10.2021						
(d)Exec	cutive Engineer,Lift Irrigation Mangaem	ent Division, Pune									
			7	Virnalla	30.3.2022						
(e)Exec	utive Engineer, Nira Right Bank Canal	Division, Phaltan ,Di	st. Satara		- 1						
			8	Phondshiras	30.1.2022						

Sr. No	Name of Dam Date of Inspec		Sr. No	Name of Dam	Date of Inspection
1	2	3	4	5	6
(2)Supe	erintending Engineer, Sangli Irriga	tion Circle, Sangli			
(a) Exe	cutive Engineer, Sangli Irrigation D	ivision,Sangli			
				Diment	0040000
	NIL		9	Birnai	28.1.2022
			10	Daribadchi	29.1.2022
			11	Dodanalla	29.1.2022
			12	Dudhebhavi	28.1.2022
			13	Pratappur	28.1.2022
			14	Shegaon	29.1.2022
(b)Exec	cutive Engineer, Tembhu Lift Irrigat	ion Management Divisio	n Oglewadi, K	arad	I
	NIL		15	Buddhihal	29.1.2022
(5)Supe	erintending Engineer Satara Irrigat	ion Circle, Satara	·		
a)Exec	utive Engineer, Krishna Irrigation D	Division Satara			
	Kanher	17.3.2022	16	Ranand	30.1.2022
(b)Exec	cutive Engineer, Satara Irrigation D	ivision Satara			I
	Dhom Balakwadi	17.3.2022			
[B]Chie	ef Engineer(S.P.) Water Resources	Department Pune			
(1)Supe	erintending Engineer Kukadi Irrigat	ion Circle Pune			
(a) Exe	cutive Engineer, Kukadi Irrigation	Div. 1 Narayangaon			

Sr. No	Name of Dam	Date of Inspection	Sr. No	Name of Dam	Date of Inspection
1	2	3	4	5	6
	Vadaj	18.3.2022	17	Ballalwadi	22.10.2021
			18	Otur Waghdara	22.10.2021
(3)Sup	perintending Engineer & Administrator,	C.A.D.A. Solapur			
(a) Exe	ecutive Engineer, Bhima Irrigation Divis	ion, Pandharpur			
			19	Chincholi	29.1.2022
(4) Su	perintending Engineer, Bhima Canal circ	le,Solapur			
(a) Exe	ecutive Engineer, Minor Irrigation Division	on No.1, Solapur			
	NIL		20	Pimpalgaon Dhale	31.1.2022
Priva	te Dam				
A) TAT	FA Power Company Ltd				
1	Thokarwadi	9.12.2021			
2	Walvhan	21.12.2021			
3	Shirwata	21.12.2021			
4	Mulashi	9.12.2021			
			1	Kundali	21.12.2021
			2	Lonavala	8.12.2021
B) INS	Shivaji	1		1	1
			3	New Shivsagar	26.8.2021
			4	Old Shivsagar	26.8.2021

Sr. No	Name of Dam	Date of Inspection	Sr. No	Name of Dam	Date of Inspection
1	2	3	4	5	6
C) KMC Koll	napur				
			5	Rankala	28.1.2022
			6	Kalamba	28.1.2022
D) Vikramsiı	nghGhatge				
			7	Sir Pirajirao	28.1.2022
E)Kagal Nag	ar Parishad, Kagal				
			8	JaisingraoTalao	28.1.2022
F) Symbiosi	s, Lavale,Pune				
			9	Lower Tank	27.8.2021
			10	Upper Tank	27.8.2021

Deficiency Classification (No.of Dam wise)

Sr. No	Authority	Total	Number of	Dams	Numbe	r of Dams (C	Class-I)	Number of Dams (Class-II)			
		Class-I	Class-II	Total	Def. Cat-1	Def.Cat-2	Def. Cat-3	Cat-1	Cat-2	Cat-3	
	Water Resources Department D	ams									
[A]	CE, WRD, Pune	48	160	208	0	47	48	0	91	158	
(I)	SE, PIC, Pune	15	47	62	0	15	15	0	35	45	
1	EE, PID, Pune	6	18	24	0	6	6	0	16	17	
2	EE, LIMD,Pune	1	8	9	0	1	1	0	3	7	
3	EE, KID, Pune	4	6	10	0	4	4	0	5	6	
4	EE, NRBC, Phaltan	1	11	12	0	1	1	0	7	11	
5	EE,CID, Pune	3	4	7	0	3	3	0	4	4	
(II)	SE,PIPC, Pune	2	1	3	0	2	2	0	0	1	
1	EE, BADD, Pune	1	1	2	0	1	1	0	0	1	
2	EE, NiraDeoghar, Sangvi	1	0	1	0	1	1	0	0	0	
(111)	SE, SIC, Sangli	3	53	56	0	3	3	0	24	53	
1	EE, SID, Sangli	1	25	26	0	1	1	0	9	25	
2	EE, TLIMD, Karad	1	27	28	0	1	1	0	15	27	
3	EE, TPD, Devrashtre	1	1	2	0	1	1	0	0	1	

Sr. No	Authority	Total	Number of	Dams	Numbe	r of Dams (O	Class-I)	Number of Dams (Class-II)			
		Class-I	Class-II	Total	Def. Cat-1	Def.Cat-2	Def. Cat-3	Cat-1	Cat-2	Cat-3	
(IV)	SE, KIC, Kolhapur	22	39	61	0	21	22	0	16	39	
1	EE, KID (N), Kolhapur	9	16	25	0	9	10	0	7	16	
2	EE, KID (S), Kolhapur	8	23	31	0	7	7	0	9	23	
3	EE, MPD-2, Kolhapur	5	0	5	0	5	5	0	0	0	
(V)	SE, SIC, Satara	6	20	26	0	6	6	0	16	20	
1	EE, KID, Satara	2	18	20	0	2	2	0	14	18	
2	EE, Koyna ID, Koynanagar	2	2	4	0	2	2	0	2	2	
3	EE, SID, Satara	2	0	2	0	2	2	0	0	0	
[B]	CE, SP, Pune	21	33	54	0	18	20	0	20	33	
(I)	SE,KukadilC,Pune	8	12	20	0	8	8	0	7	12	
1	EE, KID-1, Narayangaon	5	12	17	0	4	4	0	7	12	
2	EE, KID-2,Shrigonda	2	0	2	0	2	2	0	0	0	
3	EE, Dimbhe DD, Manchar	1	0	1	0	2	2	0	0	0	
(11)	SE, CADA, Solapur	3	16	19	0	1	2	0	9	16	
1	EE, SID, Solapur	2	11	13	0	0	1	0	6	11	
2	EE, BID, Pandharpur	0	4	4	0	0	0	0	2	4	
3	EE, BDD-2, Solapur	0	1	1	0	0	0	0	1	1	
4	EE, UDD, Bhimanagar	1	0	1	0	1	1	0	0	0	

Sr. No	Authority	Total	Number of	Dams	Numbe	r of Dams (O	Class-I)	Number of Dams (Class-II)			
		Class-I	Class-II	Total	Def. Cat-1	Def.Cat-2	Def. Cat-3	Cat-1	Cat-2	Cat-3	
(111)	SE, BCC, Solapur	0	3	3	0	0	0	0	3	3	
1	EE, MID-1, Solapur	0	3	3	0	0	0	0	3	3	
(IV)	SE, SIPC,Satara	9	2	11	0	8	9	0	1	2	
1	EE, MID, Satara	5	2	7	0	5	5	0	1	2	
2	EE, DCD, Satara	2	0	2	0	1	2	0	0	0	
3	EE, KCD, Satara	1	0	1	0	1	1	0	0	0	
4	EE,UDD,Satara	1	0	1	0	1	1	0	0	0	
(V)	SE, OIC, Osamanabad	1	0	1	0	1	1	0	0	0	
1	EE, SCD,Paranda	1	0	1	0	1	1	0	0	0	
	WRD Total	69	193	262	0	65	69	0	111	191	
	Private Dams										
1	TATA Power Company Ltd	4	2	6	0	4	4	0	1	2	
2	SAHARA Pune	3	0	3	0	0	0	0	0	0	
3	INS Shivaji	0	2	2	0	0	0	0	2	2	
4	KMC Kolhapur	0	2	2	0	0	0	0	2	2	
5	KagalNagarparishad,Kagal	0	1	1	0	0	0	0	0	1	
6	VikramsinghGhatge	0	1	1	0	0	0	0	0	1	
7	Symbiosis, Lavale, Pune	0	2	2	0	0	0	0	2	2	

Sr. No	Authority	Total	Number of	Dams	Numbe	r of Dams (C	Class-I)	Number of Dams (Class-II)			
		Class-I	Class-I Class-II Total			Def.Cat-2 Def. Cat-3		Cat-1	Cat-2	Cat-3	
	Private Total	7	10	17	0	4	4	0	7	10	
	Grand Total	76	203	279	0	69	72	0	118	201	

Note - 1. Out of 193 Govt. owned Class-II Dams, Only 164 Dams Post Monsoon Report were received in DSO and 29 Class-II Dams Post Monsoon Report were not received in DSO.

Deficiency Classification (No. of Deficiency wise)

		No. of Dams having Deficiencies						Number of Deficiencies								
		Ca	t-1	Ca	Cat-2		it-3	C	ategory	-1	Category–2			Category–3		
Sr. No	Authority	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
	Water Resources Department Dams															
[A]	CE, WRD, Pune	0	0	47	91	47	158	0	0	0	326	148	464	698	1362	2060
(I)	SE, PIC, Pune	0	0	15	35	15	45	0	0	0	168	53	221	245	384	629
1	EE, PID, Pune	0	0	6	16	6	17	0	0	0	53	22	75	102	173	275
2	EE, LIMD,Pune	0	0	1	3	1	7	0	0	0	2	4	6	14	55	69
3	EE, KID, Pune	0	0	4	5	4	6	0	0	0	50	11	61	61	46	107
4	EE, NRBC, Phaltan	0	0	1	7	1	11	0	0	0	14	8	22	17	70	87
5	EE,CID, Pune	0	0	3	4	3	4	0	0	0	49	8	57	51	40	91
(11)	SE,PIPC, Pune	0	0	2	0	2	1	0	0	0	28	0	28	19	3	22
1	EE, BADD, Pune	0	0	1	0	1	1	0	0	0	26	0	26	10	3	13
2	EE, NiraDeoghar, Sangvi	0	0	1	0	1	0	0	0	0	2	0	2	9	0	9
(111)	SE, SIC, Sangli	0	0	3	24	3	53	0	0	0	6	39	45	29	491	520

	-	No. of Dams having Deficiencies						Number of Deficiencies								
		Ca	t-1	Ca	t-2	Ca	t-3	Ca	ategory	-1	Ca	ategory	-2	С	ategory-	-3
Sr. No	Authority	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
1	EE, SID, Sangli	0	0	1	9	1	25	0	0	0	4	17	21	10	194	204
2	EE, TLIMD, Karad	0	0	1	15	1	27	0	0	0	1	22	23	11	286	297
3	EE, TPD, Devrashtre	0	0	1	0	1	1	0	0	0	1	0	1	8	11	19
(IV)	SE, KIC, Kolhapur	0	0	21	16	22	39	0	0	0	72	20	82	301	298	599
1	EE, KID (N), Kolhapur	0	0	9	7	9	16	0	0	0	48	10	48	142	104	246
2	EE, KID (S), Kolhapur	0	0	7	9	8	23	0	0	0	10	10	20	94	194	288
3	EE, MPD-2, Kolhapur	0	0	5	0	5	0	0	0	0	14	0	14	65	0	65
(V)	SE, SIC, Satara	0	0	6	16	6	20	0	0	0	52	36	88	104	186	290
1	EE, KID, Satara	0	0	2	14	2	18	0	0	0	21	34	55	38	166	204
2	EE, Koyna ID, Koynanagar	0	0	2	2	2	2	0	0	0	13	2	15	25	20	45
3	EE, SID, Satara	0	0	2	0	2	0	0	0	0	18	0	18	41	0	41
[B]	CE, SP, Pune	0	0	18	20	21	33	0	0	0	143	39	182	298	283	581
(I)	SE,KukadilC,Pune	0	0	8	7	8	12	0	0	0	76	13	89	141	109	250
1	EE, KID-1, Narayangaon	0	0	5	7	5	12	0	0	0	39	13	52	80	109	189

		Ν	o. of Da	ims hav	ving Def	iciencie	es				Numbe	er of Def	of Deficiencies			
		Ca	t-1	Ca	t-2	Ca	t-3	Ca	ategory	-1	Ca	ategory	-2	С	ategory	-3
Sr. No	Authority	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
2	EE, KID-2,Shrigonda	0	0	2	0	2	0	0	0	0	25	0	25	42	0	42
3	EE, Dimbhe DD, Manchar	0	0	1	0	1	0	0	0	0	12	0	12	19	0	19
(11)	SE, CADA, Solapur	0	0	1	9	3	16	0	0	0	10	14	24	38	127	165
1	EE, SID, Solapur	0	0	0	6	2	11	0	0	0	0	8	8	24	88	112
2	EE, BID, Pandharpur	0	0	0	2	0	4	0	0	0	0	3	3	0	30	30
3	EE, BDD-2, Solapur	0	0	0	1	0	1	0	0	0	0	3	3	0	9	9
4	EE, UDMD, Bhimanagar	0	0	1	0	1	0	0	0	0	10	0	10	14	0	14
(111)	SE, BCC, Solapur	0	0	0	3	0	3	0	0	0	0	7	7	0	26	26
1	EE, MID-1, Solapur	0	0	0	3	0	3	0	0	0	0	7	7	0	26	26
(IV)	SE, SIPC,Satara	0	0	8	1	9	2	0	0	0	45	5	50	98	21	119
1	EE, MID, Satara	0	0	5	1	5	2	0	0	0	29	5	34	67	21	88
2	EE, DCD, Satara	0	0	1	0	2	0	0	0	0	3	0	5	13	0	13
3	EE, KCD, Satara	0	0	1	0	1	0	0	0	0	11	0	11	13	0	13
4	EE,UDD,Satara	0	0	1	0	1	0	0	0	0	2	0	0	5	0	5

		N	o. of Da	ams hav	ing Def	iciencie	es				Numbe	er of De	ficienci	es		
		Ca	t-1	Ca	t-2	Ca	it-3	C	ategory	<u>–</u> 1	Ca	ategory	-2	С	ategory	-3
Sr. No	Authority	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Class-I	Class-II	Total	Class-I	Class-II	Total	Class-I	Class-II	Total
(V)	SE, OIC, Osamanabad	0	0	1	0	1	0	0	0	0	12	0	12	21	0	21
1	EE, SKD,Paranda	0	0	1	0	1	0	0	0	0	12	0	12	21	0	21
	Govt Total	0	0	65	111	69	191	0	0	0	469	187	656	996	1645	2641
	Private Dam															
1	TATA Power Company Ltd	0	0	4	1	4	2	0	0	0	5	1	6	18	10	28
2	SAHARA Pune	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3	INS Shivaji	0	0	0	2	0	2	0	0	0	0	7	7	0	10	10
4	KMC Kolhapur	0	0	0	2	0	2	0	0	0	0	2	2	0	14	14
5	KagalNagarparishad,Kagal	0	0	0	0	0	1	0	0	0	0	0	0	0	8	8
6	VikramsinghGhatge	0	0	0	0	0	1	0	0	0	0	0	0	0	9	9
7	Symbiosis, Lavale, Pune	0	0	0	2	0	2	0	0	0	0	7	7	0	11	11
	Private Total	0	0	4	7	4	10	0	0	0	5	17	22	18	62	80
	Grand Total	0	0	69	118	72	201	0	0	0	474	204	668	1014	1707	2721

Note-1.No. of Deficiencies are from 262 Pre Monsoon Reports (Class-I /69 + Class-II /191) and 229 Post Monsoon Reports (Class-I /65 + Class-II /164) received in DSO.

Table	3.8
-------	-----

Sr. No	Name of Dam	No. of deficiencies noticed	Sr. No	Name of Dam	No. of deficiencies noticed
1	2	3	4	5	6
	Class - I Da	ams		Class - II Dams	5
		N	IL		



Category-2 Deficiency Classification (Dam wise)

Sr. No	Name of Dam	No. of deficiencies noticed	Sr. No	Name of Dam	No. of deficiencies noticed						
1	2	3	4	5	6						
Class	- I Dams		Class - II Dams								
[A]Chi	ef Engineer(W.R.)Water Resources Depa	artment Pune									
(1)Sup	1)Superintending Engineer, Pune Irrigation Circle, Pune										
(a)Exe	a)Executive Engineer,Pune Irrigation Division, Pune										
1	Jadhavwadi	9	1	Mahakoshi	2						
2.	Nira devghar	8	2	Maranewadi	2						
3.	Bhatghar	12	3	Urawade	1						
4.	Vadivale	10	4	Rihe	4						
5.	Andravalley	9	5	Hadashi	1						
6.	Kasarsai	5	6	Divale	1						
			7	Naigaon	1						
			8	Wagajwadi	1						
			9	Bhongavali	1						

		No. of deficiencies			No. of deficiencies	
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed	
1	2	3	4	5	6	
			10	Gadavane	2	
			11	Hadashi	1	
			12	Khamboli	1	
			13	Pimpoli	1	
			14	shere	1	
			15	walen	1	
			16	Chinchwad	1	
(b)Exe	ecutive Engineer ,Chaskaman Irrigation	division, Pune				
7.	Aralakalmodi	14	17	Nimgaon Mhalungi	1	
8.	BhamaAskhed	8	18	Dahiwadi	2	
9.	Chaskaman	27	19	Kadus	4	
			20	Alegaon Pagaa	1	
c)Exe	cutive Engineer, Lift Irrigation Manager	ment Division,				
Pune						
10.	Nazare	2	21	Garade	1	
			22	Pilanwadi	1	

		No. of deficiencies			No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
			23	Thitewadi	2
d) Exe	cutive Engineer ,Khadakwasala Irrigatio	on Division, Pune			
11.	Panshet	5	24	Matoba	3
12.	Khadakvasla	13	25	Shirsuphal	2
13.	Warasgaon	15	26	Bhugaon	1
14.	Pawana	17	27	Malad	2
		1	28	Palasdev	3
(e)Exec	cutive Engineer, Nira Right Bank Canal I	Division, Phaltan ,Di	st. Satara	l	
15.	Veer	14	29	Naigaon	1
			30	Banganga	2
			31	Mhasavad	1
			32	Girzani	1
			33	hingangaon	1
			34	Tambave	1
			35	Phondshiras	1
(2)Sup	erintending Engineer, Pune Irrigation P	roject Circle, Pune		1	I
(a) Exe	cutive Engineer, Bhama Askhed dam di	vision, Pune			
16.	Temghar	26			
L	1				

DSO-ADHSR_2021-22/ (Pune)

		No. of deficiencies			No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
(b)Exe	cutive Engineer, Niradevghar Project Di	vision, Sangavi(Bha	tghar),Ta	I.Bhor,Dist.Pune	
17	Guniavani	2			
	Canjavani	-			
(3)Sup	erintending Engineer Sangli Irrigation of	ircle, Sangli			
(a)Exe	cutive Engineer Sangli Irrigation Divisio	on Sangli			
(u)=x0					
18.	Morna (Shirala)	4	36	Antri	1
	1		37	Soradi	1
			38	Tippehalli	1
			39	Bhiwargi	2
			40	Daribadchi	2
			41	Dodanalla	4
			42	Shegaon	2
			43	Pratappur	1
			44	Birnal	3
(b)Exe	cutive Engineer ,Tembhu Lift Irrigation I	Project Management	t Divisior	n, Ogalewadi	1
19.	Yevati masoli	1	45	Chinchani	1
			46	Atpadi	1
			47	Buddhihal	3
I					

		No. of deficiencies	s Sr No		No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
			48	Dighanchi	1
			49	Ghanand	1
			50	Hingangaon	1
			51	Kadegaon	4
			52	Karandewadi	2
			53	Morale	1
			54	Nimbhavade	2
			55	Pare	1
			56	Ped	1
			57	vejegaon	1
			58	Walunj	1
			59	Mahadikwadi	1
(c)Exec	cutive Engineer ,Takari Pump House Div	vision No.1, Devras	htre		
20.	Satpewadi barrage	1			

		No. of deficiencies	es		No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
(4)Sup	erintending Engineer Kolhapur Irrigatio	n Circle,Kolhapur			
(a) (x)	utive Engineer Medium Preject Divisi	n Not Kalkanur			
(a)⊏xeo	curve Engineer, medium Project Divisio	n Noz, Kolhapur			
21.	Ghatprabha(Phatakwadi	6			
22.	Chikotra	2			
23.	Jangamhatti	2			
24.	Keloshi Bk.	1			
25.	Jambre	3			
(b)Exe	cutive Engineer, Kolhapur Irrigation Dn.	(North) Kolhapur			
26.	Kadavi	3	60	Drayachi vadgaon	1
27.	Kasari	1	61	Kasarde	2
28.	Kumbhi	2	62	Andur	1
29.	Paleshwar	2	63	Kode	1
30.	Tulashi	5	64	Manoli	1
31.	Upwade	1	65	Olwan	2
32.	Radhanagari	12	66	Vesraf	2
33.	Warana	14			
34.	Dudhaganga	8			

		No. of deficiencies	- ···		No. of deficiencies	
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed	
1	2	3	4	5	6	
(c)Exec	cutive Engineer, Kolhapur Irrigation Dn.	(South) Kolhapur				
35.	Patgaon	1	67	Dindlkop	1	
			68	Erandol	1	
36.	Chitri	2	69	Kalasgade	1	
37.	Kitwad-2	1	70	Karanjivane	2	
38.	Kondoshi	1	71	Kitwad	1	
39.	Lakikatti	2	72	Kiumari	1	
40.	Megholi	1	73	Shendri	1	
41.	Phaye	3	74	Sundi	1	
	I	1	75	Yenechavandi	1	
(5)Sup	erintending Engineer Satara Irrigation (Circle, Satara				
a)Exec	utive Engineer, Koyna Irrigation Divisio	n Koynanagar				
42.	Koyna	7	76	Chaphal	2	
43.	Kolkewadi	6	77	Chalakewadi	1	
(b)Exe	L Cutive Engineer, Satara Irrigation Division	on Satara				
44.	Dhom	9				

	Name of Dam	No. of deficiencies	• •		No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
45.	Dhombalkawadi	9			
(c) Exe	cutive Engineer, Krishna Irrigation Divi	sion, Satara			
46.	Urmodi	2	78	Kankatreawadi	4
47.	Kanher	19	79	Thoseghar	8
			80	Ner	3
			81	Pingali	2
			8/2	Yeralwadi	1
			83	Jambhulani	2
			84	Hiware	1
			85	Ranand	5
			86	Andhali	1
			87	Arabwadi	2
			88	Daruj	1
			89	Nandwal	1
			90	Dhakani	1
			91	Kumathe	2

	Name of Dam	No. of deficiencies		Name of Dam	No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
[B]Chie	of Engineer(S.P.) Water Resources Dep	artment Pune			
(1)Sup	erintending Engineer Kukadi Irrigation	Circle Pune			
(1)000					
(a) Exe	cutive Engineer, Kukadi Irrigation Div.	1 Narayangaon			
48.	Wadaj	6	92	OturWaghdara	4
49.	Yedgaon	1	93	Ramjiwadi	1
50.	Manikdoh	14	94	Gangaldara	1
51.	Pimpalgaonjoge	5	95	Ucchil	1
52.	Dimbhe	14	96	Anepemdara	3
	I		97	Gohe	2
			98	Ballalwadi	1
(b) Exe	cutive Engineer, Kukadi Irrigation Div.	2 Shrigonda			
53.	Ghod	12			
c) Exec	utive Engineer ,Kukadi Irrigation Divisi	on No. 2, Shrigonda			
54.	Sina	13			
(d) Exe	cutive Engineer, Dimbhe Dam Div. Mai	nchar			I
55.	Chilewadi	11			

.		No. of deficiencies	• •		No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
(2)Sup	erintending Engineer Satara Irrigation I	Project Circle, Satar	a	· ·	
	autive Engineer Miner Irrigation Divisi	on Satara			
		on, Salara			
56.	Uttarmand	4	99	Mahind	4
57.	Morna(Gureghar)	7			
58.	Nagewadi	6			
59.	Kalgaon	8			
60.	Kusawade	4			
61.	Hatgeghar	1			
(b)Exe	Lutive Engineer ,Kanher Canal Division	No.2, Karwadi,Kara	d.		
62.	Tarali	11			
(c)Exe	cutive Engineer, Dhom Canal Division N	o.2,Satara			
63.	Pangare	5			
(3)Sup	erintending Engineer & Administrator,	C.A.D.A. Solapur			
(a) Exe	cutive Engineer, Solapur Irrigation Division	sion Solapur			
			100	Hingani (K)	1
			101	Mangi	2

Sr. No	Name of Dam	No. of deficiencies noticed	Sr. No	Name of Dam	No. of deficiencies noticed
1	2	3	4	5	6
			102	Kazikanbus	2
			103	Rajuri	1
			104	Chare	1
			105	Kari	1
(b) Exe	cutive Engineer, Bhimalrrigation Divisio	on, Pandharpur			
			106	Talsangi	1
			107	Chincholi	2
(b)	Executive Engineer, Ujjani Dam Manage	ement Division	(b)Execu	ive Engineer, Bhima Developemen	t Division No.2,
	Bhimanagar Dist. Solapur		Solapur.		
64.	Ujjani	10	108	Ashti	2
(4)Supe Osman	erintending Engineer Osmanabad Irriga abad	tion Circle	4)Superir	itending Engineer, Bhima Canal C	ircle Solapur
(a)Exec Sinako	cutive Engineer, legaonProjectDivisionParandaDist.Osm	anabad	(a)Execut	tive Engineer, Minor Irrigaton Divisi	on No.1, Solapur
65.	Sinakolegaon	12	109	Babhulgaon	2
	L		110	PimalgaonDhale	3
				Gholasgaon	2
			111		

		No. of deficiencies			No. of deficiencies
Sr. No	Name of Dam	noticed	Sr. No	Name of Dam	noticed
1	2	3	4	5	6
Privat	e Dam				
A) TAT	A Power Company Ltd				
1	Thokarwadi	1	1	Lonavala	1
2	Walvhan	1			
3	Shirwata	2			
4	Mulashi	1			
B) INS	Shivaji				
			2	New Shivsagar	4
			3	Old Shivsagar	3
C) KMC	C Kolhapur				
			4	Rankala	1
			5	Kalamba	1
			DSymbio	sis Pune	
			6	Upper Tank	3
			7	Lower Tank	4

Class-I Dams with Category-1 Deficiency

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Observation / Significant Deficiencies noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
			No Such	Dams under this	category is reported	

Class-I Dams with Category-2 Deficiency

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested			
ο		Inspection	Officer	Component		Noticed				
				of Dam						
1		3	4	5		6	1			
[A]Ch	lief Engineer (w.R.), water Res	sources Depar	tment, Pune							
(1) Su	perintending Engineer, Pune	Irrigation Circl	le, Pune							
(a) Ex	(a) Executive Engineer, Pune Irrigation Division, Pune 1									
1	Name : Bhatghar (Gated) Tal. BhorDist.Pune Year of completion : 1926	30.04.2021 24.11.2021	Shri. S. D. Chopade, S.E., P.I.C.,	Gallery	1.	There is no proper ventilation & lighting & handrails arrangement.(A8)	Repairs should be carried out.			
	Location : Longitude 73⁰52 ' Latitude 18⁰11 ' Height : 57.62 m		Pune		2.	Problems of inadequate drainage-Clogged porous pipes (A8)	Proper arrangement should be made for the measurement of seepage into gallery.			
	Gross Capacity : 672.65 Mm ³ Spillway capacity:1600 m ³ /sec Sr.No.In Large Dam Register			Body Wall	3.	The total seepage into gallery from the porous pipes in the dam at lake full condition - 8.50 LPS @ FRL (A10)	Repairs should be carried out in consultation with Mechanical Organization.			
	2009: MH09HH 0048			Seepage Measurement	4.	Maximum since last June12/09/2021 8.50 LPS 623.28(A11)	Necessary repairs shall be carried out.			
				Gallery	5.	There been considerable leaching observed from the seepage water and deposition of line near the seepage exit spots. (A12)	It should be kept under observation & leaching material should be sent to MERI, Nashik Lab for testing.			
				EDA	6.	Due to erosion in central spillway stilling basin, pond cannot be drained automatically below the adjacent nala bed level.(A14)	Necessary repairs shall be carried out. Necessary remedial measures should			
						,	be carried out.			

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
_		2		of Dam		
1	2	3	4	5 Outlat		1
				Outlet	arrangement working satisfactorily - Bed concrete is disturbed(A14)	
				Spillway	8. Guide wall beyond check weir and check weir is also damaged. (A16)	Necessary remedial measures should be carried out.
					 The check wall / end weir is damaged & erosion is observed at D/S of End weir. 	Necessary repair should be done.
					(A17)	Necessary remedial measures should be carried out.
					10. The obstructions in upstream or downstream of water conveyance structure - Silt	
					deposition. (B8)	Necessary remedial measures should be carried out.
				Crest of Dam End Weir	11. Pointing on Crest should be done with epoxy material.	
					(B8)	Necessary remedial measures should
				Instrmentation	12.Uplift pressure cell & Water	be carried out.
					stage recorder are not	
					working (B9)	Necessary remedial measures should be carried out.
				Spillway	13. There are automatic gates.	
				Gates	but nut bolts of guide frame	
					are not in good condition &	
					need to be replaced.(B12)	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
2	Name : Vadivale (Gated) Tal. MavalDist.Pune Year of completion : 1999 Location : Longitude 73°31'16 " Latitude 18°49'20 " Height : 29.00 m Gross Capacity: 40.87. Mm ³ Spillway capacity:	05.05.2021 30.11.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Face	 Mild seepage on D/S face of masonry. (A11) Significant leakage at Overflow Section & non-over flow section junction on downstream face. (A15) Deterioration of concrete in 	Necessary remedial measures should be carried out. Location & quantum of leakage should be investigate causes of leakage should be ascertained & proper remedial measures to prevent leakages should be carried out.
	746.82m³/sec Sr.No.In Large Dam Register			Face	ogee portion. (B8)	be carried out
	2009: MH09MH1517			Waste Weir Bar and Tail Channel	 Honeycombing to RBC outlet gate, overflow section & Pier concrete above crest RL. (B8) 	Necessary remedial measures should be carried out
				Spillway	 The surface of ogee is not smooth & it is not in profile. Big cavities, pot holes are observed on ogee surface. Heavy leakage through body of spillway is observed. Through junction of each spillway construction joint.Big cavities are observed and needs rectifications. (A15) 	Leakages should be attended in time by providing suitable remedial measures after ascertaining the exact cause of leakage.
					6.Concrete at crest level of spillway is damaged and needs rectifications. (B7)	Necessary remedial measures should be carried out
					7.Shotcreting & Concrete	Necessary remedial measures should be carried out

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
					jacketing is proposed as per methodology suggested by CWPRS(B7)	
					8. Concrete / masonry deterioration observed. (B7)	Necessary remedial measures should be carried out Necessary remedial measures should
					9. Significant leakage on spillway glacis observed (B7	be carried out
				River oulet/ Sluice	10.The heavy leakage observed from wall of intake wells & which is collected in conduit. (B10)	Leakages should be attended in time by providing suitable remedial measures after ascertaining the exact cause of leakage.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
	-			of Dam	-	
1	2	3	4	5	6	7
3	Name : Kasarsai (Gated) Tal. MulashiDist.Pune Year of completion : 1995 Location : 73⁰40'00'' Latitude 18⁰35'30'' Height : 36.0 m Gross Capacity : 17.38 Mm ³ Spillway conscity : 023 00	05.05.2021 30.11.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Slope	 Wet and slushy patches are observed at ch 300 to 360 m. on downstream slopes when water level is above 626.50m. Boils were observed from ch 300 to 360 at RL 626.50 to 626.61 m (A1) 	This deficiency should be kept under observation and after confirmation by competent field authority, if necessary repair should be carried out in consultation with CDO, Nashik.
	m ³ /sec Sr.No.In Large Dam Register 2009: MH09MH1373			EDA	 Under drainage of stilling basin is not satisfactory. Also all the open drain holes are not clear & functioning well. (A9) 	Necessary remedial measures should be carried out.
				Downstream Face	 Mild seepage observed on d/s face of masonry. (A11) 	Necessary remedial measures should be carried out.
				Outlet Gates	 The surface of gates and the paints is deteriorated. (B11) 	Necessary repairs should be carried out in consultation with Mechanical Organization.
				Downstream Slope	5. Heavy bushes observed overall length of D/s slope.(B13)	Necessary remedial measures should be carried out.
				Spillways.	 Secondary concrete near wall plates of radial gate is damaged. 	Necessary repairs should be carried out in consultation with Mechanical Organization.
4	Name : Jadhavwadi (Gated) Tal. MavalDist.Pune Year of completion : 2001	11.05.2021 07.12.2021	Shri. S. D. Chopade, S.E., P.I.C.	Downstream Drainage.	1.No relief well is constructed.(A5)	Necessary remedial measures should be carried out.
	Location : 73⁶43'00" Latitude 18⁶47'00" Height : 35.52 m Gross Capacity : 12.03 Mm ³		Pune	Outlet	2.Energy dissipation arrangement is not working satisfactorily for all	Necessary remedial measures should be carried out.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-	-	of Dam		
1	2	3	4	5	6	7
	Spillway capacity : 664.14.00 m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH1587			Spillway	discharges.(A14)3.The obstructions observed in or immediately downstream of the spillway.(A17)	Necessary repairs should be carried out in consultation with Mechanical Organization.
				Outlet Gates	4. The full length of the wire rope of the hoist is not in serviceable condition. (A18)	Necessary repairs should be carried out in consultation with Mechanical Organization.
					5. The stem rods for lifting the gates are not perfectly straight.(B5)	Necessary repairs should be carried out in consultation with Mechanical Organization.
				Upstream Slope	 Concavity appears from ch.480 m. to 545 m. and between ch.810 m. to 980 m. on U/S slope & pitching settled down. (B3) 	Necessary repairs should be carried out.
				Crest of Dam	7. There are signs of excessive and/or uneven settlement between ch. 400 to 700 & Ch. 850 to 990. (B3)	Necessary remedial measures should be carried out.
				W.W.Bar	8. Waste Weir Bar is not in good condition.(A17)9.Coping of spillway bar is damaged.(A18)	Necessary remedial measures should be carried out Necessary remedial measures should be carried out
5	Name :NiraDevghar (Gated)	30.04.2021	Shri. S. D.	Gallery	1. Maximum seepage in the	Necessary remedial measures should
1	Tal. BhorDist.Pune	24.11.2021	Chopade,		body of dam collected in	be carried out.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
	Year of completion :2007 Location :73 ⁰ 43'36" Latitude 18 ⁰ 06'18" Height :58.525m Gross Capacity :337.39 Mm ³ Spillway capacity :1852.00 m ³ /sec	17.03.2022	S.E., P.I.C., Pune E.E. D.S.Div-1 Nasik		 gallery is measured - Quantity of seepage water 37.5 LPS@FRL(A11) Leaching @ some extent is noticed. Leaching material was submitted to MERI, Nasik for testing. (A12) 	Necessary remedial measures should be carried out.
	Sr.No.In Large Dam Register 2009: MH09HH1554			W.W. Bar & Tail channal	 The energy dissipation arrangement is not working satisfactorily -Bed concrete is disturbed. (A14) There is scouring in central 	Necessary repair should be done.
					spillway stilling basin and concrete filling is proposed to prevent further scouring	Necessary repair should be done.
					 (A16). 5. Bed concrete is disturbed of D/s side of End weir wall and tail channel bed. (A16). 	be carried out.
					6. Pitting, spalling & wearing of bed concrete surface in large scale & deep. (A14)	Necessary remedial measures should be carried out.
				Insrumentation	7. The problems ensuring correct functioning of instrument- They are not in working conditions(B9)	Necessary repair should be done in consultation with IRD, Nashik.
					 The Plumb bomb, Uplift pressure cell & Piezometer pressure cells are not working.(B9) 	
6	Name-Andravalley (Ungated) Tal.MavalDist.Pune Year of completion :2003	05.05.2021 30.11.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Gallery	 Foundation gallery not accessible due to flooding during inspection.(A8) There is a substantial 	Necessary remedial measures should be carried out Necessary remedial measures should
	Location :73 39 00" Latitude 18°20'00"				seepage through the	be carried out

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component		Noticed	
		-	-	of Dam			
1	2	3	4	5		6	7
	Height :34.50m					foundation, due to choking	
	Gross Capacity :83.31 Mm ²					drain noies at ch. 0/0/0 to	
	Spillway capacity : 3021.00					0/270m.(I) Almost all porous	
	Sr No In Lorgo Dom Bogistor					pipes in inspection gallery	
					2	Almost all paraus pipes	Necessary remodial measures should
	2009. MH00HH1622				5.	blocked up to 1 to 3 m from	be carried out
						dallery roof (A9)	be carried out
					4	(ii) Seepage through porous	Necessary remedial measures should
						pipes, foundation drains &	be carried out
						monolith joints collected in	
						Gravity chamber @ D/s of	
						EDA measured manually is	
						1 lit/sec.(A10)	
				Spillway	5.	Light sweating observed at	
						foundation gallery.(A11)	
					6.	Lake filled at FRL level in	
						August - 2006. Total	
						seepage in gallery was	
						measured and was about	
						4.25 lit/sees by construction	
				Outlat Catao	7	Wing. (A15)	
				Oullet Gales	1.	changed (A18)	he carried out in consultation with
						changed.(A10)	mechanical organization
				Outlet	8	The surface of gates and the	meenamear organization.
				Outlot	0.	paints is deteriorated.(B11)	
						,	
					9.	1) Service gate & (2)	Necessary remedial measures should
						Emergency gate - Leakages	be carried out in consultation with
						is observed through rubble	mechanical organization.
						seals. It requires to be	
						changed. Electric wiring and	
						electric motor requires to be	
						repaired.(B5)	
1	1	1	1	1	1		

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies Remedial Measures Sugge	sted					
ο		Inspection	Officer	Component	Noticed						
				of Dam							
1	2	3	4	5	6 7						
(b) Executive Engineer ,Khadakwasala Irrigation Division, Pune 11											
7	Name : Panshet (Gated) Tal. VelheDist.Pune Year of completion : 1972 Location : Longitude 73⁰37 ' Latitude 18⁰22 ' 5Height : 63.56 m	04.05.2021 23.11.2021	Shri.S.D. Chopade, S.E., P.I.C., Pune	Gallery	 There is leakage observed through the well proper and the conduit concrete or masonry - details not given.(A4) The connect of the conduct of the	carried					
	Spillway capacity : 303 Mm Spillway capacity : 1162.0 m³/ sec Sr.No.In Large Dam Register 2009: MH09HH0310				2. The seepage flow is measured as on a) Date - 23.11.2021Rate of seepage flow (lpm) - 101.00 LPS @ Reservoir Level - 635.99 m;(A11)	carried					
					3. There has been considerable leaching from the seepage water and deposition of lime near the seepage exit spots. (A12)	ation & sent to					
				Instrument	4. Piezometers and water stage recorder are out of order.(B9)	lone in					
				Spillway Gates	5. The damage or wear caused to the seal plates observed.(B12) Necessary repairs should be out in consultation with Mec Organization.	carried hanical					
8	Name: Khadakvasala (Gated) Tal. Haveli Dist.Pune Year of completion : 1879 Location : Longitude 73⁰45 ' Latitude 18⁰25 ' Height : 32.92 m Gross Capacity : 86 Mm ³	04.05.2021 23.11.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Drainage. Abutment Contacts	 Standing pool observed on D/S of Dam at Ch 1/066 to 1/095 m. (A2). The presence of leaks, springs or wet spots observed in vicinity of abutment. (A3). Standing pool observed on Suitable drainage arrang should be done to drain of water. Seepage & sweating be mo and necessary remedial measu taken 	gement out the onitored ures be					
Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested				
------	--	------------	------------	--------------	-----	-------------------------------	-------------------------------------				
0		Inspection	Officer	Component		Noticed					
				of Dam							
1	2	3	4	5		6	7				
-	Spillway capacity :2755 m ³ /			Junction of	3.	The seepage is observed	It should be kept under observation				
	sec			Earth work		from outlet provided at ch.	and verification of competant				
	Sr.No.In Large Dam Register			with Masonry		0/035 to 0/040m and 0/060	authority remedial measures should				
	2009:					to 0/150m (quantity of	be taken if necessary.				
	MH09HH0013					seepage not given)(A11)					
				EDA	4.	Some friction blocks are	It should be repaired properly.				
						damaged.(A14)	,				
					5.	The concrete surface of the	It should be repaired properly.				
						stilling basin and apron (or	,				
						bucket) is not in good					
						condition. (A14)					
					6.	The scouring observed on	Proper remedial measure should be				
						downstream side of the bar	taken and scouring should be				
						and/or EDA.(A17)	monitored & prevent the further				
				End Weir	7.	The erosion and damages	scouring.				
						observed on the concrete or					
						masonry surface(A17)					
					8.	The scour noticed on the	Necessary repairs should be carried				
						immediate downstream.	out.				
						.(A17)					
				Outlet	9.	The damage noticed to the	Necessary repairs should be carried				
						conduit concrete, breast wall	out.				
						and gate slots.(B5)					
				Outlet Gates	10.	The stem rod for lifting the	Necessary repairs should be carried				
						gates is not perfectly	out in consultation with Mechanical				
						straight(B5)	Organization.				
				Waste Weir	11.	The coping over the spillway	Necessary repairs should be carried				
				Bar and Tail		bar is not in good	out.				
				Channel		condition.(B7)					
				Spillway	12.	The spillway ogee surface is	Necessary repairs should be carried				
1						damaged. Small pot and	out.				
1						erosion on surface and					
1						damage at some					
						locations.(B7)					
1				Instruments	13.	Only Pan Evaporimeter is in	Necessary repairs shall be done in				
						working condition,	consultation with IRD, Nashik.				

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component		Noticed	
				of Dam			
1	2	3	4	5		6	7
						Piezometer & Water Stage	
						Recorder are out of	
						order.(B9)	
9	Name : Warasgaon (Gated)	04.05.2021	Shri. S. D.	Gallery/Shaft	1.	Some drain holes are	Drain holes should be cleaned.
	Ial. VelheDist.Pune	23.11.2021	Chopade,	Condition		chocked (number not	Necessary repairs should be carried
	Year of completion :1972		S.E., P.I.C.,	Callan	_	mentioned) (A9)	OUT.
	Location : Longitude 13 37		Pune	Gallery	Ζ.	Foundation noies are not	Drain noies should be cleaned.
	Lallude 10 23			Dam body	2	Excessive	Necessary repairs should be carried
	Gross Capacity · 374.00			Dam bouy	5.	seenage/sweating at M6	Seenage & sweating be monitored
	Mm ³					M11 M12 M13 observed	and necessary remedial measures be
	Sr.No.In Large Dam Register					along gallery/shaft (A10)	taken.
	2009:				4.	Significant or excessive	
	MH09HH0592					leakage at M6, M11, M12,	Seepage & sweating be monitored
						M13 observed along	and necessary remedial measures be
						gallery/shaft / porous drain .	taken.
						(A10)	
				Downstream	5.	Excessive seepage /	Seepage & sweating be monitored
				Face		sweating at downstream	and necessary remedial measures be
						face (location not	taken.
						mentioned) (A11)	Conners & exception he monitored
					6.	Significant leakage on	Seepage & sweating be monitored
						downstream lace at Mb,	takon
						$(\Lambda 11)$	laken.
				Body Wall	7	There is an excessive	Seepage & sweating be monitored
				Douy man	1.	seepage sweating at	and necessary remedial measures be
						monolith no. 6. 11. 12. 13	taken.
						on the downstream face of	
						the dam. (A11)	
					8.	(v) The excessive leakage	Seepage & sweating be monitored
						at M6, M11, M12, M13	and necessary remedial measures be
						observed. (A11)	taken.
					9.	There has been a	
						considerable leaching from	It should be kept under observation &
						the seepage water and	leaching material should be sent to

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
					 deposition of lime near the seepage exit spots. (A12) 10. The first filling during 1986 wqas up to RL 629m & the leakage was 126 lps. In the year 2017 the max RL of water was 639.50 m & leakage was 262 lps. Total seepage is 210 lps on 28/11/2019. Total seepage on date 23/11/2021 is 210 lps. (A15) 	MERI/ Lab for testing. Necessary repairs should be carried out
				Tail Channel &WW Bar	 The leakages observed through divide wall. (location-foundation gallery's cross drain) (A15) The damages to guide walls, divide wall and other appurtenant observed. (A16) 	Necessary repairs should be carried out Necessary repairs should be carried out
				Downotroom	 Erosion of foundation of end weir at stilling basin observed. (A17) 	Necessary repairs should be carried out
				Drainage	14. The portions of longitudinal toe drain and exposed cross drains beyond the downstream toe of the dam is not in regular section and freely draining.(B2)	out
				Instrumentation	 Piezometer, uplift pressure cell, strain gauge & Water Stage Recorder are out of order(B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	of Dam	Noticed	
1	2	3	4	5	6	7
10	Name : Pawana (Gated) Tal. BhorDist.Pune Year of completion : 1972 Location : Longitude 73⁰40 ' 30 Latitude 18⁰21 30 '	05.05.2021 30.11.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Downstream Slope Gallery	 A small spring observed on right side spray wall & end abutment junction of spillway - above radial gate sill RL.(A3) Any safety issues - Repair 	Necessary repairs should be carried out. Necessary repairs should be carried
	Height : 42.37 m Gross Capacity : 305 Mm ³ Spillway capacity:1250 m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH 0311				 to electrical light in right side gallery required. (A8) 3. There has not been substantial progressive reduction in the seepage through the foundations. (number of drain holes cleaned not mentioned) (A9) 	out. Necessary repairs should be carried out.
					 Water jet observed inside on right side drainage gallery from sides and roof. (A10) 	Drain holes should be cleaned.
					5. L & R side both galleries leakages(A10)	Drain holes should be cleaned.
					 The seepage flow as on date of inspection - Dtd- 30/11/2021 - 1177 lpm, Reservoir Level - 611.880 m; (ii) Max since last June 2021 - 2647.52 lpm; (iii) Min since last June 2021 - 1198.10 lpm; (A11) 	Necessary repairs should be carried out.
				Downstream Face Dam Body	 Mild sweating observed on d/s face of masonry (A11) Sweating is seen on D/S surface of masonry so cleaning of porous pipes is necessary (A11) 	Necessary repairs should be carried out. Necessary repairs should be carried out.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
				Spillway	9Excessive seepage/ sweating on spillway glacis observed - location not given. (A11)	Necessary repairs should be carried out.
				EDA	10. At some places at Stilling Basin wearing of concrete layer observed. (A14)	Proper remedial measure should be taken and scouring shall be monitored & prevented further scouring.
				Dam Body	11. The first filling during 1974 was up to RL 611.0m & the leakage was 3856 lpm. The seepage in both galleries at full condition of dam RL 613.26m was 1362 lpm. The seepage at RL 611.89 m was noticed 1177 lpm. (A15)	Necessary repairs should be carried out.
				End Weir	 12. The erosion, pitting or spalling of the concrete or masonry surface observed. Details not given. (A17) 13. The scouring at D/s side of end weir observed for about 	Necessary repairs should be carried out. Necessary repairs should be carried out.
				Hoist Crane	70m portion. (A17) 14. The alternative power system for gate operation is not working properly. (A19)	Necessary repairs should be carried out.
				D/S slope	15. Toe drain balance repair work to be done (B2)16. Toe drain repair work is in	Necessary repairs should be carried out. Necessary repairs should be carried
				Instrumentation	 progress. (B2) 17. Piezometer & Uplift Pressure Cells are yet to be installed.(B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.
				Spillway Gates	18. Minor leakage at sill of gate no. 1 & 6,	Proper remedial measures to be taken in consultation with Mechanical

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component		Noticed	
				of Dam			
1	2	3	4	5		6	7
							Organization.
		Induction Div	isian Duna 44				
(C) E)	Recutive Engineer , Chaskaman	Irrigation Div	Ision, Pune 11	Description	4		
11	Name : Chaskaman(Gated)	11.05.2021	Shri. S. D.	Downstream	1.	Bolls are observed @ RD	the drainage arrangement function of
	Voar of completion : 1000	07.12.2021		Dialitage		obsorved @ 860m d/s 285m	Long cross too drains and thon
	Location :		Duno			in existing well left side (A1)	proper remedial measures shall be
	Longitude 73⁰47 '		1 dile			in existing weniert side. (717)	carried out.
	Latitude 18°57'				2.	In the d/s of dam @ ch 860m	The downstream area from toe shall
	Height :46.28 m					downstream 285m, standing	be free from slushy condition by
	Gross Capacity :241.69Mm ³					pool of water observed.	draining water properly.
	Spillway capacity : 2860 m ³ /					(existing well) (A1)	
	sec			Relief Wells	3.	The relief wells are not	Relief wells should be cleaned
	Sr.No.In Large Dam Register					properly surged and cleaned	periodically.
	2009:					periodically(A5)	
	MH09HH1522			Gallery/Shaft	4.	Gallery remains flooded due	Proper drainage arrangement shall
				and Drainage		to heavy leakages through	be provided to drain out water.
					-	porous pipe. (A8)	
					э.	Detenoration of pump and	necessary repairs shall be done
						observed - it requires	
						replacement (A8)	
					6	Other issues-continuously	Alternative arrangement should be
					0.	electricity is not available to	made.
						the pumps for pumping. (A8)	
					7.	Some porous drains and	Foundation holes should be cleaned.
						foundation drain holes are	
						not in working condition. (A9)	
					8.	Total 71 drain holes are	Foundation holes should be cleaned.
1						choked. (A9)	
1				Body Wall	9.	Significant leakage on	Necessary repairs shall be done
				(Masonry		downstream face observed	
				/Concrete)		on d/s face of masonry.	
1						(location not mentioned)	
					10	(AIU)	Alternetive errongement eksyld be
					10.	Lighting arrangement has	Alternative arrangement should be

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
				Gallery/Shaft and Drainage	been destroyed and heavy leakages in inspecting gallery. (A10) 11. Excessive seepage through porous pipe in gallery. (A10) 12. Maximum discharge on2.9.2020when the dam is at maximum - 5688 lpm (A10)	made. Proper remedial measures to be taken to reduce leakage & gallery always made available for inspection.
					 13. No separate arrangement made for the measurement of seepage in gallery. (A10) 14. The seepage flow as on date of inspection - Dtd- 07/12/2021 - 5808 lpm, Reservoir Level - 649.530m; (ii) Max since last june 2020 - Date 16/10/2021 - 5808 lpm, Reservoir Level - 649.530m;; (iii) Min since june2020 - 13/06/2021 - 1812 lpm, Reservoir Level - 632.260 m; 	Proper arrangement should be made. Proper remedial measures to be taken to reduce leakage.
				Downstream Face Body Wall	 (A11) 15. Excessive seepage / sweating observed on d/s face of masonry.(A11) 16. Maximum discharge on 04/08/2021 when the dam is at maximum is 5808 lpm. (A11) 	Proper remedial measures to be taken to reduce leakage. Proper remedial measures to be taken to reduce leakage & gallery always made available for inspection Proper remedial measures to be
					17. There is no reduction in seepage. (A11)18. There is no reduction in seepage through pipes.	taken to reduce leakage. Proper remedial measures to be taken to reduce leakage.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		•		of Dam		
1	2	3	4	5	6	1
				Caller /Chaft	(A11)	It should be kept under observation &
				Condition	19. Leachate deposition is	MERI/Lab for tosting
				Condition	pipe in gallery. (A12)	WERT/Lab for testing.
					· · · ·	It should be kept under observation &
					20. 20. There has been	leaching material should be sent to
					considerable leaching from	MERI/ Lab for testing.
					deposition of lime near the	
					seenage exit spots (A12)	
						Leaching material should be sent to
					21. The samples of the seepage	MERI/ Lab for testing.
					water and reservoir water not	3
					being regularly tested for	
					reactive and corrosive	
					properties. (A12)	
						Proper remedial measures to be
				End weir	22. There is heavy erosion at the	taken to reduce leakage.
					toe of the end wall. (AT7)	Proper arrangement should be made
					23 The alternative power	r toper arrangement should be made.
					system for gate operation is	
					not working properly. (A19)	Proper remedial measures to be
						taken to prevent the leakage.
				Outlet	24. In the concrete chamber of	
					service gate, there is a	
					leakage through the concrete	
					from u/s side. (B5)	Neessan waaring shall be done in
				Instrumentation		consultation with IRD, Nashik.
					25. Only rain gauge &	
					piezometers provided-which	
					are not in working condition	Necessary repairs shall be done in
					(B9)	CONSUITATION WITH IKD, NASHIK.
					to damage or theft in	
					to ualliage of theit l.e.	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
					inadequate protection. (B9) 27. All the instruments are not in working order. (B9)	Necessary repairs shall be done in consultation with IRD, Nashik.
12	Name : Aralakalmodi (Un Gated) Tal. Khed Dist.Pune Year of completion : 2010 Location : Longitude 73°40'30 " Latitude 19°00'00 " Height : 40.61 m Gross Capacity : 42.87Mm ³ Spillway capacity : 963.21 m³/ sec Sr.No.In Large Dam Register 2009: MH09HH1672	11.05.2021 07.12.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Gallery/ pumps Gallery/Shaft	 Electrification arrangement has not been provided. (A8) There a problem in inspecting pump - details not given. (A8) There is a obstruction observed to preventing or impairing smooth operation. (A8) Deterioration of pump and associated equipment observed. (A8) There is a problem of inadequate drainage. (A10) Excessive seepage through porous pipe in gallery. (A10) Significant or excessive leakage along gallery/shaft / porous of parts of a part of a parts o	Electrification arrangement shall be provided. Necessary repairs should be carried out Necessary repairs should be carried out. Proper remedial measures to be taken to reduce seepage. Proper remedial measures to be taken to reduce leekage.
				Outlet	 porous drain observed details not given.(A10) 8. Seepage though porous pipes, foundation drains & monolith joints collected in gravity chamber @ d/s of EDA measured(A10) 9. There is no reduction of drainage through pipe(A10) 10. The energy dissipation arrangement is not working satisfactorily for all the discharges. (A14) 11.Emergency gate is not in operating condition. (B5) 	Necessary repairs should be carried out. Proper remedial measures to be taken to reduce leekage. Proper remedial measures to be taken in consultation with Mechanical Organization

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
	-		-	of Dam		
1	2	3	4	5	6	7
				Spillway Bridge	12.Structural members & joints needs painting. (B11) 13.The surface of steel works & paints is not satisfactory(B11) 14.The parapet or railing over the bridges are not sound, safe and painted.(B11)	Proper remedial measures to be taken in consultation with Mechanical Organization Proper remedial measures to be taken in consultation with Mechanical Organization
13	Name : Bhamaaskhed (Gated) Tal. KhedDist.Pune Year of completion : 2014 (Dam Portion)	11.05.2021 07.12.2021	Shri. S. D. Chopade, S.E., P.I.C., Pune	Junction of Earth work	1. The entire length of the conduit is not in perfect order & profile and free from offset, open joint, cracks & leakage.(A4)	Necessary repairs should be carried out.
	Location : Longitude 73⁰43'00" Latitude 18⁰15'00"	18.03.2022	E.E.	Hoists, cranes	2. The alternative power system for gate operation- Standby Genrator is required.(A19)	Alternative arrangement should be made.
	Height : 51.125 m Gross Capacity : 230.473Mm³		Nasik	Outlet	3. The rollers are not working properly.(A20)	Proper remedial measures to be taken in consultation with Mechanical Organization
	Spillway capacity : 1736 m [°] /			D/s Drainage	1 Drain at at 500m is not	Necessary repairs should be corriad
	Sec Sr No In Large Dam Register				4. Drain at ch., 500m is not working (B2)	out
	2009: MH09HH1559			Outlet	 Emergency Gate is not in operation due to concrete failure of side drums, broken rubber seals & Guide T is not in plumb. (B5) 	Proper remedial measures to be taken in consultation with Mechanical Organization
				Outlet Gates	 The stem rod for lifting the gates is not perfectly straight. (B5) 	Proper remedial measures to be taken in consultation with Mechanical Organization
					 Instruments like piezometers and uplift pressure cells are not in workings condition(B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.
					8. Leakages observed through	Necessary repairs should be carried

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
	-			of Dam		
1	2	3	4	5	6	7
					Service Gates. (Quantity not	out.
(d) E	kooutivo Engineer Niro Dight	Bank aanal Di	vision Bhalton	Diat Satara	mentioned). (B12)	
(u) E	Name: Veer (Coted)	Darik Carlai Di	Shri S D	Dist. Salara	1 Evenesive cooperation	Necessary repairs should be corried
14	Tal PurandarDist Puna	20.05.2021	Chonado	D/S Face	1. Excessive seepage/sweating	out
	Vear of completion :1965	24.11.2021	SE PIC		downstream face- sweating	out.
	Location ·		Pune		is observed in NOF portion	
	Longitude 74⁰5'55		1 ano		(A11)	
	Latitude 18⁰ 07'05 "			Body Wall	2. There is excessive seepage.	Necessary repairs should be carried
	Height : 39.11 m			,	sweating observed on the d/s	out
	Gross Capacity :278.49 Mm ³				face of the dam. (Details not	
	Spillway capacity :5154 m ³ /				given). (A11)	
	sec			Waste Weir	3. Guide wall joints on both	Necessary repairs should be carried
	Sr.No.In Large Dam Register			Bar	flanks are open &	out
	2009: MH09HH0116				strengthening of wall should	
					be Carried out.(A16)	
				Structural	4. There is signs of structural	Necessary repairs should be carried
				performance	distress noticed in the dam	out
				Craille and R	spillway of foundatuion. (A16)	Necessary, war size should be serviced
				Spillway &	5. Presence of displaced, offset	Necessary repairs should be carried
				EDA	icipte on orgon wore washed	out
					away at some locations	
					specially at date No 4 5 6 &	
					7(A16)	
					6. The foundation erosion or	Necessary repairs should be carried
					scour noticed near NRBC @	out
					Ch. 0/45 to Ch. 0/510. (A16)	
				Hoists, cranes	7. The hoists are working	Necessary repairs should be carried
					satisfactorily - Crane	out in consultation with Mechanical
1					modernization required.(A18)	Organization or under their advice.
1						
1					8. Problems observed while	Necessary repairs should be carried
1					inspecting hoist/ crane/	out in consultation with Mechanical
					operating mechanism	Organization or under their advice.
					details not given.(A18)	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	<u>6</u>	7
				Outlet & Gates	 9. The full length of the chains or wire rope of the hoist is not in sound condition and not free from broken strands.(A18) 10. Emergency gate(s). Operation is not smooth. (A20) 	Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice. Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice.
				Intake/Outlet Structure	11. Operation of outlet gate is not smooth. (A20)	Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice.
					 Evidence of abrasion, cavitation or scour on intake/outlet structure- Embedded parts of S. G. no. 4, 5, 6 are eroded and concrete around embedment is leached out(B5) 	Necessary repairs should be carried out
				Instrumentation	13. The evidence of degradation to condition of instrument (rusting,	Necessary repairs shall be done in consultation with IRD, Nashik.
				Outles	vandalism) observed. (B9) 14. Service Gate-Leakage through SG 5, 4, 6 observed after closer. (B12)	Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested				
ο		Inspection	Officer	Component	Noticed					
			-	of Dam						
1	2	3	4	5	6	7				
(e) Li	ft Irrigation Management Divis	ion, Pune			· ·					
15	Name: Nazare(Gated) Tal.PurandarDist.Pune Year of completion :1974 Location : Longitude 74 ⁰ 12'50" Latitude 18 ⁰ 17'30" Height :22.545 m Gross Capacity :22.316 Mm ³ Spillway capacity :2424.71	15.05.2021 05.12.2021	Shri.S. D. Chopade, SE, P.I.C., PUNE	EDA Outlet Gates	 There is a progressive erosion and retrogression in the tail channel.(A7) The stem rod for lifting the gates is not perfectly straight. (B5) 	Necessary repairs should be carried out Necessary repairs should be carried out in consultation with Mechanical Organization or under their advice.				
	m ³ / sec Sr.No.In Large Dam Register 2009: MH09MH0453									
(2)Su	(2)Superintending Engineer, Pune Irrigation Project Circle, Pune									
(a) Ex	cecutive Engineer, BhamaAskh	ed Dam Divis	ion, pune							
16	Name Temghar Tal. MulashiDist.Pune Year of completion : 2000 Location : Longitude: 73⁰ 32 ' Latitude : 18⁰ 27 '	19.11.2021	Shri.P.S. Kolhe SE PIPC Pune	Gallery/Shaft and Drainage	 Foundation gallery is also not accessible due to accumulation of wet soil & debris from Ch.420 to 705 m (A8). Safety issues - no hand rails, 	Suitable treatment should be carried out as per suggestion of Temghar Expert Committee for balance work.				
	Gross Capacity :107.96 Mm ³				drainage - slippery stairs(A8)	out				
	Spillway capacity: 626 m ³ / sec Sr.No.In Large Dam Register 2009: MH09HH1544				 There were heavy leakages during dam full condition which makes the separate measurement of seepage difficult. That's why V- notches & trapezoidal notches are installed @ D/s of dam. (A9) 	Suitable treatment should be carried out as per suggestion of Temghar Expert Committee for balance work				
					accessible From Ch. 420 m. to 700 m. due to flooded gallery. Drain hole	out as per suggestion of Temghar Expert Committee.				

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
					observations cannot be	
					done. But all leakages in	
					foundation gallery are	
					neasured at D/s or monorith	
					5 Out of 378 \/PDs only 78 are	Suitable treatment should be carried
					functioning remaining 100	out as per suggestion of Temphar
					are slightly functioning & 200	Expert Committee
					VPDs are not operational.	
					Cleaning & re drilling of these	
					VPDs is necessary.(A9)	
				Drains	6. The pumps are not physically	Suitable treatment should be carried
					accessible as they are in the	out as per suggestion of Temghar
					foundation gallery(A9)	Expert Committee.
					7. Sump well is choked due to	Necessary repairs should be carried
					the clogging of cement water	out
				EDA	in it.(A9)	Necessary repairs should be carried
				LDA	8. The tall pond cannot be	
					Q All the open drain holes are	Suitable treatment should be carried
					blocked and hence the tail	out as per suggestion of Temphar
					pond always remains	Expert Committee.
					flooded(A9)	
				Gallery/Shaft	10. Inadequate drainage -	Suitable treatment should be carried
				and Drainage	Due to drain hole water,	out as per suggestion of Temghar
					seepage/ leakages make	Expert Committee.
					staircase become	
					Suppery.(ATU)	
					11. Excessive seepage	Suitable treatment should be carried
					observed in foundation	out as per suggestion of Temphar
					gallery from Ch.420 to700 m	Expert Committee
					(A10)	
1					12. Excessive seepage	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
_	-			of Dam		
1	2	3	4	5	6	7
					observed in gallery, VPD at	
					C_{11} C_{12} C	
				Body Wall	13 The total seenage from	
				body wan	the porous pipes cannot be	
					measured due to heavy	
					leakage in gallery. The total	Suitable treatment should be carried
					leakage observed is 175.90	out as per suggestion of Temphar
					lps. 90% reduced leakage is	Export Committee
					observed as compared to	
					max leakage observed 2587	
					lps in 2015-16. (A10)	
				D/s Face	14. Seepage observed	
					during inspection, leakages	Suitable treatment should be carried
					observed at RL 705.60 &	out as per suggestion of Temphar
					leakage was 173.20 lps.	Export Committee
					175 00 lpc of EPI (A11)	Expert Committee
					15 Significant leakage at	
					Ch 517 00 (Qtv not given)	Cuitable treatment about the comind
					(A11)	Suitable treatment should be carried
				Body Wall	16. Śweating on D/s side	out as per suggestion of Temgnar
					were observed when dam	Expert Committee
					was at FRL(A11)	Suitable treatment should be carried
					17. When dam water level	out as per suggestion of Temghar
					was at FRL, there was	Expert Committee
					seepages & spray wall	Suitable treatment should be carried
					sprinkles & sweating on D/s	out as per suggestion of Temghar
				La cara e d'a ca	SIDE. (ATT)	Expert Committee
				Inspection	ro. Leaching is observed in	
				Gallery	(C1.373 III to)	Suitable treatment should be carried
					19. There is a considerable	out as per suggestion of Temghar
					leaching from the seepage	Expert Committee
					water & deposition of lime	Suitable treatment should be carried
					near the seepage exit spots.	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
1	2	2	4	of Dam	6	7
- 1	Ζ	3	4	Spillway	(A12)	I out as per suggestion of Temphar
				Opiliway	20 There is some leakage from	Export Committoo
					spillway portion (A15)	Expert Committee
					21 Minor seenage is observed	
					apporally at the joints in the	Suitable treatment should be carried
					collwov (A15)	out as per suggestion of Temphar
				Guide	Splilway. (A15)	Expert Committee
				walls/Divide	22. There is foundation erosion	
				walls	or scour noticed. (A16)	Necessary repairs should be carried
					23. Foundation of left side	out
					guide wall is scoured. (A16)	
					24. Severe springs or trickles	Necessary repairs should be carried
					are observed from the	out
					areasadjacent to the spray	Necessary repairs should be carried
					wall. (A16)	out
				Upstream	25. Deterioration observed on	Necessary repairs should be corriad
				Face	the upstream surface.	Necessary repairs should be carried
				1 400	Carryout the repair work as	out
				Instruments	per instruction of TDEC. (B8)	
					26. Instruments are not	Necessary action shall be taken in
					installed yet. (B9)	consultation with IRD, Nashik.
(b) E>	cecutive Engineer, NeeraDeogl	har Project Div	Ision, Sangvi(I	Bhatghar), Tal	Bhor, Dist. Pune.	
17	Name -Gunjawani (Gated)		Shri.P.S.	Crest of	1. Not provided an all-weather	Necessary repairs should be carried
	Tal. VelneDist.Pune			Dam	2 There is degradation to access	Uul. Necessary repairs should be carried
	Location ·		Pune		road (B6)	
	Longitude: 73° 37 '00"		Shri.H.T	Instrumente	3. Instruments installation work is	Necessary action shall be taken in
	Latitude :18° 18 '00"		.DHumal	monumento	in progress. (B9)	consultation with IRD, Nashik.
	Height : 52.825 m	18.11.2021	SE PIPC	Spillway	4. There is leakage through	Necessary repairs should be carried
	Gross Capacity :104.69 Mm ³		Pune	Gates	rubber seal adjacent to	out out in consultation with
	Spillway capacity: 1924 m³/				spillway wall portion &	Mechanical Organization

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component	Significant Deficiencies Noticed	Remedial Measures Suggested				
		•		of Dam						
1	2	3	4	5	6	7				
	sec Sr.No.In Large Dam Register 2009: MH09HH1552				irrigation limb vertic0al gate lift gate leakage problem.					
Supe	rintending Engineer, Sangli Irr	igation Circle,	Sangli			1				
(a) Ex	(a) Executive Engineer, Sangli Irrigation Division, Sangli									
18	Name : Morna T al. Shirala Dist.Sangali Year of completion : 1984 Location : Longitude 74⁰06'30 " Latitude 16⁰59'20 " Height : 29 10 m	25.05.2021 10.12.2021	Shri M.J.Naik. S.E.SIC Sangali	Outlet	 There were Leakage through HR Well(A6) Wire Rope of Hoist not in Sound Condition (A18) Obstructing in Preventing or of impairing smooth Operations (A20) 	It should be repaired properly in consultation Mechanical organization.				
	Gross Capacity : 21.18 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1101			Hoist	 4. Hoist mechanisms is faulty & Emergency gate mechanisms is faulty (B5) 	out out in consultation with Mechanical Organization				
19	Name : Yeoti-Mhasoli Tal. Karad Dist.Sangali Year of completion : 1989 Location : Longitude $74^{0}01'00"(E)$ Latitude $17^{0}10'00"(N)$ Height :36.00 m Gross Capacity : 7.30Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1101	27-05-2021 12-10-2021	Shri M.J.Naik. S.E.SIC Sangali	D/s Slope	Vegetation was observed on U/S &D/S Dam slope and Drain (B13)	Necessary repairs should be carried out.				
(b) Ex	cecutive Engineer , Takari Pum	House Divis	ion No.1, Devi	rashtre						
20	Name : Satpewadi barrage Tal. Walwa Dist.Sangali Year of completion : 2005 Location : Longitude 74⁰21'26 "(E) Latitude 17⁰06'51"(N)	27.04.2021 12.10.2021	Shri M.J.Naik. S.E.SIC Sangali	Abutment Contacts	 Due to River Flood in Aug.2019 both side slope pitching near abutment Eroded and embankment washed out (B15) 	It should be repaired properly				

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested				
1	2	3	4	5	6	7				
	Height : 37.50 m Gross Capacity : Mm ³ Proposed for updation in NRLD 2018									
(3) Si (2) Ex	(3) Superintending Engineer, Kolhapur Irrigation Circle, Kolhapur (a) Executive Engineer, Kolhapur Irrigation Division (North), Kolhapur									
(a) L/	(a) Executive Engineer, Koinapur irrigation Division (North), Koinapur.									
21	Name: Kadavi Tal.Shahuwadi Dist. Kolhapur Year of completion : 2000 Location : Longitude 73°52'30" Latitude 17°00'05" Height : 36.05 m Gross Capacity : 71.34 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1541	28.04.202124 .11.2021	Shri M. S. Surve SE, KIC Kolhapur	Outlet W.W. Bar Instruments	 Power Outlet wall on D/s face shoes heavy leakage (A4) Waste wier bar work still not completed by construction wing .U/S & D/S face of Waste weir bar needs pointing. (B7) Majority of instruments are in dead condition. Need new installation. (B9) 	Necessary repairs should be carried out out in consultation with Mechanical Organization It should be completed. Necessary repairs should be carried out Necessary repairs shall be done in consultation with IRD, Nashik.				
22	Name: Kasari Tal.Shahuwadi Dist. Kolhapu Year of completion : 2000 Location : Longitude 73°52'30" Latitude 17°00'05" Height : 36.05 m Gross Capacity : 71.34 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1541	28.04.2021 24.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Instruments	 Instruments not in working condition (B9) 	Necessary repairs shall be done in consultation with IRD, Nashik				
23	Name : Radhanagari (Gated) Tal. Radhanagari Dist. Kolhapur	19.04.2021 09.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Gallery & shaft	1. Problems accessing or inspecting gallery/shaft (obstruction) due to size is 3x4 ft (A8)					

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component		Noticed	
		-		of Dam			
1	2	3	4	5		6	7
	Year of completion :1954			D/s Face	2.	Significant leakage at Ch.420	Proper remedial measures shall be
	Location :					to 480m & Ch. 640 to715m	taken to reduce leakage.
	Longitude 73⁰57'40 "					on downstream face(A10)	
	Latitude 16º20'20''			EDA	3.	Scouring at D/S of the	After rechecking of deficiency by
	Height :42.83 m					service gates (Sluice gate)	competent field authority, Necessary
	Gross Capacity :936.56 Mm ³					(A14)	repairs should be carried out in
	Sr.No.In Large Dam Register				4.	Condition of energy	consultation with CDO Nashik.
	2009:					dissipation arrangement is	
	MH09HH0067					not satisfactory (A14)	
				Spillway	5.	Chains/ wire ropes required	It should be repaired properly
				/Gates		to replace heavy rusted	consultation Mechanical organization
						channels rusted need to	
						repairs (A18)	
					6.	Sluice gates & Automatic	
					_	gate to be repaired .(A20)	
					1.	There is problems with the	It should be repaired properly
						rollers .(A20)	consultation Mechanical organization
					8.	Seal angle is	
						damaged. (A20)	It should be use should use a shu
					9.	Fuicrum pin & lock plate nuts	It should be repaired properly
						rusted required to replace	consultation Mechanical organization
					10	(A20)	
					10.	to be repaired or replaced	It should be repaired properly
							consultation Machanical organization
					11	Gate cannot be closed @	consultation mechanical organization
					11.	ESI (A20)	It should be repaired properly
						T OL (A20)	consultation Mechanical organization
					12	Due to wire rope hoist	consultation mechanical organization
						service gate cannot be	It should be repaired properly
						lowered @ FSL(A20)	consultation Mechanical organization
				Hoists	13.	Emergency gate loading	concentration moonanioal organization
						operation is difficult & risky	
						@ FSL (A20)	
				Acces Road	14.	One bridge across channel	
						on sluice to need to travel	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		_
1	2	3	4	5	6	1
				Instruments Gates	 across the banks. (B6) 15. Additional bridge needed to react left entry(B6) 16. Instruments not installed except one rain gauge at dam site (B9) 17. The rubber seals required to be replaced. (B12) 	Necessary repairs shall be done in consultation with IRD, Nashik. It should be replaced properly in consultation Mechanical organization
24	Name : Warana (Gated) Tal. Shirala Dist. Sangli Year of completion : 1989 Location : Longitude 73⁰05'50 Latitude 17⁰08'10 "	22.04.2021 02.11.2021	Shri M. S. Surve SE, KIC Kolhapur	D/S Face	 On the day of present inspection 2.11.2021 rate of seeoage is 777.10 LPS Reservoir level is . 626.50 m. (A1) 	Proper remedial measures shall be taken to reduce leakage.
	Height : 77.00 m Gross Capacity 974.18 Mm ³ Sr.No.In Large Dam Register			Gallery	 There is seepage or leakage through the conduit surface. (A4) 	Proper remedial measures shall be taken to reduce leakage
	2009: MH09HH1542			Relief wells	 The relief wells needs regular surging (A5) 	Necessary work shall be carried out for easily accessible gallery.
				Gallery	 Problems accessing or inspecting gallery/shaft (obstruction)due to heavy leakage. (A8) 	Proper remedial measures shall be taken to reduce leakage.
					5. Any safety issues – Safety	Proper remedial measures shall be taken to reduce leakage
					6. Dewatering pumping station fully not operational. (A8)	Proper remedial measures shall be taken to reduce leakage
					 There is problem for inspecting pump due to gallery is flooded. (A8) 	Proper remedial measures shall be taken to reduce leakage

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
1	2	3	4	of Dam	6	7
•	E.				8. Drains holes are clogged(A9)	,
					9. There is substantial	Proper remedial measures shall be
					progressive reduction in the seepage through the	taken to reduce leakage.
					foundations. Due to choking	
					10. Seepage at lower level at RD	Proper remedial measures shall be
					230 to 330m	taken to reduce leakage.
					11. There is excessive	taken to reduce leakage.
					gallery/shaft (A11)	
					12. There is significant or	Proper remedial measures shall be
					excessive leakage at along	taken to reduce leakage.
				D/S Face	gallery RD 160 to 300	
				D/STace	m(A11)	Proper remedial measures shall be
					sweating at any locations on	taken to reduce leakage.
					the D/S Face of the dam -	
				Gallery	RD160 to 230 LHS. (A11)	It should be kept upder observation
					at RHS of inspection gallery.	&leaching material should be sent to MERI/ Lab for testing.
					15. There is considerable	It should be kept under observation
				leaching from the seepage	leaching from the seepage water. (A12)	MERI/ Lab for testing.
				Bouy waii	16. There is erosion, pitting or	Necessary remedial measure to be
					spalling of the concrete or	taken by permission of field competent authority.
				River Outlet	17. The overall condition of river outlet works/river sluices is	It should be repaired properly in consultation Mechanical organization
				Outlet gates	not satisfactory(A20)	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-	-	of Dam		
1	2	3	4	5	6	7
				Instrumentation	 The stem rods of HLIO & LLIO needs to be aligned. (B5) Majority of instruments are in dead condition. Need new installation(B9) 	It should be repaired properly in consultation Mechanical organization Necessary repairs shall be done in consultation with IRD, Nashik.
25	Name: Dudhaganga (Gated) Tal. Radhanagari Dist. Kolhapur Year of completion : 1989 Location : Longitude 74⁰1 '	19.04.2021 09.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Relief Well Gallery	 Relief wells are not functioning, chocked & needs cleaning(A5) Foundation gallery is flooded and hence not easily accessible (A8) 	They should be cleaned and made functional. Necessary work shall be carried out for easily accessible gallery.
	Height : 85.30 m Gross Capacity : 719.12 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1226				 For safety issues Lighting arrangement is deteriorate (A8) Porous pipe in M-7 & M-8 are clogged, foundation drain holes in M-3 to M-5 & M-8, M-9 should be cleaned(A9) There is excessive seepage/sweating along gallery/shaft (A9) 	Proper lighting arrangement should be provided It should be kept under observation and necessary remedial measure to be taken by permission of field competent authority. It should be kept under observation and necessary remedial measure to be taken by permission of field competent authority.
				Body Wall	 6. There is excessive seepage/sweating along gallery/shaft- seepage at staircase in M-7(A10) 7. There is Excessive seepage/sweating on downstream face of Monolith no. 7, sweting on overall D/s face 	It should be kept under observation and necessary remedial measure to be taken by permission of field competent authority. It should be kept under observation & leaching material should be sent to MERI/ Lab for testing.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
	-			of Dam	-	_
1	2	3	4	5	6	7
					observed(A11) 8. Sweating observed in M-1 to M-4 & excessive seepage observed in M-7 to M-8(A11)	Proper remedial measures shall be taken to reduce leakage
					9. There is considerable leaching from the seepage water (A12)	
				Spillway	10. The embedded parts of spillway gates, emergency gates and stop-logs in Is not sound condition and free	Proper remedial measures to be taken in consultation with Mechanical Organization
				River Sluice	from corrosion (A20) 11. The overall condition of river outlet works/river sluices satisfactory (A20)	Proper remedial measures to be taken in consultation with Mechanical Organization
				Instrumentation	12. Majority of instruments are in under repair. (B9)	Proper remedial measures to be taken in consultation with IRD, Nashik.
26	Name: Chikotra Tal. Ajara Dist. Kolhapur Year of completion : 2001 Location : Longitude 16°13'30" Latitude 74°12'23"	23.04.2021 19.10.2021	Shri M. S. Surve SE, KIC Kolhapur	D/s Face	1Two seepage release inflow is observed in conduit at Ch. 110 & 170 m from service gate. Also observed some corrosion boils (A4)	Mapping of sweating with respect to reservoir water level should be done.
	Height : 59.953 m Gross Capacity : 43.115 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1226			Instrumentation	2 Instruments not installed(B9)	Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-		of Dam		
1	2	3	4	5	6	7
27	Name: Kumbhi (Gated) Tal. Gaganbavda Dist. Kolhapur Year of completion : 2007 Location : Longitude73°51'49" Latitude 16°31'29" Height : 42.58 m Gross Capacity : 76.88 Mm3 Sr No In Large Dam Register	12.05.2021 24.10.2021	Shri M. S. Surve SE, KIC Kolhapur	Gallery/ Conduit Instrumentation	 The conduit structurally sound but minor leakages are observed in conduit (A4) Instruments not installed (B9) 	After necessary investigation, repairs should be carried out to stop the leakage. Proper action shall be taken in consultation with IRD, Nashik.
	2009: MH09HH1671					
28	Name: Palaeshwer Tal. Shahuwadi Dist. Kolhapur Year of completion : 2011	28.04.2021 21.11.2021	Shri M. S. Surve SE, KIC Kolhapur	W.W.Bar	1 In Monsoon stone masonry of waste weir bar was damaged severely (B7)	Necessary remedial measures should be carried out.
	Location : Longitude73°52'30" Latitude 17°00'15"				2 The coping was damaged with masonryportion (B7)	Necessary remedial measures should be carried out.
	Height : 42.15 m Gross Capacity : 9.11 Mm3 Sr No In Large Dam Register			Instrumentation	3 Whole masonry wall needs repair urgently.(B7)	Necessary remedial measures should be carried out. Proper action shall be taken in
	2009: MH09HH1671					consultation with IRD, Nashik.
29	Name: Tulshi Tal. Radhanagari Dist. Kolhapur Year of completion : 1978 Location : Longitude 74°01'00" Latitude 16°31'15"	19.04.2021 09.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Downstream of Dam	 Measured rate of seepage on 29/08/2021 is 15 lps at reservoir level 616.910 (A1) There is signs of water logging, slushy conditions or growth of aquatic weeds 	Source of the seepage should be identified and necessary arrangement should be done to stop the seepage. Necessary remedial measures should be carried out.
	Height : 48 .6 m Gross Capacity : 96.28 Mm ³ Sr.No.In Large Dam Register			Gates	on the downstream of the dam (A2)3 The alternative power system	Necessary remedial measures should

Sr.N	Dam Features	Date of	Inspecting	Main Component	Significant Deficiencies	Remedial Measures Suggested
Ŭ		inspection	Oncer	of Dam	Noticed	
1	2	3	4	5	6	7
	2009: MH09HH0726			Instrumentation	 for gate operation is not working properly (A19) 3 There is Concrete /masonary deterioration (B8) 4 Instruments not installed except one rain gauge at dam site (B9) 	be carried out. Necessary remedial measures should be carried out. Proper action shall be taken in consultation with IRD, Nashik.
30	Name: Upwade Tal. Karaveer Dist. Kolhapur Year of completion : 1995 Location : Longitude 74°02' Latitude 16°38' Height : 32.81 m Gross Capacity 2.71 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH0726	05.05.2021 24.10.2021	Shri M. S. Surve SE, KIC Kolhapur	Instrumentation	1. Instruments not installed. (B9)	Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested					
ο		Inspection	Officer	Component	Noticed						
				of Dam							
1	2	3	4	5	6	7					
b)Exe	b)Executive Engineer , Medium Project Division No2, Kolhapur										
31	Name: Ghatprabha (Phatakwadi) Tal. Chandgad Dist. Kolhapur Year of completion : 2009 Location : Longitude 74°04'20" Latitude 15°56'45"	07.05.2021 30.11.2021	Shri M. S. Surve SE, KIC Kolhapur	General	1.There is obstructions due to excessive rainfall with land slide, large size boulders with soil & guide wall is collapsed in the stilling basin (A14)	Guide wall shall be get repaired as suggested by Design Dn. (MD2)CDOTo avoid land slide obtain the opinion from Sr.Geologist, Geology Dn CDO Nashik and do the needful.					
	Height : 48 .30 m Gross Capacity : 43 .75 Mm³ Sr.No.In Large Dam Register 2009:			W.W.Bar	2 Right side guide wall is Collapsed due to heavy rainfall and land slide On left side of W.W. there is seepage through	Guide wall shall be get repaired as suggested by Design Dn.(MD2)CDO					
	MH09HH1900				saddle dam & gradual land slide in D/S portion of dam. (A16) 3.End weir is not completed (A17)	Proper action shall be taken to complete it.					
				End Weir	4 The service gate vibrates more while operating service gate needs repair. There is No	consultation Mechanical organization					
				Outlet Gates	supply of electricity on dam site Generator is necessary Maintains and repairing of						
					service and emergency gate is necessary (A20)	It should be repaired.					
					5 Small amount of leakages was observed through waste weir(B7) Instruments not installed (B9)	Proper action shall be taken in consultation with IRD, Nashik.					
				W.W.Bar	7.Some Pitching under side of well bridge is disturbed (40sq.m(B15)	It should be repaired					
32	Name: Jambre Tal.Chandgad Dist. Kolhapur	07.05.2021 30.11.2021	Shri M. S. Surve SE,	Emergency Gate	1. Rubber seals slot are on opposite(wrong) side needs	It should be repaired properly consultation Mechanical organization					

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component of Dam	Noticed	
1	2	3	4	5	6	7
	Year of completion : 2013 Location : Longitude 74°06'40" Latitude 15°52'47" Height : 58 m		KIC Kolhapur		Repairing .Emergency gate is not in plumb line need maintaince (B5) 2. There is not providing an all-	
	Gross Capacity : 23.23 Mm ^o Sr.No.In Large Dam Register			Crest of Dam	weather road surface.(B6)	Necessary remedial measures should be carried out.
	2009: MH09HH1925			Instrumentation	3. Instruments not installed (B9)	Proper action shall be taken in consultation with IRD, Nashik.
33	Name: Jangamhatti Tal.Chandgad Dist. Kolhapur Year of completion : 2005 Location : Longitude 74°17'00" Latitude 15°51'30" Height : 31.40m Gross Capacity : 34.21 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1365	15.05.2021 21.11.2021	Shri M. S. Surve SE, KIC Kolhapur	W. W. Bar Instrumentation	 Excess amount of leakages was observed through waste weir B7) Instruments not installed(B9) 	Necessary remedial measures should be carried out. Proper action shall be taken in consultation with IRD, Nashik.
34	Name: Khleloshi Tal.Radhanagari Dist. Kolhapur Year of completion : 2010 Location : Longitude 16°31'30" Latitude 73°49'53" Height : 38.60 m Gross Capacity : 5.603 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1365	19.04.2021 09.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Instrumentation	1. Instruments not installed(B9)	Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
			-	of Dam	-	
1	2	3	4	5	6	7
35	Name: Patgaon Tal.Bhudargad Dist. Kolhapur Year of completion : 2007 Location : Longitude 73°56'15" Latitude 16°07'09" Height : 37.90m Gross Capacity :105.242 Mm³ Sr.No.In Large Dam Register 2009:	23.04.20211 9.10.2021	Shri M. S. Surve SE, KIC Kolhapur	Instrumentation	1. Instruments not installed(B9)	Proper action shall be taken in consultation with IRD, Nashik.
	MH09HH1365	rigotion Divisi	an (Sauth) Kal			
(b) Ex	cecutive Engineer, Kolhapur Ir	rigation Division	on (South) Kol	napur		
36	Name: Phaye Tal.Bhudargad Dist. Kolhapur Year of completion : 2005 Location : Longitude 74°04'15" Latitude 16°07'04" Height : 34.12m Gross Capacity : 3.932 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1629	23.04.2021 19.10.2021	Shri M. S. Surve SE, KIC Kolhapur	Gallery/Well	 There is structural damages to the intake well 6 holes are found at various level(A4) There is leakage observed through the well proper and the conduit (A4) There is damage noticed to the conduit concrete, breast wall and gate slots (A4) Instruments not installed.(B9) 	It should be repaired properly. It should be repaired properly to reduce leakages. It should be repaired properly. Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-	_	of Dam		
1	2	3	4	5	6	7
37	Name: Chitri Tal.Chargadist Dist. Kolhapur Year of completion : 2011 Location : Longitude 74°15'26"	26.04.2021 30.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Gallery/ Conduit Instrumentation	 Steel plates provided D/s of conduit portion are damaged.(A4) Instruments not installed (B9) 	Necessary remedial measures should be carried out. Proper action shall be taken in
	Latitude 15°52'49" Height : 33.05 m Gross Capacity : 7.00 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1889					consultation with IRD, Nashik.
38	Name: Kitwad Tal.Ajara Dist. Kolhapur Year of completion : 2004 Location : Longitude 74°09'30" Latitude 16°04'15" Height : 55.11m Gross Capacity : 53.414 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1889	26.04.2021 30.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Instrumentation	1 Instruments not installed (B9)	Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main		Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component		Noticed	
		-	_	of Dam			
1	2	3	4	5		6	7
39	Name: Kondoshi Tal.Bhudargad Dist. Kolhapur Year of completion : 2000 Location : Longitude 74°09'03" E Latitude 16°04'15" N Height : 30.27m Gross Capacity : 2.76 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1889	22.04.2021 19.10.2021	Shri M. S. Surve SE, KIC Kolhapur	Instrumentation	1	Instruments not installed (B9)	Proper action shall be taken in consultation with IRD, Nashik.
40	Name: Lakikatti Tal.Chandagad Dist. Kolhapur Year of completion : 2000 Location : Longitude 15°55'30" N Latitude 74°20'0" E Height : 36.34m Gross Capacity : 9.239 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1889	15.05.2021 21.11.2021	Shri M. S. Surve SE, KIC Kolhapur	Outlet Gates	1	The stem rods for lifting the gates is not perfectly straight(B5) Instruments not installed (B9)	It should be repaired properly consultation Mechanical organization Proper action shall be taken in consultation with IRD, Nashik.

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
41	MegholiUngated Tal. Bhudergad Dist. Kolhapur Year of completion : 2000	23.04.2021	Shri M. S. Surve SE, KIC Kolhapur	Seepage Measurrment	Due to geological condition of the strata in the foundation, some seepages are observed in	Necessary remedial measures are done in comsultation with CDO Nashik
	Location :				the downstream.	
	Longitude 16°11'03 N				Leakages are not observed from	
	Latitude 74°07'00 E				s waste weir bar but due to	
	Height : 34.12 m				peculiar geological conditions	
	Gross Capacity : 3.932 Mm ³				Like dykes in waste weir bar	
	Sr.No.In Large Dam Register				(A15)	
	2009:					
	MH09HH1536					
(4) Sı	perintending Engineer, Satara	Irrigation Cir	cle, Satara			
(a	a) Executive Engineer, Satara	Irrigation Divis	sion, Satara			
42	Name : Dhom (Gated)	01.06.2021	Mr.Doiphode	Dam Body	1. Junction of Earthwork with	After rechecking of deficiency by
	Tal. Wai Dist. Satara	20.12.2021	S. L.		Masonry/ Concrete Dam	competent field authority, Necessary
	Year of completion :19/6		SE, S.I.C.,		Entire length of Conduct is	repairs should be carried out in
	Location :		Salara		not in perfect order and	consultation with CDO Nashik.
	Longitude 73 40				profile and not free from	
					offsets open Joints cracks	
	Gross Capacity :332.00 Mm ³				and Leakage (A4)	
	Sr No In Largo Dam Pogistor					Necessary remedial measures should
				Downstroom	2 Excessive seepage/	he carried out
				Downstream	sweating observed in d/s	be carried out.
	MINU9HIN055			гасе	section of dam.(A11)	•
					3 Significant leakage on d/s	Necessary remedial measures should
					face of dam observed	he carried out
					details not given (A11)	be carried out.
					4 Guide wall of canal HR	
					structure damaged and	
					Collapsed. (A16)	Nocossary romodial moasures should
				Guide walls	5 The alternative power	be carried out.
					system needs renovation	
					iveeas Express Feeder	Necessary remedial measures should
				Outlet Gates	for gate Operation (A19)	be carried out.
					6 The evidence of	

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
				Instrumentation	degradation to condition of instrument (rusting, vandalism) – observed (B9) Piezometers: Out of 13 Casagrande piezometers 10 piezometers are not in working condition. (B9)	Necessary repair should be carried out in consultation with IRD, Nashik
					 Pointing of upstream face of dam not in good condition (B11) 	Proper remedial measures shall be taken.
					8 Because of canal rotation water heavy leakages could not be stopped(B12)	Necessary remedial measures should be carried out.
				Upstreme Face	9The portion of upstream and downstream of dam is not	Necessary remedial measures should be carried out.
				Downstream face	easily accessible due to growth of bushes grass and trees (B13)	
				Acces Road	10 For Pier No. 1, 4, 5 - some pitting of concrete of wall plates observed (B14)	Proper remedial measures shall be taken.
				Spillway		
43	Name : DhomBalkavadi (Gated) Tal. Wai Dist. Satara Year of completion : 2006	01.06.2021	Mr.Doiphode S. L. SE, S.I.C., Satara	D/s of Dam	1. Slushy condition or water logging immediately downstream of dam observed.(A2)	Proper remedial measures shall be taken.
	Location :			Gallery	2. For Gallery work like bottom	Proper remedial measures shall be

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
	Longitude 73⁰ 42' 30'' Latitude 17⁰51'00'' Height : 65.10 m Gross Capacity : 115.53 Mm ³	20.12.2021			flooring And proper arrangement for drainage of VDP is to be needed.(A8)	taken.
	Sr.No.In Large Dam Register 2009: MH09HH1655			Water Conveyance Structure	3. There are not proper arrangements made for the measurement of seepage into the gallery the seepage not measured separately from-Porous pipes,Foundation	Proper remedial measures shall be taken.
				Gallery	 drains,Monolith joints(A8) 4. Out of 14,13 VPD Piers are blocked with leachate material and due to which only VPD running fully with extreme turbulent flow like waterfail,it shows serious concern @ the maintenance of VPD (A9) 5 As water level during inspection was very low hence no leakage is 	It should be kept under observation & leaching material should be sent to MERI/ Lab for testing. Necessary remedial measures should be carried out.
				Gates EDA Outlet Gates	 observed .when water level rises there is heavy lekages is observed through one of the V.D.P (A10) 6 Leakage through longitudinal duct of ICPO. (A10) 7 Stagnant water observed in stilling basin. Needs dewatering.(A14) 8 Outlet Gates not Provided. (B5) 	Necessary remedial measures should be carried out. Necessary remedial measures should be carried out. Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary remedial measures should

Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component	Significant Deficiencies Noticed	Remedial Measures Suggested
		•		of Dam		
1	2	3	4	5	6	7
					9 Concrete or Masonary Deteroration.(B8)	be carried out.
				Instrumentation	10.The instruments are installed in the body of dam but are not yet connected properly to dial gauges. So they are not in working condition.(B9)	Necessary repair should be carried out in consultation with IRD, Nashik.
(b) E)	recutive Engineer, Krishna Irrig	nation Divisio	n Satara			
44	Name Kanher (Gated) Tal. Satara Dist. Satara Year of completion : 1986 Location : Longitude $73^{0}55'$ Latitude $17^{0}45'$	2805.2021 02.12.2021	Mr.Doiphode S. L. SE, S.I.C., Satara	Gallery	Damage noticed to the Conduit Concrete- Secondary Concrete Damaged Seepage noticed around the Conduit (A4) The relief wells (4 nos.) are not	Necessary repairs be carried out.
	Gross Capacity : 286.00 Mm ³ Sr.No.In Large Dam Register			Relief wells	functioning well. (A5) Safety issues observed like inadequate handrails, ventilation	out
	2009: MH09HH1141			Body Wall	Problems of inadequate drainage observed, like slippery stairs, water logging of gallery, clogged porous or foundation drains. (A8) The problems ensuring correct functioning of instrument i.e. lighting ventilation, etc (A8)	Necessary repairs should be carried
				Gallery	5The other evidence of thedrain	Out

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
0		Inspection	Officer	Component	Noticed	
1	2	3	4	of Dam	6	7
-	2	3	4	5	being blocked/ having reduced	1
				Drains	section observed. (A9) 6. The foundation and porous	Necessary repairs should be carried out to clean the drains.
					(A9)	
				Gallery	 55 porous pipes are not in function, needs to be cleaned.(A9) 	Necessary repairs should be carried out to clean the drains.
				EDA	 8. Excessiven Seepage/ sweating at any location along gallery/shaft observed Significant leakage is observed. Location details not given (A10) 9 There has been considerable leaching from the seepage water and deposition of lime near the seepage exit spots. (A12 10. The energy dissipation arrangement is not working satisfactorily- all concrete washed out, lining damaged for irrigation outlet. (A14) 11. The foundation erosion or scour noticed in d/s side of guide wall of waste weir.(A16) 	Necessary repairs should be carried out to clean the drains. Necessary repairs should be carried out Leaching material should be tested and remedial measures should be carried out as per CWPRS,Pune Necessary repairs should be carried out
				Guide walls/Divide walls	12. There is surface erosion damaged caused to face or body of such walls-LHS guide wall damaged. (A16)	Necessary repairs should be carried out

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-	-	of Dam		
1	2	3	4	5	6	7
					13. The scour noticed on the	Necessary repairs should be carried
					immediate downstream - on right	out
					retrogression is observed. Some	
				End Weir	pitting of surface observed	Necessary repairs should be carried
					(A17)	out
					14. Field officers reported that,	
					goliath /gantry crane is not	
					functioning properly	
					(A18)	
				Lisist/Crans	15.Hoist of EG of power house	Necessary repairs should be corriad
				HOISI/Crane	16 Alternate new r system of	Necessary repairs should be carried
					date operation needs	Organization
					replacement.(A19)	organization
					17.Operation of outlet gate is not	Necessary repairs should be carried
					smooth (A20)	out in consultation with Mechanical
					18. The stem rods for lifting the	Organization.
					gates is not perfectly straight	Necessary repairs should be carried
				Outlot Cotoo	(B5)	Out in consultation with Mechanical
				Outlet Gales		Organization.
					19.Instruments are not	Necessary repairs should be carried
					Infunction. (B9)	out in consultation with Mechanical
				Instrumentati	20. Problems observed while	Organization.
				on	inspecting instruments-	
					details not given(B9)	Nocossary ropair should be carried
				Catac		out in consultation with IRD Nashik
				Gales	21. Minor Leakages from Radial	out in conouncation with http://dofint.
					Gate no.1 is observed(B12)	
				Access Road		Necessary work shall be carried out
					22. The portion of upstream and	
					of dam is not easily accessible	Necessary repairs should be carried
					due to growth of bushes	out in consultation with Mechanical
Sr.N o	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
-----------	--	--------------------------	---	---	---	--
1	2	3	4	5	6	7
					grassand trees. (B13)	Organization.
45	Name Urmodi (Gated) Tal. Satara Dist. Satara Year of completion : 2012 Location : Longitude 73 ⁰ 54'40" Latitude 17 ⁰ 40' 00" Height : 51.10 m Gross Capacity : 282.14 Mm ³ SpillwayCapacity :3840 Cumecs Sr.No.In Large Dam Register 2009: MH09HH1594	18.05.2021 02.12.2021	Mr.Doiphode S. L. SE, S.I.C., Satara	Instrumentation Spillway Gates	Instruments need to repair. (B9) General condition of rubber seals- Gate no. 2 showing bottom rubber seal leakage at middle part	Necessary repair should be carried out in consultation with IRD, Nashik Necessary repairs should be carried out in consultation with Mechanical Organization
(c) Ex	cecutive Engineer, Koyana Irrig	gation Divisio	n, Koyananagai	ſ	-	
46	Name: Kolkewadi (Gated) Tal. Chiplun Dist. Ratnagiri Year of completion : 1975 Location : Longitude 73⁰38' 50'' Latitude 17⁰ 25' Height : 66.00 m	08.05.2021	Mr.Doiphode S. L. SE, S.I.C., Satara	Gallery/Shaft Condition D/s Face Seepage	 Total no. of foundation holes are 119, 109 are in chocked condition. (A9) Excessive seepage /sweating observed on downstream face(A11) Measured rate of seepage 	Necessary repairs should be carried out to clean the holes. Necessary repairs should be carried out to clean the holes. Necessary repairs should be carried
	Gross Capacity : 36.22 Mm³ Sr.No.In Large Dam Register	20.11.2021		Measurment	flow is 283.96 lpm, in one day inspection on 06/05/2021.	out to reduce seepage

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
		-	-	of Dam		
1	2	3	4	5	6	7
	2009: MH09HH0527				(A11)	
				Gallery	 Leachatedeposition observed all over gallery portion. Excessive seepage and leaching observed through the body of the dam and the foundation. (A12) 	Leaching material should be tested and remedial measures should be carried out as per CWPRS,Pune
				Seepage Measurment	5. Total leakage is 319.22 LPM, total seepage during first filling in May 1975 was 43.00 LPM. (A15)	Necessary repairs should be carried out to reduce seepage
				Spillway Gates	 6. Stoplog or Emergence Gate not Provided (B5) 7. Abrasion of the glacious 	Necessary repairs should be carried out in consultation with Mechanical Organization
				Spillway and Energy Dissipation Structure	concrete at few locations (especially near upper tangent point of the ogee) is observed. (B8)	Necessary repairs should be carried out
47	Name: Koyana (Gated) Tal. Patan Dist. Satara	08.05.2021 20.11.2021	Mr.Doiphode S. L. SE, S.I.C.,	Gallery	 Major number of drain holes choked. (number of holes not mentioned) (A9) 	Necessary repairs should be carried out to clean the holes
	Year of completion : 1967 Location : Longitude 73⁰44' 26'' Latitude 17⁰ 23'00'' Height : 103.02m Gross Capacity : 2980.68		Satara	Energy Dissipation Structure	2. Evidence of abrasion, cavitations or scour on dissipation structure observed - Surface of stilling basin apron 3 cm to 13cm eroded. (A14)	Necessary repairs should be carried out
	Mm³ Spillway Capacity : 5742.25cumecs Sr.No.In Large Dam Register			EDA	3. The energy dissipation arrangement is not working satisfactorily for the all discharges. (A14)	Necessary repairs should be carried out Necessary repairs should be carried
	2009: MH09UH0100			Outlet gates	4. There are vibrations and noise noticed in operation of	out

Sr.N	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
ο		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
				Instruments	outlet gates. (B5) 5. There is a evidence of degradation to condition of instrument (rusting, vandalism) - details not given. (B9)	Necessary repairs should be carried out
				General Condition	6. Appropriate cross drainage work need to be provided to access road.(B6)	Necessary repairs should be carried out
				Instruments	7. There is a evidence of degradation to condition of instrument (rusting, vandalism) - details not given. (B9)	Necessary repairs should be carried out
				Stilling Basin	8. Stilling Basin observed flooded. Due to standing water instilling basin it could not be inspected.(A14)	Necessary repairs should be carried out
				Spillway Gates/Sluice gates	9 Stop log of penstock No.1 & 2 and river sluice gate couldnot be lowered totally due to rusted guide tees.(B5)	Necessary repairs should be carried out in consultation with Mechanical Organization
					10 Stop log gate of river sluice is not operated up to seal bottom level from last many years due to wear & tear of guide T- valve.(B10)	Necessary repairs should be carried out in consultation with Mechanical Organization

[B] C	[B] Chief Engineer (S.P.),Water Resources Department, Pune									
(1) Su	(1) Superintending Engineer, Kukadi Irrigation Circle, Pune									
(a) Ex	(a) Executive Engineer, Kukadi Irrigation Dn No. 1, Narayangaon, Dist.Pune									
48	Name: Manikdoh (Gated)	18.05.2020	Shri H.T.	Gallery	1.	Safety issues like	Providing proper draining			
	Tal. Junnar Dist. Pune	26.11.2020	Dhumal			inadequate handrails,	arrangement seepage in the gallery.			
	Location :		SE KIC, Pune			observed Problem to	suitable treatment on unstream			
	Longitude '73 ⁰ 49'		1 une			inspect the pump observed	surface			
	Latitude :19º 14'					The deterioration of pump				
	Height : 57.80 m					and associated equipment				
	Gross Capacity :308.06 Mm ³					observed. (A8)				
	Spillway apacity: 143m³/sec				2.	Problems of inadequate	The foundation and porous holes			
	Sr.No.In Large Dam Register					drainage (slippery stairs,	shall be cleaned periodically.			
	2009:					water logging of gallery,				
	MINUSINI 1060					foundation drains of				
						observed (A8)				
					3.	Problem to inspect the pump	Necessary repairs should be carried			
						observed - pumps are	out			
						inworking condition -				
						continuous dewatering)				
						(A8)				
					4.	The deterioration of pump	Necessary repairs should be carried			
						and associated equipment	out			
					5	The foundation and porous	The foundation and porous holes			
					•.	holes not cleaned	shall be cleaned periodically.			
						periodically, with reaming				
						tool and air water jetting.				
				5		(A9)				
				Body Wall	6.	There has been a tendency	Necessary repairs should be carried			
						tor gradual reduction of	out			
						progressive appearance of				
						sweating on the downstream				
						face of the dam. (Location				
						not mentioned) (A9)				
					7.	Excessive	Necessary repairs should be carried			
						seepage/sweating along	out to reduce seepage			

1	
	gallery/shaft observed
	(location - ch. 435 to 600)
	(A10) Necessary repairs should be carried
	Significant or excessive out to reduce seepage
	leakage along gallery/shaft /
	porous drain observed.
Downstream	(A10) Necessary repairs should be carried
Face	9. It is observed that there is out to reduce seepage.
	excessive seepage,
	sweating on the downstream
	face of the dam (Location
Energy	not mentioned) (A11) Necessary repairs should be carried
Dissipation	10 Excessive seepage and out to reduce seepage
Structure	leaching through the body of
Olidolaio	the dam and the foundation -
	Leaching observed at left
Galleny	quide wall (A12) Necessary remedial measures
Callery	11 There has been should be corried out Leasthed
	appoiderable leaching from material to be called out. Leached
	the second weight and weight to be
	the seepage water and a record of quality and weight to be
	deposition of lime near the maintained. Leaching materia
	seepage exit spots. should be tested from Lab.
	(Location not mentioned)
EDA	(A12) Necessary repairs should be carried
	12. Obstructions observed in or out.
	immediately downstream of
	dissipation structure -needs
	nalla regradation. (A14) Necessary repairs should be carried
	13. Spalling of concrete out.
	observed at some places.
	(Location not mentioned
Upstream	(B8) Necessary repairs should be carried
Face	14. The pointing on upstream out.
	face of the dam is not in
Seepage	good condition. (B8)
Measurment	15. The approximate quantity of
	the leakage through the
Outlet Gates	gates not provided. (B10) The repairs should be carried out
	16. The Surface of Gate and through mechanical organization
	Paint deteriorated (B11)

49	Name: Wadaj (Gated) Tal. Junnar Dist. Pune Year of completion : 1982 Location : Longitude :73°52'30"E Latitude :19°09'00" N Height :28.00 m Gross Capacity :36 Mm ³ Spillway apacity:1426m ³ /sec Sr.No.In Large Dam Register 2009: MH09HH1006	05.06.2021 11.11.2021	Shri S.M. Sangale SE KIC, Pune	Water Conveyance Structure Spillway Gates Instruments Spillway Gates	1. 2. 3. 4. 5. 6.	The relief wells are not in good working condition and are not functioning well. (A5) To the immediate left side of non overflow section (NOF) it shows heavy leakages, records of the same is maintained by field officiels(A10) There is an evidence of seepage or leakage from water conveyance structure at ch. 435m. (A11) Gate 1 & 3 is not working smoothly (A20) The instruments are not installed29 working, 40 not working. (B9) Piezometers (i) Stand pipe - 16 nos not working condition (B9) (ii) (ii) Casagrande - 19 nos. - not in working condition(B9) The condition of the steel surface and the surface paint deteriorated - gate 3 & 5 is leakage through bottom rubber seal. (B11)	Necessary repairs should be carried out. Necessary repairs should be carried out in consultation with Mechanical Organization. Necessary repair should be carried out in consultation with IRD, Nashik Necessary repairs should be carried out in consultation with IRD, Nashik Necessary repairs should be carried out in consultation with IRD, Nashik Necessary repairs should be carried out in consultation with Mechanical Organization.
50	Name : Dimbhe (Gated) Tal. Ambegaon Dist. Pune Year of completion : 2001 Location : Longitude 74⁰44'30''E Latitude 19⁰5'45'' N	15.05.2021 11.11.2021	Shri S.M. Sangale SE KIC, Pune	Gallery	1.	Problems of inadequate drainage (slippery stairs, water logging of gallery, clogged porous or foundation drains, etc) observed. (A8)	Seepage in the gallery to be minimised by suitable treatment to upstream portion

Gross Capacity :228 22 Mm ³		absorved (A8)
Spillwov conscitut 2970 m ³ /		2 The obstruction observed
		5. The obstruction observed
Sec On No. In Lanna Dam Davistan		preventing of impairing
Sr.No.In Large Dam Register		smooth operation (A8)
2009:		4. Not mentioned anything
MH09HH1558		about deterioration of pump
		and associated equipment
		(A8)
		5. The flow in the drain is
		noticeably sporadic/
		irregular(A8)
		6. The foundation and porous Porous pipes & drain holes should
		holes not cleaned be cleaned for proper functioning.
		periodically, with reaming
		tool and air water jetting.
		(A9)
		7. There has been a tendency Quantum of seepage should be
		for gradual reduction of monitored monolithwise.
		drainage through nines and
		progressive appearance of
		sweating on the downstream
		face of the dam (Location
		not mentioned) (AQ)
		allon/chaft / porcus drain
		observed (location not
		montioned) (A10)
		0 There has not hear Seenage in the collect, to he
		9. There has not been seepage in the gallery to be
		reduction in the cooperate upstream partian
		through the foundations
		Coupe not mentioned / no
		cause not mentioned / no.
		of choked holes hol situat (A10)
	Deventere	given.(A10) Seepage is to be minimised by
	Downstream	10. Excessive seepage/ suitable treatment to upstream
	Face	Swearing inforgenous on portion
		downstream race. Significant
		leakage on downstream face
		observed (location not
		mentioned) Seepage water

					springs observed in the	
					downstream area (A11)	and
				Gallery	11. Leachate deposition weighed & record should	be
				,	observed. (A12) maintained. Leaching material to	be
					12. There has been tested from lab.	
					considerable leaching	
					observed from the seepage	
					water and deposition of lime	
					near the seepage exit spots.	
					(A12) Necessary repairs should be car	ried
				Energy	13. Problems observed out	
				Dissipation	inspectingenergy dissipation	
				Structure	structure, due to flooded flip	
					bucket. (A14) Necessary repairs should be car	ried
				D/s face	14. Obstructions observed in or out	
					immediately downstream of	
					dissipation structure (near	
				_	bridge over river) (A14) Necessary repairs should be car	ried
				Energy	15. The concrete surface of the out	
				Dissipation	stilling basin & apron is not	
				Structure	In good condition. (details	
				LI/a Clana	not given) (A14) Necessary repairs should be car	riea
				U/S Slope	disturbed et come	
					places(R8)	riod
					17 Concrete/masonny	lieu
					deterioration observed (B8) Necessary repair should be carrie	Ы
				Instruments	18 The instruments like plumb out in consultation with IRD Nash	ik
				motramento	bob. pressure cells are not	
					installed (B9). Necessary repairs should be carri	ed
				Outlet Gates	19. The surface of gates and the out in consultation with Mechanica	al
				Cullot Culloc	paint deteriorated. (B11) Organization	
51	Name: Pimpalgaonjoge	12.06.2021	Shri S.M.	Seepage	1. The approximate quantity of Seepage is to be minimised	by
	Gated	12.11.2021	Sangale	ivieasurment	the leakage through the suitable treatment to upstre	eam
	Tai. Junnar DIST. PUNE		SE KIC,		gales is 10 cusecs.(A4) portion	hu
	Location :		Fune		2. The leakage is observed Seepage is to be minimised	by
	Longitude :73 ⁰ 52'30"				the conduit concrete or portion	am
	Longitude .13 32 30				mesonry (quantity of	
		1	1	1	masonry. (quantity or	

Height : 34.204 m Gross Capacity : 235.52 Mm³ Spillway capacity: 1167.3 cu sec Sr.No.In Large Dam Register 2009: MH09MH1520	Instrumentatio n Gates	3. 4. 5.	leakage is not mentioned) (A6) The pan evaporimeter not in working order. (B9) The condition of the steel surface and the surface paint deteriorated. (B11) The approximate quantity of the leakage through the gates is 5 to 6 cusees (B12)	Necessary repairs shall be done in consultation with IRD, Nashik. Necessary repairs should be carried out in consultation with Mechanical Organization.
			gates is 5 to 6 cusecs (B12)	

(b)Ex	b)Executive Engineer ,Dimbhe Dam Division, Manchar, Dist. Pune								
52	Name : Chilewadi (Gated)	21.05.2021	Shri S.M.	Downstream	1.	There are signs of water	Necessary repairs should be carried		
	Tal. Junnar Dist. Pune	03.11.2021	Sangale	Drainage		logging, slushy conditions	out.		
	Year of completion :2000		SE KIC,			or growth of aquatic weeds			
	Location :		Pune			on the downstream of the			
	Longitude 73°50'00"E					dam. (A2)			
	Latitude 19⁰21'00"N			Energy	2.	Evidence of abrasion,	Necessary repairs should be carried		
	Height :62.56 m			Dissipation		cavitation or scour on	out.		
	Gross Capacity :25.30 Mm ³			Structure		dissipation structure			
	Spillway capacity: 1686 m ³ /					observed - A Part of Stilling			
	sec					basin is damaged)(A14)			
	Sr.No.In Large Dam Register				3.	3 The concrete surface of	Necessary repairs should be carried		
	2009: MH09HH1553					the stilling basin and apron	out		
						(or bucket) is not in good			
						condition - One Side of			
						West Weir coping eroded			
						(Approx size - 19 X 5			
						m)(A14)			
					4.	The under drainage of the	Necessary repairs should be carried		
						stilling basin (or bucket) is	out		
						not functioning			
						satisfactorily. All the open			
						drain noies are not clear			
				Wasta Mair	_	and functioning well. (A14)	Necessary repairs should be carried		
				Par and Tail	5.	One Side of West Welf			
				Channel		(Approx Size)			
				Ghannel	6	$-19 \wedge 3111$ (A14)	Necessary repairs should be carried		
					0.	The scouning observed off	Receivery repairs should be builted		

				downstroom side of the bor	out
					out.
				and/or EDA.Details not	
				given. (A17)	
			7.	Erosion on surface at d/s	Necessary repairs should be carried
				side of weir observed. The	out
				concrete eroded size -	out.
				10^{5} (A17)	
			0	The earling over the	
			о.	The coping over the	Necessary repairs should be carried
				spillway bar in good	out.
				condition or not? (not	
				clearly mentioned) (B7)	
			9.	Emergency gates are not in	Necessary repairs should be corried
		Hoists	-	working condition they are	necessary repairs should be carried
		Cranes and		in hanging position at top	out in consultation with Mechanical
		Operating		lovel. Guide toos are bent	Organization.
		Mashaniama		avide tee ie sheelutely	
				diatente de la absolutery	
		EG		disturbed, and corroded and	
				not functioning. (B5)	
			10.	The considerable noise	Necessary repairs should be carried
				noticed in operation of	out in consultation with Mechanical
				outlet gate. (B5)	Organization
			11.	The stem rods for lifting the	Organization.
				dates is bend in some	Necessary repairs should be carried
				length(B5)	out in consultation with Mechanical
			10	The storing errongement for	Organization.
			12.		Necessary repairs should be carried
				emergency gate leaves and	out in consultation with Mechanical
				the stop logs is not in	Organization.
				satisfactory condition. The	5
				Emergency Gate is in	
				hanging condition.(B5)	
			13.	The access road of WBM	Necessary repairs should be corriad
		Access Road		needs repair The	Necessary repairs should be carried
		100000110000		obstructions along or at	out.
				entrance to access road	
				childrice to access 10au	
				observed, river bridge is	
				needed. (B6)	
			14.	All the structures on the	Necessary repairs should be carried
				access roads are not	Neccosary repairs should be carried
				adequately safe for allowing	out.
				passage of plant machinery	

				Instrumentation	for emergent repairs.(B6) 15. Out of 8 only 2 piezometers are in working condition. (B9)	Necessary repairs shall be done in consultation with IRD, Nashik.
53	Name : Yedgaon Tal. Junnar Dist. Pune Year of completion : 1977 Location : Longitude 74⁰01'30'' Latitude 19⁰10'30'' Height : 23.60 m Gross Capacity : 69.204 Mm³ Spillway capacity: 3844 m³/ sec Sr.No.In Large Dam Register 2009: MH09MH0658	05.06.2021	Shri H.T. Dhumal SE KIC, Pune	Instrumentation	 The instruments are not in working order. Relief wells 29 working, 40 not working (B9) Piezometers (i) Stand pipe - 8 nos not in working condition (ii) Casagrande - 41 nos. –not in working ondition(B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.
(c)Ex	ecutive Engineer ,Kukadi Irriga	ation Division	No. 2, Shrigon	da, Dist. Ahmed	nagar	
54	Name : Ghod (Gated) Tal. Shirur Dist. Pune Year of completion : 1965 Location : Longitude 74⁰51'50 Latitude 17⁰ 8'10" Height : 34.75 m Gross Capacity : 216.30 Mm³ Spillway capacity: 7465 m³/ sec Sr.No.In Large Dam Register 2009: MH09MH0117	05.05.2021	Shri S.M. Sangale SE KIC, Pune	Structural performance Spillway EDA Body Wall EDA Downstream	 seepage noticed in conduit(A4) Sweating was observed d/s of spillway gate (A11) Few gate spillway portion minor leakage/sweating shown (A11) EDS under drainage Blocked due to debris material fall (A14) The surface erosion/damage caused, to face or body of walls observed(A16) The erosion and damages observed in r/s portion of check wall.(A17) The scour noticed on the immediate downetroom of 	Quantum of seepage should be monitored monolithwise. Necessary repairs should be carried out. Necessary repairs be carried out in consultation with Mechanical Organization. Necessary repairs should be carried out. Necessary repairs should be carried out. Necessary repairs should be carried out.

					check wall.(A17)	
				Outlet Gates	 (i)GLBC gate properly operating but stem rod is bent, seal brass cap not fixing.(ii) GRBC - leakages shown on both service gates 	Necessary repairs be carried out in consultation with Mechanical Organization
				Spillway	 (B5) 9. GLBC stem rod bend while operating.(B5) 10. The lifting beams are not in proper working order and worki	Necessary repairs be carried out in consultation with Mechanical Organization
				Acess Road	11. It does not provide an all-weather road surface -	Necessary repairs should be carried out.
				Instrumentation	 12. Piezometers: Stand pipe 10 nos not in working condition. (B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.
55	Name :Sina (Gated) Tal. Karjat, Dist.A'Nagar Year of completion :1985 Location : Longitude 74°57'00" Latitude 18°49'00" Height :28.5 m Gross Capacity : 67.95	05.05.2021 10.12.2021	Shri H.T. Dhumal SE KIC, Pune	D/s Drainage Concrete dam sections	 Local ponds at 50m from the toe drain at ch 1500m. (A2) The entire length of conduit is not in perfect order & profile & free from offsets, open joints, cracks & leakage- Details not given(A4) 	Necessary repairs should be carried out. Necessary repairs should be carried out.
	Mm ³ Sr.No.In Large Dam Register 2009:MH09MH1142			Stilling basin	 Water accumulated in stilling basin could not be drain out in proper manner(A14) Under drainage of stilling basin is unsatisfactory - drain 	Necessary repairs should be carried out. Necessary repairs should be carried out.
				Spillway	holes shall be cleaned.(A14) 5. Some minor leakages at spillway of dam are observed. (A 15)	Necessary repairs should be carried out.
				Guide walls/Check Walls	 Approach wall to HR of SRBC is damaged - needs to be reconstructed. (A16) 	Necessary repairs should be carried out.
					7. Erosion and damages	Necessary repairs should be carried

				Outlet Gates	observed in right side portion of check wall.(A16) 8. Scour noticed immediate downstream of check wall.(A16) 9. SRBC service gate no. 1 is not properly working. SLBC	out. Necessary repairs should be carried out. Necessary repairs should be carried out in consultation with Mechanical
					service gate & emergency gate both are not working properly. EG is rusted and guide channel is damaged. (B5)	Organization.
					 10. SLBC & SRBC stem rods bend. (B5) 11. The operation of outlet gates is not smooth. (B5) 	Necessary repairs should be carried out in consultation with Mechanical Organization.
				Acess Road	12. There is no properly constructed and well maintained access road.(B6)	Necessary repairs should be carried out.
				Instruments	 13. Pan Evaporimeter - 1 Nos Not in working condition (B9) 14. Wind Direction Recorder - 1 no.Not in working condition (B9) 	Necessary repairs shall be done in consultation with IRD, Nashik.
(2) Su	perintending Engineer . Sata	ra Irrigation Pr	oiect Circle. Sa	atara		
(a) Ex	ecutive Engineer , Minor Irrig	ation Division,	Satara			
56	Name :Nagewadi (Gated) Tal. Wai Dist. Satara	04.05.2021	Shri. J.S.Shinde,	Earth dam	1. The slushy patch at ch 855 to 870 near rock toe on d/s	It should be kept under observation and Necessary repairs should be
	Year of completion : 1999 Location :	14.11.2021	SE, SIPC, Satara		2. Existence of leakage,	carried out by permission of competent field authority.
	Latitude 17 ⁰ 55'17"				earthwork (A3)	
	Height :40.02 m			Hoist	3. The hoist mechanism is not	Necessary repairs should be carried
	Gross Capacity : 6.47 Mm ³			Arrangement/	available at site.(A18)	out in consultation with Mechanical
	Sr.No.In Large Dam			EG	4. Emergency gate –Chain	Organization.
	Register 2009:MH09HH1518				pulley arrangement not	Necessary repairs should be carried

				Instruments	5.	available at site to take trail of emergency gate.(B5) Instruments installed not Propely Lighted ,Ventilated and adequately Protected. (B9)	out in consultation with Mechanical Organization. Necessary repairs shall be done in consultation with IRD, Nashik.
				Outlet Gates	6.	The surface of gates and paintsare deteriorated. (B11)	Necessary repairs should be carried out in consultation with Mechanical Organization.
57	Name : Morna (Gureghar) Tal. Patan Dist. Satara Year of completion : 2000	13.05.2021 09.11.2021	Shri. J.S.Shinde, SE, SIPC,	Body Wall	1.	There is erosion, pitting, or Spalling of the Concrete Masonary surface(A17)	Necessary repairs should be carried out.
	Location : Longitude 73⁰50'00'' Latitude 17⁰17'30''		Satara	EDA	2.	Score Noticed on downstream side of Wear(A17)	Necessary repairs should be carried out.
	Height : 47.02 m Gross Capacity : 39.55 Mm ³			Hoist Arrangement	3.	The alternate hand operating system of hoist is not working.(A18)	Necessary repairs should be carried out in consultation with Mechanical Organization
	Sr.No.In Large Dam Register 2009: MH09HH1664			D/s face	4.	The indications of major active or inactive landslide observed on d/s of the dam near access road to the dam.(B6)	Necessary repairs should be carried out.
				Acess Road	5.	The obstructions along or at entrance to access road- Landslide over access road, partially blocked (B6)	Necessary repairs should be carried out.
				Instrumentation	6.	14 nos foundation type Piezometers and 36 nos embankment type piezometers and uplift pressure cell ,6 nos are not	Necessary repairs should be carried out in consultation with IRD Nashik
				Outlet Gates	7.	in working condition.(B9) The condition of steel surface and surfacepaint deteriorated.(B11)	Necessary repairs should be carried out in consultation with Mechanical Organization

58	Name :Pangare	29.5.2021	Shri.	Tail Channel	1.	Landslide in tail channel	Necessary repairs should be carried
	Tal. Satara Dist. Satara	23.11.2021	J.S.Shinde,			@ch 120m from waste weir	out
	Year of completion :2000		SE, SIPC,			has been observed.(A7)	
	Location :		Satara	Well	2.	Evidence of structural	Necessary repairs should be carried
	Longitude 73°52'30"					distress on d/s of HR	out.
	Latitude 37º09'01"					well,18m long portion of	
	Height : 32.10 m					RCC conduit has sunk ny	
	Gross Capacity:					0.45 m approx. and leakge	
	2.72Mcum					through conduit	
	Sr.No.In Large Dam					observed.(A6)	
	Register 2009:NA				3.	On d/s of H.R.Well leakage	Necessary repairs should be carried
						through Coduit (A15)	out
				Water	4.	Evidence of seepage or	Necessary repairs should be carried
				Conveance		leakage from water	out
				Structure		conveyance (A15)	
					5.	Could not be inspected due	Necessary repairs should be carried
						to Presence of Water(A20)	out
				D/s Face	6.	Rain cuts/erosion	Necessary repairs should be carried
						channel present at any	out
						Locations(B3)	
59	Name :Kalgaon	29.04.2021	Shri.	D/S Portion	1.	Slushy Conditions in the	It should be kept under observation
	Tal. Patan Dist. Satara	09.11.2021	J.S.Shinde,			gorge portionon D/S of	and Necessary repairs should be
	Year of completion : Work in		SE, SIPC,			dam(A10)	carried out by permission of
	progress		Satara		_		competent field authority.
				Spillway	2.	Little Honycombing is	Necessary repairs should be carried
	Longitude 73°53'00"				~	observed(A14)	out.
					3.	Spillway, Masonary and	Necessary repairs should be carried
	Height :32.26 m					Concrete are deterorated	out.
	Gross Capacity : 2.692Mm					(A14)	
	Sr.No.In Large Dam			Stilling Basin	4.	Leakage is Observed below	Necessary repairs should be carried
	Register 2009: MHU9HH2416			EDA	_	stilling Basin (A14)	OUT.
					э.	displayed in the second	inecessary repairs should be carried
				Spillway	c	Little Creeking in Observed	Uul.
					ю.	in the Spillwov Concrete	out
							out
						(A13)	
				Water	7.	Leakage is Observed	Necessary repairs should be carried

				Conveance Structure Spillway	8. 9. 10.	through the Well Proper and the Conduct Concrete and Masonary (A15) Cavation is Observed in End Sill Wall (A17) Little honycombing is observed in the spillway concrete (B7) Leakage is observed in Spillway Portion It is through the foundation of Spillway (B7)	out Necessary repairs should be carried out. Necessary repairs should be carried out. Necessary repairs should be carried out.
60	Name :Kusawade Tal. Satara Dist. Satara Year of completion :2010 Location : Longitude 73 ⁰ 57'00" Latitude 17 ⁰ 34'46" Height :30.90 m Gross Capacity : 3.495 Mm ³ Sr.No.In Large Dam Register 2009:MH09HH2411	27.04.2021 21.11.2021	Shri. J.S.Shinde, SE, SIPC, Satara	Hoist Arrangement Instrumentation Outlet Gates	1. 2. 3. 4.	The alternate hand operation syatem of hoist mechanism not working .(A18) There is obstructions preventing or impairing smooth operation (A20) No instruments installed at dam site.(B9) Surface of Gates and Paint Deteriorated (B11)	Necessary repairs should be carried out in consultation with Mechanical Organization Necessary repairs should be carried out in consultation with Mechanical Organization Necessary repairs shall be done in consultation with IRD, Nashik. Necessary repairs should be carried out in consultation with Mechanical Organization
(b) Ex	cecutive Engineer, Kanher Car	als Division N	o.2, Karwadi, H	Karad			
61	Name : Tarali (Gated) Tal. Patan Dist. Satara Year of completion : 2007 Location : Longitude 73⁰54'15 " Latitude 17⁰32'00 " Height : 73.41 m Gross Capacity 165.70 Mm ³ Sr.No.In Large Dam Register 2009: MH09HH1666	21.05.2021 06.11.2021	Shri. J.S.Shinde, SE, SIPC, Satara	Gallery/Shaft	1. 2. 3. 4.	There are problems accessing or inspecting gallery/shaft obstruction. (A8) Foundation gallery is not accessible due to flooding (A8) The Sump Well is flooded with seepage water (A8) Problems of inadequate drainage - There is seepage water in gallery,Some porous drains are Clogged (A9)	Providing arrangementproper madedraining galleryaccessible.Providing arrangementproper madedraining gallery accessible.Necessary remedial measurs should be carried out.Providing proper draining arrangement seepageshould be be minimized & all porous drains should be cleaned.All Foundationand Porous holes
					5.	All Foundation and Porous	

				holes are not Periodically cleaned (A9)	should be clea	ined.	
			6.	There is Significant or excessive leakage at gallery-No.17 & 18 @ ch.775 & 815 respectively (A10)	Providing arrangement minimized	proper seepage	draining should be
		OF & NOF Section	7.	Sweating and leakages observed on d/s face of dam at Monolith no.3, 4, 4A, 12,13,14,15and16 ,17,18, 21,21A (A11)	Providing arrangement minimized	proper seepage	draining should be
		D/S Face	8. 9.	The leachate deposition observed on D/s face in monolith (A12) There is considerable leaching from the seepage water and deposition of lime near the seepage exit	Leached mate recorded of qu maintained. L be tested from	rial to be co Jantity & wa Jeaching ma MERI Nas	ollected & hit to be aterial should hik.
			10. 11.	spots (A12) There is Evidence of Surface Defects (B3) There is Concrete/ Masonary Deterioration (B3)	Necessary ren be carried out. Necessary ren be carried out	nedial meas nedial meas	surs should surs should
		U/S Face	12.	The u/s face of dam is in good condition. But damages at some spots.(B8)	Necessary ren be carried out.	nedial meas	surs should
		Instrumentation	13.	Instruments are accessible. Presently there is no lighting arreangment. The Instruments are not working order. (B9)	Necessary rep consultation w	airs should ith IRD, Na	be carried shik.

(c)	Executive Engineer, Dhom Ca	anals Satara					
(c) 62	Executive Engineer, Dhom Ca Name :Uttarmand Tal. Patan Dist. Satara Year of completion: June- 2010. Location : Longitude 74 ⁰ 00'28"(E) Latitude 17 ⁰ 24'24"(N) Height :44.45 m Gross Capacity 24.925 Mm ³ Sr.No.In Large Dam Register 2010: MH09HH1591	anals Satara 13.05.2021 21.11.2021	Shri. J.S.Shinde, SE, SIPC, Satara	Stilling Basin Equipments Gates	1. 2. 3. 4.	Concrete Surface of stilling Basin and apron not in good condition (A14) Erosion, pitting or spelling of the concrete or masonary surface(A17) Deterioration of equipment (B11) The surface of gates and paints are deteriorated. (B11)	Necessary remedial measurs should be carried out. Necessary remedial measurs should be carried out. Necessary remedial measurs should be carried out. Necessary remedial measurs should be carried out.
63	Name : Hateghar Tal. Jawali Dist. Satara Year of completion : Location : Longitude 73⁰49'00 " Latitude 17⁰52'00 " Height : 38.55 m Gross Capacity 7.371 Mm³ Sr.No.In Large Dam Register 2009: MH09HH1591	28.04.2021 08.11.2021	Shri. J.S.Shinde, SE, SIPC, Satara	U/S Slope		Section of dam and Upstream slope not appear structurally sound and stable (B3)	Necessary remedial measurs should be carried out in consultation with CDO Nashik.
(3)Su	perintending Engineer & Admi	nistrator, C.A.	D.A. Solapur				
(a) E X	ecutive Engineer, Ujjani Dam N	nanagement D	ivision, Bhima	nagar, Solapur			
64	Name : Bhima Ujani (Gated) Tal. MadhaDist Solapur Year of completion : 1980 Location : Longitude 75⁰7'15''	06.05.2021	Shri. D.B. Sale SE & Adm. CADA, Solapur.	Gallery	1.	In gallery safety issues arrangement (inadequate handrails, nosing to steps is necessary.) (A8)	Gallery should be cleaned and proper safety rrabgements should be made
	Latitude 18 ⁰ 04'24' Height :56.40 m Gross Capacity :332.00 Mm ³				2.	Porous pipes need cleaning (A9)	Porous pipes need should be cleaned.
				Body wall	3.	Presence of leaks,Springs,or	Necessary remedial measurs should

Sr.No.In Large Dam Register				Wet Spots in Vicinity of	be carried out.
2009: MH09HH0843				Seen (A11)	
		Body wall	4.	There is considerable	Leached material to be collected &
				leaching at some places,	recorded of quantity & wait to be
				ioints (A12)	should be tested from MERI Nashik
		Stilling Basin	5.	Flow Condition in the Stilling	Necessary remedial measurs should
		-		Basin (or bucket) have a	be carried out in consultation with
				I endency to to draw material	CDO Nashik.
				churning and abrasion	
				damage to Surface of	
				buckets battale blocks,	
		EDA	6.	There is retrospective	Proper remedial measure be taken
				erosion on d/s of tail pond	and scouring be monitored
				weir on d/s of EDA. It needs	&prevented further scouring.
		U/S Slope	7.	Concavity seen on U/S	Necessary remedial measurs should
				between Ch.2015 to 2040 m.	be carried out.
				IS SINCE last 20 years.	
				in its concavity thereafter.	
				(B3)	
		Spillway	8.	Ugee crest shows	Necessary remedial measurs should be carried out
				many places.(B7)	
		Instrumentation	9.	some Instruments are not	Necessary repairs should be carried
				as per Annexure-I (B9)	consultation with IRD, Nashik.
		River sluice	10.	River sluice conduits need	It should be kept under observation.
				attention. (B10)	

(3)Su	(3)Superintending Engineer Osmanabad Irrigation Circle, Osmanabad												
(a)Ex	ecutive Engineer, SinaKolegad	onProject Divi	sion, Paranda	Dist. Osmanaba	d								
65	Name :SinaKolegaon Tal.ParandaDist Osmanabad Year of completion : 2007	03.05.2021 21.11.2021	Shri. B.R. Shingade SE OIC	D/S Face	1.	There is slushy condition or water logging immediately downstream of dam (A2)	Necessary remedial measurs should be carried out.						
	Location : Longitude $75^{\circ}23'55'$ Latitude $18^{\circ}18'59'$ Height : 26.10 m Gross Capacity : 150.49 Mm ³		Osmanabad	Gallery	2.	Drainage Gallery is not accessible, In gallery safety issues arrangement not provided (inadequate handrails, lighting or ventilation) (A8)	Draibage gallery should be cleaned and proper safety rrabgements should be made.						
	Sr.No.In Large Dam Register 2009: MH09HH1673				3.	There is Significant or excessive leakage at along gallery/shaft / porous (A10)	It should be kept under observation and Necessary repairs should be carried out by permission of competent field authority.						
				Stilling basin	4.	The under drainage of the stilling basin (or bucket) not satisfactory The open drain holes are not clear and functioning well (A14)	Necessary remedial measurs should be carried out in consultation with CDO Nashik.						
				General	5.	Generated Battery Need to be Provided (A19)	It should be repaired properly						
				D/S Drainage	6.	There is the portions of longitudinal toe drain and exposed cross drains beyond the downstream toe of the dam is not in regular section and freely draining (B2)	Drains should be cleaned. Drain section should be restored as per design.						
				Body Wall	7.	At the Junction of Masonary and earthen dam ch2253.8 to 2380m shows sign of excessive and uneven settlement (B3)	Dam section should be restored to design section.						

NOF	 Earthen portion near masonry dam have been settled to tune of 90 Cm. in depth for 55 Mtr in length (B3) 	Dam section should be restored to design section.
Junction	9. Gap along the Joint (B3) 10. At Very Places need repair pointing (B8)	Necessary repairs should be done Necessary repairs should be done
Body Wall	11. Small seepage found through the body of the dam (B8)	Necessary repairs should be done
Instrumentation	12. Instruments are not installed in dam (B9)	Instruments should be installed in consultation with IRD, Nashik.
	NOF Junction Body Wall Instrumentation	NOF8. Earthen portion near masonry dam have been settled to tune of 90 Cm. in depth for 55 Mtr in length (B3)Junction9. Gap along the Joint (B3) 10. At Very Places need repair pointing (B8)Body Wall11. Small seepage found through the body of the dam (B8)Instrumentation12. Instruments are not installed in dam (B9)

Table 3.12

Class-I Dams with Category-3 Deficiency

Sr. No	Name of Dam	Date of Compl	Location	Heigh t in	Gross Capacity	Design Spillway	Sr.No. in	Gated / Ungated	Date of Inspection	Deficiencies noticed	Total Deficien
		-etion	Latitude	m	Mm ³	Capacity m ³ / sec	Register	enguiou	Pre & Post		cies
1	2	3	4	5	6	7	8	9	10	11	12
[A]C	hief Engineer(W.I	R.)Water F	Resources De	partmen	t Pune		1			l	
(1)S	uperintending En	gineer, P	une Irrigation	Circle, F	Pune						
(a)E	xecutive Enginee	r, Pune I	rrigation divis	sion, Pun	e						
1	Jadhavwadi	2001	73°43'0	35.52	1.203	664.14	мноонн	Ungated	11.05.2021	3.1,3.6,3.9,,3.16,3.20,3.2	10
	Tal.Haveli Dist. Pune		18°47'00"				1587		07.12.2021	3,3.24,3.26,3.27,3.34	
2	Nira devghar	2008	73°43'00"	65.69	337.39	1398		Gated	24.11.2021	3.1,3.3,3.5,3.6,3.9,3.11,	14
	Tal.Maval Dist.		18°06'00"				мноэнн		30.04.2021	3.12,3.16,3.18,3.19,	
	Pune						1554		17.03.2022	3.20,3.21,3.24,3.25,3.26,	
										3.28,3.29,3.30,3.31,3.33,	
2	Photobor	1029	72 ⁰ 52' 00	57.00	670.65	1600		Catad	20.04.2024	3.34,3.35,3.30	16
3	Tal	1920	135200 $18^{0}10'30$	57.92	072.00	1600	MH09HH	Galed	30.04.2021	3 10 3 20 3 23 3 24 3 25	10
	BhorDist Pune		10 10 30				0048		24.11.2021	3 28 3 29 3 31 3 34 3 35	
4	Vadivale	1999	73 ⁰ 31'16"	29.00	40.87	746.82		Gated	05.05.2021	3 1 3 6 3 7 3 9 3 11 3 13	19
	Tal.		18 ⁰ 49'20"N				MH09MH		30.11.2021	3 16 3 10 3 20 3 21 3 24	
	MavalDist.Pune						1517			3 25 3 28 3 29 3 31 3 32	
										3.33.3.34.3.35	
5	Andravallev	2003	73 ⁰ 39'00"	34.50	83.31	3021.00		Ungated	05.05.2021	3.6.3.13.3.16.3.18.3.19	16
	Tal.Maval		18 ⁰ 20'00"				МН09НН	0	30.11.2021	,3.20,3.21,3.22,3.23,3.24,	
	Dist.Pune						1622			3.25,3.27,3.28,3.29,3.30,	
										3.31	
6	Kasarsai	2003	73 ⁰ 40'00"	29.20	17.38	933.00		Gated	05.05.2021	3.1,3.6,3.7,3.9,3.11,3.13,	18
	Tal. Mulashi		18°35'30"				мноэмн		30.11.2021	3.16,3.20,3.21,3.22,3.24,	
	Dist.Pune						1373			3.26,3.28,3.29,3.30,3.31,	
										3.33,3.35	
(b)F	kecutive Enginee	r Chaska	man Irrigation	n Divisio	n Pune		1				
7	Aralakalmodi	2010	73°40'30"	40.61	42.87	963.21	МН09НН	Ungated	15.5.2021	3.1, 3.13, 3.16, 3.20,	15
	Tal.Khed Dist.		19°00'00"		-		1672		07.12.2021	3.21,3.23, 3.24,	-

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11	12
	Pune									3.25,3.28,3.29, 3.30,3.31, 3.34, 3.35,3.36.	
8	BhamaAskhed Tal. Khed Dist. Pune	2014	73°43'00" 18°15'00"	51.125	230.47	1118	MH09HH 1559	Ungated	15.05.2021 07.12.2021 18.03.2022	3.1, 3.2,3.3, 3.6, 3.9, 3.11,3.17, 3.18,3.20,3.21, 3.23, 3.24, 3.25, 3.28,3.29, 3.30, 3.31,3.32,3.33, 3.34, .	20
9	Chaskaman Tal. Khed Dist.Pune	1999	73°47'15" 18°15'40"	46.28	241.69	2860	MH09HH 1522	Gated	11.05.2021 07.12.2021	3.1, 3.3, 3.9,3.10,, 3.16,, 3.19, 3.20, 3.21,3.23, , 3.24, 3.28,3.29,3.30, 3.31, 3.34,3.36	16
(d)E	xecutive Enginee	r,Lift Irri	igation Manag	gement D	Division, Pu	ne					
10	Nazare Tal.Sasvad Dist. Pune	1974	74°12'50" 18°17'30"	22.545	223.20	980	MH09MH 0453	Gated	15.05.2021 05.12.2021	3.1, 3.2, 3.6, 3.7, 3.9, 3.19, 3.20, 3.22, 3.23, 3.24, 3.25, 3.29, 3.31, 3.33,	14
(e) E	xecutive Enginee	er, Khadak	wasala Irriga	tion Divi	sion, Pune	11					
11	Panshet Tal. Velhe Dist.Pune	1968	73 [°] 37' 18 [°] 22'	63.56	310.61	1162.0	MH09HH 0310	Gated	04.05.2021 23.11.2021	3.1,3.5,3.16.3.19,3.25, 3.30	6
12	Khadakvasala Tal. Haveli Dist.Pune	1879	73 [°] 46' 18°28'	32.92	86	2755	MH09HH 0013	Gated	04.05.2021 23.11.2021	3.1, 3.5, 3.6, 3.13,3.19, 3.20,3.22, 3.24, 3.25,3.28,3.29, 3.30,3.31 3.33, 3.35.	15
13	Warasgaon Tal. Velhe Dist.Pune	1992	73°37' 18°23'	66.60	375.36	1416	МН09НН 0592	Gated	04.05.2021 23.11.2021	3.1, 3.6, 3.7, 3.9, 3.16, 3.18,3.19, 3.20, 3.21, 3.25, 3.26, 3.28, 3.31, 3.32, 3.34,	15
14	Pawana Tal. Maval Dist.Pune	1972	73 ⁰ 40'30" 18 ⁰ 21'30"	42.37	305.28	1250	MH09HH 0311	Gated	05.05.2021 30.11.2021	3.1,3.2,3.5,3.6,3.7,3.9,3.15, 3.16,3.19,3.20,3.21,3.24, 3.26,3.27,3.28,3.30,3.31, 3.32,3.34,3.35	20
(f)Ex	ecutive Engineer	', Nira Rig	ht Bank Cana	al Divisio	n, Phaltan ,	Dist. Satara					

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	2	4	5	6		Q	0	10	11	12
15	Veer	1965	- 74 ⁰ 5'55	34.66	278.49	5154	0	Gated	28.05.2021	31 32 35 36	17
	Tal.Purandar Dist.Pune	1000	18 ⁰ 07'05"	04.00	210.43	0104	MH09HH 0116	Culcu	24.11.2021	3.9,3.11,3.16, 3.19, 3.20, 3.21,3.24, 3.25, 3.27, 3.28, 3.29,3.31, 3.34	
(2)Su	perintending En	igineer, P	une Irrigation	Project	Circle, Pune	e		•	L.	• • • •	
(a) E	xecutive Enginee	er, Bhama	Askhed dam	division,	pune						
16	Temghar Tal. Mulashi Dist.Pune	2000	73 [°] 32' 18 [°] 27'	86.67	107.96	626	MH09HH 1544	Ungated	19.11.2021	3.1,3.6,3.20,3.22,3.24, 3.29,3.30,3.31,3.34,3.36	10
(c)Ex	ecutive Enginee	r, Niradev	ghar Project I	Division,	Sangavi(Bł	hatghar),Ta	Bhor,Dist.	Pune		•	
17	Gunjavani Tal.Velhe Dist. Pune	2001	73°38'27" 18°18'30"	52.82	104.69	1280.03	MH09HH 1552	Gated	18.11.2021	3.1, 3.5,3.9, 3.13, 3.24,3.25, 3.29,3.30,3.31	9010
(3)Sı	uperintending En	ngineer Sa	angli Irrigatior	n circle, S	Sangli						
(a)Ex	ecutive Enginee	r ,Sangli lı	rrigation Divis	sion, Sar	ngli						
18	Morna (Shirala) Tal Shirala Dist. Sagli	1984	74°06'30" 16°59'20"	38.10	21.18	1075	MH09HH 1101	Ungated	25.05.2021 10.12.2021	3.1,3.6,3.7,3.13,3.24, 3.26,3.27,3.28,3.30,3.31	10
(b)E	kecutive Enginee	r ,Tembhu	Lift Irrigation	n Project	Manageme	ntb Divisio	n, Ogalewad	<u>ik</u>			
19	Yevati masoli Tal Karad Dist. Satara	1989	74°11'00" 17°00'00"	36.00	7.30	330	MH09HH 1218	Ungated	27.05.2021 12.10.2021	3.1,3.6,3.9,3.13,3.20 ,3.24,3.25,3.26,3.27,3.28, 3.31	11
(c)Ex	ecutive Enginee	r ,Takari P	ump House	Division	No.1, Devra	shtre	1				
20	Satpewadi barrage Tal Walwa Dist. Sangli	2005	74°21'26" 18°06'51"	37.50	3.886	554.80	Proposed for updating in NRLD 2018	Gated	24.07.2021 12.10.2021	3.1,3.2,3.6,3.11,3.15,3.20 ,3.29, 3.30,	8

Sr.	Name of Dam	Date of	Location	Heigh	Gross	Design	Sr.No. in	Gated /	Date of	Deficiencies noticed	Total
No		Compl	Longitude/	t in	Capacity	Spillway	NRLD	Ungated	Inspection		Deficien
		-etion	Latitude	m	Mm°	Capacity	Register		Pre & Post		CIES
1	2	3	4	5	6	7	8	9	10	11	12
(4)Sı	uperintending Er	igineer Ko	hapur Irriga	tion Circ	e,Kolhapur				4		•
(a)E	kecutive Enginee	r, Kolhap	ur Irrigation	Division	(South), Ko	lhapur					
21	Ghatprabha(Ph	2009	74°04'20"	48.30	43.75	1452		Ungated	07.05.2021	3.1,3.2, 3.6,	14
	atakwadi)		15°56'45"				MH09HH		30.11.2021	3.13,3.16,3.18,3.20,3.22,	
	Tal.Chandgad						1900			3.24,3.26,3.29,3.30,3.31,	
	Dist.Koinapur									3.35	
22	Jambre	2013	74°06'40"	38.06	23.23	530.90		Ungated	08.05.20200	3.1,3.2, 3.5,3.6,3.9,	15
	Tal.Chandgad		15°52'47"	5			МН09НН		4.12.2020	3.13,3.16,3.19,	
	DistKolhapur						1025			3.20,3.24,3.26,3.29,	
							1925			3.30.3.31.3.32.3.33	
b)Ex	ecutive Engineer	, Medium	Project Divi	ision No.	2 Kolhapu	r					1
23	Chikotra	2008	74°12'23"	60.78	43.11	393		Gated	23.04.2021	3.1,3.11,3.13,3.18,3.20,	11
	Tal.Ajara		16°13'30"				MH09HH		19.10.2021	3.21, 3.23, 3.24, 3.29	
	DistKolhapur						1582			3.30,3.31	
24	Jangamhatti	2005	74°18'00"	31.40	34.21	567	МН09МН	Ungated	15.05.2021	3.1,3.2,3.5,3.6,3.9,3.10,	16
	Tal.Chandgad		15°51'30"					_	21.11.2021	3.13,3.16,3.20,3.24, 3.26,	
	DistKolhapur						1366			3.29,3.30,3.31,3.32,3.34	
25	Keloshi Bk.	2010	73°49'53"	38.60	5.603	228.42	МН09НН	Ungated	19.04.2021	3.2.3.6.3.9.3.13.3.20	9
	Tal.Radhanagari		16°31'30"				-	C C	09.11.2021	3.23. 3.24.3.26. 3.30	
	DistKolhapur						1935				
3.13,	(b)Executive Engi	neer, Kolh	apur Irrigation	Dn.(Nortl	h) Kolhapur	500.07		L La satu L			10
26	Kadavi Tal Shahuwadi	2000	73°52′30″	35.25	71.24	506.87		Ungated	28.04.20212	3.1,3.2,3.5,3.6,3.7,3.9,	18
	Dist Kolhapur		17-00-05				MH09HH		4.11.2021	3.13,3.19,3.20,3.21,3.23,	
	Disttoinapui						1541			3.26,3.27,3.30,3.31,3.32,	
										3.33,3.34	
27	Kasari	1989	73°47'41"	85.30	78.565	860		Ungated	24.04.20212	3.6,3.7,3.11,3.13,3.20	13
	l al ChahuwadiDiat		16°51′42″				MH09HH		8.04.2021	,3.21,3.24,3.25,3.26,3.30,	
	Kolbanur						1240			3.31,3.34,3.35	
28	Kumbhi	2007	73°51'49"	42.58	76.88	416,10	MUQQUU	Gated	12 05 20212	3 1 3 6 3 9 3 11 3 13 3 16	20
20	Tal.Gaganbavad	2007	16°31'29"	12.00	, 0.00	110.10	1671	Culou	12.03.20212	3.1,3.0,3.7,3.11,3.13,3.10	20
	a DistKolhapur						1071		4.10.2021	, 0, 10,, 0, 17,, 0, 20, 0, 21,	

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11	12
										3.22,3.23,3.24,3.25,3.26,	
										3.29,3.30,3.31,3.34,3.35	
29	Paleshwar Tal	2011	73°52'30"	42.15	9.11	635		Ungated	26.04.202124	3.6,3.7,3.9,3.18,3.19,3.20	14
	ShahuwadiDist		17°00 15″				MH09HH 1546		.11.2021	,3.21,3.24,3.26,3.27,3.29,	
	Rolliapui						1340			3.30,3.31,3.32,	
30	Tulashi	1978	74°31'00"	48.6	98.29	640	мноэнн	Ungated	19.04.20210	3.1,3.5,3.6,3.9,3.13,3.16,.	17
	Tal: Radhanagari.		16°31′15″				0726		9.11.2021	3.18,3.19,3.20,3.21,3.22,	
	Dist. Noiriapui									3.26,3.27,3.28,3.29,3.31,	
										3.35	
31	Upwade	1996	74°05'00	32.81	2.71	71	милони	Ungated	05.05.2021	3.1,3.6,3.7,3.9,3.13,3.16,	15
	Tal.KarveerDist		16°40'00"				1385		24.10.2021	3.18,3.19,3.20,3.21,3.24,	
	Koinapur						1000			3.26,3.27,3.28,3.30,	
32	Radhanagari	1954	73 [°] 57'40"	42.83	936.56	283	мноонн	Gated	19.04.2021	3.1,3.11,3.16,3.18,3.19,	12
	Tal.Radhanaga		16°20′20″				0067		09.11.2021	3.20,3.21,3.22,3.28,3.31,	
	II Dist.Koinapui									3.32,3.33	
33	Warana	1989	73°05'50	77.00	974.18	974.18		Gated	22.04.2021	3.2,3.5,3.6,3.9,3.13,3.16,	20
	Tal. Shirala		17°08′10″				МН09НН		02.11.2021	3.18,3.19,3.20,3.21,3.22,	
	Dist. Sarigii						1542			3.25,3.28,3.30,3.31,3.32,	
										3.33,3.34,3.35,3.36	
34	DudhagangaTa	1987	74° 1' 0"	85.30	719.12	1940	мноонн	Gated	19.04.2021	3.1,3.6,3.18,3.19,3.20,	13
	I.Radhanagari		16° 21' 0''				1226		09.11.2021	3.21,3.22,3.25,3.26,3.28,	
	Dist. Kolhapul									3.29,3.31,3.35	
(c)E>	ecutive Engineer,	Kolhapur	Irrigation Dn.(S	South) Ke	olhapur	(00					
35	Patgaon	2007	/3°56′15″	37.90	105.242	499		Ungated	23.04.2021	3.1,	16
	Dist Kolhapur		10/9				MH09HH		19.10.2021	3.3,3.6,3.7,3.9,3.13,3.18,	
	Biotintoinapai						1242			3.19,3.20,3.21,3.23,3.24,	
00	A see la succe all'	0040	74000145"	00.05	7.4.4	470.00			15.05.005.1	3.26,3.30,3.31,3.35	10
36	Ambewadi Tal Chargadiat	2013	14°33′45"	33.05	/.11	170.62	MH09HH	Ungated	15.05.2021	3.1,3.9,3.13,3.16,3.20,	13
	Kolhanur		15 52 49						21.11.2021	3.21,3.23,3.24,3.26,3.27,	
	nonapu						1889			3.30,3.31,3.33	

Sr.	Name of Dam	Date of	Location	Heigh	Gross	Design	Sr.No. in	Gated /	Date of	Deficiencies noticed	Total
NO		-etion	Longitude/	m	Mm ³	Capacity	Register	Ungated	Pre & Post		cies
						m ³ / sec	_				
1	2	3	4	5	6	7	8	9	10	11	12
37	Chitri	2004	74°09'30"	55.11	53.41	571		Ungated	26.04.2021	3.1,3.7,3.9,3.11,3.13,3.19	13
	Tal.Ajara		16°04'15"						19.05.2021	3.20,3.21,3.24, 3.26,	
	DistKolhapur						1200			3.30,3.31,3.32	
38	Kitwad-2	2009	75°25'15"	36.72	5.92	674.34	-	Ungated	13.05.2021	3.1,3.9,3.13,3.16,3.20,	12
	Tal. Chargad		15°45'30"				мноэнн	_	21.11.2021	3.21.3.26.3.27.3.30.3.31.	
	DistKolhapur						1902		_	3.32.3.33	
39	Kondoshi	2000	74°09'00"	30.27	2.76	133.35		Ungated	22.04.2021	3.1.3.6.3.9.3.13.3.24.3.26	8
	Tal.		16°04'15"				МН09НН	_	19.10.2021	.3.30.3.31	
	Bhudargad						1533			,	
10	DistKolhapur	0000	740001001	00.04	0.000	004			15.05.0004		
40	Lakikatti	2000	74°20'00"	36.34	9.239	231	мноэнн	Ungated	15.05.2021	3.1,3.6,3.9,3.13,3.16,3.20	16
	Diet Kolhanur		15 55 50				1538		21.11.2021	,3.21,3.23,3.24,3.26,3.27,	
	DistKoinapui		0							3.29,3.30,3.31,3.33,3.34	
41	Megholi	2000	74 [°] 07'00	34.12	3.932	238.35	милони	Ungated	19.05.2020	3.1,3.9,3.13,3.20,,3.24,	8
	Tal. Bhudergad		16°11'03"				1536			3.26,3.30,3.31	
	Dist. Kolhapur						1550				
42	Phaye	2004	74°04'15"	34.12	3.932	190.40	мноонн	Ungated	23.04.2021	3.1,3.9,3.13,3.20,3.24,	8
	Tal.Bhudargad		16°07'04"				1629		19.10.2021	3.26,3.30, 3.31	
(5)0	DistKolhapur				0-1						
(5)51	uperintending Er	ngineer Sa	atara Irrigatio	n Circle,	Satara						
(a)⊏/		1, KOYIIA I	70°44'28"	103 02	2080 68	5465.8		Gated	08 05 2021	3 1 3 6 3 10 3 12 3 16	18
43	Tal Patan	1907	17°23'00"	103.02	2900.00	5405.8	мноолн	Galeu	20 11 2021	3 18 3 19 3 20 3 21 3 23	10
	Dist Satara		17 20 00				0100		21 11 2020	3 24 3 25 3 28 3 29 3 30	
	Diot. Odiara						0100		21111.2020	3.32,3.33,3.35	
44	Kolkewadi	1975	73°38'50'	66.30	36.22	1081	MUQQUU	Gated	08.05.2021	3.18, 3.20,	7
	Tal. Chiplun		17 ⁰ 28'				MH09HH		20.11.2021	3.21,3.24,3.26,3.27,3.29	
	Dist. Ratnagiri						UJZI				
(b)E	xecutive Enginee	r, Satara	Irrigation Div	ision Sat	ara						
45	Dhom	1976	73°49'04"	62.18	382.32	1778.29	МНОЭНН	Gated	15.5.2020	3.1,3.2,3.6,3.9,3.11,3.13,	17
	Tal. Wai Dist.		17°58′39"				0655		18.12.2020	3.16,3.19,3.20,3.24,3.26,	
1	Satara			1						3.27,3.28,3.29,3.30,3.31,	

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
						m ³ / sec					
1	2	3	4	5	6	7	8	9	10	11	12
										3.34	
46	Dhombalkawadi	2006	73°42'30"	65.10`	115.53	1576		Ungated	01.06.2021	3.1, 3.2,3.3,3.6, 3.9,	24
	Tal. Wai Dist.		17°51'00"						20.12.2021	3.10,3.11,3.12,3.13,	
	Satara						MH09HH			3.18,3.20,3.21,3.24,3.25,	
							1665		17.03.2022	3.26,3.27, 3.28,	
										3.29,3.30,3.31, 3.33,3.34,	
										3.35.3.36	
(c)E>	ecutive Enginee	r, Krishna	a Irrigation Di	vision, S	atara		1				1
47	Urmodi	2012	73°54'40"	51.10	282.14	2407		Gated	18.05.2021	3.1, 3.6,3.9, 3.11, 3.13,	15
	Tal.Parali&		17°40′00″				MH09HH		02.12.2021	3.18, 3.19, 3.20, 3.21,	
	Dist. Satara						1594			3.23, 3.24, 3.26, 3.33,	
10	Kaabaa	4000	70055	50.04	000	2002		Catad	00.05.0004	3.34, 3.30.	00
48		1988	13 33 17 ⁰ 40'	50.34	280	3203		Galed	28.05.2021	3 9 3 11 3 12	23
	Tal. Salara		17 40						02.12.2021	3.13.3.18.3.19.3.20. 3.24.	
	DISL Salara									3.25, 3.26,3.27,	
							мноэнн			3.28,3.29,3.30, 3.31, 3.33,	
							1141		17 03 2022	3.34,3.35,3.36	
									17.00.2022		
[2]Cł	nief Engineer(S.P	.) Water R	esources De	partment	Pune			•			
(1)Sເ	uperintending Eng	gineer Ku	kadi Irrigatio	n Circle	Pune						
(a) E	xecutive Enginee	er, Kukadi	i Irrigation Di	v. 1 Nara	yangaon						
49	Wadaj	1983	73°52'30"	28.00	35.90	1426		Gated	05.06.2021	3.1,3.2,3.3,3.5,	21
	Tal.Junnar Dist.		19°09'00"				мноонн		11.11.2021	3.6,3.9,3.11,3.13,3.18,,	
	Pune						1006		18.03.2022	3.19,3.20, 3.23, 3.24,	
							1000			3.25, 3.26,3.28,	
										3.29,3.30,3.31,3.32,3.34	
50	Yedgaon	1977	74°01'30"	2360	69.204	3844	мноомн	Gated	05.06.2021	3.1, 3.5, 3.6, 3.7, 3.9,	12
	Tal.Junnar		19°10'30"				0658		11.12.2021	3.13, 3.20, 3.23,3.24,	
	Dist. Pune						0000			3.25,3.28,3.31,	
51	Manikdoh	1984	73 [°] 49'00	53.00	308.06	143	MH09HH	Gated	13.05.2021	3.1,3.2,3.6,3.11,3.13,3.18	18

Sr. No	Name of Dam	Date of Compl	Location Longitude/	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien
		otion	Lunduo			m ³ / sec	regiotor		110 0 1 000		0.00
1	2	3	4	5	6	7	8	9	10	11	12
	Tal. Junnar		19 ⁰ 14'00				1060		11.12.2021	,3.20,3.21,3.22,3.23.3.24,	
	Dist. Pune									3.25,3.28,3.31,	
										3.33,3.34,3.35,3.36	
52	Pimpalgaon	2000	73 ⁰ 52'30"	28.97	235.28	1167.3		Gated	12.06.2021	3.1,3.2,3.4,3.5,3.6, 3.7,	21
	joge		19°18'45"				мноомн		12.11.2021	3.9, 3.11, 3.13, 3.18,	
	Tal. Junnar						1520			3.19,3.20, 3.21, 3.23,	
	Dist. Pune						1020			3.24, 3.25, 3.26, 3.31,	
			0					_		3.32,3.33,3.34	
53	Dimbhe	2001	73°44'30"	72.10	382.22	2870	мноэнн	Gated	15.5.2021	3.1, 3.6,3.13,.3.18, 3.20,	13
	Tal. Ambagaon		19°5'45"				1558		11.11.2021	3.23, 3.24, 3.25, 3.29, 3.30,	
	Dist. Pune									3.31, 3.34.,3.35	
(b)E	xecutive Enginee	r, Kukadi	Irrigation Div	1.2 Shrigo	onda						
54	Ghod	1965	74°51'50	34.75	216.30	7465		Gated	05.05.2021	3.1, 3.2, 3.5,3.6, 3.9,	21
	Tal. Shirur		17° 8'10"				мноэмн		10.12.2021	3.10, 3.15, 3.16, 3.19,	
	Dist. Pune						0117			3.20, 3.21, 3.23, 3.24,	
							••••			3.26, 3.27, 3.28, 3.29,	
										3.30, 3.31, 3.34,3.35.	
D) E	xecutive Enginee	r, Kukadi	Irrigation Div	ISION NO.	2, Shrigon	da			00.00.0004		04
55	C:								08.06.2021	3.1, 3.5, 3.6, 3.7, 3.9,	21
	Sina Tol Koriot	1005	74°57'00"	00 F	67.05	4450	MH09MH		19.11.2021	3.16, 3.19, 3.20, 3.21,	
	Diet A Neger	1985	18°49'00"	28.5	67.95	4450	1142			3.22, 3.23, 3.24, 3.25,	
	Dist A. Nagar									3.20, 3.27, 3.28, 3.29,	
(a) F	waantina Enginaa	r Dimaha		onohor						3.31,3.32,3.33,3.35.	
(C) E				anchar	07.17	1696		Cotod	21 05 2021	21 2526 20211	10
90		2000	73 50 00 10 ⁰ 21'00"	02.50	27.17	1080		Galed	21.05.2021	3.1, 3.5, 3.0, 3.9, 3.11,	19
	Diet Duno		19 21 00				MH09HH		03.11.2021	3.10, 3.20, 3.21, 3.22,	
	DISI. FUILE						1553			3.24,3.23, 3.20,3.27,	
										3 22 3 23 3 3 4	
(2)5	uporintonding Er	ainoor Sa	tara Irrigatio	Project	Circle Sat					3.32,3.33,3.34	
(2)3 (2)5	vecutive Engineer	r Minor	Irrigation Divi	sion Sat	ara	ala					
57		2001	74°28'00"	44 45	24 925	1223		Ungated	12 4 2020	31323639318320	12
0,	Tal Patan	2001	17°24'24"		27.020	1220	MH09HH	Singuieu	2 12 2020	3 21 3 24 3 26 3 29 3 30	12
	Dist. Satara						1591		22.2020	3.31	

Sr.	Name of Dam	Date of	Location	Heigh	Gross	Design Spillwov	Sr.No. in	Gated /	Date of	Deficiencies noticed	Total Deficion
NO		-etion	Latitude	m	Mm ³	Capacity	Register	Ungated	Pre & Post		cies
						m°/sec					10
1	2	3	4	5	6	7	8	9	10	11	12
58	Morna(Guregh	2013	73°50'00"	47.02	36.99	2247		Ungated	13.05.2021	3.1,3.2,3.3,3.4,3.6,3.9,	17
	ar) Tel Deter Diet		17°17′30″				MH09HH		09.11.2021		
	Tal.PatanDist.						1664			3.19,3.20,3.21,3.233.24,3	
50	Satara	4000	70054145"	40.00	0.47	2000		Catad	04.05.0004	.25, 3.26,3.28,3.29, 3.31	40
59	Nagewadi	1999	73 51 45 47 ⁰ 55'47"	40.02	6.47	326	мноэнн	Gated	04.05.2021	3.1,3.3,3.13,3.20,3.21,	13
	Tal. Wai Dist.		17 55 17				1518		14.11.2021	3.22,3.24,3.26,3.29,3.30,	
	Satara									3.32,3.33,3.34	
(b)E	xecutive Enginee	r,Kanher	Canal Divisio	n No.2, I	Karwadi,Kar	ad.		-		1	1
60	Tarali	2007	73°54'15"	73.41	165.70	1721	мноэнн	Gated	06.05.2021	3.9,3.10,3.13,3.19,3.20,	13
	Tal. Patan		17°32'00"				1666		21.05.2021	3.21,3.22,3.24,3.28,3.30,	
	Dist. Satara									3.31,3.34,3.36	
(b)E	xecutive Enginee	r, Dhom C	anals Divisio	n No.2,S	atara		T				
61	Mahu	2001	73°48'30"	54.35	31.052	705	мноэнн	Gated	28.04.2021	3.13,3.20,3.24,3.26,3.34	5
	Tal Jawali Dist.		17°52'30"				1588		08.11.2021		
	Satara	<u> </u>	750 40100"	00.55	77.074	450			00.4.0004	0.5.0.00.0.01.0.01.0.00	
62	Hatgeghar	Gorge in 2001	75°49'00″	38.55	11.371	150	MH09HH	Ungated	20.4.2021	3.5,3.20,3.21,3.24,3.26	8
	Tal Jawali Dist.	Dam under	17°52'30″				1568		08.11.2021	,3.30,3.31,3.34	
	Satara	constructio									
		n									
c)Ex	ecutive Engineer	Minor Irr	igation Divisi	on Satai	(a)						
63	Kalgaon	Work in		Un ,Oala	u			Ungated	29.04.2021	3 1 3 6 3 9 3 13 3 16 3 18	13
00	Tal Patan Dist	progres	73°56'45"	33 50	2 692	199 64	MH09HH	ongated	09 11 2021	3 24 3 26 3 27 3 29 3 30	10
	Satara	s	17°09'03"	00.00	2.052	133.04	2416		05.11.2021	3 32 3 36	
64	Kusawade	2010	73°51'47"		3 495			Ungated	27 04 2021	31333639310318	12
04	Tal Satara	2010	17°34'46''	30.90	0.400			ongated	21 11 2021	3 20 3 21 3 24 3 26 3 30	12
	Dist. Satara			50.00						3.34	
						155.02	мноэнн				
							2411				

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Heigh t in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11	12
D)Ex	cecutive Engineer	, Uramod	i Dam Divisio	n ,Satara	1						
65	Pangare Tal. Satara Dist. Satara	2000	73°52'30" 37°09'01''	32.10	2.72	255.65	NA	Ungated	29.05.2021 23.11.2021	3.5,3.22,3.26,3.30,3.33	5
(3)Si	uperintending Eng	gineer & A	Administrator	, C.A.D.A	A. Solapur						
(a) E	xecutive Enginee	r, Solapu	r Irrigation Di	vision S	olapur						
66	Bori Tal. Akkalkot Dist.Solapur	2005	76°04'00" 17°37'00"	15.20	23.292	3653	MH09MH. 1641	Gated	31.05.2020	3.6,3.13,3.16,3.20,3.21,3. 24,3.26,3.27,3.28,3.30,3. 31,3.33	12
67	Ekrukh Tal & Dist Solapur	1871	75°54'30" 17°43'30"	21.45	61.160	1381	MH09MH 0007	Ungated	12.05.2020	3.1,3.2,3.4,3.5,3.6,3.9, 3.10,3.13,3.16,3.26,3.27, 3.30	12
(b)E	xecutive Enginee	r, Ujjani 🛛	Dam Managen	nent Div	ision Bhima	anagar Dist	. Solapur				
68	Ujjani Tal. Madha Dist Solapur	1980	73 ⁰ 7'18'' 14 ⁰ 08'00'	56.40	332	180.10	MH09HH 0843	Gated	11.05.2020	3.1,3.5,3.6,3.7,3.9,3.10, 3.13,3.18,3.19,3.20,3.22, 3.28,3.31,3.35	14
(4)Si	uperintending Eng	gineer Os	smanabad Irri	gation C	ircle Osmai	nabad					
(a)E	xecutive Engineer	r, Sinakol	egaonProject	Division	ParandaDis	t.Osmanaba	ad				
69	Sinakolegaon Tal.Paranda Dist.Osmanaba d	2007	7 <u>5°23'55</u> " 18°18'59"	36.60	19.19	3653	МН09МН 1673	Gated	03.03.2021 21.11.2021	3.1,3.2,3.5,3.6,3.7,3.9 ,3.10,3.13,3.18,3.20,3.24, 3.26,3.27,3.28,3.29,3.30, 3.31,3.32,3.33,3.4,3.36	21

Table 3.13

Class-II Dams with Category-1 Deficiency

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Observation / Significant Deficiencies noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
			- No Such Da	ams under this	category is reported	

Table 3.14

Class-II Dams with Category-2 Deficiency

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
NO.		n	Officer	of Dam		
1	2	3	4	5	6	7
[A]Chie	ef Engineer (W.R.) Water Resour	ces Departm	ent, Pune		-	-
(1)Supe	erintending Engineer Pune Irriga	tion Circle, I	Pune			
(a)Exec	cutive Engineer, Pune Irrigation	Division, Pu	ne			
1	Name : Marnewadi	4.5.2021	Shri.	Outlet	Strenghtening work is essential for	Necessary repairs to be carried out
	Tal. Mulashi Dist. Pune	Not Received	Rajendra		outlet well.(A6)	Superimpose
	Date of completion:-1998		Dhodapkar			
	Location :		E.E		2. The stem rod for lifting the gate is	Necessary repairs should be carried
	Longitude - 73°40'00"		PID. Pune	Outlet Gate	not perfectly straight.(B5)	out.
	Latitude- 18°30'00"					Depending on severity of bending
	Height :- 18.35 m.					Stem Rod should be either repaired
	Gross capacity :- 0.87 Mcum					or replaced in consultation with
	Sr.No.In Large Dam Register					Mechanical Organization.
	2012: MH09MH1453					
1						

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
2	Name : Mahakoshi	2.6.2021	Shri.	W.W.Bar	1. Spillway central portion	Necessary repairs should be carried
	Tal.Mulashi Dist. Pune	Not	Rajendra		38.00mtr washed out. (B7)	out.
	Date of completion:-1998	Received	Dhodapkar			
	Location:		E.E	Outlet	2. The stem rod for lifting the	Depending on severity of bending
	Longitude :-73°50'00"		PID. Pune		gate is not perfectly	Stem Rod should be either repaired
	Latitude : -18°05'00"				straight.(B5)	or replaced in consultation with
	Height :-24.00 m.					Mechanical Organization.
	Gross capacity :- 2.28 Mcum					
	Sr.No.In Large Dam Register					
2	2012. MINU9MIN 1474	4 5 2021	Shri	Outlot	1. The store red for lifting the	Depending on coverity of bonding
5.	Tal Mulashi Dist Pune	4.5.2021 Not	Baiendra	Oullet		Stem Rod should be either repaired
	Date of completion:-1983	Received	Dhodapkar		gate is not perfectly	or replaced in consultation with
	Location:	rteeereu	E.E		straight.(B5)	Mechanical Organization
	Longitude :- 74°56'00 "		PID. Pune			
	Latitude : -18°30'00"					
	Height :-23.48 m.					
	Gross capacity :- 2.00 Mcum					
	Sr.No.In Large Dam Register					
	2012: MH09MH0964					
4.	Name : Rihe		Shri.	Outlet	1.The stem rod for lifting the	Depending on severity of bending
	Tal.Mulashi Dist. Pune	29.4.2021	Rajendra		gate is not perfectly	Stem Rod should be either repaired
	Date of completion:-1977		Dhodapkar		straight.(B5)	or replaced in consultation with
			E.E			Mechanical Organization
			PID. Pune			
	Latitude : -18°34'00"		Tost			
	Gross conscient 1 59 Mour	27/8/2021	inspected by		2 Divide wall between	Repairs of the same shall be done
	Sr No In Largo Dam Pogistor	21/0/2021	FF DSD 1	Divide wall	embankment and overflow	in consultation with CDO Nashik
	2012 MH09MH0642		Nashik	Divide wai	section shows leakages(A16)	with preapproval from competent
						field officials before taking the work
						in hand.
					3. Earthen section seems to be	Superimpose Existing Cross
					under section in certain portion.	Section on Design Cross Section at

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
					Undulations on dam top is observed.(B1)	every 30 m C/C to ascertain whether earthen embankment is
						under section or not. Communicate facts to DSO, Nashik.
					4. Downstream nappe of WW bar is in damaged condition.Also leakages are observed from WW Bar.(B7)	Repairs of the same shall be done in consultation with CDO, Nashik with preapproval from competent field officials before taking the work
						in hand.
5	Name : Hadashi Tal.Mulashi Dist. Pune Date of completion:-1991 Location: Longitude :-73°32'00" Latitude : -18°36'00" Height :-21.83 m. Gross capacity :- 3.07 Mcum Sr.No.In Large Dam Register 2012:MH09MH1235	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
6	Name : Divale Tal.Mulashi Dist. Pune Date of completion:- 1985 Location: Longitude :- 73°55'00'' Latitude : - 18°15'00'' Height :- 20.83 m. Gross capacity :- 2.14 Mcum Sr.No.In Large Dam Register 2012: MH09MH1082	2.6.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
7	Name : Naigaon Deogaon Tal.BhorDist. Pune Date of completion:-1979 Location: Longitude :-73°53'00" Latitude : -18°17'00" Height :-22.49 m. Gross capacity :- 1.332 Mcum Sr.No.In Large Dam Register 2012:MH09MH0762	2.6.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
8	Name : Wagajwadi Tal.Bhor Dist. Pune Date of completion:- 2001 Location: Longitude :- 73°50'00'' Latitude : - 18°15'00'' Height :- 20.57 m. Gross capacity :- 1.66 Mcum Sr.No.In Large Dam Register 2012: MH09MH1235	24.5.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
9	Name : Bhongawali Tal.Bhor i Dist. Pune Date of completion:- 2015 Location: Longitude :- 74°00'00'' Latitude : - 18°15'00'' Height :- 25.00 m. Gross capacity :- 3.32 Mcum Sr.No.In Large Dam Register 2012: Proposed for NRLD	2.6.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
-----	---	------------------------------	--	------------------	---	---
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
10	Name : Gadadavne Tal.Mulashi Dist. Pune Date of completion:-2007 Location: Longitude :-73°32'00" Latitude : -18°36'00" Height :-21.83 m. Gross capacity :- 3.07 Mcum Sr.No.In Large Dam Register 2012:MH09MH1235	4.5.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet WW Bar	 The stem rod for lifting the gate is not perfectly straight.(B5) Spillway centre portion 38m is washed out. (B7) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
11	Name : Hadashi-2 Tal.Mulashi Dist. Pune Date of completion:-1999 Location: Longitude :-73°52'00" Latitude : -18°36'00" Height :-20.45 m. Gross capacity :- 1.14 Mcum Sr.No.In Large Dam Register 2012:MH09MH1674	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
12	Name : Khamboli Tal.Mulashi Dist. Pune Date of completion:- 2000 Location: Longitude :- 73°35'00'' Latitude : - 18°35'00'' Height :- 25.36 m. Gross capacity :- 2.065 Mcum Sr.No.In Large Dam Register 2012: MH09MH1535	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
13	Name : Pimpoli Tal.Mulashi Dist. Pune Date of completion:- 1984 Location: Longitude :- 73°30'00" Latitude : - 18°36'00" Height :- 22.13 m. Gross capacity :- 1.53 Mcum Sr.No.In Large Dam Register 2012: MH09MH1045	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
14	Name : Shere Tal.Pune Dist. Pune Date of completion:-1998 Location: Longitude :-73°52'00" Latitude : -18°36'00" Height :-22.98 m. Gross capacity :- 1.72 Mcum Sr.No.In Large Dam Register 2012:MH09MH1235	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
15	Name : Walen Tal.Mulashi Dist. Pune Date of completion:-1989 Location: Longitude :-73°30'00" Latitude : -18°35'00" Height :-20.75 m. Gross capacity :- 1.51 Mcum Sr.No.In Large Dam Register 2012:MH09MH1216	29.4.2021 Not received	Shri. Rajendra Dhodapkar E.E PID. Pune	Outlet	1.The stem rod for lifting the gate is not perfectly straight.(B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
16	Name : Chinchwad Tal.Pune Dist. Pune Date of completion:-1984	4.5.2021 Not received	Shri. Rajendra Dhodapkar	Outlet	1. The stem rod for lifting the gate is not perfectly straight (B5)	Stem Rod should be either repaired or replaced in consultation with
	Location:	Teoervea	E.E		Straight.(D0)	Mechanical Organization
	Longitude :- 73°40'00" Latitude : - 18°36'00"		PID. Pune			
	Height :- 21.83 m.					
	Sr.No.In Large Dam Register					
(b)Exe	cutive Engineer Khadakwasala li	rigation Div	ision, Pune11			
17	Name : Bhugaon		Shri.	Earthen	1. Sectioning of embankment is	Necessary repairs should be carried
	Tal. Mulashi Dist. Pune	22.5.2021	V.P.Patil	Embankmen	necessary(B1)	out.
	Date of completion:-1983	5.12.2021	E.E	t		
	Longitude: -73° 45'00"		KID. Pune			
	Latitude:-18°30'00"					
	Gross conscitute 1 00 Moum					
	Sr No In Large Dam Register					
	2012: MH09MH0963					
18	Name : Matoba	23.5.2021	Shri.	E. E.	1. Standing pool of water	This area should be well drained so
	Tal. Daund Dist. Pune	28.11.2021	V.P.Patil		observed on RHS of	as to avoid any stagnant pools of
	Date of completion:-1978		E.E		embankment at some places.	water.
	Longitude: -74° 34'00"		KID. Pune		(A2)	
	Latitude:-18°00'23"			www.Bar	2. Stone of masonry spillway and	Necessary repairs should be
	Height :-17.50				due to beavy rain Foundation	carried out
	Sr No In Large Dam Register				of spillway is now visible.	
	2012: MH09MH0721				Masonry spillway bar need	
					strengthening urgently.(B7)	Necessary repairs should be
				Tail channel	3. Huge scouring is observed on	carried out
					D/S of bar.(A7)	

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
19	Name : Malad Tal. Daund Dist. Pune Date of completion:- 1979 Longitude: - 74° 34'00" Latitude:- 18°23'00" Height :- 15.63 Gross capacity :- 1.74 Mcum Sr.No.In Large Dam Register 2012: MH09MH0796	23.5.2021 28.11.2021	Shri. V.P.Patil E.E KID. Pune	Outlet Tail Channel	 Leakages through outlet well observed.(A6) Outlet gate not in operation since 10 years. (B5) 	Necessary repairs should be carried out. It should be repaired. Necessary repairs should be carried out
20	Name : Palasdeo Tal. Indapur Dist. Pune Date of completion:- 1953 Longitude: - 74° 34'00" Latitude:- 18°23'00" Height :- 18.23 Gross capacity :- 1.09 Mcum Sr.No.In Large Dam Register 2012: MH09MH0063	23.5.2021 28.11.2021 Test Inspected by DSO 31.1.2022	Shri. V.P.Patil E.E KID. Pune Test Inspected by EE DSD1 nashik	W.W.Bar	 W. W. Bar is damaged due to heavy rainfall@ 14.10 2020 (B7) Scouring is observed on d/s side of bar.(A7) Earthen section seems to be under section in certain portion.(B1) 	Necessary repairs should be carried out. Necessary repairs should be carried out. Superimpose Existing Cross Section on Design Cross Section at every 30 m C/C to ascertain whether earthen embankment is under section or not. Communicate facts to DSO, Nashik.
21	Name : Shirsuphal Tal. Baramati Dist. Pune Date of completion:- 1879 Location: Longitude: - 74° 35'20" Latitude:- 18°21'00" Height :- 20.11 Gross capacity :- 10.1 Mcum Sr.No.In Large Dam Register 2012: MH09MH0011	23.5.2021 28.11.2021 Test Inspected by DSO 31.1.2022	Shri. V.P.Patil E.E KID. Pune Test Inspected by EE DSD1 nashik	Earthen Embankmen t Downstream side	 Crest profile is below by 1.15 m. than design crest and section is disturbed. (B1) Ponding observed on immediate downstream side of Dam.(A2) 	Necessary repairs are to be carried out to proper section after confirmation by competent field authority. Exact Source from which that particular water is coming, should be find out and do necessary action for the same.

Sr. No.	Dam Features	Date of	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested	
		n		of Dam			
1	2	3	4	5	6	7	
(d) Executive Engineer, Nira Right Bank Canal Division, Phaltan							
22	Name : Naigaon	15.5.2021	Shri.	W.W. Bar	1. Waste weir bar is damaged	Necessary repairs are to be carried	
	Tal.Khandala Dist. Satara	Not	S.R.	and tail	condition. Heavy Leakage is	out. Leakage record needs to verify	
	Date of completion: 1983	received	Bodke	channel	observed through Waste weir	before repair.	
	Location:		E.E.		bar. (B7)		
	Longitude: 73° 58' 5"		N.R.B.C.				
	Latitude: 18° 06' 10"		Division				
	Height : 18.0 m.		Phaltan				
	Gross capacity :1.34 Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09MH.0986						
23	Name : Mhasavad	17.5.2021	Shri.	EE	1.Cracks are observed in	Necessary repairs are to be carried	
	Tal.Man Dist. Satara	Not	S.R.		longitudinal direction. (B4)	out.	
	Date of completion: 1876	received	Bodke				
	Location:		E.E.				
	Longitude: 74° 53' 00"		N.R.B.C.				
	Latitude: 17° 35' 00"		Division				
	Height :24.00m.		Phaltan				
	Gross capacity :46.13Mcum						
	Sr.No.In Large Dam Register						
	2012: MH09ŇH0017						
24	Name : Banganga	23.5.2021	Shri.	Downstream	1. Wet patches are seen at	Necessary repairs are to be carried	
	Tal.Phaltan Dist. Satara	23.10.2021	S.R.		downstream portion between	out to proper section after	
	Date of completion: 1975		Bodke		LBC and RBC (A2)	confirmation by competent field	
	Location:		E.E.	EE		authority.	
	Longitude: 74° 25' 5"		N.R.B.C.				
	Latitude: 17° 40' 00"		Division		2. Edges of crest are cut up	Necessary repairs should be carried	
	Height :16.76m.		Phaltan		resulting reduction in width of	out	
	Gross capacity :6.50 Mcum				dam top(B1)		
	Sr.No.In Large Dam Register						
	2012: MH09MH.0071						

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
25	Name : Girzani Tal.Malshiras Dist. Satara Date of completion: 1989 Location: Longitude: 74° 59' 00" Latitude: 17° 52' 00" Height :17.98m. Gross capacity :2.07 Mcum Sr.No.In Large Dam Register 2012:MH09MH1223	23.5.2021 Not received	Shri. S.R. Bodke E.E. N.R.B.C. Division Phaltan	Relief wells	1.Relief wells are not working condition. (A5)	Necessary repairs should be carried out
26	Name : Hingangaon Tal.Khatav Dist. Satara Date of completion: 1975 Location: Longitude: 74° 58' 05" Latitude: 17° 06' 10" Height :17.53m. Gross capacity :1.47 Mcum Sr.No.In Large Dam Register 2012:MH09MH0473	22.5.2021 4.11.2021	Shri. S.R. Bodke E.E. N.R.B.C. Division Phaltan	D/s	1.Sign of water logging, slushy conditions and growth of acquatic weeds on d/s of dam observed.(A2)	Necessary repairs should be carried out
27	Name : Tambave Tal.Phaltan Dist. Satara Date of completion: 1966 Location: Longitude: 74° 10' 00" Latitude: 18° 00' 00" Height : 16.80m. Gross capacity : 5.42 Mcum Sr.No.In Large Dam Register 2012: MH09MH0167	22.5.2021 4.11.2021	Shri. S.R. Bodke E.E. N.R.B.C. Division Phaltan	D/S	1.Sign of water logging, slushy conditions and growth of acquatic weeds on d/s of dam observed.(A2)	Necessary repairs should be carried out

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
28	Name : Phondshiras Tal.Malshiras Dist. Satara Date of completion: 1966 Location: Longitude: 74° 49' 00'' Latitude: 18° 08' 00'' Height : 16.68m. Gross capacity : 2.92 Mcum Sr.No.In Large Dam Register 2012: MH09MH1277	25.5.2021 Test inspected by DSO 30.1.2022	Shri. S.R. Bodke E.E. N.R.B.C. Division Phaltan Test Inspected by EE DSD1 Nashik	D/S	1.Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam. (A2)	Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO.
	cutive Engineer Lift Irrigation M	anagement	Division Pune	<u> </u>		<u> </u>
29	Name : Pilanwadi Tal.Purander Dist. Pune Date of completion: 1978 Location: Longitude: 73° 52' 00" Latitude: 18° 36' 00" Height : 22.77 m. Gross capacity : 1.94 Mcum Sr.No.In Large Dam Register 2012: MH09MH.0729	27.5.2021 16.11.2021	Shri. M. B. Kanitkar, EE, L.I.M.D, Pune	Outlet	 Stem Rod of outlet gate is not in operation ,need to be changed.(B5) 	Necessary repairs to be carried out in consultation with mechanical organization.
30	Name : Garade Tal.Purander Dist. Pune Date of completion: 1979 Location: Longitude: 73° 55' 30" Latitude: 18° 15' 00" Height :18.82 m. Gross capacity :1.869 Mcum Sr.No.In Large Dam Register 2012:MH09MH.0794	20.5.2021 15.11.2021	Shri.M.B. Kanitkar EE LIMD,Pune	WW Bar	 Leakage through masonry from WW bar foundation is observed.(B7) 	Necessary repairs to be carried out

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
31	Name : Thitewadi Tal.Purander Dist. Pune Date of completion: 2003 Location:	13.5.2021 6.12.2021	Shri.M.B. Kanitkar EE LIMD,Pune	WW Bar	1.Guide bund 200 m length is washed out in heavy flood.(A16)	Necessary repairs to be carried out
	Longitude: 74° 02' 30" Latitude: 18° 48' 00" Height : 21.10 m. Gross capacity : 9.86 Mcum Sr.No.In Large Dam Register 2012: MH09MH1623			Tail Channel	2. Scouring (Aprox. Depth 1.5 m) in tail channel.(A7)	Necessary repairs to be carried out
(f)Exec	utive Engineer, Chaskaman Irrig	ation Divisio	on, Pune	1		
32	Name : Alegaon Pagga Tal.Shirur Dist. Pune Date of completion: 1971 Location: Longitude: 74° 12' 30" Latitude: 18° 43' 30" Height :17.30 m. Gross capacity :3.37 Mcum Sr.No.In Large Dam Register 2012:MH09MH.0993	23.5.2021 12.11.202 1	Shri. B. K. Shete, E E CID, Pune	EE	1.Dam profile is not as per designTop width of dam is not as per design section.(B1)	Necessary repairs to be carried out
33	Name : Nimgaon Mhalungi Tal.Shirur Dist. Pune Date of completion: 1971 Location: Longitude: 74° 12' 30" Latitude: 18° 43' 30" Height :17.30 m. Gross capacity :3.37 Mcum Sr.No.In Large Dam Register 2012:MH09MH.0993	23.5.2021 12.11.2021	Shri. B. K. Shete, E E CID, Pune	Earthen Embankment	 Embankment is not as per design section ./ T.W. is not as per design section.(B1) 	Necessary repairs should be carried out.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
34	Name : Dahiwadi Tal.Shirur Dist. Pune Date of completion: 1971 Location: Longitude: 74° 12' 30" Latitude: 18° 43' 30" Height : 17.30 m.	23.5.2021 12.11.2021	Shri. B. K. Shete, E E CID, Pune	WW Bar Outlet	 Top width of embankment is not as per design (B1) Outlet gate of left bank canal is not functioning.(B5) 	Necessary repairs should be carried out. Necessary repairs should be carried out.
	Gross capacity : 3.37 Mcum Sr.No.In Large Dam Register 2012: MH09MH.1623					
35	Name : Kadus Tal.Khed Dist. Pune Date of completion: 1986 Location: Longitude: 73° 55' 00"	23.5.2021 18.11.2021	Shri. B. K. Shete, E E CID, Pune	Outlet	1.Top width of embankment is not as per design B1	Necessary repairs should be carried out in consultation with mechanical organization.
	Latitude: 18° 56 00" Height : 16.65 m. Gross capacity : 2.63Mcum Sr.No.In Large Dam Register 2012: MH09MH.1126	Test Inspected by DSO 22.10.2021	Test Inspected by DSD1 Nashik		2.Guide wall of tail is washed away.A16	Repairs of the same shall be done in consultation with CDO, Nashik with preapproval from competent field officials before taking the work in hand.
					3.Downstream nappe of WW bar is in damaged condition.The Coping over spillway bar is in damaged condition.Pointing is required.(B7)	Necessary repairs shall be done in consultations with CDO, Nashik with preapproval from competent field officials before taking the work in hand.
					4. Retrogression and scouring on immediate downstream side of the bar is observed. Also Scouring in stilling basin is observed. (A7)	

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
(2)Sup	erintendingEngineer,Sangli Irriga	ation Circle S	angli			
Execut	ive Engineer,Sangli irrigation Di	vision, Sang	li			
36	Name : Antri Tal. Shirala Dist. Sangli Date of completion:- 1991 Location : Longitude -74°05′00 Latitude -17°02′00 Height :- 22.79 m. Gross capacity - 2.82Mcum Sr.No.In Large Dam Register MH09MH1215	23.5.2021 29.11.2021	Smt. J.A.Deokar EE,SID Sangali	Embankmen t Outlet	 Leakage or oozing is noticed on d/s side (A1) 	Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly. It should be repaired properly.
37	Name : Soradi Tal. Jath Dist. Sangli Date of completion:-1983 Location : Longitude -75°22′30" Latitude -17°03′05" Height :-18.08 m. Gross capacity - 4.40 Mcum Sr.No.In Large Dam Register MH09MH1002	11.5.2021 14.12.2021	Smt. J.A.Deokar EE,SIDSan gali	Outlet	1. Stem rod is not straight (B5)	Necessary remedial measures should be done in consultation with mechanical organization.
38	Name : Tippehalli Tal. Jath Dist. Sangli Date of completion:-1975 Location : Longitude -74°04′00" Latitude -17°08′00" Height :-18.12 m. Gross capacity - 2.02 Mcum Sr.No.In Large Dam Register MH09MH0513	18.5.2021 2.12.2021	Smt. J.A.Deokar EE,SIDSan gali	Outlet	1.Outlet gate is completely damaged .Stem rod is broken.(B5)	Necessary remedial measures should be done

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
39	Name : Bhiwargi Tal. Jath Dist. Sangli Date of completion:-2001 Location : Longitude -73°31′50" Latitude -17°25′00" Height :-15.85 m. Gross capacity - 11.2 Mcum Sr.No.In Large Dam Register MH09MH1597	28.5.2021	Smt. J.A.Deokar EE,SIDSan gali	WW Bar Outlet	1.There is leakage through WW bar. B72.There is leakage through outlet gate.A4	Necessary remedial measures should be done Necessary remedial measures should be done
40	Name- Daribadchi Tal. Jath Dist. Sangli Date of completion:-2010 Location : Longitude -75°24′00" Latitude -17°02′28" Height :-15.38 m. Gross capacity - 1.87 Mcum Sr.No.In Large Dam Register MH09MH29.1.2022	04.06.2021 14.12.2021 Test Inspected by DSO 29.1.2022	Smt. J.A.Deokar EE,SIDSan gali Test Inspected by EE DSD 1 nashik	D/S D/S	 On immediate d/s side Farm is there, hence its difficult to find out leakages from dam.(A2) As per report of field officials, leakages are observed on d/s side in monsoon season(A1) 	Regular vigilance should be there if there are leakages and record of the same should be maintained with respect to reservoir levels.
41	Name- Dodanalla Tal. Jath Dist. Sangli Date of completion:-1986 Location : Longitude -75°30'32" Latitude -17°13'00" Height :-16.20 m. Gross capacity - 6.50 Mcum Sr.No.In Large Dam Register MH09MH1136	11.05.2021 14.12.2021 Test Inspected by DSO 29.1.2022	Smt. J.A.Deokar EE,SIDSan gali Test Inspected by EE DSD 1 nashik	EE Toe of Dam	 Dam top seems to be undulating. Top width is reduced. Settlement of embankment and Gully formation on d/s side is observed. No proper access on dam top.(B1) Field officials reported that there is minor leakage approx 3 lps near gorge portion @ toe of dam.(A1) Stagnant Water (Ponding of Water) is observed on immediate 	Existing L-Section shall be superimposed on design L-Section to ascertain changes in design dam top level. Communicate facts to DSO, Nashik. Necessary remedial measures should be done Source of stagnant water shall be traced out by draining the same and

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
NO.		n	Officer	of Dam		
1	2	3	4	5	6	7
				D/S Outlet	 d/s side near Gorge portion of dam.(A2) 4.As per filed officials report, leakage through gate and through periphery of well is observed. Gate is not properly closed.(A6) 	facts regarding the same should be communicated to DSO. Proper maintenance of outlet gate should be done in consultation with mechanical wing with pre approval from competent authority.
42	Name- Shegaon Tal. Jath Dist. Sangli Date of completion:-1975 Location : Longitude -75°09'15" Latitude -17°09'02" Height :-19.82 m. Gross capacity - 8.08 Mcum Sr.No.In Large Dam Register MH09MH0529	18.05.2021 2.12.2021 Test Inspected by DSO 29.1.2022	Smt. J.A.Deokar EE,SIDSan gali Test Inspected by EE DSD 1 nashik	Dam Top D/S	 1.Dam top seems to be undulating. Top width is reduced. Settlement of embankment and Gully formation on d/s side is observed.(B1) 2. Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam.(A2) 	Existing L-Section shall be superimposed on design L-Section to ascertain changes in design dam top level. Communicate facts to DSO, Nashik. Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO.
43	Name- PratappurTal. Jath Dist. SangliDate of completion:-1987Location :Longitude -75°04'00"Latitude -17°09'25"Height :-16.90 m.Gross capacity - 1.66 McumSr.No.In Large Dam RegisterMH09MH1165	04.05.2021 2.12.2021 Test Inspected by DSO 28.1.2022	Smt. J.A.Deokar EE,SIDSan gali Test Inspected by EE DSD 1 nashik	D/S	1.Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam.(A2)	Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
44	Name- Birnal Tal. Jath Dist. Sangli Date of completion:-1977 Location : Longitude -75°20'00" Latitude -17°04'50" Height :-18.60 m. Gross capacity - 2.433 Mcum Sr.No.In Large Dam Register MH09MH0637	18.05.2021 2.12.2021 Test Inspected by DSO 28.1.2022	Smt. J.A.Deokar EE,SIDSan gali Test Inspected by EE DSD 1 nashik		 1.Dam top seems to be undulating. Top width is reduced. Earthen section seems to be under section in certain portion. (B1) 2. WW Bar is damaged at some places.(B7) 3. Well is not in working condition. Operation of outlet gate is not seems to be smooth.(A6) 	Superimpose Existing Cross Section on Design Cross Section at every 30 m C/C to ascertain whether earthen embankment is under section or not. Communicate facts to DSO, Nashik. Repairing of the WW Bar is necessary as per design drawing. Trial Run of Gate/Valve is must to keep it fit for emergency use. Authenticated Register of Trial run must be maintained.
(a) Exe	cutive Engineer, Tembhu Lift Irri	gation Projec	t Managemen	t Division, Og	alewadi	
45	Name- Chinchani Tal. Kadegaon Dist. Sangli Date of completion:-1989 Location : Longitude -73°31′50" Latitude -17°20′25" Height :-17.46 m. Gross capacity - 4.31 Mcum Sr.No.In Large Dam Register MH09MH1222	6.1.2021 30.11.2021	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Outlet	1. Minor bend is observed in stem rod. Rubber seals of some automatic gates are damaged and one manually operated gate is not in operating condition. (B5)	Necessary remedial measures should be done in consultation with mechanical organization.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	_	
		n		of Dam		
1	2	3	4	5	6	7
46	Name : Atpadi Tal. Atpadi Dist. Sangli Date of completion:- 1972 Location : Longitude -74°55′00" Latitude -17°24′00" Height :- 16.50 m. Gross capacity - 8.67Mcum Sr.No.In Large Dam Register MH09MH0314	6.5.2021 30.10.2021	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Outlet	1. Stem rod is bent (B5)	Necessary remedial measures should be done in consultation with mechanical organization.
47	Name : Buddhihal Tal. Mangalwedha Dist. Solapur Date of completion:- 1966 Location : Longitude - 74°59'54 '' Latitude - 17°18'30'' Height :- 18.52 m. Gross capacity - 19.03Mcum Sr.No.In Large Dam Register MH09MH0134	23.4.2021 12.10.2021 Test Inspected by DSO 29.1.2022	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi Test Inspected by DSD 1 Nashik	Embankmen t	 Raincuts are developed on embankment. Crest profile is not at proper elevation. Undulations and local depression are observed. (B4) There are major leakages through gate.(A4) Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam. (A2) 	Original dam section should be restored. Necessary remedial measures should be done Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO.
48	Name : Dighanchi Tal. Atpadi Dist. Sangli Date of completion:- 1976 Location : Longitude - 74°55'30'' Latitude - 17°24'30'' Height :- 15.80 m. Gross capacity - 4.0Mcum Sr.No.In Large Dam Register MH09MH0591	6.5.2021 30.10.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	1. Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
49	Name : Ghanand Tal. Atpadi Dist. Sangli Date of completion:- 1986 Location : Longitude - 74°44'00'' Latitude - 17°44'30'' Height :- 15.46 m. Gross capacity - 1.44 Mcum Sr.No.In Large Dam Register MH09MH1120	7.4.2021 4.10.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	1. Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
50	Name : Hingangaon Tal. Atpadi Dist. Sangli Date of completion:- 1998 Location : Longitude - 74°12'00'' Latitude - 17°55'30'' Height :- 16.02 m. Gross capacity - 2.01 Mcum Sr.No.In Large Dam Register MH09MH1462	22.4.2021 8.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	1.Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
51	Name :Kadegaon Tal. Kadegaon Dist. Sangli Date of completion:- 1975 Location : Longitude -74°16′00" Latitude -17°16′00" Height :- 17.54 m. Gross capacity - 2.36 Mcum Sr.No.In Large Dam Register MH09MH0510	22.4.2021 8.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Embankmen t Outlet	 There is standing pool on d/s side at 400m. chainage (A2) Leakage or oozing through dam slope is observed(A1) Stem rod is slightly bent.(B5) Masonry of outlet well is 	It should be kept under observation and its source should be identified Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly. Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
					disturbed at top coping (A6)	It should be repaired properly

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
52	Name :Karandewadi Tal Kadegaon Dist. Sangli Date of completion:-1995 Location : Longitude -74°17'12" Latitude -17°22'00" Height :-18.45 m. Gross capacity - 1.36Mcum Sr.No.In Large Dam Register MH09MH1348	22.4.2021 8.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Embankmen t Outlet	 Settlement is gorge is observed, top width is reduced than design. (B1) Stem rods are not straight.(B5) 	Original dam section should be restored. Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
53	Name : Morale Tal Tasgaon Dist. Sangli Date of completion:- 1974 Location : Longitude - 74°42'09 " Latitude - 17°11'43 " Height :- 16.10 m. Gross capacity - 0.65 Mcum Sr.No.In Large Dam Register MH09MH023	2.5.2021 29.10.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	General	 Approach road is not provided. (B6) 	Road should be constructed
54	Name : Nimbhavade Tal Atadi Dist. Sangli Date of completion:- 1986 Location : Longitude - 74°52'30'' Latitude - 17°28'00'' Height :- 16.13 m. Gross capacity - 6.68 Mcum Sr.No.In Large Dam Register MH09MH1187	6.5.2021 30.10.2021	Shri. L.B.Kengar SDO,TLIM Dn. Ogalewadi	Embankment Outlet	 Outlet well is not in good condition. Concrete on top of well is disturbed (A6) Stem rod is bent (B5) 	It should be repaired properly Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n .		of Dam		
1	2	3	4	5	6	7
55	Name : Pare Tal Khanapur Dist. Sangli Date of completion:- 1973 Location : Longitude - 74°35'00'' Latitude - 17°12'00'' Height :- 18.73 m. Gross capacity - 34.6 Mcum Sr.No.In Large Dam Register MH09MH0296	24.4.2021 9.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Masonry Portion	 Upper slab, masonary portion of 1.5 m height completely damaged. (A6) 	It should be repaired properly
56	Name : Ped Tal Tasgaon Dist. Sangli Date of completion:- 1972 Location : Longitude - 74°40'08'' Latitude - 17°12'05'' Height :- 19.04 m. Gross capacity - 1.57 Mcum Sr.No.In Large Dam Register MH09MH0272	2.5.2021 29.10.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	1.Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
57	Name : Vejegaon Tal Khanapur Dist. Sangli Date of completion:- 1979 Location : Longitude - 74°36'00'' Latitude - 17°23'00'' Height :- 16.77 m. Gross capacity - 2.21 Mcum Sr.No.In Large Dam Register MH09MH0296	24.4.2021 9.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	D/S	1. Boils and wet patches are observed on downstream side (A1)	Necessary repairs should be carried out properly.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
58	Name : Walunj Tal Lath Dist. Sangli Date of completion:- 1984 Location : Longitude -74°00'37" Latitude -17°00'19" Height :- 17.81 m. Gross capacity - 1.69 Mcum Sr.No.In Large Dam Register MH09MH0635	24.4.2021 9.11.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	1.Stem rod is bent (B5)	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
59	Name : Mahadikwadi Tal Atpadi Dist. Sangli Date of completion:- 2003 Longitude - 74°40'00'' Latitude - 17°11'00'' Height :- 16.02 m. Gross capacity - 2.10 Mcum Sr.No.In Large Dam Register MH09MH1547	6.5.2021 30.10.2021	Shri.R.Y. Reddiyar EE,TLIPD Ogalewadi	Outlet	 Leakage through outlet gate is observed (A4) 	Necessary remedial measures should be done in consultation with mechanical organization.
(3)Sup	erintending Engineer, Kolhapur	Irrigation Cir	cle, Kolhapur			
(a) Exe	ecutive Engineer. Kolhapur Irriga	tion Division	, (North) Kolh	apur		
60	Name : DaryachiVadgaon Tal. Chandgad Dist. Kolhapur Date of completion:- 1993 Location: Longitude:- 74°00' Latitude: - 16°36' Height -: 23.65 m. Gross capacity- 0.8473 Mcum Sr.No.In Large Dam Register 2012: MH09MH1302	15.5.2021 20.10.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Embankment	 Leakage through dam body is observed when water level at R.L. 88.00 to 92.70 m. from ch.135 to 195 m, but water is clear.(A1) 	Leakage data should be mainted and reason for leakage should be investigated & treated properly. It should be kept under observation strictly.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	_	
		n		of Dam		
1	2	3	4	5	6	7
61	Name : Kasarde Tal. Shahuwadi Dist. Kolhapur Date of completion:- 2009 Location: Longitude -74°51′00" Latitude -16°55′30" Height -: 29.85 m. Gross capacity- 4.416 Mcum Sr.No.In Large Dam Register 2012: MH09MH1908	17.5.2021 24.11.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Embankment Outlet	 There are some boils / wet patches on downstream of dam within 200m. (A1) Stem rod was broken in monsoon season.(B5) 	Necessary repairs should be carried out properly Necessary repairs should be carried out properly
62	Name : Andur Tal. Gadhinglaj Dist. Kolhapur Date of completion:- 1982 Location: Longitude -73°58′00" Latitude -16°36′00" Height -: 24.51 m. Gross capacity- 5.75 Mcum Sr.No.In Large Dam Register 2012: MH09MH0914	12.5.2021 24.10.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Outlet	1.Stem rod is slightly bend. (B5)	Necessary repairs should be carried out properly
63	Name : Kode Tal. Gadhinglaj Dist. Kolhapur Date of completion:- 1989 Location: Longitude -73°52'00" Latitude -16°28'00" Height -: 24.77 m. Gross capacity- 6.06 Mcum Sr.No.In Large Dam Register 2012: MH09MH1224	12.5.2021 24.10.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Outlet	1.Stem rod is slightly bend.(B5)	Necessary repairs should be carried out properly

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
64	Name : Manoli Tal. Gadhinglaj Dist. Kolhapur Date of completion:- 2000 Location: Longitude -74°45′30" Latitude -16°55′00" Height -: 29.50 m. Gross capacity- 5.196 Mcum Sr.No.In Large Dam Register 2012: MH09MH1537	17.5.2021 24.11.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	D/S	1.Boils, wet patches, water seepage on d/s of dam observed.(A1)	Necessary repairs should be carried out properly
65	Name : Olwan Tal. Gadhinglaj Dist. Kolhapur Date of completion:- 1996 Location: Longitude -74°52′00" Latitude -16°23′00" Height -: 24.74 m. Gross capacity- 1.875 Mcum Sr.No.In Large Dam Register 2012: MH09MH1389	19.4.2021 9.11.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Outlet	 A6 Major jet is observed through inside portion of wall. A4 Major leakages are observed through rubber seal. (Quantity of leakage is not given.) 	Necessary repairs should be carried out properly Necessary repairs should be carried out properly
66	Name : Vesraf Tal. Gadhinglaj Dist. Kolhapur Date of completion:- 1996 Location: Longitude -74°52'00" Latitude -16°23'00" Height -: 24.74 m. Gross capacity- 1.875 Mcum Sr.No.In Large Dam Register 2012: MH09MH1389	12.5.2021 24.10.2021	Shri.R. B. Bandiwade kar EE. KID (North) Kolhapur	Outlet	1.B5 Stem rod is slightly bend 2.A6 Cracks are observed to the outlet well.	Necessary repairs should be carried out properly Necessary repairs should be carried out properly.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested			
No.		Inspectio	Officer	Component					
		n		of Dam					
1	2	3	4	5	6	7			
(b) Exe	Executive Engineer,Kolhapur Irrigation Circle (South), Kolhapur								
67	Name :Dindalkop Tal. gadhinglaj, Dist. Kolhapur Date of completion:- 2014 Location: Longitude- 74°25'30" Latitude: -15°45'45" Height :- 27.61 m. Gross capacity 2.625 Mcum Sr.No.In Large Dam Register 2012: MH09MH1925	7.12.2021 7.12.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	 Stem rods for lifting gate are not straight (B5) 	Necessary remedial measures should be done in consultation with mechanical organization.			
68	Name : Erandol Tal. chandgad, Dist. Kolhapur Date of completion:- 1999 Location: Longitude- 74°11′00" Latitude: -16°03′00" Height :- 30.55 m. Gross capacity 4.210 Mcum Sr.No.In Large Dam Register 2012: MH09MH1514	26.4.2021 30.11.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	WW Bar	1. WW bar is partially constructed.(B7)	Necessary remedial measures should be done			
69	Name : Kalasgade Tal. chandgad, Dist. Kolhapur Date of completion:- 2000 Location: Longitude- 74°13'30" Latitude: -16°49'30" Height :- 16.46 m. Gross capacity 1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH1532	26.4.2021 21.11.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	EE	 At saddle dam there is small leakage below the dam pitching. (A1) 	Necessary remedial measures should be done			

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
70	Name : Karanjivane Tal. chandgad, Dist. Kolhapur Date of completion:- 1989 Location: Longitude- 74°14′00" Latitude: -16°21′00" Height :- 21.00 m. Gross capacity 1.51 Mcum Sr.No.In Large Dam Register 2012: MH09MH1209	12.5.2021 23.11.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	 Cracks are observed in UCR masonry well from top.(A6) Due to improper functioning of stem rod , circumferential crack observed from outer side. Stem rod in bend (B5) 	Necessary remedial measures should be done Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization
71	Name : Kitwad - 1 Tal. chandgad, Dist. Kolhapur Date of completion:- 2000 Location: Longitude- 75°25′00" Latitude: -15°58′00" Height :- 29.59 m. Gross capacity 5.53 Mcum Sr.No.In Large Dam Register 2012: MH09MH1543	15.5.2021 21.11.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	 Stem rods for lifting gate are not straight (B5) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
72	Name : Kumari Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1998 Location: Longitude- 74°18′00" Latitude: -15°30′00" Height :- 23.64 m. Gross capacity 2.59 Mcum Sr.No.In Large Dam Register 2012: MH09MH1457	18.5.2021 28.10.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	 Stem rods for lifting gate are not straight (B5) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
73	Name : Shendri Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1981 Location: Longitude- 74°21′00" Latitude: -16°16′00"	19.4.2021 23.11.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	1. H.R. well is damaged (A6)	It should be repaired properly.
	Height :- 21.14 m. Gross capacity 1.81 Mcum Sr.No.In Large Dam Register 2012: MH09MH0853					
74	Name : Sundi Tal. Chandgad, Dist. Kolhapur Date of completion:- 2009 Location: Longitude- 74°22′00" Latitude: -15°16′00" Height :- 27.00 m. Gross capacity 2.594 Mcum Sr.No.In Large Dam Register 2012: MH09MH1910	15.5.2021 7.12.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Outlet	 Stem rod for lifting gate is not straight (B5) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization.
75	Name : Yenechavandi Tal. Gadhinglaj, Dist. Kolhapur Date of completion:- 1996 Location: Longitude- 74°20' Latitude: - 16° 11' Height :- 21.65 m. Gross capacity 1.545 Mcum Sr.No.In Large Dam Register 2012: MH09MH139	18.5.2021 28.10.2021	Shrimati S.C. Mane E.E. KID (S) Kolhapur	Earth Dam	1. D/S leakages at Ch 100 & 240m is observed. (A1)	It should be kept under observation. Leakage data should be mainted and reason for leakage should be in investigated & treated properly. Necessary repairs be carried out to damage portion.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed Remedial Measures Suggested
No.		Inspectio	Officer	Component	
		n		of Dam	
1	2	3	4	5	6 7
(4)Sup	erintending Engineer, Satara Irri	gation Circle	e, Satara		
(a) Exe	cutive Engineer, Krishna Irrigati	on Division,	Satara		
76	Name : Kankatrewadi Tal. Phaltan Dist. Satara Date of completion: 1978 Location: Longitude: 74°35′00 " Latitude: 17°29′00 " Height : 19.51 m. Gross capacity : 1.24 Mcum Sr.No.In Large Dam Register 2012: MH09MH0736	17.5.2021 27.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Earthen Embankment W.W.Bar D/S	 There is leakage between joint of guide wall and earthen embankment ,clear water comes from guide wall. (A3) Leakage through masonry and from the foundation is observed(B7) Boil,wet patches ,water seepage ,slushy ground on the d/s of dam within 200mtr from the toe drain are observed (
				Outlet	 4. Outlet well is not in good condition. (A6) Necessary repairs should be carried out
77	Name : Thoseghar Tal. Satara Dist. Satara Date of completion:- 1989 Location : Longitude- 73°52'00 " Latitude - 17°36'00 " Height :- 18.05 m. Gross capacity : 1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH1208	4.5.2021 2.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Earthen Dam Outlet W.W.Bar	 Relief wells are not functioning. (A5) Some leakage is observed through w.w. bar. Repairing of WW bar is required. Waste weir bar is temporary supported with large size boulders and rubble in between boulders and waste weir bar coping is provided over partial length of waste weir bar (B7) Relief wells are not functioning. (A5) Necessary repairs should be carried out. Causes of exact leakages shou be investigated & treate accordingly. Necessary repairs should be carried out.
				Tail Channel	3. Tail channel is heavily damaged. (A7)

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed Remedial Measures Suggested
No.		Inspectio	Officer	Component	
		n		of Dam	
1	2	3	4	5	6 7
					4. Guide wall,divide wall and guide bund damaged.(A16) Necessary repairs should be carried out.
				Outlet Gate	 5. Gate is not working smoothly.(A4) 6. Upstream slope near well is sunk by some depth (B3)
				FF	Sunk by Some depth.(DS)
				Outlet	7. Leakage through wall of well and leakage through gate is observed Necessary repairs should be carried out.
				ounor	8. Stem rod is slightly bend.(B5)
78	Name :Ner Tal. Khatav Dist. Satara Date of completion:-1981 Location : Longitude- 74°18'00" Latitude -17°44'00" Height :-22.50 m. Gross capacity :9.12 Mcum Sr.No.In Large Dam Register 2012: MH09MH0018	17.5.2021 27.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Earthen Embankmen t WW bar EDA	 Longitudinal cracks are observed on dam top during summer period. (B4) There should be close vigil on the behavior of cracks. Depthwise extend of crack shall be find out and proposed remedial action with necessary drawings shall be communicated to DSO, Nashik. There is weak construction joint observed 3ft below ww bar and heavy leakage through these jonts.(B7) There should be close vigil on the behavior of cracks. Depthwise extend of crack shall be find out and proposed remedial action with necessary drawings shall be communicated to DSO, Nashik.
					3. EDA needs urgent repairs and construction.(A14) Necessary remedial actions should be taken.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
79	Name : Pingali Tal.Man Dist. Satara Date of completion:- 1878 Location :	10.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Earthen Embankment	 Standing pool of water is observed on D/S side of earthen dam.(A2) 	Necessary repairs shall be carried out.
	Longitude- 74°33'00 " Latitude - 17°41'00 " Height :- 16.00 m. Gross capacity : 2.38 Mcum Sr.No.In Large Dam Register 2012: MH09MH00731			Outlet	2. Outlet well not in good condition.(A6)	Necessary repairs should be carried out in consultation with mechanical organization.
80	Name : Yeralwadi Tal.Khatav Dist. Satara Date of completion:- 1973 Location : Longitude- 74°29'35 " Latitude - 17°31'24 " Height :- 19.50 m. Gross capacity : 32.80 Mcum Sr.No.In Large Dam Register 2012: MH09MH00386	7.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet	 Stem rod of both gates are bent.(B5) 	Necessary repairs shall be carried out through mechanical organization.
81	Name : Jambhulani Tal.Man Dist. Satara Date of completion:- 1981 Location : Longitude- 74°60'00 " Latitude - 17°34'00 "	10.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet	 Stem rod for lifting the gate is not straight.(B5) Outlet well not in good 	Necessary repairs shall be carried out through mechanical organization. Necessary repairs should be carried
	Height :- 15.21 m. Gross capacity : 2.41 Mcum Sr.No.In Large Dam Register 2012: MH09MH0516			Outlet well	condition.(A6)	out.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
No. 1 82	2 Name :Ranand Tal.Man Dist. Satara Date of completion:-1956 Location : Longitude- 74°40'00" Latitude -17°43'00" Height :-19.32 m. Gross capacity :7.12 Mcum Sr.No.In Large Dam Register 2012: MH09MH0078	Inspectio n 3 10.5.2021 28.12.2021 Test Inspected by DSO 30.1.2022	Officer 4 Shrimati S.S.Magdum E.E., KID, Satara Test Inspected by EE DSD1 Nashik	Component of Dam 5 D/S Tail Channel EE EE	 6 Standing pool of water on d/s of dam is observed. (A2) Retrogessiopn/scouring noticed in tail channel.(A7) 3. Earthen section seems to be under section in certain portion. (B1) 4.Dam top seems to be undulating. Top width is reduced. Settlement of embankment is observed. (B3) 	7 Necessary repairs shall be carried out. Necessary repairs should be carried out Superimpose Existing Cross Section on Design Cross Section at every 30 m C/C to ascertain whether earthen embankment is under section or not. Communicate facts to DSO, Nashik. Existing L-Section shall be superimposed on design L-Section to ascertain changes in design dam top level. Communicate facts to DSO, Nashik.
					5. Minor leakages are observed from WW Bar.(B7)	Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO. Necessary Raking & Pointing of stone masonry of WW Bar at portion of sweating and minor leakage areas should be done with pre approval from competent field authority.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component	-	
		n		of Dam		
1	2	3	4	5	6	7
83	Name : Andhali Tal.Man Dist. Satara Date of completion:- 1997 Location : Longitude- 74°30′00" Latitude - 17°45′07" Height :- 18.60 m. Gross capacity : 9.273 Mcum Sr.No.In Large Dam Register 2012: MH09MH01443	10.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet well	 Repairing of outlet well is required.(A6) 	Necessary repairs shall be carried out.
84	Name : Arabwadi Tal.Koregaon Dist. Satara Date of completion:- 1977 Location : Longitude- 74°04′00" Latitude - 17°50′07" Height :- 17.35 m. Gross capacity : 1.89 Mcum Sr.No.In Large Dam Register 2012: MH09MH00621	5.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet Gate	 Stem rod for lifting the gate is not straight.(B5) Top width of tha dam is reduced. Local depressions and small undulations on dam top. (B1) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization. Original dam section should be restored
85	Name : Daruj Tal.Khatav Dist. Satara Date of completion:- 1956 Location : Longitude- 74°25′00" Latitude - 17°40′00" Height :- 16.46 m. Gross capacity : 2.88 Mcum Sr.No.In Large Dam Register 2012: MH09MH00074	17.5.2021 27.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet well	1.Outlet well not in good condition.(A6)	Necessary repairs shall be carried out.
86	Name : Dhakani Tal.Man Dist. Satara Date of completion:- 1994 Location :	10.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID,	EE	 Relief wells are not functioning properly.(A5) 	Necessary repairs shall be carried out.

Sr.	Dam Features	Date of	Inspecting	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested
NO.		n	Oncer	of Dam		
1	2	3	4	5	6	7
	Longitude- 74°41′00" Latitude - 17°35′00" Height :- 18.50 m. Gross capacity : 3.05 Mcum Sr.No.In Large Dam Register 2012: MH09MH01335		Satara			
87	Name : Hiware Tal.Man Dist. Satara Date of completion:- 1974 Location : Longitude- 74°11′00" Latitude - 17°50′00" Height :- 18.14 m. Gross capacity : 2.74 Mcum Sr.No.In Large Dam Register 2012: MH09MH00443	5.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet	1.B5 Stem rod for lifting the gate is not straight	Necessary repairs shall be carried out.
88	Name : Kumathe Tal.Man Dist. Satara Date of completion:- 2001 Location : Longitude- 73°52′00" Latitude - 17°26′00" Height :- 27.13 m. Gross capacity : 2.86 Mcum Sr.No.In Large Dam Register 2012: MH09MH01682	4.5.2021 2.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	Outlet D/S	 1.A6 Leakage through outlet well is observed. 2.A1 Boils ,wet patches,water seepage slushy ground on the d/s of dam 	Necessary repairs shall be carried out. Necessary repairs shall be carried out.
89	Name : Nandwal Tal.Koregaon Dist. Satara Date of completion:- 2008 Location : Longitude- 74°11′00 " Latitude - 16°37′10 "	5.5.2021 28.12.2021	Shrimati S.S.Magdum E.E., KID, Satara	EE	1. B4 Some small rain cuts are observed on d/s of dam and longitudinal cracks ,crab holes observed on top	Necessary repairs shall be carried out.

Sr. No.	Dam Features	Date of Inspectio n	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed Remedial Measures S	uggested
1	2	3	4	5	6 7	
	Height :- 18.78 m. Gross capacity : 9.39 Mcum Sr.No.In Large Dam Register 2012: MH09MH01640					
(b) Exe	cutive Engineer, Koyna Irrigation	Division, K	oynanagar			
90	Name : Chaphal Tal. Satara Dist. Satara Date of completion:- 1983 Location : Longitude- 74°00′28 " Latitude - 17°24′24 " Height :- 18.05 m. Gross capacity : 1.91 Mcum Sr.No.In Large Dam Register 2012: MH09MH0966	20.5.2021	Shri. K.H. Patil E.E., Koyna Irrigation Division, Koynanagar	WW Bar	1. There is damages below the protection wall (@base of the wall of UCR masonry,) (B7) 	CR masonry ones shall be g of UCR ne following raking etc
91	Name : Chalakewadi Tal. Satara Dist. Satara Date of completion:- 1991 Location : Longitude- 74°05′00 " Latitude - 17°11′00 " Height :- 21.53 m.	18.5.2021 26.11.2021	Shri. K.H. Patil E.E., Koyna Irrigation Division, Koynanagar	Outlet	1. Stem rod fro lifting the gate is not straight.(B5) out.	II be carried

Sr. No.	Dam Features	Date of Inspectio	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested
		n		of Dam		
1	2	3	4	5	6	7
	Gross capacity : 0.80 Mcum Sr.No.In Large Dam Register 2012: MH09MH1258					
[B] Chi	ef Engineer (S.P) Water Resour	ces Departm	nent, Pune			
(1) Sup	erintending Engineer Kukadi Irr	igation Circle	e Pune			
(a) Exe	cutive Engineer ,Kukadi Irrigatio	n Division N	o. 1 Narayang	aon		
92	Name : Ramjewadi Tal. Junnar Dist. Pune Date of completion:1983 Location: Longitude -73°41'00" Latitude - 19°13'00" Height :- 21.48m. Gross capacity 1.72 Mcum Sr.No.In Large Dam Register 2012:MH09MH 0965	20.5.2021 26.11.2021	Shri.P.P. Kaduskar EE KID, Narayngaon	Outlet	1.Sign of concavity near irrigation outlet. (the cross section at random locations and suspected locations with tape and level is not given in report) (B5)	Necessary repairs should be carried out.
93	Name : Otur Waghdara Tal. Junnar Dist. Pune Date of completion:1992 Location: Longitude - 74°02'00'' Latitude - 19°05'00'' Height :- 20.16m. Gross capacity 0.953 Mcum Sr.No.In Large Dam Register 2012:MH09MH1262	19.5.2021 24.11.2021 Test Inspected by DSO 22.10.202 1	Shri.P.P. Kaduskar EE KID, Narayngaon Test Inspected by EE DSD 1 Nashik	E E Outlet D/S	 1.Leakage through dam foundation and storage created in dam depletes in one to two months. (A1) 2.Outlet well gate not in working condition.(B5) 3.Leakages are observed on d/s side of the dam. Also water Ponding is observed on the d/s of dam. (A2) 	Necessary repairs should be carried out. It should be lubricated periodically. At least, it should be properly lubricated after monsoon season. Source and quantity of leakage should be measured in consultation with the CDO, Nashik with preapproval from competent field officials immediately without fail.As field officials reported that water level is going down automatically & leakage is not observed.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
NO.		n	Officer	of Dam		
1	2	3	4	5	6	7
				Outlet	4. Outlet well gate repair is required. Outlet gate is not in working condition. (A6)	Necessary repairs shall be done in consultations with Mechanical Wing with preapproval from competent field officials before taking the work in hand.
94	Name : Ghangaldara Tal. Junnar Dist. Pune Date of completion:2009 Location: Longitude - 74°00'00'' Latitude - 18°20'00'' Height :- 26.34m. Gross capacity 2.34 Mm3 Sr.No.In Large Dam Register 2012: MH09MH1906	20.5.2021 26.11.2021	Shri.P.P. Kaduskar EE KID, Narayngaon	E. Gate	 Emergency gate is supplied but not installed. (B5) 	Necessary repairs should be carried out.
95	Name : Ucchil Tal. Junnar Dist. Pune Date of completion:2001 Location: Longitude - 73°41'00'' Latitude - 19°13'00'' Height :- 13.01m. Gross capacity 3.12 Mm3 Sr.No.In Large Dam Register 2012:MH09MH1572	20.5.2021 26.11.2021	Shri.P.P. Kaduskar EE KID, Narayngaon	WW bar	 UCR Masonry of spillway bar is totally damaged and leakage through masonry is seen.(B7) 	Necessary repairs should be carried out.
96	Name : Anepemdara Tal. Junnar Dist. Pune Date of completion:1998 Location: Longitude - 73°14'00 "	21.5.2021 24.11.2021	Shri.P.P. Kaduskar EE KID, Narayngaon	Outlet WW Bar	 Operation of outlet gate is not smooth (B5) Stem rod damaged (B5) Heavy leakage between joint of earthwork and flank wall, 	Necessary repairs should be carried out. Necessary repairs should be carried out.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n	-	of Dam		_
1	2	3	4	5	6	7
	Latitude - 19°11'00"				heavy leakage through WW	
	Height :- 14.37m.				bar. (B7)	
	Gross capacity 2.09 Mcum					
	Sr.No.In Large Dam Register					
	2012: MH09LH 1473					
97	Name : Gohe	22.6.2021	Shri.P.P.	WW bar	1.Damage to waste weir bar is	Necessary repairs should be carried
	Tal. Junnar Dist. Pune	27.11.2021	Kaduskar		observed (B7)	out.
	Date of completion:1996		EE KID,			
	Location:		Narayngaon		2 Slight leakage is observed at	
	Longitude -73°44'00''			Embankmen	iunction between ombankment	Necessary repairs should be carried
	Latitude - 19°04'00''			t		out.
	Height :- 17.49m.				and spillway.(B7)	
	Gross capacity 1.28 Mm3					
	Sr.No.In Large Dam Register					
	2012: MH09MH1397					
98	Name : Ballalwadi	4.6.2021	Shri.P.P.	D/S	1.Leakages/Seepage are observed	Source of leakage should be find out
	Tal. Junnar Dist. Pune	24.11.2021	Kaduskar		on d/s side of the dam.(A1)	and quantity of leakage should be
	Date of completion:1996		EE KID,			measured in accordance to the
	Location:		Narayngaon			various reservoir levels & record of
	Longitude -73°55'30''	lest				the same should be maintained and
	Latitude - 19°15'00"	Inspected	Test			communicated to DSO, Nashik
	Height :- 20.16m.	by DSO	Inspected			
	Gross capacity 2.34 Mm3	22.10.2021	by EEDSD1			
	Sr.No.In Large Dam Register		Nashik			
	2012: MH09MH1397					
(2) Sup	perintending Engineer & Admn.	C.A.D.A. Sol	apur			
(a) Exe	cutive Engineer,Solapur Irrigation	on Division, S	Solapur			
99	Name : Chare	5.5.2021	Shri.	Embankmen	1.Some rain cuts are observed on	Necessary remedial measures
	Tal. Karmala Dist. Solapur	10.11.2021	M.T.Jadhvar	t	dam top at ch 0/30to 0/70. Crack	should be done
	Date of completion:1983		EE,SID,		shown of 3 to 3.6m in length width	
	Location:		Solapur		75-100 mm and denth unto 0.60m	
	Longitude -75°45'30"					
	Latitude - 18°35'42"				(D4)	
	Height :- 16.30m.					
	Gross capacity 1.50 Mcum					

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
	Sr.No.In Large Dam Register 2012: MH09MH0973					
100	Name : Hingani (K) Tal. Karmala Dist. Solapur Date of completion:1974 Location: Longitude -75°24'30" Latitude - 18°16'00" Height :- 16.15 m. Gross capacity 2.22 Mcum Sr.No.In Large Dam Register 2012:MH09MH 0441	8.5.2021 10.11.2021	Shri. M.T.Jadhvar EE,SID, Solapur	Outlet	1. One stem rod is bend (B5)	Necessary remedial measures should be done in consultation with mechanical organization.
101	Name : Kazikunbus Tal. Akkalkot Dist. Solapur Date of completion:1992 Location: Longitude - 76°10'00'' Latitude - 17°43'00'' Height :- 20.00m. Gross capacity 4.031 Mcum Sr.No.In Large Dam Register 2012: MH09MH 1224	10.5.2021 16.11.2021	Shri. M.T.Jadhvar EE,SID, Solapur	Outlet	 1.Gate operation is not working due to stem rod problem In head regulator stem rod is broken, repairing is necessary. Stem rod is kniped by farmers hence gate is not in operation. (B5) 2. Coping over the spillway bar is fully washed out. (B7) 	Necessary repairs should be carried out in consultation with Mechanical organisation. Necessary repairs should be carried out
102	Name : Kari Tal. Akkalkot Dist. Solapur Date of completion:1973 Location: Longitude -75°00'20'' Latitude - 18°55'00'' Height :- 20.00m. Gross capacity 4.031Mcum Sr.No.In Large Dam Register 2012:MH09MH 1224	5.5.2021 10.11.2021	Shri. M.T.Jadhvar EE,SID, Solapur	WW Bar	1.Some masonry of W.W. bar is disturbed. Tail channel badly eroded near flank wall & immediate repair is needed. (B7)	Necessary repairs should be carried out
103	Name : Mangi Tal. Karmala Dist. Solapur Date of completion: 1966	8.5.2021 12.11.2021	Shri. M.T.Jadhvar & Shri. D.J.	Embankment	 Longitudinal cracks developed in embankment Ch 1621- 1645m. variable depth approx. 	Original dam section should be restored

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
1	2	n 3	4	of Dam	6	7
	Location: Longitude -75°17'00" Latitude -17°17'00" Height :- 22.95 m. Gross capacity : 3.09 Mcum Sr.No.In Large Dam Register 2012: MH09MH0131		Kondekar EE,SID,Sola pur		 1.2m (B4) 2. Relief wells are not in working condition (A5) 	They should be cleaned and made functional.
104	Name : Rajuri Tal. Karmala Dist. Solapur Date of completion: 1981 Location: Longitude - 74°58 ' Latitude - 18°22 ' Height :- 19.29 m. Gross capacity : 2.520 Mcum Sr.No.In Large Dam Register 2012: MH09MH0894	8.5.2021 12.11.2021	Shri. M.T.Jadhvar & Shri. D.J. Kondekar EE,SID, Solapur	Tail Channel	 Heavy retrogression is noticed on downstream of bar near divide wall. (A7) 	Protective measures, as per necessity shall be undertaken to prevent progressive damage.
(b)Exe	cutive Engineer Bhima Develope	ment Divisio	on No.2, Solap	ur		
105	Name : Ashti Tal. Mohol Dist. Solapur Date of completion:-1883 Location : Longitude - 75°-26' 00'' Latitude - 17°47'30'' Height :- 17.60 m. Gross capacity :23.01 Mcum Sr.No.In Large Dam Register 2012: MH09MH0014	6.5.2021 9.11.2021	Shri. R. N. kshirsagarE E BDD no.2 Solapur	Earthen Embankmen t	 Cracks are observed at top of embankment in between ch. 2230 to 2385 m (Longitudinal and minor cracks are observed(B4) Top of embankment not as per design section of dam. Ch 2340 m. to 2360 m (B1) Relief wells are not functioning properly.(A5) 	Necessary repairs should be carried out and dam section should be restored. Necessary repairs should be carried out and dam section should be restored.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
(c)Exec	utive Engineer Bhima Irrigation	Division, Pa	ndharpur	•	·	
106	Name : Talsangi Tal. Mangalwedha Dist. Solapur Date of completion:-1973 Location : Longitude - 75°-26' 00'' Latitude - 17°01'20'' Height :- 15.24 m. Gross capacity : 2.43 Mcum Sr.No.In Large Dam Register	14.5.2021 11.1.2022	EE BID Pandharpur	WW Bar	1.Some portion of WW Bar (about 12 to 15 m) lonf is not constructed.(B7)	Necessary repairs should be carried out
107	2012: MH09MH0579 Name : Chincholi Tal. Mangalwedha Dist. Solapur Date of completion:-1966 Location : Longitude - 75°-28' 00'' Latitude - 17°24'20'' Height :- 15.24 m. Gross capacity : 2.74 Mcum Sr.No.In Large Dam Register 2012: MH09MH0128	13.5.2021 11.1.2022 Test Inspected by DSO 29.1.2022	EE BID Pandharpur Test Inspected by EE DSD1 Nashik		 Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam. (A2) Earthen section seems to be under section in certain portion. (B1) 	Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO. Superimpose Existing Cross Section on Design Cross Section at every 30 m C/C to ascertain whether earthen embankment is under section or not. Communicate facts to DSO, Nashik.
Superi	ntending Engineer, Bhima Cana	I Circle Sola	pur			
(c)Exec	cutive Engineer Minor Irrigaton E	Division No.1	, Solapur			
108	Name : Babhulgaon Tal. Mohol Dist. Solapur Date of completion:-1993 Location : Longitude - 75°-46' 55'' Latitude - 18°19'23''	12.5.2021 9.10.2021	Shri. R.P.More EE,MID No.1 Solapur	Outlet	1. Outlet well not in good condition. HR well are fully silted up due to that HR gates are not functioning.(A6)	Well should be desilted.
	Height :- 16.93 m. Gross capacity :6.40 Mcum Sr.No.In Large Dam Register			Earthen Embankmen t	 Boils, wet patches or water seepage slushiness is seen on d/s slope(A1) 	Necessary repairs should be carried out
Sr. No.	Dam Features	Date of Inspectio	Inspecting Officer	Main Component	Significant Deficiencies noticed	Remedial Measures Suggested
------------	---	---	--	-------------------	---	--
		n .		of Dam		
1	2	3	4	5	6	7
	2012: MH09MH1620					
109	Name : Gholasgaon Tal. Akkalkot Dist. Solapur Date of completion:-2004 Location : Longitude - 76°-15' 18'' Latitude - 17°30'50'' Height :- 16.24 m. Gross capacity :2.08 Sr.No.In Large Dam Register 2012: Proposed for updation in NRLD 2020	9.3.2021 NR	Shri. R.P.More EE,MID No.1 Solapur		1.B4 Longitudinal cracks is seen on dam top for considerable length.Dam top seems to be undulating.2.A5 Relief wells are not operated yet.	
110	Name : PimpalgaonDhale Tal. Barshi Dist. Solapur Date of completion:-2008 Location : Longitude - 75°47'40" Latitude - 18°10'10" Height :- 18.70 m. Gross capacity :12.66 Mcum Sr.No.In Large Dam Register 2012: MH09MH1840	12.5.2021 9.10.2021 Test Inspection by DSO 31.1.2022	Shri. R.P.More EE,MID No.1 Solapur Test Inspected by EE DSD 1 Nashik	Outlet	 1.Stem rod for lifting gate is not straight (B5) 2Dam top seems to be undulating. Top width is reduced.(B1) 3.Stagnant Water (Ponding of Water) is observed on immediate d/s side of dam.(A2) 	Depending on severity of bending Stem Rod should be either repaired or replaced in consultation with Mechanical Organization. Existing L-Section shall be superimposed on design L-Section to ascertain changes in design dam top level. Communicate facts to DSO, Nashik. Source of stagnant water shall be traced out by draining the same and facts regarding the same should be communicated to DSO.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies noticed	Remedial Measures Suggested
No.		Inspectio	Officer	Component		
		n		of Dam		
1	2	3	4	5	6	7
(2) Sup	perintending Engineer, SataraPro	oject Irrigatio	n Circle, Sata	ara		
(a) Exe	cutive Engineer, Minor Irrigation	Division Sat	ara			
111	Mahind Tal- Patan Dist- Satara Date of completion: 2000 Location: Longitude 73°54'13" Latitude 17°22'05" Height :21.32 m. Gross capacity- 2.404Mcum Sr.No.In Large Dam Register 2012: MH09MH1838	14.5.2021	Shri.S.J. Hiray EE MID Satara	W.W.Bar and Tail Channel E.E. Embankment Outlet	 Retaining wall of right side of tail channel is collapsed for length of 19m (A7) Top width of dam as per design is 3.00m.Due to movement of live stock it is eroded and now top width remains 2.50m on average throughout the length of dam.(B1) The portion of the longitudinal toe drain and exposed cross drains beyond the d/s toe of the dam are not in regular section and not freely draining.(B2) Depression in embankment near head regulator is observed.A pit of size 3X3 m is formed. Also a pit is formed in u/s embankment at ch 155 to 165.(B3) Leakage is observed through pipe joints of outlet. UCR masonry and concrete on d/s side of irrigation outlet is eroded and required repairs(A3) 	Necessary repairs should be carried out. Original dam section should be restored Necessary repairs should be carried out. Necessary repairs should be carried out.

Class-II Dams with Category-3 Deficiency

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
[A]Ch	nief Engineer (W.R.) V	Vater Reso	ources Depart	ment Pun	e					
(1) Si	uperintending Engine	er Pune Ir	rigation Circle	e. Pune						
(a) E)	ecutive Engineer. Pu	ne Irrigati	on Division, F	Pune						
1	Adale	gan								
	Tal. Mawal Dist	1985	73°37'00″	19.17	1.27	330.0	MH09MH	Not		
	.Pune		18°39'00				1086	received		
2	Chinghwad		708 40100#					4.5.2021	3.1, 3.2, 3.5, 3.6, 3.16, 3.20,	10
	Tol Duno Dict Duno	1984	73°40'00″	20.92	1.53	137.70		Not	3.23, 3.30, 3.31,3.9	
	Tal. Purle Dist .Purle		18 15 00				1033	received		
3	Divale		73° 55'00"				мноэмн	2.6.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.16,	11
	Tal. Bhor , Dist.	1985	18°15'00"	20.83	2.14	273	1082	Not	3.20, 3.23,3.30, 3.31,3.9	
<u> </u>	Pune		10 10 00					received		
4	GadadwaneTal.Mu	0007	73°35'00″	00.00	4.050	0004	МН09МН	4.5.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.16,	11
	lashi Dist. Pune	2007	18°14'00	26.20	1.859	3224	1668	NOT	3.20, 3.23, 3.30, 3.31,3.9	
5	Hadashi								21 25 26 27 216 220	10
5	Tal Mulashi Dist	1001	73° 32'00"	21.83	3.07	181	МН09МН	29.4.2021 Not	3.1, 5.3, 5.0, 5.7, 5.10, 5.20, 3.23, 3.30, 3.31, 3.00	10
	Pune	1331	18°36'00"	21.05	5.07	101	1235	received	3.23, 3.30, 3.31, 3.3	
6	Hadashi-2							29.4.2021	3.1. 3.5. 3.6. 3.7. 3.16. 3.20.	10
Ũ	Tal.Mulashi Dist.	1999	73°52'00″	20.45	1.41	81.48	MH09MH	Not	3.23. 3.30. 3.31.3.9	10
	Pune		18°36'00				1674	received		
7	Mahakoshi		72° 50'00"					2.6.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.16,	11
	Tal. Bhor Dist	1998	18°05'00"	24.00	2.28	583	1474	Not	3.20, 3.23, 3.30, 3.31,3.9	
	.Pune		10 03 00				14/4	received		
8	Naigaondevgaon		73° 53'00"				мноэмн	2.6.2021	3.1, 3.2, 3.5, 3.6, 3.16, 3.20,	10
	Tal. Bhor Dist	1979	18°17'00"	22.49	1.332	241	0762	Not	3.23, 3.30, 3.31,3.9	
1	.Pune							received		

Sr.	Name of Dam	Date of	Location	Height	Gross	Design	Sr.No. in	Date of	Deficiencies noticed	Total
NO		Compl-	Longitude/	in m	Capacity Mm ³	Spillway	NRLD Pogistor	Inspection Bro & Bost		Deficien
		ellon	Latitude		IVIII	m ³ /sec	Register	FIE & FUSL		CIES
1	2	3	4	5	6	7	8	9	10	11
9	Pimpoli		70800/00//					29.4.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.16,	11
	Tal. Mulashi Dist	1984	18°36'00	22.13	1.53	257.0	1045	Not	3.20, 3.23, 3.30, 3.31,3.9	
10	Pune								21 22 25 26 27 216	11
10								29.4.2021 Not	3.1, 3.2, 3.3, 3.0, 3.7, 3.10, 3.20, 3.23, 3.30, 3.31, 3.9	11
	Rihe							received	0.20, 0.20, 0.00, 0.01,0.0	
	Tal. Mulashi Dist	1977	73°39'00″	21.95	1.58	698.90	MH09MH	Test		
	.Pune		18°34'00				0642	Inspected		
								by DSO		
								27.8.2021		
11	Shere		73°52'00″				мноэмн	4.5.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.16,	11
	Tal Puner Dist Pune	1998	18°36'00	22.98	1.72	123.20	1458	Not	3.20, 3.23, 3.30, 3.31,3.9	
			10 00 00					received		
12	Shetphal	4004	75°00'30″	00.44	17.00	No	МН09МН	26.5.2021	3.1, 3.2, 3.6, 3.9, 3.10, 3.13	6
	Tal. Indapur Dist	1901	18°01'00	20.11	17.36	Spillway	0021	NOT		
13	.Fulle							20 / 2021	31 32 36 37 316 320	10
15	Walen	1989	73°30'00″	20.75	1 51	90.0	МН09МН	29.4.2021 Not	3 23 3 30 3 31 3 9	10
	Tal. Pune Dist .Pune	1000	18°35'00	20.10	1.01	00.0	1216	received	0.20, 0.00, 0.01,0.0	
14	Urawade							4.5.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.9, 3.16,	11
	Tal.Mulashi Dist.	1983	74°56'00″	23.48	2.00	203.50	MH09MH	Not	3.20, 3.23, 3.30, 3.31	
	Pune		18-30.00				0964	received		
15	Khamboli		73°35'00"				мноонн	29.4.2021	3.1, 3.5, 3.6, 3.7, 3.16, 3.20,	9
	Tal.Mulashi Dist.	2000	18°35'00"	25.36	2.065	227.50	1535	Not	3.23, 3.30, 3.31,3.9	
	Pune		10 00 00					received		
16	Mannaali							4.5.2021	3.1, 3.2,3.5, 3.6, 3.7, 3.16,	11
	Tal Mulachi Dist	1008	73°40'00″	19.25	0.87	64.06	MH09MH	Not	3.20, 3.23, 3.30, 3.31,3.9	
		1990	18°30'00	10.55	0.07	04.00	1453	received		
17								24 5 2024	3.1, 3.2, 3.5, 3.6, 3.16, 3.20,	10
	WaghajwadiTal.Bh	2001	73°50'00″	20.57	1 66	215	МН09МН	24.5.2021 Not	3.23, 3.30, 3.31,3.9	
	or Dist. Pune	2001	18°15'00	20.57	1.00	215	1574	received		
								10001400		

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
18	BhongavaliTal.Bh or Dist. Pune	2015	74°00'00″ 18°15'00	25.00	3.32	239.96	Proposed for NRLD	2.6.2021 Not received	3.1, 3.2, 3.5, 3.6, 3.16, 3.20, 3.23, 3.30, 3.31,3.9	10
(b) E	kecutive Engineer, Li	ft Irrigation	n Managemei	nt Divisio	n Pune	L				
19	Ghorwadi Tal. Purandar Dist. Pune	1996	74°18'00" 18°10'00"	19.81	1.912	104.50	MH09MH. 1413	20.5.2021 15.11.2021	3.1,3.2,3.6, ,3.9,3.13,3.20,3.31	7
20	Mahur Tal.Purandar Dist. Pune	1978	74°10'00" 18°04'00"	22.99	2.36	563	MH09MH. 0732	27.5.2021 16.11.2021	3.2, 3.5, 3.7, 3.10, 3.13, 3.16, 3.22, 3.31	8
21	Malwandi Tal.Maval Dist. Pune	2000	73°31'00" 18° 39'30"	20.45	3.68	282.80	MH09MH 1529	Not Received		
22	Pilanwadi Tal. Saswad Dist .Pune	1978	73°52'00″ 18°36'00	22.77	1.94	771.20	MH09MH 0729	27.5.2021 16.11.2021	3.2,3.9,3.13,3.16,3.20,3.21,3.3 1,3.34	8
23	Pingori Tal. Purandar Dist. Pune	1969	74°07'00" 18°13'00"	22.13	1.54	191	MH09MH. 0178	27.5.2021 15.11.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.13, 3.20	7
24	Virnalla Tal. Purandar Dist. Pune	1956	74°05'00" 18°10'00"	21.81	3.585	925.75	MH09MH. 1415	27.5.2021	3.1, 3.2, 3.7, 3.13,3.16,3.31	6
25	Garade Tal. Purandar Dist. Pune	1979	73°55'00" 18°15'00"	18.82	1.869	3224	MH09MH. 0794	20.5.2021 15.11.2021	3.2,3.5,3.7,3.13,3.16,3.19,3.20, 3.21,3.31	9
26	Thitewadi Tal. Shirur Dist. Pune	2003	74°02'30" 18°48'00"	21.10	9.86 Mcum	1623.64	MH09MH 1623	13.5.2021 6.12.2021	3.1, 3.2, 3.7, 3.9, 3.10, 3.13, 3.16, 3.19, 3.20, 3.21.	10

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
(c) E>	cecutive Engineer, Kl	nadakwasl	a Irrigation Di	vision Pu	ne					
27	Ambegaon Tal. Haweli Dist. Pune	1979	73°50′30" 18°26′30"	21.78	1.93	230	MH09MH 0758	22.5.2021 5.12.2021	3.1, 3.2, 3.7, 3.9, 3.13, 3.19, 3.20, 3.22, 3.31	9
28	Bhugaon Tal. Mulashi Dist. Pune	1983	73°45'00" 18° 30'00"	21.19	1.90	208	MH09MH 0963	22.5.2021 5.12.2021	3.1, 3.2, 3.7, 3.13, 3.19, 3.20, 3.22.	7
29	Malad Tal. Daund Dist. Pune	1979	74°34'00" 18° 23'00"	15.63	1.74	800	MH09MH 0796	23.5.2021 28.11.2021	3.9, 3.13, 3.16, 3.19, 3.20, 3.28	6
30	Palasdeo Tal. Shirur Dist. Pune	1953	74°34'00" 18°23'00"	18.23	1.09	383.0	МН09МН 0063	23.5.2021 28.11.2021 Test Inspected by DSO 31.1.2022	31,3.2,3.5,3.6, 3.13, 3.16, 3.20, 3.25, 3.28	9
31	Matoba Tal. Daund Dist. Pune	1978	74° 34'00" 18°00'23	17.50	45.2	476	MH09MH 0721	23.5.2021 28.11.2021	3.1, 3.2, 3.7, 3.9, 3.13, 3.16, 3.19, 3.22, 3.28.	9
32	Shirsuphal Tal. Baramati Dist. Pune	1879	74° 35'20" 18°21'00"	20.11	10.1	112	MH09MH 0011	23.5.2021 28.11.2021 Test Inspected by DSO 31.1.2022	3.1, 3.2, 3.5,3.6, 3.7, 3.9	6
(d) Ex	kecutive Engineer, Ni	ira Right B	ank Canal Div	ision, Ph	altan					
33	Banganga Tal.Phaltan Dist. Satara	1955	74° 25'00" 17°40'00"	16.76	6.50	1110	MH09MH. 0071	23.5.2021 23.10.2021	3.1, 3.5 ,3.6,3.9,3.26	5
34	Girzani Tal.Malshiras Dist. Solapur	1989	74° 59'00" 17°52'00"	17.98	2.07	663	MH09MH. 1223	23.5.2021 Not received	3.1, 3.7	2

Sr. No	Name of Dam	Date of Compl-	Location Longitude/	Height in m	Gross Capacity	Design Spillwav	Sr.No. in NRLD	Date of Inspection	Deficiencies noticed	Total Deficien
		etion	Latitude		Mm ³	Capacity m ³ / sec	Register	Pre & Post		cies
1	2	3	4	5	6	7	8	9	10	11
35	Hingangaon Tal. Khatav Dist. Satara	1975	74° 58'05" 17°06'10"	17.53	1.47	465.80	MH09MH 0473	22.5.2021 4.11.2021	3.1, 3.6,3.7, 3.9, 3.10, 3.13,3.15, 3.20, 3.21, 3.34	10
36	Mhaswad Tal. Man Dist. Satara	1876	74° 53'00" 17°35'00"	24.00	46.13	4321.41	MH09MH 0017	17.5.2021 Not received	3.1, 3.5, 3.7, 3.9	4
37	Nimgaon Tal. Malshiras Dist. Solapur	1986	74° 59'00" 17°52'00"	20.30	6.958	909	MH09MH. 0247	25.5.2021 Not received	3.1, 3.7	2
38	Phondshiras Tal. Malshiras Dist. Solapur	1991	74°49'00" 18°08'00"	16.68	2.92	725	MH09MH. 1277	25.5.2021 Test inspected by DSO 30.1.2022	3.1, 3.2,3.5.3.7,3.9,3.22	6
39	Sangvi Shirwal Tal.Khandala Dist. Satara	1993	73° 58'00" 18°07'00"	18.00	1.335	1371	MH09MH. 1318	15.5.2021 Not received	3.1, 3.7, 3.9, 3.13, 3.20, 3.21,3.16	7
40	Tambave Tal.Phaltan Dist. Satara	1966	74°10'00″ 18°00'00	16.80	5.42	961.0	MH09MH 0167	22.5.2021 4.11.2021	3.1,3.5,3.6,3.7,3.9,3.10, 3.13, 3.15,3.16, 3.20, 3.21, 3.22,3.28	13
41	Tisangi Tal. P'pur Dist. Solapur	1966	74° 10'05" 17°35'00"	19.00	2.446	300	MH09MH. 0124	13.5.2021 Not received	3.1, 3.5, 3.7, 3.9, 3.33.	5
42	Wadgaon Tal.Khandala Dist. Satara	1980	75°55'00" 18°15'00"	21.70	2.97	638.45	MH09MH. 0835	15.5.2021 Not received	3.1, 3.5, 3.7, 3.9, 3.13, 3.20, 3.16, 3.19, 3.21, 3.28	10
43	Naigaon Tal.Khandala Dist. Satara	1983	73°58'05" 18°06'10"	18.0	1.34	396.29	MH09MH. 0986	15.5.2021 Not received	3.6,3.7, 3.13, 3.19, 3.20, 3.21,	6
(e) E>	cecutive Engineer, Ch	naskaman	Irrigation Div	ision, Pur	ne					
44	Alegaonpaga Tal. Shirur, Dist.Pune	1961	74° 20'30" 18°38'00"	15.24	2.03	695	MH09MH 0264.	23.5.2021 12.11.2021	3.1, 3.2, 3.9, 3.13, 3.16, 3.19, 3.20, 3.21	8

Sr.	Name of Dam	Date of	Location	Height	Gross	Design	Sr.No. in	Date of	Deficiencies noticed	Total
NO		etion	Longitude/	in m	Mm ³	Capacity	Register	Pre & Post		cies
						m ³ / sec	_			
1	2	3	4	5	6	7	8	9	10	11
45	Dahiwadi TalShirur Dist .Pune	1973	74°18'00" 18°42'00"	13.74	1.35	567.0	MH09MH 0371	23.5.2021 12.11.2021	3.6, 3.7, 3.9, 3.13, 3.17, 3.19, 3.20, 3.25, 3.34	11
46	Kadus Tal. Khed Dist .Pune	1986	73°55'00″ 18°56'00	16.65	2.63	607.30	МН09МН 1126	23.5.2021 18.11.2021 Test Inspected by DSO 22.10.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.13, 3.16, 3.19, 3.20, 3.21,3.22, 3.25	12
47	Nimgaon Mhalungi Tal. Shirur Dist. Pune	1971	74° 12'30" 18° 43'30"	17.30	3.37	980	MH09MH 0993	23.5.2021 12.11.2021	3.1,3.2, 3.6, 3.7, 3.9, 3.13,3.17, 3.19,3.20, 3.25,3.34	9
(2)) S	Superintending Engi	neer, Pune	Irrigation Pro	oject Circ	le, Pune					
(a) Ex	Br, Brgineer, Br	amaAskh	ed Dam Divis	ion, Pune						
48	Palsunde Tal.AkoleDist.A.Na gar	2018	74°02′00" 19°50′00"	25.00	2.442	300.16	Proposed for NRLD	Not received 12.11.2021	3.20, 3.24, 3.26	3
(3) St	perintending Engine	er. Sangli	Irrigation Cir	cle. Sana	li					
(a)Ex	ecutive Engineer San	alilrrigatio	on Division. S	Sangli						
49	Antri Tal. Shirala Dist. Sangli	1991	74°05′00" 17°02′00"	22.79	2.82	235	MH09MH 1215	23.5.2021 29.11.2021	3.1, 3.2,3.16, 3.13, 3.20, 3.28,3.35	7
50	Bassappawadi Tal. K'mahankal Dist. Sangli	1981	74° 00'00" 17°02'00"	16.90	7.78	1386	MH09MH. 0900	4.5.2021 3.12.2021	3.1, 3.2, 3.5, 3.34, 3.22, 3.21, 3.13, 3.33	8
51	Bhiwargi Tal. Jath Dist. Sangli	2001	73°31′50" 17°25′00"	15.85	11.2	22.35	MH09MH. 1597	28.5.2021	3.1, 3.2, 3.9, 3.13, 3.20, 3.22, 3.33, 3.34, 3.35	9
52	Bhose Tal. Miraj Dist Sangli	1974	74°44′00" 16°57′00"	15.18	1.03	160	MH09MH. 0404	4.5.2021 3.12.2021	3.1, 3.2, 3.13, 3.20, 3.21, 3.22	6

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
53	Birnal Tal. Jath Dist. Sangli	1977	75°20′00" 17°4′50"	18.60	2.433	528	МН09МН. 0637	2.12.2021 Test Inspected by DSO 28.1.2022	3.1,3.2,3.5, 3.7,3.9,3.13,3.16,3.20	8
54	Daribadachi Tal. Jath Dist. Sangli	2010	75°24′00" 17°02′28"	15.38	1.87	674.79	MH09MH 2254	14.12.2021 Test Inspected by DSO 29.1.2022	3.1, 3.2, 3.5,3.6,3.7, 3.9,3.13, 3.20	8
55	Doddanalla Tal. Jath Dist. Sangli	1986	75°30′32" 17°13′00"	16.20	6.50	1211	МН09МН. 1136	14.12.2021 Test Inspected by DSO 29.1.2022	3.1,3.2,3.5,3.6, 3.9,3.13,3.20,3.22	8
56	Dudhebhavi Tal. Kavathemahankal Dist. Sangli	1983	75°15′00" 17°09′37"	19.33	3.98	568	МН09МН. 0996	3.12.2021 Test Inspected by DSO 29.1.2022	3.13.2,3.5,3.6,3.7,3.13,3.21, 3.22	8
57	Karve Tal. Walawa Dist. Sangli	1974	74°11′00" 16°57′04"	16.86	1.64	90	MH09MH. 0395	25.5.2021 29.11.2021	3.2, 3.5, 3.6, 3.13, 3.20, 3.22, 3.35,3.16	8
58	Nangole Tal. Kavathemahankal Dist. Sangli	1978	74°35′45" 17°01′00"	15.45	1.85	280	МН09МН. 0700	4.5.2021 3.12.2021	3.2, 3.5, 3.13, 3.20	4
59	Pratappur Tal. Jath Dist. Sangli	1987	75°04′00" 17°09′25"	16.90	1.66	657.09	MH09MH. 1165	2.12.2021 Test Inspected	3.1,3.2, 3.5,3.7,3.9,3.13, 3.19, 3.20,3.21, 3.35, 3.33,3.22	12

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
								by DSO 28.1.2022		
60	Raywadi Tal. Kmahankal Dist. Sangli	1976	74° 54'00" 17°17'00"	20.35	2.16	523	MH09MH. 0586	4.5.2021 3.12.2021	3.1,3.2, 3.5, 3.13, 3.16, 3.20, 3.35	7
61	Revnal Tal. Jath Dist. Sangli	1978	75°12′15" 17°06′30"	18.60	2.37	174	MH09MH. 0679	18.5.2021 2.12.2021	3.1, 3.2, 3.5, 3.6,3.13,3.16,3.20,3.21	8
62	Sankh Tal. Jath Dist. Sangli	1995	75°32′00" 17°15′00"	17.66	19.93	3228	MH09MH. 1382	4.6.2021 14.12.2021	3.1, 3.2, 3.9, 3.13, 3.20, 3.34	6
63	Sanmadi Tal. Jath Dist. Sangli	1979	74°20′00" 17°16′00"	17.46	1.98	529	MH09MH. 0796	11.5.2021 14.12.2021	3.5, 3.6, 3.7, 3.9, 3.13, 3.20	6
64	Shegaon Tal. Jath Dist. Sangli	1975	75°09′15" 17°09′02"	19.82	8.08	1274	МН09МН. 0529	2.12.2021 Test Inspected by DSO 29.1.2022	3.1, 3.2 3.5, 3.6, 3.9, 3.13, 3.20,3.21, 3.22	9
65	Shivani Tal. Shirala Dist. Sangli	1991	74°05′30" 17°00′00"	16.23	1.69	132	MH09MH. 1263	25.5.2021 29.11.2021	3.1, 3.2, 3.13, 3.16,3.22, 3.20, 3.28,3.35	8
66	Siddhnath Tal. Jath Dist. Sangli	1981	75°20′25" 16°45′30"	18.96	8.58	1530	MH09MH. 0654	11.5.2021 14.12.2021	3.1, 3.2, 3.6, 3.7, 3.13, 3.19, 3.20, 3.34	8
67	Soardi Tal. Jath Dist. Sangli	1983	75°22′30" 17°03′05"	18.08	4.40	921	MH09MH. 1002	11.5.2021 14.12.2021	3.2, 3.5,3.7,3.13, 3.20, 3.21, 3.34, 3.35	8
68	Takave Tal. Shirala Dist. Sangli	1989	74°07′00" 17°05′00"	24.81	2.97	283.50	MH09MH. 1217	25.5.2021 29.11.2021	3.1,3.2, 3.13, 3.20, 3.22, 3.28, 3.35,3.16	8

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
69	Tippehalli Tal. Jath Dist. Sangli	1975	74°4'00" 17°8'00"	18.12	2.02	578	MH09MH 0513	18.5.2021 2.12.2021	3.1, 3.2, 3.6, 3.7, 3.9, 3.13, 3.35, 3.21, 3.34,3.16	10
70	Umrani Tal. Jath Dist. Sangli	1999	75°30′00" 17°30′00"	15.33	4.23	509	MH09MH. 1512	28.5.2021 14.12.2021	3.2,3.5, 3.6, 3.7, 3.9, 3.13, 3.19	7
71	Wakurde Tal. Shirala Dist. Sangli	1985	70°02′00" 17°03′30"	19.25	1.61	156.10	MH09MH. 1073	25.5.2021 29.11.2021	3.1,3.2,3.6,3.20 , 3.13, 3.35,3.22	7
72	Walekhind Tal. Jath Dist. Sangli	1973	75°07′32" 17°13′32"	16.18	4.13	41	MH09MH. 0322	18.5.2021 2.12.2021	3.1, 3.2, 3.5, 3.21, 3.13, 3.22, 3.20	7
73	Yelavi Tal. Khanapur Dist. Sangli	1975	74°20'00'' 17°30'00''	15.90	2.26	639	MH09MH 0514	11.5.2021	3.9, 3.2, 3.5, 3.6, 3.7, 3.13, 3.20, 3.16, 3.35	9
(b) E>	cecutive Engineer Ter	mbhu Lift	Irrigation Pro	ject Mana	gement Divi	ision Ogalew	/adi			
74	Anjani Tal.Tasgaon Dist. Sangli	1970	74°02′00" 17°04′00"	15.00	2.09	14.27	MH09MH. 0230	27.5.2021 20.10.2021	3.1,3.5,3.7,3.9,3.10,3.13,3.16,3.22,3.34,3.35,3.28	11
75	Arjunwadi Tal. Atpadi Dist. Sangli	2005	74°51′00" 17°17′00"	17.94	2.352	739.0	MH09MH 1609	7.4.2021 4.10.2021	3.5, 3.7, 3.9, 3.13, 3.20, 3.22, 3.21, 3.28, 3.6,3.16	10
76	Atpadi Tal. Atpadi Dist. Sangli	1972	74°55′00" 17°24′00"	16.50	8.67	1727	MH09MH. 0314	6.5.2021 30.10.2021	3.1, 3.2, 3.5, 3.7, 3.9,3.13 ,3.16,3.20, 3.21, 3.6, 3.22, 3.34	12
77	Bhakuchiwadi Tal Khanapur Dist. Sangli	1989	74°23′00" 17°21′00"	19.20	7.40	150	MH09MH. 1211	24.4.2021 9.11.2021	3.1, 3.5, 3.7, 3.9, 3.10, 3.20, 3.21,3.34, 3.35	9
78	Bhambarde Tal.Khanapur Dist. Sangli	1972	74°35′00" 17°19′00"	22.00	1.32	391	MH09MH. 0295	24.4.2021 9.11.2021	3.5, 3.7, 3.9, 3.20,3.21, 3.35	6
79	Buddhihal Tal.Mangalwedha Dist. Solapur	1966	74°59'54" 17°18'30"	18.52	19.03	2510	MH09MH 0134	23.4.2021 12.10.2021	3.2,3.5,3.7,3.9,3.13,3.20,3.21,3.22,3.34,3.35,	13

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
								Test Inspected by DSO 29.1.2022	3.6, 3.19,3.16	
80	Dighnchi Tal. Atpadi Dist. Sangli	1976	74°55′30" 17°24′30"	15.80	4.00	1301	MH09MH. 0591	6.5.2021 30.10.2021	3.1, 3.5, 3.7, 3.9, 3.10, 3.13, 3.9, 3.20, 3.22, 3.21, 3.34, 3.6	12
81	Ghanand Tal. Atpadi Dist. Sangli	1986	74°44′00" 17°44′30"	15.46	1.44	341	MH09MH. 1120	7.4.2021 4.10.2021	3.1,3.2, 3.5, 3.6,3.7, 3.9, 3.13, 3.20, 3.21,3.22,3.28,3.31,3.34	13
82	Hingangaon Tal.KadegaonDist. Sangli	1998	74°12′00" 17°55′00"	16.02	2.01	156	MH09MH. 1462	22.4.2021 8.11.2021	3.2, 3.5,3.13, 3.19, 3.20 , 3.34, 3.35	7
83	Jambhulani Tal. Atpadi Dist. Sangli	1975	74°60′00" 17°34′00"	15.87	2.85	668	MH09MH. 0517	7.4.2021 4.10.2021	3.1, 3.5, 3.7, 3.9, 3.10, 3.13, 3.16,3.20, 3.22, 3.34, 3.21, 3.6, 3.28	13
84	Kacharewasti Tal. Jath Dist. Sangli	1974	75°51′00" 17°21′20"	18.75	3.13	973	MH09MH. 0447	7.4.2021 4.10.2021	3.2, 3.5, 3.7, 3.9, 3.13, 3.35, 3.20, 3.21,3.28	9
85	Kadegaon Tal. Kadegaon Dist. Sangli	1975	74°16′00" 17°16′00"	17.54	2.36	508.70	MH09MH. 0510	22.4.2021 8.11.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.13, 3.35, 3.20	8
86	Karandewadi Tal. Kadegaon Dist. Sangli	1995	74°17′12" 17°22′00"	18.45	1.36	39.45	MH09MH. 1348	22.4.2021 8.11.2021	3.1, 3.5, 3.7, 3.13, 3.21, 3.35, 3.20	7
87	Lodhe Tal.Tasgaon Dist. Sangli	1996	74°40′00" 17°05′00"	16.76	4.63	1593	MH09MH. 1412	27.5.2021 20.10.2021	3.1,3.5,3.7, 3.10, 3.2, 3.20, 3.22, 3.21,3.28,3.31,3.9, 3.13, 3.35, 3.34, 3.19	15
88	Morale Tal. Tasgaon Dist. Sangli	1974	74°42′09" 17°11′43"	16.10	0.65	141.0	MH09MH. 0239	2.5.2021 29.10.2021	3.1, 3.2, 3.5, 3.6, 3.7, 3.9.3, 10, 3.1 3, 3, 20, 3, 21, 3, 22, 3, 28, 3, 31, 3, 34 , 3, 35,	15
89	Nhavi	1981	74°15′20"	17.48	2.19	314.0	МН09МН.	22.4.2021	3.2, 3.7, 3.13, 3.16, 3.19,	11

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
	Tal. Kadegaon Dist. Sangli		17°15′20"				1050	8.11.2021	3.20, 3.21, 3.22, 3.34, 3.35, 3.33	
90	Nimbawade Tal. Atpadi Dist. Sangli	1986	74°52′30" 17°28′00"	16.13	6.68	1233	MH09MH. 1187	6.5.2021 30.10.2021	3.2, 3.6,3.7, 3.9, 3.13, 3.20, 3.21,3.22,3.28, 3.31,3.34	10
91	Pare Tal. Khanapur Dist. Sangli	1973	74°35′00" 17°12′00"	18.73	34.16	4081.0	MH09MH 0296	24.4.2021 9.11.2021	3.2, 3.13, 3.19, 3.21, 3.20, 3.34, 3.35, 3.31	8
92	Ped Tal. Tasgaon Dist. Sangli	1972	74°40′08" 17°12′05"	19.04	1.57	158	MH09MH. 0272	2.5.2021 29.10.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.13, 3.16, 3.20, 3.21, 3.34, 3.31, 3.35	12
93	Punadi Tal. Tasgaon Dist. Sangli	1987	74°37′00" 17°30′00"	17.00	1.414	225	MH09MH. 1156	27.5.2021 20.10.2021	3.1,3.5,3.6,3.7,3.9,3.13,3.16,3.20,3.21,3.22,3.28,3.31,3.34,3.35	14
94	Shalgaon TalKadegaon Dist. Sangli	1976	74°00′00" 17°07′00"	15.00	2.287	406	MH09MH. 0578	22.4.2021 8.11.2021	3.2, 3.5, 3.35,3.20	4
95	Siddhewadi Tal. Tasgaon Dist. Sangli	1977	74°06′00" 17°60′00"	18.81	6.43	1571	MH09MH. 0902	27.5.2021 20.10.2021	3.1,3.2,3.5,3.6,3.7,3.9,3.13,3.16,3.19,3.22,3.20,3.21,3.283.34, 3.35	15
96	Vejegaon Tal.Khanapur Dist. Sangli	1979	74°36′00" 17°23′00"	16.77	2.21	426	MH09MH. 0782	24.4.2021 9.11.2021	3.2, 3.5, 3.9, 3.35, 3.20,3.21,3.22	7
97	Vibhutewadi Tal. Atpadi Dist. Sangli	1983	73°30′00" 17°28′30"	16.21	1.32	16.62	MH09MH. 1013	6.5.2021 30.10.2021	3.2,3.5,3.7,3.10,3.9,3.13,3.20,3.22,3.34,3.21,3.28,3.6	12
98	Walunj Tal. Jath Dist. Sangli	1977	74°00′37" 17°00′19"	17.81	1.69	475	MH09MH. 0635	24.4.2021 9.11.2021	3.2,3.5, 3.7, 3.9, 3.35, 3.21, 3.20,	7
99	TalgaonGhogaon Tal. Khanapur Dist. Sangli	1984	74°11'00" 17°00'00"	21.18	56.26	475	MH09MH 0635	30.4.2021 1.11.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.13, 3.35, 3.19, 3.20, 3.21,3.22,	12

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
									3.31	
100	Mahadikwadi Tal. Atpadi Dist. Sangli	2003	74°40′00" 17°11′00"	16.02	2.10	789.38	MH09MH 1547	6.5.2021 30.10.2021	3.1, 3.2, 3.7, 3.5, 3.9,3.10, 3.13, 3.16, 3.20, 3.21, 3.22, 3.35, 3.28, 3.6	14
(d) Ex	ecutive Engineer Tal	kari Pump	House Divisi	on No.1, I	Devarashtre					
101	Chinchani Tal.Kadegaon Dist. Sangli	1989	73°31′50" 17°20′00"	17.46	4.31	628	MH09MH. 1222	6.1.2021 30.11.2021	3.1, 3.2, 3.5,3.7, 3.9, 3.13, 3.20 3.22, 3.23, 3.28,3.34	D, 11
(4) Sı	uperintending Engine	er, Kolha	pur Irrigation	Circle, Ko	olhapur					
(a	a) Executive Enginee	r, Kolhapı	ur Irrigation D	Division (I	North), Kolh	apur				
102	Andur Tal. Gadhinglaj Dist. Kolhapur	1982	73°58′00" 16°36′00"	24.51	5.75	98.0	MH09MH. 0914	12.5.2021 24.10.2021	3.2, 3.7, 3.9, 3.13, 3.16,3.2 3.22, 3.31,3.34	0, 9
103	Kandalgaon Tal. Gadhinglaj Dist. Kolghapur	1980	74°20′00" 16°40′00"	19.41	1.70	98	MH09MH. 0811	15.5.2021 20.10.2021	3.2,3.5, 3.7, 3.9, 3.13, 3.20, 3.2 3.34, 3.31.	1, 9
104	Kaneriwadi Tal. Gadhinglaj Dist. Kolhapur	1974	74°17′05" 16°37′47"	17.5	2.60	182	MH09MH. 0408	15.5.2021 20.10.2021	3.2, 3.5, 3.9, 3.13, 3.20, 3.22,	6
105	Kasarde Tal.Gadhinglaj Dist. Kolhapur	2009	74°51′00" 16°55′30"	29.85	4.416	268.8	MH09MH 1908	17.5.2021 24.11.2021	3.13,3.20, 3.22, 3.31	4
106	Keaskarwadi Tal. Shahuwadi Dist. Kolhapur	1998	73°30′00" 16°49′00"	26.28	5.67	52.85	MH09MH. 1452	10.5.2021 24.11.2021	3.7, 3.9, 3.13, 3.22, 3.20, 3.21.	6
107	Khandwan Tal.Shahuwadi Dist. Kolhapur	2000	73°32′30" 17°02′45"	29.86	5.59	119	MH09MH. 1548	17.5.2021 2.11.2021	3.1,3.2 3.13, 3.35, 3.2 3.25,3.31,3.33	D, 8
108	Kode Tal. Gadhinglaj	1989	73°52′00" 16°28′00"	24.77	6.06	234	MH09MH. 1224	12.5.2021 24.10.2021	3.7, 3.9, 3.16, 3.25, 3.20, 3.31	6

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
	Dist. Kolhapur									
109	Kumbhawade Tal. Shahuwadi Dist. Kolhapura	1999	73 °46'00" 16 °47'00"	25.16	5.615	141	MH09MH. 1499	10.5.2021 24.11.2021	3.1,3.6,3.7,3.9,3.13, 3.16,3.35,3.20, 3.21, 3.22,3.25	11
110	Manpadale Tal. Gadhinglaj Dist. Kolhapur	1971	74°13′00" 16°48′00"	20.80	1.43	37	MH09MH. 0234	15.5.2021 2.10.2021	3.5, 3.7, 3.20,3.21 ,3.31	5
111	Nandari Tal. Shahuwadi Dist. Kolhapur	1999	73°57′00" 16°47′00"	26.40	3.208	99.5	MH09MH. 1497	10.5.2021 24.11.2021	3.1,3.5, 3.13, 3.20, 3.22, 3.6	6
112	Olwan Tal. Gadhinglaj Dist. Kolhapur	1996	74°52′00" 16°23′00"	24.740	1.875	157	MH09MH. 1389	19.4.2021 9.11.2021	3.5, 3.7, 3.13, 3.16, 3.20, 3.21 3.22, 3.31	1, 8
113	Padsali Tal. Gadhinglaj Dist. Kolhapur	1997	74°50′50" 16°42′00"	29.15	6.90	186	MH09MH. 1427	10.5.2021 24.11.2021	3.1, 3.7, 3.9, 3.13, 3.16,3.20 3.21, 3.22), 8
114	Pombre Tal. Panhala Dist. Kolhapur	1985	73°50′15" 18°42′35"	24.11	6.50	235	MH09MH. 1078	10.5.2021 24.11.2021	3.7, 3.1, 3.9, 3.13, 3.22, 3.20 3.21), 7
115	Vesraf Tal. Gaganbavda Dist. Kolhapur	1984	73°52′00" 16°35′00"	19.21	3.37	106	МН09МН. 1026	12.5.2021 24.10.2021	3.7, 3.9, 3.13, 3.20, 3.22	6
116	Manoli Tal. Gadhinglaj Dist. Kolhapur	2000	74 ° 45' 30" 16° 55' 30"	29.50	5.196	222.35	MH09MH 1537	17.5.2021 24.11.2021	3.5, 3.13, ,3.31	3
117	DaryachiVadgaon Tal. Chandgad Dist. Kolhapur	1993	74°00' 16°36'	23.65	0.8473	59.22	MH09MH 1302	15.5.2021 20.10.2021	3.13, 3.31	2

Sr.	Name of Dam	Date of	Location	Height	Gross	Design	Sr.No. in	Date of	Deficiencies noticed	Total
No		Compl-	Longitude/	in m	Capacity	Spillway	NRLD Bogistor	Inspection		Deficien
		ellon	Lallude		IVITT	m ³ / sec	Register	FIE & FUSL		cies
1	2	3	4	5	6	7	8	9	10	11
(b) E	kecutive Engineer, Ko	olhapur Irr	igation Divisi	ion (Sout	h), Kolhapu	r				
118	Benikre Tal. Gadhinglaj Dist. Kolhapur	1973	74°14′00" 16°24′00"	20.99	1.82	No spilway	MH09MH 0320	12.5.2021 23.11.2021	3.1,3.2, 3.5,3.7,3.9, 3.13, 3.35, 3.34, 3.21, 3.6	10
119	Dhangarwadi Tal. Ajara, Dist. Kolhapur	1999	74°05' 09" 16°02'30"	18.22 m	2.64	301	MH09MH 1506	23.4.2021 11.12.2021	3.1,3.9, 3.21, 3.27, 3.31, 3.34, 3.13	7
120	Dindalkop Tal. Gadhinglaj Dist. Kolhapur	2014	74°25′30" 15°45′45"	27.61	2.625	183.76	MH09MH. 1925	7.12.2021 7.12.2021	3.1, 3.9, 3.13, 3.35, 3.16, 3.19, 3.20, 3.21, 3.28	9
121	Erandol Tal.MangalwedhaDi st. Solapur	1999	74°11′00" 16°03′00"	30.55	4.210	586.34	MH09MH. 1514	26.4.2021 30.11.2021	3.1,3.2, 3.6,3.9, 3.13, 3.16,3.23	7
122	Hanbarwadi Tal.Kagal Dist. Kolhapur	1998	74°16′00" 16°18′00"	26.65	2.67	207	MH09MH. 1465	12.5.2021 23.11.2021	3.1,3.2,3.5, 3.6, 3.9, 3.13, 3.20,3.22,3.34	9
123	Here Tal. Gadhinglaj Dist. Kolhapur	1998	74'10'00" 15°52'30"	27.32	3.926	72	MH09MH. 1456	7.5.2021 30.11.2021	3.1, 3.9, 3.13, 3.16, 3.21, 3.20, 3.28	7
124	Jelugade Tal.Chandgad Dist. Kolhapur	2000	74°13′40" 15°52′30"	29.25	4.86	140.35	MH09MH. 1534	26.4.2021 21.11.2021	3.1, 3.9, 3.13, 3.35, 3.19, 3.16, 3.21, 3.20, 3.28	9
125	Kalasgade Tal.Gadhinglaj Dist. Kolhapur	2000	74°13′30" 16°49′30"	16.46	1.91	119	MH09MH. 1532	26.4.2021 21.11.2021	3.1,3.9, 3.13, 3.16, 3.19, 3.20, 3.21, 3.28. 3.35	9
126	Karambali Tal. Gadhinglaj Dist. Kolghapur	2007	74°17′30" 16°12′00"	27.44	2.91	90.72	MH09MH. 1667	19.4.2021 23.11.2021	3.1,3.6, 3.7, 3.9, 3.13, 3.21, 3.28.	7
127	Karanjgaon Tal. Chandgad Dist. Kolhapur	1998	74°14'00" 16°54'00"	29.81	3.50	64	MH09MH. 1454	7.5.2021 21.11.2021	3.1,3.6, 3.9, 3.13, 3.16, 3.19, 3.20, 3.21, 3.28	9

Sr.	Name of Dam	Date of	Location	Height	Gross	Design Spillway	Sr.No. in	Date of	Deficiencies noticed	Total Deficien
		etion	Latitude		Mm ³	Capacity m ³ / sec	Register	Pre & Post		cies
1	2	3	4	5	6	7	8	9	10	11
128	Karanjwane Tal. Kagal Dist. Kolhapur	1989	74°14'00" 16°21'00"	21.00	1.51	124	MH09MH. 1209	12.5.2021 23.11.2021	3.1,3.2, 3.5,3.6, 3.7, 3.9, 3.13, 3.35, 3.34, 3.21	10
129	Khadakohol Tal. Chandgad Dist. Kolhapur	1999	74° 16'00" 15° 54'00"	16.42	1.82	157	MH09MH. 1502	26.4.2021 21.11.2021	3.1, 3.9, 3.13, 3.19, 3.16, 3.20, 3.31, 3.35	8
130	Khanapur Tal. Gadhinglaj Dist. Kolhapur	1988	74°10′00" 16°05′00"	21.35	0.84	38	MH09MH. 1177	26.4.2021 11.12.2021	3.9, 3.13, 3.31	3
131	Kitwad Tal.Chandgad Dist. Kolhapur	2000	75°25′00" 15°58′00"	29.59	5.53	611	MH09MH. 1543	15.5.2021 21.11.2021	3.6, 3.9, 3.13, 3.19, 3.16, 3.35, 3.20, 3.21, 3.28.	9
132	Kumari Tal. Gadhinglaj Dist. Kolhapur	1998	74°18′00" 15°30′00"	23.64	2.59	94	MH09MH. 1457	18.5.2021 28.10.2021	3.1, 3.6, 3.9, 3.13, 3.19, 3.16, 3.35, 3.20,3.21, 3.28.	10
133	Narewadi Tal. Gadhinglaj Dist. Kolhapur	1981	74°08′30" 16°25′30"	23.75	2.22	282	MH09MH. 0871	18.5.2021 28.10.2021	3.1, 3.9, 3.13, 3.28,3.21, 3.27	6
134	Nittur-2 Tal. Gadhinglaj Dist. Kolhapur	2000	74°22′30" 15°44′54"	28.04	4.38	90.65	MH09MH. 1530	15.5.2021 7.12.2021	3.1, 3.6, 3.9, 3.13, 3.19, 3.16, 3.20,3.21, 3.27, 3.28	10
135	Patane Tal. Chandgad Dist. Kolhapur	2001	73°13′30" 15°51′15"	26.82	4.55	78.7	MH09MH. 1563	7.5.2021 21.11.2021	3.1, 3.6, 3.9, 3.13, 3.19, 3.16, 3.20,3.21, 3.27, 3.28	10
136	Shendri Tal. Gadhinglaj Dist. Kolhapur	1981	74°21′00" 16°16′00"	21.14	1.81	130	MH09MH. 0853	19.4.2021 23.11.2021	3.1, 3.5, 3.6, 3.9, 3.13,3.16, 3.21, 3.27, 3.28	9
137	Sundi Tal. Chandgadj Dist. Kolhapur	2009	74°22′00" 15°16′00"	27.00	2.594	169.05	MH09MH. 1910	15.5.2021 7.12.2021	3.1, 3.6, 3.9, 3.13,3.16, 3.19, 3.20, 3.35, 3.28, 3.21, 3.27	11
138	Terani Tal. Gadhinglaj Dist. Kolhapur	1996	74°28'00" 16°8'00"	20.66	3.476	516	MH09MH. 1399	18.5.2021 28.10.2021	3.7, 3.9, 3.13, 3.28, 3.27, 3.21, 3.6, 3.1	8

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
139	Vairagwadi Tal. GadhinglajDist.Kol ghapur	1984	74°20′30" 16°09′30"	20.34	1.50	96	МН09МН. 1022	18.5.2021 28.10.2021	3.1, 3.6, 3.9, 3.13,3.21, 3.7, 3.27, 3.31, 3.28	9
140	Yenechavandi Tal.Gadhinglaj, Dist. Kolhapur	1996	74°20' 16° 11'	21.65	1.545	182	МН09МН 1339	18.5.2021 28.10.2021	3.1, 3.6, 3.7, 3.9, 3.13, 3.21, 3.20, 3.28	8
(5)Su	perintending Engine	er, Satara	Irrigation Cir	cle, Satar	a					
(a) Ex	kecutive Engineer, Kr	rishna Irrig	ation Divisio	n, Satara			•			
141	Andhali Tal. Man Dist. Satara	1997	74° 30'00" 17° 45'00"	18.60	9.273	1422.0	MH09MH. 1443	10.5.2021 28.12.2021	3.1,3.2,3.5,3.7,3.9,3.10,3.13,3. 16,3.20,3.21,3.22	11
142	Arabwadi Tal.Koregaon Dist.Satara	1977	74°04' 50" 17°50' 07"	17.35	1.89	246	MH09MH. 0621	5.5.2021 28.12.2021	3.1,3.5,3.7, 3.10,3.13, 3.20,3.21,3.22	8
143	Daruj Tal. Khatav Dist. Satara	1956	74° 25'00" 17°40'00"	16.46	2.88	364	MH09MH. 0074	17.5.2021 27.12.2021	3.2,3.5,3.7,3.9,3.10,3.13,3.16, 3.19,3.20	9
144	Dhakani Tal. Man Dist. Satara	1994	74° 41'00" 17°35'00"	18.50	3.05	602	MH09MH. 1335	10.5.2021 28.12.2021	3.2,3.5,3.9,3.10,3.13,3.16, 3.20,3.21,3.22,3.23	10
145	Hiware Tal.Koregaon Dist. Satara	1974	74° 11'00" 17°50'00"	18.14	2.74	657	MH09MH. 0443	5.5.2021 28.12.2021	3.1,3.5, 3.13,3.16,3.20,3.21	6
146	Jambhulani Tal. Man Dist. Satara	1981	74° 60'00" 17° 34'00"	15.21	2.41	514.00	MH09MH. 0516	10.5.2021 28.12.2021	3.2,3.5,3.9,3.13,3.16, 3.20,3.21	7

Sr. No	Name of Dam	Date of Compl-	Location Longitude/	Height in m	Gross Capacity	Design Spillway	Sr.No. in NRLD	Date of Inspection	Deficiencies noticed	Total Deficien
		etion	Latitude		Mm³	Capacity m ³ / sec	Register	Pre & Post		cies
1	2	3	4	5	6	7	8	9	10	11
147	Kumathe Tal.Satara Dist. Satara	2001	73°52′00" 17°26′00"	27.13	2.86	143.00	MH09MH. 1682	4.5.2021 2.12.2021	3.1,3.7,3.9,3.13,3.16,3.19,3.20, 3.21, 3.22,3.23	10
148	Mandawe Tal.Koregaon Dist. Satara	1994	73°59′00" 17°34′00"	19.50	1.15	229	MH09MH. 1323	4.5.2021 2.12.2021	3.1,3.7, 3.13,3.16,3.20,3.21,3.22	7
149	Masalwadi Tal. Man Dist. Satara	1975	74° 50'30" 17°40'00"	14.30	2.41	839.94	MH09MH. 0377	10.5.2021 28.12.2021	3.2,3.5,3.7,3.9,3.13,3.16,3.19,3 .20,3.21, 3.23, 3.34	11
150	Mayani Tal. Khatav Dist. Satara	1872	74° 34'00" 17°26'00"	18.00	1.46	1384	МН09МН. 0008	17.5.2021 27.12.2021	3.2, 3.7, 3.9, 3.10, 3.13, 3.20, 3.21, 3.23, 3.28.	9
151	Nandwal Tal. Koregaon Dist. Satara	2008	74° 11'00" 16°37'10"	18.78	09.39	39.2	MH09MH. 1640	5.5.2021 28.12.2021	3.4,3.5,3.7,3.9,3.16,3.20, 3.21,3.22	8
152	Ner Tal. Khatabv Dist. Satara	1981	74° 18'00" 17°44'00"	22.50	9.12	1478	MH09MH. 0018	17.5.2021 27.12.2021	3.1,3.2,3.5,3.7,3.9,3.10,3.13,3.16, 3.20,3.21, 3.23,3.25,3.34	13
153	Pingali Tal. Man Dist. Satara	1878	74° 33'00" 17°41'00"	16.00	2.38	811	MH09MH. 0731	10.5.2021 28.12.2021	3.1,3.2,3.5,3.7,3.9,3.10,3.13, 3.19,3.20,3.21,3.23,3.25,3.34	13
154	Ranand Tal. Man Dist. Satara	1956	74° 40'00" 17° 43'00"	19.32	7.12	1168.7	MH09MH. 0078	10.5.2021 28.12.2021 Test Inspected by DSO 30.1.2022	3.2,3.5,3.7,3.9,3.13,3.16,3.19 3.20,3.21 3.22,3.23	11
155	Yeralwadi Tal.Khatav Dist.Satara	1973	74°29′35" 17°31′24"	19.50	32.80	2083	MH09MH. 0386	7.5.2021 28.12.2021	3.5,3.9,3.13,3.16,3.19,3.22,3.29,3. 34	8
156	Kankatrewadi Tal. Phaltan Dist. Satara	1978	74°35′00" 17°29′00"	19.51	1.24	1283	MH09MH0 736	17.5.2021 27.12.2021	3.2,3.7,3.9,3.10,3.13,3.16,3.19, 3.20,3.21	9

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/	Height in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
		0				m ³ / sec	itegiotoi			0.00
1	2	3	4	5	6	7	8	9	10	11
157	Name : Thoseghar Tal. Satara Dist. Satara	1989	73°52′00" 17°36′00	18.05	1.91	113	MH09MH 1208	4.5.2021 2.12.2021	3.2,3.5,3.10,3.13,3.16,3.19, 3.20, 3.22.	8
158	Deur Tal Koregaon Dist. Satara	1994	74°08′00" 17°54′00"	18.60	1.856	475	МН09МН. 1329	29.5.2021 6.12.2021	3.1,3.2,3.7,3.9,3.13,3.20,3.21,3 .30	8
(b) E	xecutive Engineer, Ko	oyna Irriga	tion Division	Koynana	gar		•			
159	Chalkewadi Tal. Patan Dist. Satara	1991	74°05′00" 17°11′00"	21.53	0.80	39	MH09MH. 1258	18.5.2021 26.11.2021	3.7,3.9,3.10,3.13,3.16,3.20,3.2 2, 3.31,3.34,3.35	10
160	Chaphal Tal.Koregaon Dist. Satara	1983	74°00′28" 17°24′24"	21.50	1.45	229	MH09MH. 0966	20.5.2021	3.1,3.2,3.5,3.7,3.13,3.16,3.19,3 .20,3.21,3.22	10
[A] C	hief Engineer (S.P) W	later Reso	urces Departr	nent Pune	9					
(1) St	uperintending Engine	er Kukadi	Irrigation Cire	cle Pune						
(a) Ex	kecutive Engineer ,Κι	ukadi Irriga	ation Division	No. 1 Nar	ayangaon					
161	Anepemdara Tal. Junnar, Dist. Pune	1998	73° 14'00" 19° 11'00"	14.34	2.09	545	MH09LH. 1473	21.5.2021 24.11.2021	3.2,3.7,3.9,3.10,3.13,3.16, 3.20,3.21,3.34	9
162	Ballalwadi Tal. Junnar, Dist. Pune	1996	73° 55'30" 19° 15'00"	20.16	1.95	1968	МН09МН. 1414	4.6.2021 24.11.2021 Test Inspected by DSO 22.10.2021	3.1,3.2,3.5,3.7,3.9,3.10,3.13,3. 16, 3.19,3.20,3.22,3.34	12
163	Ghangaldara Tal. Junnar, Dist. Pune	2009	74° 00'00" 18° 20'00"	26.34	2.34	152.88	MH09MH. 1906	20.5.2021 26.11.2021	3.5,3.7,3.9,3.10,3.13,3.25	6
164	Gohe Tal. Ambegaon, Dist. Pune	1996	73° 44'00" 19° 04'00"	17.49	1.28	338	MH09MH. 1397	22.6.2021 27.11.2021	3.2,3.5,3.7,3.9,3.10,3.13,3.19,3 .22	8

Sr. No	Name of Dam	Date of Compl- etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
						m ³ / sec				
1	2	3	4	5	6	7	8	9	10	11
165	Otur - waghadara Tal. Junnar Dist. Pune	1992	74° 02'00" 19° 05'00"	20.16	0.953	137.3	МН09МН. 1262	19.5.2021 24.11.2021 Test Inspected by DSO 22.10.2021	3.1,3.2,3.5,3.7,3.9,3.10,3.13,3. 20, 3.16, 3.33,3.34,3.22	12
166	Parunde Tal. Junnar, Dist. Pune	1989	73° 47'30" 19° 09'45"	20.02	1.92	146	MH09MH. 1210	4.6.2021 24.11.2021	3.7,3.9,3.10,3.13,3.16,3.20, 3.21,3.33,3.34	9
167	Ramjewadi Tal. Junnar, Dist. Pune	1983	73° 41'00" 19° 13'00"	21.48	1.72	209	MH09MH. 0965	20.5.2021 26.11.2021	3.2,3.6,3.7,3.9,3.10,3.13,3.16,3 .19,3.20,3.21	9
168	Ucchil Tal. Junnar, Dist. Pune	2001	73° 41'00" 19° 13'00"	13.01	3.12	201.0	MH09MH. 1572	20.5.2021 26.11.2021	3.2,3.5,3.7,3.9,3.10,3.13,3.16, 3.20,3.21	9
169	Yenere Tal. Junnar, Dist. Pune	1979	73° 47'00" 19° 10'00"	19.50	2.07	281	MH09MH. 0768	20.5.2021 26.11.2021	3.2,3.5, 3.9,3.10,3.13,3.16,3.20, 3.33,3.34	9
170	Shivdoh Tal. Parner, Dist. A.Nagar	2003	74° 16'45" 19° 01'06"	12.70	1.16	295	MH09LH 2031	24.5.2021 7.12.2021	3.2,3.5,3.7,3.9,3.13,3.16,3.20,3 .21,3.22,	9
171	Devibhoyare Tal. Parner, Dist. A.Nagar	2002	74° 17'38" 19° 00'45"	15.70	2.77	330	MH09LH 2032	24.5.2021 7.12.2021	3.2,3.5,3.7,3.9,3.13,3.16,3.20, 3.21,	8
172	Jhadhavwadi Tal. Parner, Dist. A.Nagar	2001	74° 20'59" 19° 02'21"	15.70	1.39	440.60	MH09LH 2033	24.5.2021 7.12.2021	3.2,3.5,3.7,3.9,3.13,3.16,3.20, 3.21,3.34	9

Sr.	Name of Dam	Date of	Location	Height	Gross	Design	Sr.No. in	Date of	Deficiencies noticed	Total
No		Compl-	Longitude/	in m	Capacity	Spillway	NRLD	Inspection		Deficien
		etion	Latitude		wim	m ³ /sec	Register	Pre & Post		cies
1	2	3	4	5	6	7	8	9	10	11
(a) Ex	ecutive Engineer ,So	lapur Irrig	ation Division	n Solapur		•				
173	Chare Tal. Barshi Dist. Solapur	1983	75°45'00" 18°35'42"	16.30	1.50	286	MH09MH. 0973	5.5.2021 10.11.2021	3.1, 3.9, 3.13, 3.16, 3.20, 3.21, 3.23, 3.22, 3.33	9
174	Hingani(k) Tal. Karmala Dist Solapur	1974	75°24'30" 18°16'00"	16.15	2.22	571	MH09MH. 0441	8.5.2021 10.11.2021	3.9, 3.34, 3.13, 3.20, 3.22,3.28, 3.35	7
175	Hingani(p) Tal. Barshi Dist. Solapur	1977	75°50'00" 18°07'00"	21.87	45.51	2435	MH09MH. 0657	14.5.2021 10.11.2021	3.1, 3.6,3.10, 3.2, 3.13, 3.16, 3.19, 3.20, 3.21, 3.22	10
176	Jawalgaon Tal. Barshi Dist. Solapur	1985	75°54'00" 18°01'00"	21.71	34.92	1837	MH09MH. 1340	14.5.2021 10.11.2021	3.2, 3.13, 3.16, 3.19, 3.20, 3.21, 3.22	7
177	Kari Tal. Barshi Dist. Solapur	1973	75°00'20" 18°55'00"	15.72	1.70	364.8	MH09MH. 0363	5.5.2021 10.11.2021	3.2, 3.7, 3.9, 3.13, 3.16, 3.19, 3.20, 3.33, 3.34, 3.35	10
178	Koregaon Tal. Barshi Dist.Solapur	1985	75 °45'00" 18 °25'00"	21.64	1.96	335	MH09MH. 1200	5.5.2021 10.11.2021	3.5, 3.7, 3.13	3
179	Mangi Tal. Karmala Dist Solapur	1966	75°17'00" 17°17'00"	22.95	30.92	2237	MH09MH. 0131	8.5.2021 12.11.2021	3.13, 3.20	2
180	Pathari Tal. Barshi Dist. Solapur	1905	75°50'00" 18°19'00"	19.43	11.87	512	MH09MH. 0025	14.5.2021 10.11.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.16, 3.21, 3.35	8
181	Shirwalwadi Tal.Akkalkot Dist Solapur	1978	76°18'00" 17°02'20"	16.10	3.26	461.56	MH09MH 0720	10.5.2021 16.11.2021	3.1, 3.2, 3.5,3.6, 3.7, 3.9, 3.13, 3.16, 3.19, 3.20, 3.21,3.28, 3.35	13
182	Kazikunbus Tal. Akkalkot Dist. Solapur	1992	76°10'00" 17°43'00"	20.00	4.031	692.15	MH09MH 1224	10.5.2021 16.11.2021	3.1,3.2, 3.5,3.9, 3.22, 3.13, 3.16, 3.19, 3.20, 3.21, 3.28	11

Sr. No	Name of Dam	Date of Compl-	Location Longitude/	Height in m	Gross Capacity	Design Spillway	Sr.No. in NRLD	Date of Inspection	Deficiencies noticed	Total Deficien
		etion	Latitude		IVIT	m ³ /sec	Register	Pre & Post		cles
1	2	3	4	5	6	7	8	9	10	11
183	Rajuri Tal. Karmala Dist. Solapur	1981	74°58' 18°22'	19.29	2520	694.33	MH09MH 0894	8.5.2021 12.11.2021	3.1, 3.2, 3.5, 3.7, 3.9, 3.13, 3.16,3.21	8
(b) Ex	ecutive Engineer ,Bl	nima Irriga	tion Division	Pandharp	ur					
184	Chikhalgi Tal.Mangalwedha Dist. Solapur	1990	75°25'20" 17°17'30	18.37	8.74	1966	MH09MH. 0251	14.5.2021 11.1.2022	3.1,3.2,3.9,3.23,3.29	5
185	Chincholi Tal. Sangola Dist. Solapur	1966	75°28'00" 17°24'00	15.24	2.74	991	МН09МН. 0128	13.5.2021 11.1.2022 Test Inspected by DSO 29.1.2022	3.1,3.2,3.5,3.9,3.16,3.23,3.2 6,3.29,3.20	10
186	Padwalkarwadi Tal.Mangalwedha Dist. Solapur	1973	75°22'00" 17°12'45"	15.17	2.99	483	MH09MH. 0378	14.5.2021 11.1.2022	3.1,3.5,3.7,3.26,3.29,3.1, 3.23	7
187	Talsangi Tal.Mangalwedha Dist. Solapur	1896	75°26'00" 17°01'20"	15.24	2.43	411.7	MH09MH. 0579	14.5.2021 11.1.2022	3.1,3.2,3.5, 3.7, 3.13, 3.26,3.29,3.35	8
(b) Executive Enginee	r Bhima D	evelopement	Division I	No.2, Solapı	ır				
188	Name : Ashti Tal. Mohol Dist. Solapur	1883	75°26' 00" 17°47'30	17.60	23.01	1359.21	MH09MH 0014	6.5.2021 9.11.2021	3.1,3.2, 3.6, 3.7, 3.9, 3.13, 3.16,3.20, 3.21	9
(3) Su	perintending Engine	eer ,Bhima	Canal Circle	, Solapur				I	-	
(a) Ex	ecutive Engineer ,Mi	nor Irrigat	ion Division N	No 1 Solap	our					
189	Babhulagaon Tal.Barshi Dist. Solapur	1993	75°46'55" 18°19'23"	16.93	6.40	1046.89	МН09МН. 1620	12.5.2021 9.10.2021	3.1 3.2, 3.9, 3.34,3.20, 3.13,3.21,	7

Sr.	Name of Dam	Date of	Location	Height	Gross	Design Spillway	Sr.No. in	Date of	Deficiencies noticed	Total Deficien
NO		etion	Latitude		Mm ³	Capacity	Register	Pre & Post		cies
						m ³ / sec				
1	2	3	4	5	6	7	8	9	10	11
190	Pimpalgaon Dhale Tal.Mangalwedha Dist. Solapur	2008	75°47'40" 18°10'10"	18.70	12.66	2242	MH09MH 1840	12.5.2021 9.10.2021 Test Inspection by DSO 31.1.2022	3.1,3.2, 3.5, 3.7, 3.9, 3.10, 3.13,3.20,3.31, 3.33	10
191	Gholasgaon Tal. Akkalkot. Dist- Solapur	2004	76°15'18" 17°30'50"	16.24	2.08	496.25	Proposed for updation in NRLD 2020	9.3.2021 NR	3.1,3.2, 3.7, 3.9, 3.13,3.20, 3.21,3.33,3.34	9
(4) St	perintending Engine	eer, Satara	a Project Irriga	ation Circ	le, Satara	•	-		·	
(a) Ex	ecutive Engineer ,Mi	nor Irrigat	tion Division S	Satara						
192	Mahind Tal. Patan Dist. Satara	2000	73°54'13" 17°22'05"	21.32	2.404	750.00	MH09MH 1838	14.5.2021	3.1,3.2,3.5,3.6,3.7,3.16,3.21,3. 23, 3.29,3.30, 3.34	11
193	Chiteghar Tal. Patan Dist. Satara	2010	73°53'20" 17°25'15"	23.4	3.90	1015.00	MH09MH 2409	13.5.2021	3.1, 3.6, 3.9, 3.20, 3.21 ,3.22,3.23,3.24,3.30 3.34	10

Class-I Dams with Category-1 Deficiency (Private Owned)

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
			No Su	ch Dams under	this class	

Class-I Dams with Category-2 Deficiency (Private Owned)

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
No		Inspection	Officer	Component of Dam	Noticed	
1	2	3	4	5	6	7
						·
(1)	The Tata Power Co. Ltd. Lon	avala				
1	Name :Thokarwadi (gated) Tal. Maval Dist. Pune Year of completion : 2006 Location : Longitude 73°30'34" Latitude 18°54'00" Height : 59.44 m Gross Capacity : 36370 Mcum Spillway capacity: 546 m³/sec Sr. No. in Large Dam Register :MH09MH0043	9.12.2021	Smt.S.Y.Kurhade EE. DSD 2, Nashik	Dam body	 The sign of leakages and sweating were observed with vegetation on downstream surface of NOF section (A11) 	Measurement of leakage and mapping sweating patches are done.It shall be kept under observation and record shall be kept with respect to reservoir water level.
2	Name :Walwhan (gated) Tal. Maval Dist. Pune Year of completion : 1916 Location : Longitude 73°25'25" Latitude 18°45'51" Height : 26.37 m Gross Capacity : 72.50 Mcum Spillway capacity: 546 m³/sec Sr. No. in Large Dam Register :MH09MH0036	21.12.2021	Shri.S.Amale SE. DSO, Nashik	Dam body	1.Minor leakages and sweating were observed with vegetation on downstream surface of NOF section (A11)	This vegetation needs to be cleaned from down stream sloping surface of NOF section of dam. The records of leakages wrt reservoir level shall be kept.

Sr.	Dam Features	Date of	Inspecting	Main	Significant Deficiencies	Remedial Measures Suggested
No		Inspection	Officer	Component	Noticed	
				of Dam		
1	2	3	4	5	6	7
3	Name :Shirwata (gated) Tal. Maval Dist. Pune Year of completion : 1920 Location : Longitude 73°28'41" Latitude 18°47'59" Height : 38.70 m Gross Capacity : 186.84 Mcum Spillway capacity: 593m ³ /sec Sr. No. in Large Dam Register :MH09MH0041	3 4 3 21.12.2021 Shri.S.Amale Dam body 1.There was through the overflow and overflowsed SE. DSO, Nashik 2.Sweating, leaching we surface of th and buttress the length of visit.On the grouting & p seen in procession		 There was leakage observed through the junction of overflow and non overflowsection.(A15) Sweating,leakage and leaching were observed slope surface of the NOF sections and buttresses for the most of the length of dam in earlier visit.On the day of visit grouting & pointing work were 	The leakage needs to be measured and necessary remedial measures shall be carried out. It is instructed that literature and standard procedure of application of this material shall be given to DSO for record.In next season sweating and leakages shall be observed where pointing is done.Thse observations shall be	
4	Name :Mulashi Tal. Mulashi Dist. Pune Year of completion : 1927 Location : Longitude 73°30'50" Latitude 18°31'31" Height : 50.60 m Gross Capacity : 794.95 Mcum Spillway capacity: 1892m ³ /sec Sr. No. in Large Dam Register :MH09MH0049	9.12.2021	Smt.S.Y.Kurhade EE. DSD 2, Nashik	Dam Body	1.Considerable leakage along with sweating and leaching are observed.	Measurement of lekages with measuring devicesshall be done and sweating patches shall be measured.It shall be kept under observation with respect to reservoir water level and necessary grouting and pointing as per shirwata dam shall be done if leakages are beyond permissible limit.

Class-I Dams with Category-3 Deficiency (Private Owned)

Sr. No	Name of Dam	Date of Completion	Location	Height in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Gated / Ungated	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
			Latitude			m ³ /sec	Ū				
1	2	3	4	5	6	7	8	9	10	11	12
(1)The Tata Power Co. Ltd. Lonavala											
1	Thokarwadi Tal.Maval Dist. Pune	1922	73°30'34" 18°54'00''	59.44	363.70	546.00	MH09HH 0043	Ungated	9.12.2021	3.1, 3.9, 3.16,3.26	4
2	Shirwatta Tal.Maval Dist. Pune	1920	73°28'41" 18°47'59''	38.70	186.84	593	MH09HH 0041	Ungated	21.12.2021	3.9,3.12,3.16,3.33	4
3	Mulashi Tal.Mulashi Dist. Pune	1927	73°30'50" 18°31'31''	50.60	794.95	1892	MH09HH 0049	Gated	9.12.2021	3.1,3.12,3.16,3.19,3.20	5
4	Walwan Tal.Maval Dist. Pune	1916	73°25'25" 18°45'51''	26.37	72.50	171	MH09MH. 0036	Ungated	21.12.2021	3.1, 3.6,3.9, 3.16,3.20	5
(2)S	ahara India (A	Ambey Valley)	Limited Pune	e		-	<u> </u>	-		-	
5	Vishakhar Tal. mulashi Dist. Pune	2006.	73°25'00" 18°40'00''	38.00	4.22	245	MH09MH 1904	Ungated	Not Inspected		
6	Ambavane Tal. Mulashi Dist. Pune	2000	73°25'00" 18°40'00"	38.76	8.575	738	MH09MH 1898	Gated	Not Inspected		
7	Kolawali Tal. Mulashi Dist. Pune	2000	73°25'00" 18°40'00"	43.50	2.17	90	MH09MH 1903	Ungated	Not Inspected		

Class-II Dams with Category-1 Deficiency (Private Owned)

Sr. No.	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
			No Such Da	ams under this cat	egory is reported	

Class-II Dams with Category-2 Deficiency (Private Owned)

Sr. No	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
(1) (Commissioner,Municipal Cor	poration Kolh	apur			
1.	Name : Kalamba Tal. Karveer Dist.Kolhapur Date of completion: 1983 Location: Longitude 74°21'27 ″ Latitude 16°55'41 ″ Height : 16.26 . m . Gross capacity 2.75 Mcum Sr.No.In Large Dam Register	28.1.2021	Inspected by EE DSD 1 Nashik	Earthen Embankment	 Earthen section seems to be undersection in certain portion .(B1) 	Superimpose existing cross section and L section on design cross and L section at every 30 m. C/C to ascertain whether earthen embankment is undersection or not. Communicate facts to DSO, Nashik
2.	2012: MH09MH1015 Name : Rankala Tal. Karveer Dist.Kolhapur Date of completion: 1883 Location: Longitude 73°40'00 ″ Latitude 16°43'00 ″ Height : 15.00 . m . Gross capacity 4.30 Mcum Sr.No.In Large Dam Register 2012: MH09MH0010	28.1.2022	Inspected by EE DSD 1 Nashik		 Waterway is blocked due to pipes, stones and ongoing concreting in tail channel. Also in tail channel there is obstructions in the form of enchrochment due to civilization.(A7) 	Sufficient waterway is must to pass safely overflow discharge. Hence clear the obstacles and encroachments in tail channel.
(2)	INS Shivaji ,Indian Navy , Lo	navala.			1	
3.	Name : Old Shivsagar Tal. Mawal Dist. Pune Date of completion:1989 Location:	26.8.2021	Inspected by EE DSD 1 Nashik	Body of dam	1. Water jets and leakages are observed through masonry section.(A11)	Leakage should be quantified and records of leakage with respect to water levels in reservoir should be maintained.
	Longitude- 73°52'00 " Latitude 18°45'00 Height : 2570 m			Section	2. The expansion joints of WW bar was seen opened.Heavy	Leakage should be quantified and

S N	r. Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
	2	3	4	5	6	7
	Gross capacity 1.81 Mcum Sr.No.In Large Dam Register MH09MH1230				leakages were observed.(B7) 3. Big trees, heavy vegetation are seen on d/s of ww bar in tail channel.(B2)	records of leakage with respect to water levels in reservoir should be maintained. Vegetation should be removed for free flow of water for disposal of water through tail channel without any obstruction
4	Name : New Shivsagar Tal. Mawal Dist. Pune Proposed for updation in NRLD 2018	26.8.2021	Inspected by EE DSD 1 Nashik	Masonry Section Embankment	 leakages were observed through masonry section @ chainages 117m to 123m (A11) Heavy Vegetation, bushes are observed@ 0m to120m on d/s of dam. Drains are not observed due to vegetation.(B2) Water jets are observed in the junction of overflow & non overflow section of masonry dam.(A15) Heavy leakages were observed @205m &.210m.Also minor leakages were observed at some places. Vertical porous drains in inspection gallery shows heavy leakages even after grouting of the masonry dam as informed by field officials. (A10) 	Leakage should be quantified and records of leakage with respect to water level in reservoir should be maintained. Vegetation and bushes should be removed for free flow of water and proper inspection of side slope of dam. Leakages through the mentioned junction are observed for varying levels of reservoir & record of the same should be maintained. Leakage should be quantified and records of leakage with respect to water level in reservoir should be maintained. Leakages through VPD pipes are observed for varying levels of reservoir & record of the same should be maintained.

Sr. No	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
(3)	Symbiosis,Lavale,Pune			I		
5	Name : Upper Tank Tal. Mulashi Dist. Pune Date of completion: Location: Longitude- 73°43'39" Latitude 18°32'04 Height :15.00 m Gross capacity 2.1694 Mcum Sr.No.In Large Dam Register	27.8.2021	EE DSD1 Nashik		 Waste Weir bar is not provided resulting in tail channel forming gutter.(B7) Toe drain of upper tank is submerged due to water of lower tank. Hydraulic study of Upper tank & Lower tank should be carried out in order to prevent submergence of toe drain of upper tank. Cross drains and longitudinal drains are not visible due to vegetation.(B2) 	Construct WW Bar to maintain reservoir level at FRL. Vegetation and bushes must be uprooted before they will grow into trees endangering the safety of earthen embankment. Vegetation should be removed for free flow of drains and also for proper inspection of the same. Approved Design note & Drawings shall be submitted to CDO/DSO, Nashik for study & suggesting proper remedial measures.
					3. Tail Channel erosion is observed. Heavy vegetation is observed in tail channel. Also tail channel get contracted towards lower tank. Erosio of earthen dam due to tail channel towards the d/s of upper tank is in progress.(A7)	To avoid further erosion, construct cross bar in tail channel wherever drastic change in slope. Also vegetation is removed for free flow of water in tail channel. Protection wall from dam side should be constructed in order to prevent the erosion of earthen dam in future.

Sr. No	Dam Features	Date of Inspecting Inspection Officer		Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested
1	2	3	4	5	6	7
<mark>6</mark>	Name : Lower Tank	27.8.2021	EE DSD1 Nashik		1. Sagging noticed on the	There should be closed
	Tal. Mulashi Dist. Pune				upstream face.(B3)	observations on the sagged portion
	Location:					of embankment to notice distresses
	Longitude- 73°43'39"					if any.
	Latitude 18°32'04				2. Drains are not observed	
	Height :15.00 m				due to heavy vegetation.	
	Gross capacity 2.1694				According to the approved	
	Sr No. In Lorgo Dom Bogistor				drawings of lower tank & field	Vegetation should be removed for
	SI:NO.III Large Daini Register				berm of lower tank a road was	inspection of side slope of dam.
					prepared, and while	Approved design note & drawings
					constructing the road the toe	& suggesting proper remedial
					drain of lower tank get	measures.
					overburden due to	
					SOI/WUTUUTT.(BZ)	
					3. Waste Weir bar is	WW bar should be reconstructed as
					damaged.(B7)	per design.
					4. It seems that water way is	Verify and communicate to DSO
					contracted due to construction	are sufficient to pass the design
					on the downstream of second	discharge of spillway to suggest
					pipe culvert there may be	remedial measures.
					erosion of d/s berm toe	Protection wall for d/s berm is
						necessary to avoid erosion of toe

Sr. No	Dam Features	Date of Inspection	Inspecting Officer	Main Component of Dam	Significant Deficiencies Noticed	Remedial Measures Suggested	
1	2	3	4	5	6	7	
(4)T	ata Power Company Ltd Lona	wala,Dist Pun	e				
7	Name : Lonavala Tal. Mawal Dist. Pune Date of completion: 1916 Location: Longitude- 73°24'07″ Latitude 18°44'00 Height :15.35 m Gross capacity 11.50 Mcum Sr.No.In Large Dam Register MH09MH0035	8.12.2021	Smt.S.Y.Kurhade EE. DSD 2, Nashik		 Sweating on d/s side of dam was observed . Leakage through dam masonry was observed at some places.(A11) 	Mapping of leakage and seating shpuld be done, It should be kept under observation and record should be kept with respect to reservoir water level.	

Class-II Dams with Category-3 or No Deficiency (Private Owned)

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ / sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
1	2	3	4	5	6	7	8	9	10	11
(1)T	he Tata Power c	o. Ltd. Lo	onavala							
1	Lonavala Tal. Maval Dist. Pune	1916	73°24'07" 18°44'40"	15.35	11.50	129	MH09MH. 0035	8.12.2021	3.1,3.9,3.13,3.26,3.28	5
2	Kundali Tal. Maval Dist. Pune	1998	73°51'24" 18°31'13"	39.26	6.34	746	МН09МН. 1589	21.12.2021	3.1,3.2,3.12,3.18,3.26	5
(2) (Commissioner, N	lunicipal	Corporatio	n Kolhaj	our					-
3	Rankala Tal.KarveeDist. Kolhapur	1883	73°40' 00" 16°43'00"	15.00	4.30	116	MH09MH 0010	23.02.2021	3.2,3.9,3.27,3.28	4

Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/	Height in m	Gross Capacity Mm ³	Design Spillway Capacity	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
			Latitude			m°/sec				
1	2	3	4	5	6	7	8	9	10	11
4	Kalamba Tal. Karveer Dist.Kolhapur	1983	74°21'27″ 16°55'41″	16.26	2.75	11.50	MH09MH1015	23.02.2021	3.2, 3.1, 3.4,3.5,3.7, 3.9, 3.16,3.19,3.20, 3.21	10
(3)	Kagal Nagar Pari	shad, Ka	gal, Kolhapı	ır	1			1		1
5	Jaisingrao Talao Tal. Karveer Dist.Kolhapur	1923	74°12'30" 16°22'45"	12.68	2810	38	MH09MH1912	23.02.2021	3.1, 3.2, 3.5,3.9, 3.16, 3.19,3.28,3.29	8
(3)5	ShriVikramsingh	Shatge	Kolhapur	r	1	r			T	-
6	Sir Pirajirao Talav Tal. Kagal. Dist. Kolhapur	1923	74°03'00" 17°41'29"	21.95	2.91	30.0	MH09MH. 0046	28.1.2022	3.1,3.2, 3.4,3.5, 3.9, 3.16, 3.32,3.35,3.2	9
(4)I	NSShivaji, Indian	Navy ,L	onawala Dist	- Pune				-		
7	New Shivsagar Tal. Mawal Dist .Pune	1989	73°52'00″ 18°45'00	25.70	1.81	70.0	MH09MH 1230	26.8.2021	3.1,3.2,3.9,3.12,3.16,3.27 3.35	7
8	INS Shivaji (Old) (Shivsagar) Tal. Mawal Dist .Pune	-	-	-	-	-	Proposed for updation in NRLD 2018	26.8.2021	3.1, 3.2,3.9	3
Sr. No	Name of Dam	Date of Compl -etion	Location Longitude/ Latitude	Height in m	Gross Capacity Mm ³	Design Spillway Capacity m ³ /sec	Sr.No. in NRLD Register	Date of Inspection Pre & Post	Deficiencies noticed	Total Deficien cies
-----------	-----------------	----------------------------	------------------------------------	----------------	--------------------------------------	---	-------------------------------	-------------------------------------	-------------------------------	---------------------------
1	2	3	4	5	6	7	8	9	10	11
5) S	ymboisis Univer	sity, Lav	ale, Pune.							
9	Upper Tank	-	73°43'39″ 18°32'04	15	2.1694	-	Not yet registered	27.8.2021	3.1,3.2, 3.9, 3.16, 3.19,	5
10	Lower Tank	-	73°43'39″ 18°32'04	13.50	0.4550	-	Not yet registered	27.8.2021	3.1,3.2, 3.5, 3.9, 3.16, 3.19	6

Category-1 Deficiency in Class-I Dams

Sr. No	Deficiency	Names of dams	Total No. of dams
1	2	3	4
1	2 NIL	3	4

Category-2 Deficiency in Class-I Dams

Sr N o	Deficiency	Names of dams	Total No. of dams
1	A.1 : Boil leakage/ seepage/ wet patches/ slushiness, in Earthen Dam.	Kasarsai, Chaskaman, Warana, Tulshi	4
2	A 2: Standing pool / Ponding / Water Logging / Slushy condition on D/S of Dam	Khadakvasala, Tulshi, Dhom, Balkavadi, Chilewadi, Sina, Nagewadi, Sina Kolegaon	8
3	A 3 : Leakages in vicinity of junction between earthen dam & masonry dam portion.	Khadakvasala, Pawana, Nagewadi	3
4	A 4: Major leakages through outlet conduit/ pipe joints / Gates.	Panshet, Bhamaaskhed, Kadavi, Warana, Chikotra, Kumbhi, Phaye, Chitri, Dhom ,Kanher, Pimpalgaonjoge, Ghod, Sina	13
5	A 5: Relief wells not functioning properly./ Abnormal rise in water level in wells.	Jadhavwadi, Chaskaman,Warana, Dudhaganga,Kanher, Wadaj	6
6	A 6: Outlet well is damaged/not in good condition /cracks observed/jets of water in well.	Morna, Pimpalgaonjoge, Pangare	3
7	A 7: Retrogression /scouring in tail channel.	Nazare, Pangare	2
8	A 8: Drainage gallery inaccessible/No adequate lighting./ No dewatering arrangement or failure.	Bhatghar, Andra valley, Pawana, Chaskaman, Arala kalmodi, Temghar Radhanagari, Warana, Dudhaganga, DhomBalkavadi, Kanher, Manikdoh Dimbhe, Tarali, Bhima Ujani,Sina Kolegaon	16
9	A 9: Foundation drains / holes/ porous pipes/chocked/ no seepage through foundation drain holes.	Kasarsai, Andra valley, Warasgaon, Chaskaman, Temghar, Warana, Dudhaganga, DhomBalkavadi, Kanher, Kolkewadi, Koyana, Manikdoh, Dimbhe, Tarali, Bhima Ujani	15
10	A 10: Heavy leakages through porous pipes/ through dam body in gallery /monolith joints.	Bhatghar, Andra valley, Warasgaon, Pawana, Chaskaman, Arala kalmodi, Temghar, Radhanagari, Dudhaganga, DhomBalkavadi, Manikdoh, Wadaj, Dimbhe, Kalgaon ,Tarali, Sina Kolegaon	16
11	A 11 : Sweating / seepages through D/S of masonry dam	Bhatghar, Vadivale, Kasarsai, NiraDevghar, Andra valley, Panshet, Khadakvasala, Warasgaon, Pawana, Chaskaman, Veer, Temghar Dudhaganga,Dhom ,Kanher, Kolkewadi, Manikdoh, Wadaj ,Dimbhe	22

Sr N o	Deficiency	Names of dams	Total No. of dams
		Ghod, Tarali, Bhima Ujani	
12	A 12: Excessive considerable leaching from seepage water.	Bhatghar, NiraDevghar, Panshet,Chaskaman, Temghar, Warana, Dudhaganga, Kanher, Kolkewadi, Manikdoh, Dimbhe, Tarali, Bhima Ujani	13
13	A 13: Swelling / minor cracking observed on body of dam.	Nil	
14	A 14: EDA / Stilling basin damaged/Hydraulic performance not good.	Bhatghar, Jadhavwadi, NiraDevghar, Khadakvasala, Arala kalmodi, Radhanagari Ghatprabha DhomBalkavadi Kanher Koyana Manikdoh Dimbhe Chilewadi Ghod Sina Kalgaon Uttarmand Bhima Ujani Sina Kolegaon	18
15	A 15: Leakages through spillway /piers//junction of flank wall.	Vadivale, Andra valley, Warasgaon, Pawana, Temghar, Kolkewadi, Sina, Pangare, Kalgaon	9
16	A 16 : Damages / foundation erosion/ scour/undermining observed in vicinity of flank walls/ guide walls/ junction walls/return walls.	Bhatghar, NiraDevghar, Warasgaon, Veer, Temghar, Ghatprabha, Dhom, Kanher, Ghod, Sina	10
17	A 17 :End weir not in good condition / scouring noticed on immediate D/S.	Bhatghar, Jadhavwadi, Khadakvasala,Warasgaon, Pawana, Chaskaman, Radhanagari, Warana, Ghatprabha ,Kanher, Chilewadi, Ghod, Morna (Gureghar), Kalgaon, Uttarmand, Bhima Ujani	16
18	A 18: Wire ropes of hoist not in good condition / hoisting structure damaged / cracked.	Jadhavwadi, Andra valley, Veer, Morna,Kanher, Nagewadi, Morna (Gureghar), Kusawade	8
19	A 19: Alternative power system Generator for gate operation not working properly.	Chaskaman, Bhamaaskhed, Tulshi, Dhom, Kanher, Sina Kolegaon	6
20	A 20: Operation of gates not smooth needs repair.	Bhamaaskhed, Morna, Radhanagari, Warana, Dudhaganga, Ghatprabha, Kanher, Wadaj, Pangare, Kusawade	10
21	B 1 Dam section is not as per design		
22	B 2 : Cross and toe drains not working properly/ drains silted or vegetated causing stagnant pool of water.	Warasgaon, Pawana, Bhamaaskhed, Sina Kolegaon	4
23	B 3: Considerable settlement of embankment / Rock toe/Pitching/ U/S & D/S slops, bulging/concavity of slopes.	Jadhavwadi,Pangare, Tarali, Hateghar, Bhima Ujani, Sina Kolegaon	6
24	B 4: Longitudinal / Transverse cracks/ low area/sink holes/gully		-

Sr N o	Deficiency	Names of dams	Total No. of dams
	formation on top side slope of earthen dam.		
25	B 5: Outlet gates not functioning properly. Stem rod is bent(Service gate/Emergency gate/Stop log gate/sluice gate)	Jadhavwadi, Andra valley, Khadakvasala, Chaskaman, Arala kalmodi, Bhamaaskhed, Nazare, Morna, Warana, Jambre, Lakikatti, DhomBalkavadi, Kanher, Kolkewadi, Koyana, Chilewadi, Ghod, Sina,Nagewadi, Morna (Gureghar)	20
26	B 6: Approach to dam through all weather road not constructed/maintained properly.	Gunjawani, Radhanagari, Jambre, Koyana, Chilewadi, Ghod ,Sina	7
27	B 7: Waste weir/waste weir bar not in good condition/coping damaged/leakage through waste weir.	Vadivale, Khadakvasala, Kadavi, Palaeshwer,Ghatprabha, Jangamhatti, Chilewadi, Pangare, Kalgaon, Bhima Ujani	10
28	B 8: Pointing on U/S face of dam not in good condition./deterioration spalling of concrete surface.	Bhatghar, Vadivale, Temghar Tulshi, DhomBalkavadi,kolkewadi, Manikdoh, Dimbhe, Tarali, Sina Kolegaon	10
29	B 9 : Instruments not in working condition.	Bhatghar, NiraDevghar, Panshet, Khadakvasala, Warasgaon, Pawana, Chaskaman, Bhamaaskhed, Temghar, Gunjawani, Kadavi, Kasari, Radhanagari, Warana, Dudhaganga, Chikotra, Kumbhi ,Tulshi,Palaeshwer,Upwade, Ghatprabha ,Jambre ,Jangamhatti, Khleloshi, Patgaon, Phaye, Chitri, Kitwad ,Kondoshi, Lakikatti, Dhom, DhomBalkavadi, Kanher, Urmodi, Koyana,Wadaj, Dimbhe, Pimpalgaonjoge, Chilewadi, Yedgaon, Ghod, Sina, Nagewadi, Morna (Gureghar), Kusawade, Tarali, Bhima Ujani,Sina Kolegaon	48
30	B 10: Leakages through River sluice.	Vadivale, Koyana, Manikdoh, Bhima Ujani	4
31	B 11 : Surface paint/steel surface of spillway gates deteriorated.	Kasarsai, Andra valley, Arala kalmodi, Dhom, Manikdoh, Wadaj, Dimbhe, Pimpalgaonjoge, Nagewadi, Morna (Gureghar), Kusawade, Uttarmand	12
32	B 12 : Damage to Rubber seals/ considerable Leakages through gates.	Bhatghar, Panshet, Bhamaaskhed, Veer, Gunjawani, Radhanagari, Dhom, Kanher, Pimpalgaonjoge	9

Sr N o	Deficiency	Names of dams	Total No. of dams
33	B 13: Heavy vegetation/big trees on embankment top/slope making	Kasarsai, Yeoti-Mhasoli, Dhom,Kanher	4
	dam portion not accessible.		
34	B 14: Deck bridge slab/ pier / damaged cracked/ alignment	Dhom	1
	disturbed.		
35	B 15 : Major portion of Pitching damaged/washed away.	Satpewadibarrage, Ghatprabha	2

Category-1 Deficiency in Class-II Dams

Sr. No	Deficiency	Names of dams	Total No. of dams
1	2	3	4
1	2 NIL	3	4

Category-2 Deficiency in Class-II Dams

Sr. No	Deficiency	Names of dams	Total no of dams
1	2	3	4
1	A.1 : Boil leakage/ seepage/ wet patches/ slushiness, in Earthen Dam.	Antri, Daribadchi, Dodanalla, Kadegaon, Vejegaon, DaryachiVadgaon, Kasarde, Manoli, Kalasgade, Yenechavandi, Kankatrewadi, Kumathe, Otur Waghdara, Ballalwadi, Babhulgaon	15
2	A 2: Standing pool / Ponding / Water Logging / Slushy condition on D/S of Dam	Matoba, Shirsuphal, Banganga, Hingangaon, Tambave, Phondshiras, Daribadchi, Dodanalla, Shegaon, Pratappur, Buddhihal, Kadegaon, Pingali, Ranand, Otur Waghdara, Chincholi, PimpalgaonDhale	17
3	A 3 : Leakages in vicinity of junction between earthen dam & masonry dam portion.	Kankatrewadi, Mahind	2
4	A 4: Major leakages through outlet conduit/ pipe joints / Gates.	Bhiwargi,Buddhihal, Mahadikwadi, Olwan, Thoseghar	5
5	A 5: Relief wells not functioning properly./ Abnormal rise in water level in wells.	Girzani, Thoseghar, Dhakani, Mangi, Ashti, Gholasgaon	6
6	A 6: Outlet well is damaged/not in good condition /cracks observed/jets of water in well.	Marnewadi, Malad, Dodanalla,Birnal, Kadegaon, NimbhavadePare, Olwan, Vesraf, Karanjivane, Shendri,	18

		Kankatrewadi, Pingali, Jambhulani, Andhali, Daruj, Kumathe, Babhulgaon	
7	A 7: Retrogression /scouring in tail channel.	Matoba, Palasdeo, Thitewadi, Kadus, Thoseghar, Ranand, Rajuri, Mahind	8
8	A 8: Drainage gallery inaccessible/No adequate lighting./ No dewatering arrangement or failure.		
9	A 9: Foundation drains / holes/ porous pipes/chocked/ no seepage through foundation drain holes.		
10	A 10: Heavy leakages through porous pipes/ through dam body in gallery /monolith joints.		
11	A 11 : Sweating / seepages through D/S of masonry dam		
12	A 12: Excessive considerable leaching from seepage water.		
13	A 13: Swelling / minor cracking observed on body of dam.		
14	A 14: EDA / Stilling basin damaged/Hydraulic performance not good.		
15	A 15: Leakages through spillway /piers/ junction of flank wall.		
16	A 16: Damages / foundation erosion/ scour/undermining observed in vicinity of flank walls/ guide walls/ junction walls/return walls.	Urawade, Thitewadi, Kadus, Thoseghar	4
18	A 17 :End weir not in good condition / scouring noticed on immediate D/S.		
19	A 18: Wire ropes of hoist not in good condition / hoisting structure damaged / cracked.		
20	A 19: Alternative power system Generator for gate operation not working properly.		
21	A 20: Operation of gates not smooth needs repair.		

22	B 1 Dam section is not as per design	Urawade, Bhugaon, Palasdeo, Shirsuphal, Banganga, Alegaon pagga, Nimgaon Mhalungi, Dahiwadi, Kadus Dodanalla, Shegaon, Ashti, Chincholi Birnal, Karandewadi, Ranand, Arabwadi, PimpalgaonDhale, Mahind	19
23	B 2 : Cross and toe drains not working properly/ drains silted or vegetated causing stagnant pool of water.	Mahind	1
24	B3: Considerable settlement of embankment / Rock toe/Pitching/U/s & D/S slopes,bulging/Concavity of slopes	Thoseghar, Ranand, Mahind	3
25	B 4 : Longitudinal / Transverse cracks/ low area/sink holes/gully formation on top side slope of earthen dam.	Mhasavad, Buddhihal, Ner, Nandwal, Chare, Mangi, Ashti, Gholasgaon	8
26	B 5: Outlet gates not functioning properly. Stem rod is bent(Service gate/Emergency gate/Stop log gate/sluice gate)	Marnewadi, Mahakoshi, Urawade, Urawade, Hadashi, Divale, Naigaon Devgaon, Wagajwadi, Bhongavali, Gadadavne, Hadashi, Khamboli, Pimpoli, Shere, Walen, Chinchwad Malad, Pilanwadi, Dahiwadi, Soradi, Kasarde Tippehalli, Chinchani, Atpadi, Dighanchi, Ghanand, Hingangaon, Kadegaon, Ped , Walunj Karandewadi, Nimbhavade, Andur, Kode, Vesraf, Dindalkop, Karanjivane, Kitwad – 1, Kumari, Sundi, Thoseghar, Yeralwadi, Jambhulani, Arabwadi, Hiware, Chalalkewadi, Ramjewadi, Otur Waghdara, Ghangaldara, Anepemdara, Hingani (K), Kazikunbus, PimpalgaonDhale	55
27	B 6: Approach to dam through all weather road not constructed/maintained properly.	Morale	1
28	B 7 : Waste weir/waste weir bar not in good condition/coping damaged/leakage through waste weir.	Mahakoshi, Urawade, Matoba, Palasdeo, Naigaon, Garade, Kadus, Bhiwargi, Birnal, Erandol, Kankatrewadi, Kazikunbus, Kari	20

		Thoseghar, Ranand, Chaphal, Ucchil, Anepemdara, Gohe, Talsangi	
29	B 8: Pointing on U/S face of dam not in good condition./deterioration spalling of concrete surface.		
30	B 9 : Instruments not in working condition.		
31	B 10: Leakages through River sluice.		
32	B 11: Surface paint/steel surface of spillway gates deteriorated.		
33	B 12 : Damage to Rubber seals/ considerable Leakages through gates.		
34	B 13 : Heavy vegetation/big trees on embankment top/slope making dam portion not accessible.		
35	B 14: Deck bridge slab/ pier / damaged cracked/ alignment disturbed.		
36	B 15: Major portion of Pitching damaged/washed away.		

Annexure-1

Graphical Representation















Annexure-2

Snapshots of Dams Inspected by DSO



Snapshot-2

Vadaj Dam (Class-I) Taluka – Junnar Dist- Pune Date of Inspection – 18.3.2022 To the immediate left side of non overflow section (NOF) it shows heavy leakages, record of the same is maintained by field officials with respect to dam reservoir level.

Snapshot-1

Kanher Dam (Class-I) Taluka –Satara Dist- Satara Date of Inspection – 17.3.2022 Minor leakages from Radial Gate No.1 is observed.



Snapshot – 3

Otur Waghdara Dam (Class-II) Taluka – Junnar Dist-Pune Date of Inspection - 22.10.2021 Leakages are observed on d/s side of the dam. Also water Ponding is observed on the d/s of dam

Shetphal Dam (Class-II) Taluka – Indapur Dist-Pune Date of Inspection – 30.1.2022 Earthen section seems to be under section in certain portion. At some places Gully formation and cuts are observed due to trespassers



Part-4: Annual Performance Report of Dam Instruments

4.1 General:

The main purpose of instrumentation in dam is to warn of any changes that could in danger the safety of a dam, as well as to provide a confirmatory check in design assumptions and methods of computation.

Instruments embedded in or installed at the surface of the dam keeps a constant watch over the performance and indicate the distress spots for which remedial measures may be taken. Thus, instruments play an important role in monitoring and evaluating the performance of the dams during the construction as well as operation.

In general it is observed that Dam Instrumentation is somewhat neglected part in Dam maintenance. Instruments are installed in or on the Dam Body. However due to poor Maintenance they are not functioning. It is must for field officers to recognize importance of data derived from instruments and its analysis to upkeep of Dams in safe condition.

4.2 Instrumentation in Earthen Dams :

1. Pore Pressure Meter :

They are installed in bore holes drilled below the foundation or through already completed embankment. Hence cannot be repaired or replaced.

2.Casagrande /Standpipe Piezometers :

These are used for measuring pore water pressure in soil. These instruments can be installed at any time at desired location after completion of construction of the dam.

3. Twin Tube Piezometers :

These are also used for measuring pore water pressure in earthen dam. These are installed in foundation and embankment during construction of dam. If PVC pipes are found chocked due to leached material then it can be cleaned with CuSo4. If pipes are cut / broken then it cannot be replaced as those are in body of dam. Outside measuring assembly can be repaired. Periodical maintenance, reading and calibration are of utmost important.

4. Earth Pressure Cells :

These are installed in the foundation. The cables which are outside the body can be replaced if damaged. The sensor cannot be repaired or replaced.

5. Settlement Gauges (Surface Settlement Gauges/Vertical Cross Arms) :

These are used for measuring settlement in earth fill dam, rock fill dam and high embankment. Initially when the dam is under construction these instruments are installed.

Settlement of dam is more in initial period, which gradually decreases and it is almost nil after certain period. As such these gauges also do not show settlement after few years.

6. Slope Indicator :

This is installed in foundation with one end at bottom and other at top of the dam. It measures horizontal and vertical movement of the dam. This can be replaced.

4.3 Instrumentation in Concrete / Masonry Dams :

1. Stress meters :

The stress meters measure stresses inside the dam body. These instruments are embedded in concrete/masonry during construction stage hence cannot be repaired or replaced.

2. Strain Meter/ No Stress Strain Meter :

The strain meters measures the deformation in the structure at the particular location due to strain, creep, temperature etc. The main purpose is to determine the stress distribution in the concrete dam during and after construction of dam. Since instrument is installed in the body of the dam it cannot be repaired or replaced.

3.Uplift pressure cells

The bowl type uplift pressure cells are provided in the foundation of dam. Uplift pressure cell is used for monitoring uplift pressure of water in the foundation of dam and concrete structure. The pressure cell pipes can be cleaned if choked. The pressure gauges can be repaired or replaced.

4. Plumb Bob /Co-Ordimeter :

Conventional / Inverted Plumb Bob is used to measure deflection of the dam body. It measures the horizontal displacement in dam's foundation and abutment. Plumb bob can be repaired or replaced.

5. Thermocouples/ Thermometers :

These are used to measure the temperature variations in the body of concrete dam. These are installed in layers at various levels and can not be replaced or repaired after construction.

6. Long Gauge Extensometer :

It is used to measure the deformation/displacement in the foundation of the concrete dam. Once it fails to function can not be repaired.

7. Joint meters :

The joint meters measure the opening of the joints across which they are embedded. As such they are located near the joints.

4.4 Status Of Dam Instrumentation In The Region :

Considering the fact that most of the instruments were non-functional from many years, Govt. of Maharashtra appointed a committee to study these instruments. The recommendations of the committee were accepted and incorporated in G.R. धसुसं २०१४(६२१/१४)/ सिं.व्य. (कामे) Dated. 31/12/2015. Accordingly to every dam owner, it is informed by Dam Safety Organization to update the list of instruments at the dam site. In this report the updated details of instruments are considered.

The status of dam instrumentation in the Pune region is given in table No.4.1. Similarly the details of mortality of instruments is given in table No.4.2 and comparison of mortality rate with respect to previous year is given in table no. 4.3

4.5 Observations

- 1) Various instruments numbering 1571 have been installed on these 27dams. Out of which 198 were working and 1373 were not working i.e. 87.39 % instruments are in non-working condition.
- 2) In the Pune Region instrument data reading are available from Koyna, Kolkewadi for Instrumentation data analysis report.
- 3) The observations of the instruments should be taken regularly and need to be sent to D.S.O. Nashik for analysis.
- 4) Comparison of mortality rate of instrument as compared to last year is given as per table No.3.3.

Table No. 4.1 Dam wise Status of Dam Instruments Installed on Large Dams (Pune Region)

Sr.	D No		Date of		Functional Status (F/N.F)		
No.	Dam Name	Instrument Name	Installation	Iotal	Functional	Non Functional	Remark as per Pre -post monsoon report 2021
1	2	3	4	5	6	7	8
CHIE	F ENGINEER	(W.R), PUNE	·				
	Bhatghar	Uplift pressure cell	-	4	0	4	
	Dam	Plumb bob	-	1	0	1	
2	Pawana	Twin tube Piezometer	-	49	0	49	
2	Dam	Uplift pressure cell	-	8	0	8	
3	Panshet Dam	Twin tube Piezometer	-	52	0	52	No data
4	Varasgaon	Plumb bob	2015	2	2	0	
5	Veer	Casagrande piezometer	-	3	0	3	Not Installed As per the post Monsoon Report 2021
	Nira deodhar	Casagrande piezometer	2005	6	6	0	
		Twin tube piezometers	2005	75*	75*	0*	
6		Uplift pressure cells	2005	18	9	9	* As per the post Monsoon Report 2021
		Settlement plug	2005	158	0	158	
		Plumb bob	2011	1	0	1	
7	Kasari Dam	Casagrande Piezometer	-	10	0	10	Not Installed As per the post Monsoon Report 2021
		Joint meters	-	4♦	0♦	4♦	
0	Dudhaanaa	Pore pressure cells	81-86	26	0	26	▲ As par the past Mansaan Papart 2021
0	Duunganga	Uplift pressure cells	81-85	32♦	0♦	32♦	▼ As per the post Monsoon Report 2021
		cassagrande piezometers	1998	26	19	7	
9	Chilewadi	Cassagrande piezometers	-	10•	2•	8•	 As per the post monsoon report 2021
		Stand pipe piezometers	-	7*	0*	7*	
10	Bhama	Cassagrande piezometers	-	7*	0*	7*	As per the post monsoon report 2021 As per
10	Askhed	Twin tube Piezometers	-	59	0	59	dated 13.05.2015
		▲Earth pressure cells	-	8	0	8	

		Strainmeters	-	2	0	2			
		Foundation piezometers	-	12	0	12			
		Embankment piezometers	-	71	0	71			
11		Casagrande piezometer	-	17	0	17			
	Warna	Earth pressure cells	-	0	0	0	All Non-Functional		
		Slope Indicator	-	0	0	0			
		Pore pressure cells	-	38	0	38			
		Uplift Pressure cells	-	22	0	22			
		Thermometers	2006	9#	0#	9#			
		Stress meters	2006	3	0	3			
		Strain meters	2006	24#	0#	24#			
	Koyna Dam	Joint meters Mon 17	1972	5	0	5			
			2006	3#	0#	3#			
			1961	42	9	33			
12		Uplift pressure cells	1972	4	0	4	# As per the post monsoon report 2021		
			2006	18#	0#	18#			
		Plumb bob Co-ordimeter Mon 22 & 25	1961	2	2	0			
		Piezometer	2006	4	0	4			
		Dial Guages		0	0	0			
		Tilt meter	2006	2	0	2			
		Pore pressure cells	1972	7	0	7			
		Extentiometer Joint meter Special long	73-75	8	6	2			
13	Kolkewadi	Joint meter	72-74	14	11	3	\$ As per the post monsoon report 2021		
		Uplift pressure cell	1976	30	0	30			
		Plumb bob Co-ordimeter	-	1	0	1			
		Reverse pendulum	-	1\$	1\$	0\$			
	CE Wise Total for 13 Dams 905					763			

CHIE		R (S.P), PUNE					
		Casagrande piezometer	1982	7	0	7	
14	Dhom	Twin tube piezometers	1982	6*	3*	3*	* As per the post Monsoon Report 2021
		Uplift pressure cells	1976	7	0	7	
		Plumb bob	1986	1	0	1	
15	Manikdah		1986	9	0	9	No Data
15	IVIAIIIKUUII	Uplift Pressure Cells	1986	7	0	7	No Data
			1986	6	0	6	
			1982	7	0	7	
		Casagrande piezometers	1982	7	0	7	
16	Wadaj		1982	5	0	5	
		Stand nine niezemetere	1982	6	6	0	
		Stand pipe piezometers	1982	10	0	10	
	Yedgaon	Casagrande piezometers	1985 2014	40	0	40	
17		Stand nine niezometers	1985	0	0	0	
			1985	8	0	8	
		Plumb bob	N.A.	1	0	1	
18	Dimbhe		N.A.	0	0	0	No data
		Uplift Pressure cell	N.A.	11	0	11	
		Casagrande piezometer	1982	10	0	10	
10	Kanber	Twin tube piezometers	1982	47	0	47	
13	Ranner	Uplift pressure cells	1984	18	0	18	
		Plumb bob	1989	1	0	1	
		Foundation piezometers	2006	6	0	6	
20	Dhom	Embankment piezometers	2006	70	0	70	
20	balkawadi	Casagrande piezometer	2006	8	0	8	
		♥Earth pressure cells	2006	3	0	3	
			1998	8	0	8	
21	Urmodi	Foundation Piezometers	2000	17	0	17	No Data
			2000	8	0	8	

			1998	23	0	23	
		Embankment Piezometers	2000	19	0	19	
			2000	22	0	22	
		Casagrande piezometers		5	5	0	
		♥Earth pressure cells		27	0	27	
		Plumb bob	Mar-83	1♦	1♦	0♦	
22	Ujjani	Uplift pressure cells	Mar-83	22♦	11♦	11♦	 This is as per IRD's inspection note dated 07.09.2021
		Casagrande piezometers	81-82	27♦	25♦	2♦	
		Twin Tube piezometers	2013	16	0	16	
23	Mahu (u/c)	Foundation piezometers	2013	12	0	12	under construction
		Earth Pressure cell	2013	4	0	4	
24	Ghod	standpipe piezometer	-	5	5	0	
		Uplift pressure cells	2000	33	0	33	
	Tarali	Stress meters	May-08	5	0	5	
25	(2008) Dist :-	Strain meters	May-08	5	0	5	 As per the post monsoon report 2021
	Satara	Thermometers	Dec-09	10•	0•	10•	
		Plumb bob	Jan-15	1	0	1	
	Morna	Foundation Piezometers	2000	14	0	14	
26	Gurheghar	Embankment piezometers	2000	36	0	36	
	(2010)	Earth Pressure Cells	2000	6	0	6	
	Uttar	Foundation Piezometers	2000	24	0	24	
27	Mand	Embankment piezometers	2000	11	0	11	Not Installed As per the post monsoon report 2021
	(2010)	Earth Pressure Cells	2000	4	0	4	
		CE Wise Total for 14 Dams		666	56	610	
PUNE Region Total for 27 Dams			1571	198	1373		

	TABLE NO 4.2										
	Mortality Status of Instruments installed on Large Dams										
	(Pune Region)										
Sr.	Sr. Type of Instruments Numbers of Instruments										
NO.		Total	Working	Non-Working	Mortality (%)						
1	2	3	4	5	6						
	(A) Earth Dams										
1	Casagrande / Stand pipe /Vibrating wire Piezometers	235	68	167	71.06						
2	Twin tube Piezometers	657	78	579	88.13						
3	Horizontal/Vertical device / Cross arm surface settlement plug	158	0	158	100						
4	Earth pressure cells	52	0	52	100						
5	Slope indicator	0	N.A	N.A	N.A						
	Total	1102	146	956	86.75						
			(E	B) Masonry Da	Ims						
1	Pore pressure meters	71	0	71	100						
2	Stress meter	8	0	8	100						
3	Strain meter/ No stress-strain meter	31	0	31	100						
4	Uplift pressure cells	291	29	262	90.03						
5	Plumb bob/ Inverted Plumb Bob / co- ordimeter /pendulum	13	6	7	53.85						
6	Long Gauge extensometer, Multiple Bore hole extensometer	0	N.A	N.A	N.A						
7	Thermometers	19	0	19	100.00						
8	Joint meters /Dial Gauge	34	17	17	50.00						
9	Tilt meter	2	0	2	100.00						
	Total 469 52 417 88.91										

	Instruments in	Total	Working	Non-Working	Mortality
A)	Earth Dams	1102	146	956	86.75
B)	Masonry Dams	469	52	417	88.91
	Grand Total	1571	198	1373	87.40

	Table No. 4.3										
	Comparative Statement For Status of Instruments in Dams										
	Pune Region										
	Year			HSR 2020	0		HSR 2021				
Sr.No	Name of Chief Engineer	Total Dams	Total Instruments	Functioning	Not- Functioning	% functioning	Total Dams	Total Instruments	Functioning	Not- Functioning	% functioning
1	Chief Engineer (W.R) Pune	13	909	152	757	16.72	13	1102	146	956	13.25
2	Chief Engineer (S.P) Pune	14	667	59	608	8.85	14	469	52	417	11.09
	Total	27	1576	211	1365	13.39	27	1571	198	1373	12.60



Part- 5 : Annual Performance Report of Meteorological Instruments

5.1 General :

Hazard potential of dam depends upon the possible hazard it poses to population on the downstream during flood. In case of gated spillways, generally flood is considered to impinge when reservoir is at F.R.L. If flood forecasting and warning systems are in place, flood impingement can be considered at lower when F.R.L. considering prior depletion.

The establishment of hydro-meteorological stations in the vicinity of every Class-I dam and rain gauge network in its catchments assumes vital importance due to its role in flood forecasting and warning. The hydro-meteorological station shall be capable of recording data relating to, among other parameters, rainfall, atmospheric pressure, maximum & minimum temperature and humidity, wind speed, wind direction, height of waves and reservoir water temperature. It is important that a representative proportion of the rain gauge network is linked to flood forecasting and warning control center by telemetry.

5.2 Observations :

From Pre/Post Monsoon Reports it is seen that the ANNEXURE-IV which is "Checklist of Various Meteorological Instruments installed on Dams" is not filled properly and quantity of number of instruments varies from year to year. As this status of instruments is submitted to C.W.C., New Delhi. Field authorities need to make sure that correct information is filled. Table 4.1 gives the damwise status of the meteorological instruments, and Table 4.2 gives the status of morality of meteorological instruments installed in the region.

- As per Pre/Post Monsoon reports of Pune region it is seen that 178 various meteorological instruments installed on dams out of which 150 are functioning and 28 are non functioning. The non-functioning should be repaired/replaced on priority.
- As per the government circular CDA-1013/(207/13)/CAD(works)/ August-2013. It is mandatory to install **Pan Evaporimeter** to measure evaporation on all major and medium projects.

Efforts should be taken by field officers to establish automatic flood warning systems which will help in saving lives, livestock and property and will invariantly contribute to lessening of the overall impact of floods.

Table - 5.1

Status of Dam Meteorological instrumentation

(Pune region)

Sr. No	Name of Dam	Name of instruments	No. of instru-	Perform	ance	Status of Data Analysis	
•			ments	Working	Not Working		
1	2	3	4	5	6	7	
		1)Rain Gauge on dam (ordinary)	1	1	0	_	
1	Bhatghar Dist-Pune	2)Rain Gauge on dam (Self recorder)	1	1	0	Data collection is done at field	
		3)Rain Gauge in the catchment (Self Recorder)	3	3	0	level	
	Nazare	1)Rain Gauge on dam (Ordinary)	1	1	0	Data	
2	Dist- Pune	2)Pan evaporimeter	1	1	0	done at field	
		3)Water level recorder	1	1	0	level	
3	Khadakwasala	1)Rain Gauge on dam (Ordinary)	1	1	0	Data collection	
0	Dist- Pune	2)Pan evaporimeter	1	1	0	level	
4	Pawana	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection	
	Dist- Pune	2)Pan evaporimeter	1	1	0	level	
5	Panshet	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection	
	Dist- Pune	2)Reservoir Level Gate	1	1	0	level	
6	Kasarsai Dist- Pune	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level	
		1)Rain Gauge on dam (ordinary)	1	1	0	Data collection	
7	varasgaon Dist- Pune	2)Rain Gauge on dam (self recorder)	1	1	0	level	
		3)Pan evaporimeter	1	0	1	Data collection is done at field	

						level
		4)Rain Gauge in catchment (Self recorder)	1	1	0	Data collection is done at field level
		1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
	Veer	2)Rain Gauge in catchment(ordinary)	2	2	0	level
8	Dist- Pune	3)Rain Gauge in catchment (Self recorder)	1	1	0	
		4)Pan evaporimeter	1	1	0	
		1)Rain Gauge on dam (Ordinary)	1	1	0	Data collection
9	Yedgaon	2)Pan evaporimeter	1	0	1	level
	Dist- Pune	3)Wind velocity recorder	1	0	1	
		4)Wind direction recorder	1	0	1	
10	Andravalley	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
	Dist- Pune	Pune 2)Rain Gauge on dam (self recorder)		1	0	level
		1)Rain Gauge on dam (ordinary)	1	0	1	Data collection
		2)Pan evaporimeter	1	0	1	level
11	BhamaAskhed	3)Rain Gauge on dam (self Recorder)	1	1	0	•
	Dist- Pune	4)Rain Gauge in catchment(self recorder)	2	2	0	
		5)Gate Sensors (Other part)	4	4	0	
		1)Rain Gauge on dam (ordinary)	1	1	0	
		2)Rain Gauge on Dam (Self Recorder)	1	1	0	-
12	NiraDeoghar Dist- Pune	3)Rain Gauge in catchment (Self Recorder)	3	3	0	Data collection is done at field level
		4)Pan Evaporimeter	1	1	0	•
		5)Wet & Dry bulb thermometer	1	1	0	

		6) Barometer	1	1	0		
		7)Reservoir Level Gate	1	1	0	-	
13	Temghar Dist- Pune	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level	
14	Vadivale	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is	
	Dist- Pune	2)Rain Gauge on dam (Self Recorder)	1	1	0	level	
	Ghod	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is	
15	Dist- Pune	2)Pan evaporimeter	1	1	0	level	
		3)Wind direction recorder	1	0	1	-	
	Dimbhe	1)Rain Gauge ion dam(ordinary)	2	2	0	Data collection is done at field	
16	Dist- Pune	2)Pan Evaporimeter	1	1	0	level	
		3)Rain Gauge in Catchment	3	3	0		
17	ChaskamanDist-	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field	
	Pune	2)Rain Gauge in catchment(ordinary)	2	2	0	level	
		1) Rain Gauge on dam (ordinary)	1	1	0	Data collection is	
		2)Rain Gauge in catchment(ordinary)	1	1	0	level	
18	ManikdohDist- Pune	3)Pan evaporimeter	1	1	0	_	
		4)Wind Velocity recorder	1	1	0		
		5)Wind Direction Recorder	1	1	0	-	
19	AralaKalmodiDis t- Pune	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level	
20	Wadaj	1) Rain Gauge on dam (ordinary)	1	1	0	Data collection is	
20	Dist- Pune	2)Pan evaporimeter	1	1	0	level	
	Chilewadi	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is	
21	Dist- Pune	2)Rain Gauge in catchment (self recorder)	1	1	0	level	
	PimpalgaonJoge 1)Rain Gauge on dam (ordinary)		2	2	0	Data collection is done at field	
----	--	---------------------------------	---	---	---	--	
22	Dist- Pune	2)Rain Gauge in catchment	1	1	0	level	
		3)Pan evaporimeter	1	0	1		
23	Adale 1)Rain Gauge on Dam (ordinary Dist- Pune		1	1	0	Data collection is done at field level	
24	MarnewadiDist - Pune	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field level	
25	ThitewadiDist- Pune	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level	
26	Kadus Dist- Pune 1)Rain Gauge on Dam (ordinary)		1	0	1	Data collection is done at field level	
27	AlegaonPagaD ist- Pune	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level	
28	DahiwadiDist- Pune	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level	
20	KolkewadiDist-	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection	
29	Satara	2)Rain Gauge in catchment	2	2	0	level	
30	Shere Dist- Pune	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level	
31	Gohe Dist- Pune	1) Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level	
32	JadhavwadiDis t- Pune	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field level	
33	Koyna	1)Rain Gauge on Dam (ordinary)	6	6	0	Data collection	
	Dist-Satara	2)Pan Evaporimeter	1	1	0		

		3)Wind velocity recorder	1	1	0	level
		4)Wind direction recorder	1	1	0	-
		5)Wet/dry bulb thermometer	1	1	0	_
		6)Thermometer for air Temp	2	2	0	-
34	Dhom	1)Rain Gauge on dam (ordinary)	2	2	0	Data collection
	Dist-Satara	2)Pan Evaporimeter	1	1	0	level
35	MornaGuhegh arDist-Satara	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
36	UttaramandDis t-Satara	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
37	DhomBalkawa	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
01	diDist-Satara	2)Pan Evaporimeter	1	1	0	level
38	Mahu 1)Rain Gauge on dam (ordinary) Dist-Satara		1	1	0	Data collection is done at field level
39	HatgegharDist- Satara	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
		1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
40	Tarali Dist-Satara	2)Rain Gauge on dam (Self Recorder)	1	0	1	level
		3)Pan Evaporimeter	1	1	0	-
41	NagewadiDist- Satara	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
	UrmodiDist-	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
42 Satara		2)Rain Gauge in catchment (ordinary)	2	2	0	level
43	DudhgangaDis	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection
	t-Kolhapur	2)Rain Gauge on dam (Self	1	0	1	

		Recorder)				level
		3)Rain Gauge in catchment(ordinary)	2	2	0	-
		4)Rain Gauge in catchment (self recorder)	1	0	1	-
		5)Pan evaporimeter	1	1	0	-
44	Chitri Dist-Kolhapur	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
45	Kumbhi Dist-Kolhapur	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field level
46	RadhanagariDi st-Kolhapur	anagariDi hapur 1)Rain Gauge on dam (ordinary)		1	0	Data collection is done at field level
47	7 TulshiDist- Kolhapur 1)Rain Gauge on Dam (ordinary)		1	1	0	Data collection is done at field level
48	PatgaonDist- Kolhapur 1)Rain Gauge on Dam (ordinary)		1	1	0	Data collection is done at field level
49	ChikotraDist- Kolhapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level
50	KadaviDist-	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
	Kolhapur	2)Rain Gauge in Catchment	2	2	0	level
		1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
	SingkologoonD	2)Pan evaporimeter	1	1	0	level
51	ist-Osmanabad	3)Wind velocity recorder	1	1	0	
		4)Wind direction recorder	1	1	0	
		5)Wet/dry bulb thermometer	1	1	0	
52	GhatprabhaDis t-Kolhapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field level

53	KasariDist- Kolhapur	riDist- apur 1)Rain Gauge on Dam (ordinary)		1	0	Data collection is done at field level
		1)Rain Gauge on dam (self recorder)	2	1	1	Data collection is done at field
		2)Rain Gauge in catchment (ordinary)	4	4	0	level
F 4	Liinni	3)Pan evaporimeter	1	1	0	
54	Dist-Solapur	4)Wind velocity recorder	1	0	1	-
		5)Wind direction recorder	1	0	1	-
		6)Wet/Dry bulb thermometer	1	0	1	-
		7)Thermometer For air temp	1	0	1	-
55	Bori	1)Wind velocity recorder	1	1	0	Data collection
	Dist-Solapur	2)Wind direction recorder	1	1	0	level
56	Ekrukh Dist-Solapur 1)Rain Gauge on dam (Ordinary)		1	1	0	Data collection is done at field level
57	ChikhalgiDist- Solapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
58	JawalgaonDist -Solapur	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field
59	KazikanbusDis t-Solapur	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field level
60	MangiDist- Solapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
61	Koregaon Dist- Solapur	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field
62	ChincholiDist- Solapur	choliDist- pur 1)Rain Gauge on Dam (ordinary)		1	0	Data collection is done at field
63	Budhihal 1)Rain Gauge on Dam (ordinary) Dist- Sangali		1	0	1	Data collection is done at field
64	TalasangiDist- Solapur	TalasangiDist- Solapur 1)Rain Gauge on Dam (ordinary)		0	1	Data collection is done at field
65	Padawalkarwa diDist-Solapur	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field

66	AshtiDist- Solapur	1)Rain Gauge on Dam (Self Recording)	1	0	1	Data collection is done at field
67	PathariDist- Solapur	1)Rain Gauge on Dam (ordinary)	1	0	1	Data collection is done at field
68	Hingani (k) Dist-Solapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
69	Hingani (p) Dist-Solapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
70	RajuriDist- Solapur	1)Rain Gauge on Dam (ordinary)	1	1	0	Data collection is done at field
71	MornaShiralaD ist-Sangali	1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field
72	PratapurDist- Sangali	apurDist- gali 1)Rain Gauge on dam (ordinary)		0	1	Data collection is done at field
73	BangangaDist- Sangali	ngangaDist- 1)Rain Gauge on dam (ordinary) ngali		1	0	Data collection is done at field
		1)Rain Gauge on dam (ordinary)	1	1	0	Data collection is done at field
74	Warna	2)Rain Gauge in catchment (ordinary)	2	2	0	level
	Dist-Kolhapur	3)Rain Gauge on dam (self recorder)	1	1	0	
		4)Rain Gauge in catchment (self recorder)	3	3	0	
75	75 SinaDist-Pune 1)Rain Gauge on dam		1	1	0	Data collection is done at field level
TOTAL		178	150	28		

Table No. 5.2

Mortality status of Meteorological Instruments Installed on Dam

		Number Of Instruments				
Sr. No.	Type of Instruments	Total	Working	Non- Working	Mortality (%)	
1	2	3	4	5	6	
1	Rain gauge on dam (Ordinary)	80	68	12	15.00	
2	Rain gauge on dam (Self Recorder)	12	8	4	33.33	
3	Rain gauge in catchment (Ordinary)	23	23	0	0.00	
4	Rain gauge in catchment (Self Recorder)	15	14	1	06.66	
5	Pan Evaporimeter	20	16	4	20.00	
6	Wind velocity recorder	6	4	2	33.33	
7	Wind direction recorder	7	4	3	42.85	
8	Wet/dry bulb thermometer	4	3	1	25.00	
9	Thermometer for air Temp	3	2	1	33.33	
10	Thermometer for reservoir water	0	0	0	0.00	
11	Water level Recorder	1	1	0	0.00	
12	Barometer	1	1	0	0.00	
13	Sun shine recorder	0	0	0	0.00	
14	Max & Min thermometer	0	0	0	0.00	
15	Wave height recorder	0	0	0	0.00	
16	Hydrometer	0	0	0	0.00	
17	Humidity Meter	0	0	0	0.00	
18	Automatic fully climatological station	0	0	0	0.00	
19	Stevenmeter	0	0	0	0.00	
20	DWLL	0	0	0	0.00	
21	Other Instruments	6	6	0	0.00	
	Total	178	150	28	15.73	

Part-6 **National Committee on Dam** Safety (NCDS) Documents

Part-6 National Committee on Dam Safety (NCDS)

Documents

Importance of National Committee on Dam Safety (NCDS) Documents:

Central Water Commission (CWC) has laid down various guidelines covering the standardized dam safety practices-essentially guiding the dam owners in preparation of Emergency Action Plans, Periodical Dam Safety inspections, comprehensive dam Safety evaluation and appropriate institutional framework for dam safety. Their implementation is emphasized during the meetings of National Committee on Dam Safety (NCDS) and through the communications sent in this regard.

During the 34th meeting held at Chennai in March 2015 it was requested to all the Dam owners to take necessary steps for preparation of EAPs & other documents & report to NCDS Secretariat about the number of Dams for which EAPs & other documents have been prepared, along with the target dates for the preparation of EAPs & other documents for the remaining Dams.

The documents to be prepared as per National Committee on Dam Safety are as under & these shall be properly maintained and kept up to date by including latest information available.

1. EAP

2. R.O.S & G.O.S.

3. Data Book

4. O & M manual

5. Record Drawing & Completion Report,

1. EAP : Emergency Action Plan:

An Emergency action plan is a formal plan that identifies potential emergency conditions at a dam prescribes the procedures to be followed to minimize property damage and loss of life. The EAP contains procedures and information to assist the dam owner in taking necessary actions in time to moderate or alleviate the problems, in addition to issuing early warning & notification messages to responsible emergency management authorities,viz.,DistrictMagistrate/Collector, Armed Forces, Paramilitary forces, Project Authorities & other Central/State Agencies. It also contains inundation maps to show the emergency management authorities of the critical areas for necessary relief and rescue actions in case of an emergency. In a nutshell, it outlines "who does, what, where, when and how" in an emergency situation or unusual occurrence affecting the Dams.The Emergency Action Plan has to be prepared as per CWC Guidelines are available on official website-

https://damsafety.in/ecm-includes/PDFs/Guidelines_Developing_EAP_Dam.pdf

2. R.O.S. (Reservoir operation schedule) & G.O.S. (Gate operation schedule) :

It is very necessary to lay down operating procedures of all storage reservoirs with the objective to limit the flood stages in the river downstream and with maximum feasible utilization of the flood capacity of the river channel downstream of reservoirs, consistent with the safety of the dam. A proper reservoir operation schedule should be in place.

For this purpose a schedule of opening and closing the gates to limit the reservoir levels to preset gauges should be laid down. Schedule for the dam as per operation & maintenance manual should be strictly adhered. The entire capacity of reservoir is used for active conservation. When the reservoir rises above active conservation, operation will be in accordance with the standing operation procedures. Inflow forecasting arrangement should be made for easy operation of gates. The Engineer in charge should inform immediately to the flood maintenance engineer downstream and flood –fighting center of the releases from the reservoir.

3. Data book:

Proper assessment of dam safety involves a thorough review of design, construction and performance records prior to conducting a field examination. The Data Book is an unpublished document which is prepared before the initial safety inspection of each dam. This book is abbreviated, convenient source of information, summarizing all pertinent records and history related to the safety of a dam and is a reference for the evaluation team. This Data Book should answer most questions about the dam. A list of reference is included if additional information is needed. Continual updating of the Data Book will be required as future inspections are

made, new problems arise, new investigations are undertaken and remedial treatments performed. Documentation of all projects may be done in the Data Book format which is the primary data base for the team evaluating the safety of a dam. (Guidelines on standardized Data Book format are available at http://www.cwc.gov.in/ Dam_safety.html)

4. O & M Manual:

It is desirable that a separate manual is available with the officers .The officers Incharge of such works are requested to personally go through the manual and maintain the records from time to time in such a manner as to give their successors complete and correct idea of the state of each of the several storage works in their charge and the different standing orders on all matters concerning the works. This will enable them to tackle problems as they arise, by quickly referring to the manual as far as possible without having to depend on the office to give information. The complete set of manual for each of the storage works should be personally handed over to successor by each concerned officer.

Copies of the maintenance manual shall be maintained at all offices right from sectional office to Circle office.

It is also necessary that the manuals are inspected at the time of inspection by the superior officers. Record of handing over and inspection should be maintained.

5. Record Drawing & Completion Report :

The importance of record drawings & completion report as an archival data need not be emphasized. All efforts should be made by field engineers to prepare Record Drawing & Completion Report and store them for future reference.

Sr. No.	Name of CE	Total	Received	Not Received	Remarks
1	C.E. (W.R.)Pune	48	24	24	All EAP must be
2	C.E. (S.P.) Pune	21	5	16	CWC guide lines
3	Private Dams	7	0	7	2016 & copy of EAP
	Total	76	29	47	should be made available to DSO.

Table-6.1 Status of Emergency Action Plan (EAP)

Table-6.2 Status of Reservoir Operation Schedule (ROS)

Sr. No.	Name of CE	Total	Received	Not Received	Remarks
1	C.E. (W.R.)Pune	24	22	2	Updated copy of
2	C.E. (S.P.) Pune	14	12	2	RUS snould be
3	Private Dams	2	1	1	DSO.
	Total	40	35	5	

Table-6.3 Status of Gate Operation Schedule (GOS)

Sr. No.	Name of CE	Total	Received	Not Received	Remarks
1	C.E. (W.R.) Pune	24	22	2	Updated copy of
2	C.E. (S.P.) Pune	14	8	6	GOS snoula be
3	Private Dams	2	0	2	DSO.
	Total	40	30	10	

Table-6.4 Dam Wise Status of GOS & ROS, EAP (Class-I Dams)

Sr.No.	Name of dam	GOS	ROS	EAP					
1	2	3	4	5					
	Pune Region								
A)Chief Engineer(W.R.)Water Resources Department Pune									
I) Superintending Engineer, Pune Irrigation Circle, Pune									
1) Executive Engineer, Pune Irrigation Division, Pune									
1	Jadhavwadi(UG)	-	_	NR					
2	Niradevghar	NR	R(2006)	R(2007)					
3	Bhatghar(AG)	AG	AG	R(2006)					
4	Vadivale	R(2002)	R(2009)	R(2006)					
5	Andravalley(UG)	-	-	R(2014)					
6	Kasarsai	NR	R(2007)	NR					
2) Executiv	ve Engineer ,Chaskaman Irr	igation division, Pun	e						
7	Aralakalmodi(UG)	-	-	R(2014)					
8	BhamaAskhed	NR	R(2015)	R(2014)					
9	Chaskaman	NR	R(2015)	NR					
3) Executiv	ve Engineer, Lift Irrigation	Management Divisio	n, Pune						
10	Nazare(AG)	AG	AG	NR					
4) Executiv	ve Engineer ,Khadakwasala	Irrigation Division, P	une 11						
11	Panshet	NR	R(2015)	NR					
12	Khadakvasal	NR	R(2015)	NR					
13	Warasgaon	NR	R(2015)	NR					
14	Pawana	NR	R(2015)	NR					
5)Executiv	e Engineer, Nira Right Bank	Canal Division, Pha	Itan ,Dist. Satara						
15	Veer	R(1990)	R(2010)	R(1993)					
II) Superin	tending Engineer, Pune Irri	gation Project Circle	,Pune						
1) Executive Engineer, BhamaAskhed Dam Division, Pune									
16	Temghar(UG)	-	-	R(2006)					
2)Executiv	e Engineer, Niradevghar Pro	oject Division, Sanga	vi(Bhatghar),Tal.	Bhor,Dist.Pune					
17	Gunjavani	NR	NR	R(2004)					
III) Superir	III) Superintending EngineerSangli Irrigation circle, Sangli								

Sr.No.	Name of dam	GOS	ROS	EAP					
1	2	3	4	5					
1) Executiv	1) Executive Engineer ,Sangli Irrigation Division, Sangli								
18	Morna (Shirala) (UG)	-	-	NR					
2)Executive Engineer ,Tembhu Lift Irrigation Project Managementb Division, Ogalewadi									
19	YevatiMasoli(UG)	-	-	NR					
3)Executiv	e Engineer ,Takari Pump Ho	ouse Division No.1, I	Devrashtre						
20	Satpewadi Barrage	NR	NR	NR					
IV) Superii	ntending Engineer Kolhapu	r Irrigation Circle, Ko	olhapur						
1) Executiv	ve Engineer , Medium Projec	ct Division No2, Kolh	apur						
21	Ghatprabha(Phatakwadi) (UG)	_	_	NR					
22	Chikotra	NR	R(2015)	NR					
23	Jangamhatti(UG)	_	_	NR					
24	Keloshi Bk. (UG)	_	_	NR					
25	Jambre(UG)	-	-	NR					
2)Executiv	e Engineer, Kolhapur Irrigat	ion Dn.(North) Kolha	apur						
26	Kadavi(UG)	-	-	NR					
27	Kasari	NR	R(2015)	NR					
28	Kumbhi	NR	R(2008)	NR					
29	Paleshwar(UG)	_	_	R(2014)					
30	Tulashi	R(1998)	R(2007)	R(1998)					
31	Upwade(UG)	_	_	NR					
32	Radhanagari(UG)	AG	AG	NR					
33	Warana	R(1999)	R(2007)	R(2007)					
34	Dudhaganga	R(1997)	R(2009)	R(2007)					
3)Executiv	3)Executive Engineer, Kolhapur Irrigation Dn.(South) Kolhapur								

Sr.No.	Name of dam	GOS	ROS	EAP
1	2	3	4	5
35	Patgaon(UG)	_	-	NR
36	Ambewadi(UG)	_	_	NR
37	Chitri(UG)	-	-	NR
38	Kitwad-2(UG)	_	-	R(2014)
39	Kondoshi(UG)	_	-	R(2014)
40	Lakikatti(UG)	_	-	R(2014)
41	Megholi(UG)	_	-	R(2010)
42	Phaye(UG)	_	-	R(2014)
V)Superin	tending EngineerSatara Irri	gation Circle, Satara		
1)Executiv	ve Engineer, Koyna Irrigatior	n Division Koynanag	ar	
43	Koyna	R (2006)	R(2009)	R(2010)
44	Kolkewadi	R (1990)	R(2009)	R(2011)
2)Executi	ve Engineer, Satara Irrigatio	n Division Satara		
45	Dhom	R(1984)	R(2007)	R(2001)
46	Dhombalkawadi	R(2016)	R(2007)	R(2008)
3)Executi	ve Engineer, Krishna Irrigati	on Division, Satara		
47	Urmodi	NR	R(2015)	R(2008)
48	Kanher	R(1984)	R(2015)	R(2001)
	Total	24	24	48
	(R) Received	10	22	24
	(NR) Not Received	14	02	24
B)Chief E	ingineer(S.P.) Water Resourc	ces Department Pune	•	
I) Superin	tending Engineer Kukadi Irri	gation Circle Pune		

Sr.No.	Name of dam	GOS	ROS	EAP			
1	2	3	4	5			
1) Executi	1) Executive Engineer, Kukadi Irrigation Div. 1 Narayangaon						
49	Wadaj	R(1990)	R(2015)	NR			
50	Yedgaon	R(1989)	R(2015)	R(1983)			
51	Manikdoh	R(1990)	R(2007)	NR			
52	Pimpalgaonjoge	NR	R(2015)	NR			
53	Dimbhe	R(2007)	R(2007)	R(2014)			
2)Executiv	ve Engineer, Kukadi Irrigatio	on Div.2 Shrigonda	·				
54	Ghod	R(1997)	R(2015)	NR			
3)Executiv	e Engineer ,Kukadi Irrigatio	n Division No. 2, Sh	rigonda				
55	Sina(UG)	-	-	NR			
4)Executiv	ve Engineer, Dimbhe Dam D	iv. Manchar					
56	Chillewadi	R(2014)	R(2015)	R(2014)			
II) Superin	tending EngineerSatara Irri	gation Project Circle	e, Satara				
1) Executi	ve Engineer,Minor Irrigatio	on Division, Satara					
57	Uttarmand	NR	R(2015)	NR			
58	Morna(Gureghar)	NR	R(2016)	NR			
59	Nagewadi(UG)	_	-	NR			
60	Kusawade(UG)	-	-	NR			
61	Kalgaon(UG)	-	-	NR			
62	Pangare(UG)	-	-	NR			
2)Executiv	e Engineer ,Kanher Canal D	ivision No.2, Karwa	di,Karad.				
63	Tarali	NR	R(2016)	R(2008)			
3)Executiv	e Engineer, Dhom Canal Div	vision No.2,Satara	· · · · · · · · · · · · · · · · · · ·				
64	Mahu	NR	NR	NR			

Sr.No.	Name of dam	GOS	ROS	EAP			
1	2	3	4	5			
65	Hatgeghar(UG)	-	_	NR			
III) Superir	ntending Engineer & Admin	istrator, C.A.D.A. So	lapur				
1) Executiv	1) Executive Engineer, Solapur Irrigation Division Solapur						
66	Bori	R(2007)	R(2007)	NR			
67	Ekrukh(UG)	-	-	NR			
2)Executiv	e Engineer, Ujjani Dam Mar	nagement Division B	Shimanagar Dist. S	Solapur			
68	Ujjani	R(1990)	R(2015)	R(2007)			
IV)Superin	tending Engineer Osmanat	ad Irrigation Circle (Dsmanabad				
1)Executiv	e Engineer, Sinakolegaon P	roject Division Parar	ndaDist.Osmanaba	ad			
69	Sinakolegaon	NR	NR	NR			
	Total	14	14	21			
	(R) Received	8	12	5			
	(NR) Not Received	6	2	16			
		Private Dam					
Tata Powe	r Co, Ltd. Khopoli						
1	Mulsi	NR	R(2016)	NR			
2	Shirvata(AG)	-	-	NR			
3	Thokarwadi	NR	NR	NR			
4	Walvan(AG)	-	-	NR			
Ambevally	(SAHARA)			I			
5	Ambewane (UG)	-	-	NR			
6	Visakhar (UG)	-	-	NR			
7	Koliwali (UG)	-	-	NR			

Sr.No.	Name of dam	GOS	ROS	EAP
1	2	3	4	5
	Total	2	2	7
	(R) Received	0	1	0
	(NR) Not Received	2	1	7

Sr		Total Completion Report		Record Drawing		Data Book		O&M Manual		
No.	Name of CE	no. Of	Received	Not	Received	Not	Received	Not	Received	Not
		dams	Received	Received	Received	Received	Received	Received	Received	Received
1	CE, WR Pune	48	5	43	17	31	9	39	5	43
2	CE, SP, Pune	21	0	21	0	21	1	20	1	20
	Private Dam	7	0	7	0	7	0	7	0	7
	Total	76	5	71	17	59	10	66	6	70

Table-6.5 Status of Other NCDS Documents (Class-I Dams)

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual
1	2	3	4	5	
		Pune Regi	on		
A)Chief Er	ngineer(W.R.)Water Resourc	es Department Pu	ne		
I) Superint	ending Engineer, Pune Irrig	gation Circle, Pune)		
1) Executiv	ve Engineer, Pune Irrigatio	n Division, Pune			
1	Jadhavwadi	NR	NR	NR	NR
2	Niradevghar	NR	NR	NR	NR
3	Bhatghar	R	R	NR	R
4	Vadivale	NR	NR	NR	NR
5	Andravalley	NR	NR	NR	NR
6	Kasarsai	NR	NR	NR	NR
2) Executiv	ve Engineer ,Chaskaman Irr	igation division, P	une		
7	Aralakalmodi	NR	NR	NR	NR
8	BhamaAskhed	NR	NR	NR	NR
9	Chaskaman	NR	R	NR	NR
3) Executiv	ve Engineer, Lift Irrigation	Management Divis	sion, Pune		
10	Nazare	R	R	R	R
4) Executiv	ve Engineer ,Khadakwasala	Irrigation Division	, Pune 11		
11	Panshet	NR	R	R	NR
12	Khadakwasala	NR	NR	NR	NR
13	Warasgaon	NR	R	NR	NR
14	Pawana	NR	R	NR	NR
5)Executiv	e Engineer, Nira Right Bank	Canal Division, P	haltan ,Dist. S	atara	
15	Veer	R	R	R	R
II) Superin	tending Engineer, Pune Irri	gation Project Circ	le,Pune		
1) Executiv	ve Engineer, BhamaAskhed	dam division, Pur	ne		
16	Temghar	NR	NR	NR	NR
2)Executiv	e Engineer, Niradevghar Pro	oject Division, Sar	ngavi(Bhatghai	r),Tal.Bhor,Dist.Pu	ne
17	Gunjavani	NR	NR	NR	NR

Table-6.6 Dam Wise Status of Other NCDS Documents

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual
1	2	3	4	5	
III) Superir	ntending EngineerSangli Irr	igation circle, San	gli		
1) Executi	ve Engineer ,Sangli Irrigatio	n Division, Sangli			
18	Morna (Shirala)	NR	NR	NR	NR
2)Executiv	e Engineer ,Tembhu Lift Irri	gation Project Mai	nagementb Div	vision, Ogalewadi	
19	YevatiMasoli	NR	NR	NR	NR
3)Executiv	e Engineer ,Takari Pump Ho	ouse Division No.	I, Devrashtre		
20	Satpewadi Barrage	NR	NR	NR	NR
IV) Superi	ntending Engineer Kolhapu	r Irrigation Circle,	Kolhapur		
1) Executiv	ve Engineer , Medium Projec	ct Division No2, Ko	olhapur		
21	Ghatprabha(Phatakwadi	NR	NR	NR	NR
22	Chikotra	NR	R	NR	NR
23	Jangamhatti	NR	NR	NR	NR
24	Keloshi Bk.	NR	NR	NR	NR
25	Jambre	NR	NR	NR	NR
2)Executiv	e Engineer, Kolhapur Irriga	tion Dn.(North) Ko	lhapur		
26	Kadavi	NR	NR	NR	NR
27	Kasari	NR	R	NR	NR
28	Kumbhi	NR	NR	NR	NR
29	Paleshwar	NR	NR	R	NR
30	Tulashi	NR	R	NR	NR
31	Upwade	NR	NR	R	NR
32	Radhanagari	NR	R	NR	NR
33	Warana	NR	R	R	NR

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual	
1	2	3	4	5		
34	Dudhaganga	NR	NR	R	NR	
3)Executiv	e Engineer, Kolhapur Irrigat	tion Dn.(South) Ko	olhapur			
35	Patgaon	NR	R	NR	NR	
36	Ambewadi	NR	NR	NR	NR	
37	Chitri	NR	NR	NR	NR	
38	Kitwad-2	NR	NR	NR	NR	
39	Kondoshi	NR	NR	NR	NR	
40	Lakikatti	NR	NR	NR	NR	
41	Megholi	NR	NR	NR	NR	
42	Phaye	NR	NR	NR	NR	
V)Superin	tending EngineerSatara Irrig	gation Circle, Sata	ra			
1)Executiv	e Engineer, Koyna Irrigatior	n Division Koynan	agar			
43	Koyna	R	R	R	R	
44	Kolkewadi	R	R	R	R	
2)Executiv	e Engineer, Satara Irrigatio	n Division Satara				
45	Dhom	NR	R	NR	NR	
46	Dhombalkawadi	NR	NR	NR	NR	
3)Executiv	3)Executive Engineer, Krishna Irrigation Division, Satara					
47	Urmodi	NR	NR	NR	NR	
48	Kanher	NR	R	NR	NR	
	Total	48	48	48	48	
	(R) Received	5	17	9	5	

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual		
1	2 (ND) Not Depaired	3 43	4 31	5 39	43		
	(NR) NOT Received						
B)Chief E	ngineer(S.P.) Water Resourc	ces Department Pu	ine				
I) Superint	ending Engineer Kukadi Irri	gation Circle Pun	e				
1) Executiv	1) Executive Engineer, Kukadi Irrigation Div. 1 Narayangaon						
49	Wadaj	NR	NR	NR	NR		
50	Yedgaon	NR	NR	NR	NR		
51	Manikdoh	NR	NR	NR	NR		
52	Pimpalgaonjoge	NR	NR	NR	NR		
53	Dimbhe	NR	NR	NR	NR		
2)Executiv	e Engineer, Kukadi Irrigatio	on Div.2 Shrigonda	1				
54	Ghod	NR	NR	NR	NR		
3)Executiv	e Engineer ,Kukadi Irrigatio	n Division No. 2, S	hrigonda				
55	Sina	NR	NR	NR	NR		
4)Executiv	e Engineer, Dimbhe Dam D	iv. Manchar					
56	Chillewadi	NR	NR	NR	NR		
II) Superin	tending EngineerSatara Irri	gation Project Cire	cle, Satara				
1) Executiv	ve Engineer, Minor Irrigatio	on Division, Satara					
57	Uttarmand	NR	NR	NR	NR		
58	Morna(Gureghar)	NR	NR	NR	NR		
59	Nagewadi	NR	NR	NR	NR		
60	Kusawade	NR	NR	NR	NR		
61	Kalgaon	NR	NR	NR	NR		
62	Pangare	NR	NR	NR	NR		

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual		
1	2	3	4	5			
2)Executiv	e Engineer ,Kanher Canal D	vivision No.2, Karw	adi,Karad.				
63	Tarali	NR	NR	NR	NR		
3)Executiv	e Engineer, Dhom Canal Div	vision No.2,Satara					
64	Mahu	NR	NR	NR	NR		
65	Hatgeghar	NR	NR	NR	NR		
III) Superir	ntending Engineer & Admin	istrator, C.A.D.A.	Solapur				
1) Executiv	ve Engineer, Solapur Irrigati	on Division Solap	our				
66	Bori	NR	NR	NR	NR		
67	Ekrukh	NR	NR	NR	NR		
2)Executiv	2)Executive Engineer, Ujjani Dam Management Division Bhimanagar Dist. Solapur						
68	Ujjani	NR	NR	R	R		
IV)Superin	tending Engineer Osmanak	bad Irrigation Circl	e Osmanabad				
1)Executiv	e Engineer, Sinakolegaon P	Project Division Pa	randaDist.Osr	nanabad			
69	Sinakolegaon	NR	NR	NR	NR		
	Total	21	21	21	21		
	(R) Received	0	0	1	1		
	(NR) Not Received	21	21	20	20		
		Private Da	m				
Tata Power	Co, Ltd. Khopoli						
1	Mulsi	NR	NR	NR	NR		
2	Shirvata(AG)	NR	NR	NR	NR		
3	Thokarwadi	NR	NR	NR	NR		
4	Walvan(AG)	NR	NR	NR	NR		

Sr.No.	Name of dam	Completion Report	Record Drawing	Data Book	O& M Manual				
1	2	3	4	5					
Ambevally (Ambevally (SAHARA)								
5	Ambewane (UG)	NR	NR	NR	NR				
6	Visakhar (UG)	NR	NR	NR	NR				
7	Koliwali (UG)	NR	NR	NR	NR				
	Total	7	7	7	7				
	(R) Received	0	0	0	0				
	(NR) Not Received	7	7	7	7				



Part-7 DHARMA: Dam Health and Rehabilitation monitoring application

Introduction :

Dam health & Rehabilitation Monitoring application (DHARMA) is a web based asset management software to support the effective collection and management of authentic asset and health data for all large dams in India and address key dam safety challenges of

- i)Insuring Completeness of information.
- ii) Bring stake holders together
- iii) Effectively managing asset inventory.
- iv) Assess soundness of dame health.

Design and Development :

DHARMA software will consist of seven modules.

i)project features

- ii) Project portfolio
- iii) Engineering features.
- iv)Asset health.
- v) Asset rehabilitation.
- vi) Stake holders and
- vii) Document library.

The first three modules (i to iii consist of mostly static data, to be enter once and rarely undergo a change where as modules iv) and v) will be dynamic and requires regular updating with information associated with inspections investigations, instrumentation and rehabilitation works. Modules vi) and vii)contain information useful for reference.

All field EE's are required to fillup attached two forms (Dam Data Manager & Dam Health Engineer) for each Dam in their jurisdiction by 15th July 2021 & its review will be taken by Hon. DG, MERI, Nashik by 15th Aug 2021.

DHARMA DHARMAApplicationUserRegistrationForm



Dam Data Manager

1.	Date of Application:	< dd/mm/yyyy>			
2.	Type of User:	DamDataManager			
3.	Name of the Applicant:	<title>. <name></name></title>			
4.	Designation:				
5.	Name of the Organization:				
6.	Complete Postal Address:				
7.	Email ID:				
8.	Mobile Number:	Office Tel. Number:			
9.	Current Responsibilities:	 Coordinating DamSafety Water ResourceManagement DamDesign Dam Construction /Rehabilitation DamOperations Academic /Research Other: Colleases			
10.	Viewing Permission Required for:	 ProjectFeatures ProjectPortfolio EngineeringFeatures 			
11.	Editing Permission Required for:	 ProjectFeatures ProjectPortfolio EngineeringFeatures 			
12.	Provide List of Dams				

Please select out of the choice provided; add separate sheets for providing additional information.

Declaration: I, hereby declare that the information provided in the application is true. I further declare that I will not use the information collected from DHARMA software for any unlawful activities and/or to the detriment of the Central or StateGovernments.

Signature and Seal / stamp	Signature:	
	Name:	
of the Applicant:	Designation:	
	Seal / Stamp:	

Please send the completed Application Form to the concerned Licensee.



DHARMAApplicationUserRegistrationForm Dam Health Engineer



1.	Date of Application:	< dd/mm/yyyy>							
2.	Type of User:	JamHealthEngineer							
3.	Name of the Applicant:	<title>. <name></name></title>							
4.	Designation:								
5.	Name of the Organization:								
6.	Complete Postal Address:								
7.	Email ID:								
8.	Mobile Number:	Office Tel. Number:							
9.	Current Responsibilities:	 Coordinating DamSafety Water ResourceManagement DamDesign Dam Construction /Rehabilitation DamOperations Academic /Research Other: <pleasespecify></pleasespecify> 							
10.	Viewing Permission Required for:	 Project Features Project Portfolio Engineering Features 							
11.	Editing Permission Required for:	 Project Features Project Portfolio Engineering Features 							
12.	Provide List of Dams								

Please select out of the choice provided; add separate sheets for providing additional information.

Declaration: I, hereby declare that the information provided in the application is true. I further declare that I will not use the information collected from DHARMA software for any unlawful activities and/or to the detriment of the Central or StateGovernments.

	Signature:	
Signature and Seal / stamp of the Applicant:	Name:	
	Designation:	
	Seal / Stamp:	

Please send the completed Application Form to the concerned Licensee.

TABLE – 7.1

Data filling status on Dam Health and Rehabilitation Monitoring Application (DHARMA) portal of Pune Region.

Sr.	Name of Dam	NRLD	Dharma data	Remarks							
No		registration	filling status								
		number	(%)								
[A]Chi	ef Engineer(W.R.)Water Res	ources Department	Pune								
(1)Sup	perintending Engineer, Pune	e Irrigation Circle, P	une								
(a)Exe	cutive Engineer, Pune Irrig	ation Division, Pune	9								
1.	Jadhavwadi	MH09HH1587	10								
2.	Nira devghar	MH09HH1554	10								
3.											
4. Vadivale MH09MH1517 11											
5.	Andravalley	MH09HH1622	11								
6.	Kasarsai	MH09MH1373	11								
(b)Exe	cutive Engineer ,Chaskama	n Irrigation division	, Pune								
7.	Aralakalmodi	MH09HH1672	9								
8.	BhamaAskhed	MH09HH1559	10								
9.	Chaskaman	MH09HH1522	10								
(c)Exe	(c)Executive Engineer , Lift Irrigation Management Division, Pune										
10. Nazare MH09MH0453 10											
d) Exe	cutive Engineer ,Khadakwa	sala Irrigation Divisi	ion, Pune 11								
11.	Panshet	MH09HH0310	10								
12.	Khadakvasal	MH09HH 0013	11								
13.	Warasgaon	MH09HH0592	10								
14.	Pawana	MH09HH0311	10								
(e)Exe	cutive Engineer, Nira Right	Bank Canal Divisior	n, Phaltan ,Dist. S	atara							
15.	Veer	MH09HH0116	10								
(2)Sup	erintending Engineer, Pune	e Irrigation Project C	Circle, Pune								
(a) Exe	ecutive Engineer, BhamaAsl	khed dam division, p	pune								
16.	Temghar	MH09HH1544	10								
(c)Exe	cutive Engineer, Niradevgha	ar Project Division,	•								
Sanga	vi(Bhatghar),Tal.Bhor,Dist.F	Pune									
17.	Gunjavani	MH09HH1552	11								
(3)Sup	perintending Engineer Sang	li Irrigation circle, S	angli								
(a)Exe	cutive Engineer ,Sangli Irrig	ation Division, San	gli								
18.	Morna (Shirala)	MH09HH1101	11								
(b)Exe	cutive Engineer ,Tembhu Li	ft Irrigation Project	Management Divi	sion, Ogalewadi							
19.	Yevati masoli	MH09HH1218	10								
(c)Exe	cutive Engineer ,Takari Pun	np House Division N	No.1, Devrashtre								
20.	Satpewadi barrage	MH09MH2406	07								
(4)Sup	perintending Engineer Kolha	apur Irrigation Circle	e,Kolhapur								
(a)Exe	cutive Engineer, Medium P	roject Division No2,	Kolhapur								
21.	Ghatprabha(Phatakwadi	MH09HH 1900	11								
22.	Chikotra	MH09HH1582	10								
23.	Jangamhatti	MH09MH1366	10								
24.	Keloshi Bk.	MH09HH1935	09								

Sr.	Name of Dam	NRLD	Dharma data	Remarks
No		registration	filling status	
		number	(%)	
25.	Jambre	MH09HH1921	11	
(b)Exe	cutive Engineer, Kolhapur I	rrigation Dn.(North)	Kolhapur	1
26.	Kadavi	MH09HH1541	10	
27.	Kasari	MH09HH1245	11	
28.	Kumbhi	MH09HH1671	10	
29.	Paleshwar	MH09HH1546	11	
30.	Tulashi	MH09HH0726	03	
31.	Upwade	MH09HH1385	03	
32.	Radhanagari	MH09HH0067	10	
33.	Warana	MH09HH1542	14	
34.	Dudhaganga	MH09HH1226	10	
(c)Exe	cutive Engineer, Kolhapur I	rrigation Dn.(South)	Kolhapur	1
35.	Patgaon	MH09HH1242	10	
36.	Ambewadi	MH09HH1899	11	
37.	Chitri	MH09HH1586	11	
38.	Kitwad-2	MH09HH1902	11	
39.	Kondoshi	MH09HH1533	10	
40.	Lakikatti	MH09HH1538	11	
41.	Megholi	MH09HH1536	10	
42.	Phaye	MH09HH1629	11	
(5)Sup	erintending Engineer Satar	a Irrigation Circle, S	Satara	
a)Exec	utive Engineer, Koyna Irriga	ation Division Koyna	anagar	
43.	Koyna	MH09VH0100	50	
44.	Kolkewadi	MH09HH0527	27	
(b)Exe	cutive Engineer, Satara Irrig	ation Division Sata	ra	
45.	Dhom	MH09HH0655	56	
46.	Dhombalkawadi	MH09HH1665	10	
(c) Exe	ecutive Engineer, Krishna Ir	rigation Division, Sa	atara	
47.	Urmodi	MH09HH1594	08	
48.	Kanher	MH09HH1141	50	
[B]Chi	ef Engineer(S.P.) Water Res	ources Department	Pune	
(1)Sup	erintending Engineer Kukao	di Irrigation Circle F	Pune	
(a) Exe	ecutive Engineer, Kukadi Irr	igation Div. 1 Naray	rangaon	1
49.	Wadaj	MH09HH1006	11	
50.	Yedgaon	MH09MH0658	11	
51.	Manikdoh	MH09HH1060	51	
52.	Pimpalgaonjoge	MH09MH1520	11	
53.	Dimbhe	MH09HH1558	52	
(b) Exe	ecutive Engineer, Kukadi Iri	rigation Div.2 Shrigo	onda	
54.	Ghod	MH09MH0117	11	
c) Exe	cutive Engineer ,Kukadi Irrig	gation Division No. 2	2, Shrigonda	
55.	Sina	MH09MH1142	11	
(d) Exe	ecutive Engineer, Dimbhe D	am Div. Manchar		1
56.	Chilewadi	MH09HH1553	11	

Sr.	Name of Dam	NRLD	Dharma data	Remarks							
No		registration	filling status								
		number	(%)								
(2)Superintending Engineer Satara Irrigation Project Circle, Satara											
(a)Exe	(a)Executive Engineer, Minor Irrigation Division, Satara										
57.	Uttarmand	MH09HH1591	10								
58.	Morna(Gureghar)	MH09HH1664	11								
59.	Nagewadi	MH09HH1518	11								
60.	Kalgaon	MH09HH2411	07								
61.	Kusawade	MH09HH2416	09								
(b)Exe	cutive Engineer ,Kanher Ca	nal Division No.2, K	arwadi,Karad.								
62. Tarali MH09HH1666 09											
(c)Exe	cutive Engineer, Dhom Can	al Division No.2,Sat	ara								
63.	Mahu	MH09HH1588	10								
64.	Hatgeghar	MH09HH1568	11								
65.	Pangare			NRLD Updation is Pending							
(3)Sup	erintending Engineer & Ad	ministrator, C.A.D.A	. Solapur								
(a) Exe	ecutive Engineer, Solapur Ir	rigation Division Sc	olapur								
66.	Bori	MH09MH1650	11								
67.	Ekrukh	MH09MH0007	11								
(b)Exe	cutive Engineer, Ujjani Dan	n Management Divis	sion Bhimanagar	Dist. Solapur							
68.	Ujjani	MH09HH0843	66								
(4)Sup	erintending Engineer Osma	anabad Irrigation Ci	rcle Osmanabad								
(a)Exe	cutive Engineer, Sinakolega	on Project Division	ParandaDist.Osn	nanabad							
69.	Sinakolegaon	MH09HH1673	55								

Part-8 **Health Status of Gated Dam** (As per Mechanical Organization)

Part- 8 Health Status of Gated Dam (As per Mechanical Organisation)

8.1 General

As per GR.NO.ID/1078/23/8/IMP/2 Dtd.10/09/1980, Dam Safety Organization has been established by Government of Maharashtra for effective monitoring the safety aspects of dam.

As per Maharashtra Government Guidelines and regulation, Chief Engineer (Mechanical), Water Resources Dept. Nashik assigned Dams gate Inspection work to Superintending Engineer, Mechanical Circle, Nashik to assure proper operation and maintenance of Dam gates

Under Superintending Engineer, Mechanical Circle, Nashik Executive Engineer, Inspection unit, Aurangabad and Executive Engineer, Sluice Gate Mfg. Division, Dapodi, Pune are looking after all the inspection works.

Division offices Conduct all pre monsoon & Post Monsoon Gate Inspection work of Government, Semi Government, & Private Dams and send Reports to related authorities for same.

After Inspection work the observed points or deficiencies are classified into various categories as given below.

Def. Category-1	Dams with Major Deficiencies which may lead to dam failure	Very Serious Defects			
Def. Category-2	Dams with rectifiable Deficiencies	Serious Defects (2A)			
(Z A)& (ZB)	needs immediate attention	Require immediate attention (2B)			
Def. Category-3	General Defects	General Defects			

In the year of 2021 Pre and Post Monsoon inspection of total 161 Gated dams have been carried out by Mechanical Organization. It is to be noted that Chief engineer (Mechanical) W.R.D Nashik, prepares independently the detail Health status Report of all the gated dams inspected by mechanical Organization. This report is published and submitted to WRD and circulated to all Concern Chief Engineers.

In this Health Status Report, only the dam wise numbers of deficiencies noted by mechanical Organization are given in this part of ADHSR. For details regarding the actual deficiencies Health Status Report circulated by Mechanical Organization shall be referred.

8.2 Overall Health Statues of Gated Dams

40 Class-I gated dams in the Pune region are inspected by Mechanical Organization.

Category -1 deficiency is not observed on any dam. Category -2 & 3 deficiencies are observed on all the 40 dams. Total 863 Category -2 deficiencies and total 2149 Category -3 deficiencies are observed on the dams in the region.

Table 8.1Status of Deficiencies

		Number of Gated Dams			Report	Da	Dam category - I			Dam category - II		
Sr.	Region & Name of	as per	dam Cate	egory	Taken	Ε	Difficienci	es	D	ifficien	cies	
No.	Dam	Cat-I	Cat-II	Total	Into Account	Cat-I	Cat-II	Cat-III	Cat-I	Cat- II	Cat-III	
1	2	3	4	5	6	7	8	9	10	11	12	
	Pune Region											
1	Kasarsai	1	0	1	Yes	0	32	105	0	0	0	
2	Wadivale	1	0	1	Yes	0	49	83	0	0	0	
3	Bhataghar	1	0	1	Yes	0	9	29	0	0	0	
4	Niradevghar	1	0	1	Yes	0	19	56	0	0	0	
5	Khadakwasla	1	0	1	Yes	0	44	105	0	0	0	
6	Pawana	1	0	1	Yes	0	22	33	0	0	0	
7	Varasgaon	1	0	1	Yes	0	37	94	0	0	0	
8	Panshet	1	0	1	Yes	0	27	59	0	0	0	
9	Bhama Askhed	1	0	1	Yes	0	41	56	0	0	0	
10	Chasakaman	1	0	1	Yes	0	42	66	0	0	0	
11	Gunjawani	1	0	1	Yes	0	10	31	0	0	0	

		Number of Gated Dams			Report	ort Dam category - I			Dam category - II		
Sr.	Region & Name of	as per	dam Cate	egory	Taken	[Difficienci	es	D	ifficien	cies
No.	Dam	Cat-I	Cat-II	Total	Into Account	Cat-I	Cat-II	Cat-III	Cat-I	Cat- II	Cat-III
1	2	3	4	5	6	7	8	9	10	11	12
12	Veer	1	0	1	Yes	0	26	27	0	0	0
13	Ghod	1	0	1	Yes	0	16	46	0	0	0
14	Mula	1	0	1	Yes	0	27	56	0	0	0
15	Kumbhi	1	0	1	Yes	0	20	37	0	0	0
16	Warna	1	0	1	Yes	0	39	78	0	0	0
17	Tulshi	1	0	1	Yes	0	14	41	0	0	0
18	Radhanagari	1	0	1	Yes	0	20	38	0	0	0
19	Kasari	1	0	1	Yes	0	22	67	0	0	0
20	Dudhganga	1	0	1	Yes	0	38	125	0	0	0
21	Chikotra	1	0	1	Yes	0	11	49	0	0	0
22	Koyana Dam	1	0	1	Yes	0	30	13	0	0	0
23	Kolakewadi	1	0	1	Yes	0	23	62	0	0	0
24	Dimbhe	1	0	1	Yes	0	31	61	0	0	0

		Number of Gated Dams			Report	Da	m category - I		Dam category - II		
Sr.	Region & Name of	as per	dam Cate	egory	Taken	[Difficienci	es	D	ifficien	cies
No.	Dam	Cat-I	Cat-II	Total	Into Account	Cat-I	Cat-II	Cat-III	Cat-I	Cat- II	Cat-III
1	2	3	4	5	6	7	8	9	10	11	12
25	Manikdoh	1	0	1	Yes	0	23	60	0	0	0
26	Wadaj	1	0	1	Yes	0	12	28	0	0	0
27	Pimpalgaon Joge	1	0	1	Yes	0	3	50	0	0	0
28	Yedgaon	1	0	1	Yes	0	10	29	0	0	0
29	Chilhewadi	1	0	1	Yes	0	14	37	0	0	0
30	Dhom	1	0	1	Yes	0	15	46	0	0	0
31	Dhom balakawadi	1	0	1	Yes	0	8	29	0	0	0
32	Kanher	1	0	1	Yes	0	13	45	0	0	0
33	Urmodi	1	0	1	Yes	0	9	44	0	0	0
34	Mahu	1	0	1	Yes	0	10	57	0	0	0
35	Tarali	1	0	1	Yes	0	13	56	0	0	0
36	Uttarmand	1	0	1	Yes	0	5	35	0	0	0
37	Morna gureghar	1	0	1	Yes	0	8	45	0	0	0
		Number of Gated Dams			Report	Dam category - I Difficiencies			Dam category - II		
-----	------------------	----------------------	--------	-------	---------	-----------------------------------	--------	---------	-------------------	------	---------
Sr.	Region & Name of	as per dam Category			Taken				Difficiencies		
No.	Dam	Cat-I	Cat-II	Total	Into	Cat-I	Cat-II	Cat-III	Cat-I	Cat-	Cat-III
		Cat-i	Cat-II	Total	Account	Cat-I	Cat-II	Cat-III	Cat		Cat-III
1	2	3	4	5	6	7	8	9	10	11	12
38	Ujani	1	0	1	Yes	0	52	71	0	0	0
39	Bori	1	0	1	Yes	0	14	65	0	0	0
	Private Dam										
40	Mulashi	1	0	1	Yes	0	5	35	0	0	0
	Total	40	0	40		0	863	2149	0	0	0



Kanher Dam